

ABT Burner Issues

Discussion with Staff

October 26, 2005

History

F3 Burner Fire

- Melt Down of Coal Nozzle
- New Burner Module on Order (delivery in late Nov.)
- Suspect erosion of nozzle as cause
- Inspected all 6 burners during U2 tube-leak outage

Elbow Damage

- F1 & F2, eroded through elbows
- F4 & F5, eroded through inner ceramic lining

Nozzles

- F6; coal erosion at 3:00 and 9:00 o'clock at exit from X-vane

Tip Damage

- Erosion at 11:00 and 1:00 o'clock positions
 - All of F tips
 - E1 E6 C2 & C5
- Cracking of tip noted in all of F, E1 and C2
- Warping of CS at tip on all of F nozzles. (Overheat in out-of-service burners)

Thermocouples

- 1/4" TC's can't be inserted into thermowells
 - Tight bends
 - Pipe rather than tubing used
- 1/16" TC's substituted
- Temperature switches disabled
- Alarms added to TC's

ABT

Reply to initial letter

- Wear parts
- Velocities higher than design conditions
- Deny warrantee claims
- Invited (Tuesday) to site for U2 outage; did not send anyone
- Have sent them preliminary findings and photos

Pulverizer Issues

Biases

- High PA Flows (duct pressures up)
- Feeder biases
- Improper limits on F-row for 5-burners

Options

Classifiers

8-mill operation

Redesign burners with ABT

Change PA flow curves for new rotating throats

Modify elbows

Other suggestions?

Actions



271 Route 202/206
P.O. Box 410
Pluckemin, NJ 07978
P 908.470.0470
F 908.470.0479

www.advancedburner.com

August 16, 2006

Mr. George W. Cross
President and Chief Operations Officer
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, Utah 84624

Subject: Intermountain Generating Station Unit 2 Low NO_x Burners

Ref: Response to IPSC Letter Dated July 31, 2006

Dear Mr. Cross:

Having reviewed the referenced letter it is clear that there are significant misunderstandings regarding our positions, design conditions, evaluations of the problems being reported and our actual experience. It is regrettable that you choose to claim that ABT has fallen "short of the claims, guarantees and warranties" provided for in the contract. In truth, all of our claims have been and are correct and we have met or exceeded all performance guarantees expressed in the contract; in addition to our predictions. It now appears that, regardless of our previously supplied objective comments, which we do not consider differences of opinions or viewpoints, you have chosen to make a warranty claim for damage that you have been led to believe is ABT's fault.

Regarding our claims: if IPSC personnel have not already done so, we suggest that they contact all of the references we have provided as part of the proposal phase. You will find that all of the claims we made were true at that time and since.

Regarding performance guarantees: You may be aware that our service manager, Tarkel Larson, was at the site to start up the boiler. Although we were ready at that time to commence optimization, the station was not. The reason we were given was that the test grid was not ready and we should leave and would be called back "soon". After nearly six weeks we called to enquire when we could return to perform the testing. At that time we were told that the station was attempting to tune our burners using new flame scanners and burner air flow measurements and those attempts were not successful. In fact we were told there must be something wrong with our burners since attempting to move the flame so as to see changes in the new scanners was proving unsuccessful. Had we been advised that this was the plant's intent, we would have advised against it. For the simple fact that we have gone to considerable extent to develop a low NO_x burner that produces a very stable flame, low NO_x, low CO and UBC and very good turndown. Once the grid was installed we demonstrated all guarantees in a matter of days. All retentions were then paid.

While it is not my intention to respond here to all the comments in your multi-page letter, I do have a few brief comments to make:

Overheating: The only concern that IPSC personnel ever expressed to ABT was overheating of the original B&W registers. IPSC insisted on substituting a high alloy steel, 253 MA, for the other carbon and stainless steels we normally use; despite our assurances that we have never experienced, with our registers, the high temperatures in the register locations that were of concern and that we saw no need to substitute exotic materials for our normal ones. Nevertheless, the plant chose to proceed with the 253 MA.

JV-GC8-16-06.DOC

IP7_031180



Subsequent to the startup at no time did the register temperatures exceed the normal values we have seen, thereby confirming our predictions.

However, as I noted in previous correspondence, at no time was ABT ever informed that high burner barrel temperatures had been experienced with the OEM burners and that the solution was adding an extension made of stainless steel; this is a completely different problem than the register temperature. Clearly ABT should have been advised of this history so that we could make our own design decisions as to how to deal with that problem (which we have never seen on any other B&W burners we have replaced; thereby indicating that there is something amiss at Delta). As you have noted it is not IPSC's responsibility to design our equipment; but as I have noted it is incumbent upon IPSC to provide us with any and all relevant information so that we can design to the proper conditions. Clearly, ABT was not provided all the relevant information.

Large Burner Throats: It seems clear that you have completely misunderstood my comments. No, we are not "just beginning to understand that burner fronts with large throats can cause overheating in the barrel." Quite the contrary: on installations of ours with large burner throats, none have ever experienced overheating problems on any part of the burner. We have installations on very hot pre-NSPS boilers with 52" throats that have been in service since the late 1990's with no such indications, let alone failures.

In fact there is a site that has our first installation in Vernal, Utah, Deseret's Bonanza #1, which has burners installed in 1997, has 54" throats and has had no problems of reliability. This unit typically operates at NO_x levels in the 0.35-0.4 range and is not equipped with overfire air. You should also note that when Deseret became aware that their operating conditions could change they asked us to do an evaluation of the new conditions and render an opinion (which we did at not cost to them) rather than make assumptions as to how our equipment would react under the new conditions. As a consequence, that plant has had no problems even though they have made major modifications to their operation.

To repeat: there is no ABT installation that suffers the problems that occur at Delta #2. Logic as well as common sense would dictate that the problem is not in the burner design but in the site-specific conditions that ABT was never notified about. The responsibility to provide the burner design conditions, and maintain them during operations, remains with the owner; in this case IPSC.

All of the above notwithstanding, we have been very clear all along that we are willing to work with IPSC to address the situation as it now stands. I suggest that the only way this can be accomplished is by a direct meeting between you and me with no more than one or two of our respective staff members who are most familiar with this retrofit project.

If you are in agreement, please call me to finalize a meeting date (908-470-0720).

Sincerely,



Joel Vatsky, President

Cc: Sal Ferrara

Sept 7, 2006

ABT Burner - Attorney


- Jason, Dean Loral, Gary C, Jerry Lintze
Jon Robinson.

- High ash coal

- 176C didn't challenge their capabilities
Jerry said that he felt uncomfortable
with their abilities


Not the debate over air flows -
discussion about us not accepting
their incompetence.

PROPERTY OF ADVANCED
WITHOUT THE WRITTEN
SYSTEM AND DUAL




DETAIL D
SCALE 1 : 12
THERMOCOUPLE LOCATION

THERMOCOUPLE
PLATE
WELD TO
VERTICAL FLUTE




SECTION C-C
VIEW IS
03008-400-A00-D0
ONLY





DETAIL E
SCALE 1 : 12
BODY THERMOCOUPLE LOCATION


THERMOCOUPLE
PLATE



SECTION F-F



SUPPORT RING
OVER PLATE
STING WINDBOX



SECTION A-A

ABT FUEL DISTRIBUTION

30" OD FLANGE
1 1/8" HOLES
20 PLACES ON
27 1/2" D.B.C.


EXISTING ELBOW

OPEN	5 3/4"
OPEN	16"
NPT	6"
TO OPEN	
PREP	
CP	

A03008	03008-100-A00-D0 CW	24
A03008	03008-100-A00-D0 CCW	24
CONTRACT NO.	PART NO.	QTY.

EST. WEIGHT: 8829.63 lb.
MATERIAL:
SIZE:
TYPE:
ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED

TOLERANCES UNLESS SPECIFIED			CAD DO H
PARTS	MACHINE	WELD FABRICATED	
UP TO 6" INCL	±0.015"	±0.03"	DRAWN CHECKED ENG APPR. MFG APPR. Q.A.
OVER 6" TO 12" INCL	±0.03"	±0.05"	
OVER 12" TO 24" INCL	±0.05"	±0.07"	
OVER 24"	±0.07"	±0.125"	
ANGLES ±10°-30° SURFACE ROUGHNESS NOT EXCEED 125 BREAK SHARP CORNERS DO NOT SCALE PRINT			
CUSTOMER NAME	PLANT NAME	UNIT	
I.P.S.C.	IGS	2	



8	A03008-500-A02-D0	48
CT NO.	PART NO.	QTY.

From: Aaron Nissen
To: Aaron Nissen; Alan Dewsnap; Bob Morris; Dean Wood; Dennis Killian; Garry Christensen; George Cross; Jeff Payne; Jerry Hintze; Joe Duwel; Joe Hamblin; Jon Christensen; Keith Mangrum; Kelly Cloward; Ken Lebbon; Lynn Labrum; Mike Alley; Richard Schmit; Will Lovell
Date: 10/15/2005 8:45:29 PM
Subject: U2 Outage F Burner Inspection

U2 Outage F Burner Inspection Summary

Reason- F3 Burner Fire (which resulted in the isolation of this new ABT burner)

When- Inspection conducted during U2 Boiler WW Tube Leak (on 2 1/2 floor) 10/12/2005

What- Removed burner elbows to inspect coal nozzles & tips and repair damage found

Inspection- Phil Hales & Aaron Nissen

FOUND: (referenced attached pics)

F3 Burner- major meltdown of the coal nozzle into the outer sleeve. 40% of the entire length of the nozzle has melted (bottom right). Due to the damage on the outer sleeve, the burner assembly needs to be replaced (during next Spring U2 Outage), although the air register assemblies look intact.

Coal Nozzles- coal erosion found in the 3:00 & 9:00 clock positions on all nozzles (below where the X-vane cross piece rides)

This erosion is within the first 18" of the nozzle. F6 nozzle, left side, had a hole eroded completely through.

Nozzle tips- major erosion and holes in the flowered tip (designed for coal staging), plus cracks in the "high tech alloy". Near impossible to weld up and due to high temps from furnace flame, impractical to RTV or nordbak/ceramic patch. Also the weld interface from the nozzle to the tip has creep damage (warped)

Coal Elbows- major erosion at the top of the nozzle. F1 & F2 already had eroded thru the original ceramic lining and thru the elbow material requiring external patches. F2 had a hole already in the external patch. F4 & F5 had holes eroded in the ceramic, but not yet thru the elbow metal. F6 has not yet eroded through the ceramic.

REPAIRS:

Coal Nozzles- ALL (except F3) coal nozzle sidewalls weld repaired at (3:00 & 9:00 clock position)

Coal Elbows- ALL (except F3) elbows were ceramic (nordbak) repaired at the very top (holes in ceramic) F2 also had an external patch installed due to a hole in the 1st external patch

NOTE: Place F pulv back in-service LAST (to allow ceramic Nordbak to cure in elbows- 24 hr cure time)

ALSO- Maintenance closed several of the Burner Isolation gates locally (originally weren't closed as part of the clearance). Operations needs to verify all iso gates are open before placing pulv I/S (F1 & F2 were closed, need to check others).

NOTE: U2 F Pulv will be coming O/S in the next several weeks for major overhaul and NEW rotating throats

However, during this time will be taking primary air flow measurements to check line velocities.

FUTURE: U2 Spring Outage- F3 burner will need to be replaced, as well as all other coal nozzles, preferably ceramic lined and new designed nozzle tips. Elbows also needed revamped or better yet replaced (so have one spare set to modify and rotate), also X-vanes needed replaced or modified (they aren't doing their job).

Final Inspection Report will follow

rest of pics located are at the following address:

N:\Current\Outages\2005 Outages\U2 2005 Unscheduled Outages\
05-1010 U2 external Tube Leak 2.5 NW LVL\Burner Row U2 F Inspection\pics

July 31, 2006

Received on
August 17, 2006
After being sent.

Joel Vatsky, CEO
Advanced Burner Technologies
271 Route 202/206
P.O. Box 410
Pluckemin, NJ 07978

Intermountain Generating Station Unit 2 Low NO_x Burners
Contract 04-45606; Response to ABT Letter dated May 9, 2006

Dear Mr. Vatsky:

We regret that the burners supplied by ABT fall short of the claims, guarantees, and warranties provided for in Contract 04-45606. The burner deficiencies have caused IPSC to incur considerable cost and inconvenience. We reiterate that we are holding ABT responsible for those costs allowed for in the subject contract. We request a favorable response to these claims by August 18, 2006. If we are not satisfied with your response, we will refer this claim to our attorneys.

While your May 9, 2006 letter very eloquently denied our claims, your responses did not address contractual guarantees made by ABT. In fact, there is clear evidence that ABT did not adequately design the burners as required by the contract specifications. It is not our intent to engage in a tit-for-tat debate over opinions and differences in viewpoint. Rather, we would like to refocus this issue on the contractual guarantees and the expectations we had of your burners that failed us. We illustrate just a few examples in the following paragraphs.

1. Burner Design

You claimed in the subject letter that IPSC had not been forthcoming with you when you claimed, *"In this case two critical items were not provided to ABT: the expected fuel change that resulted in significant increases in fuel and primary air flow, and the overheating of the original equipment burner barrels."* Under item 1 of said letter *"IPSC has operated for an extended period of time (September 2004 through April 2005) on coals having significantly lower HHV properties than allowed by ABT's design."* Let us address each of these items separately:

Design Fuel

IPSC has not changed its fuel. As stated in ABT's proposal under Executive Summary and Philosophy *"The specification (Referring to Specifications 45606; Attachment 3; General Coal Properties) lists several western bituminous coals, none of which, either singly or in the combinations specified, present any problem to ABT."* This list has coals with High Heating Values (HHV) ranging from 11,292 Btu/lb to 13,069 Btu/lb. Intermountain's average HHV over the two years of operation (April 2004 to April 2006) was 11,481 Btu/lb. We recognize a four-month period during these two years when we received poor quality coal, but we compensated operationally by either running eight mills or reducing load such that the burners did not exceed the contract maximum-rated BTU throughput of 220 Mbtu/hr.

IP7_031186

Burner Design Basis (Fuel and Primary Air Flows)

In Section 4.9 of the Contract (ABT's proposal) you state that *"ABT will design the burners for full load primary air flow, per mill, as per the OEM mill curves, with one mill out of service at boiler full load."* This should have been the design basis of your burners. Mr. Sal Ferrara confirmed that this was the basis you intended to use when he responded by e-mail to this specific question on 10/28/05, stating; *"the fuel injector was designed based on the OEM Mill 'Present Curve' (see e-mail attachment) for full load, with one mill out of service. Based on the curve, the burner design point is 62 MCFM PA flow @ 102 Mlb/hr coal flow."*

Whereas your intent to use the OEM curves was clear, it appears you made an error in establishing your basis. The point stated by Mr. Ferrara comes from the OEM curves but at a steam flow of 6,400 Mlb/hr (6,400,000 lb/hr) steam flow which is not the steam flow of the contract. As stated in the contract and in ABT's proposal introduction, the rated steam flow is 6,900 Mlb/hr (6,900,000 lb/hr).

Using the same OEM curve but extending it to 6,900 Mlb/hr with seven mills in-service, the primary air (PA) flow from the curve reads 63.5 MCFM at 110 Mlb/hr coal flow. This correlates to 248,031 lb/hr PA flow. Section 4.1 of your proposal allows for ± 5 percent tolerance in the PA flow. Therefore, the design should allow for PA flows up to 260,433 lb/hr with no damage to the burners or elbows.

You claim to have used a design point of 210,000lb/hr as the design flow for your fuel injector sizing and further claim that this point was confirmed by Mr. Phil Hailes of IPSC. Mr. Hailes' e-mail response to your question was specifically, *"3,500 lbs/min is the average rate that Unit 1 at 950 MW is running at today with seven mills. What specified condition are you requesting?"*. If you used this statement to determine your design point you did so in error. The number Mr. Hailes provided was a snapshot average of **Unit 1** and has no bearing on Unit 2. Your design point should have been based on the OEM curves as stated above.

2. Overheating

Again, in the subject letter, you accuse IPSC of not providing ABT with information concerning the overheating of the original equipment burner barrels. In item 3 it states, *"Note that this was the first time ABT was advised of this overheating condition with the OEM burners and had this been conveyed to ABT during the bidding or design phase of the project, we would have extended the stainless steel portion of the barrel."*

Materials Selection

How can you make this assertion? It is ABT's responsibility to design for the environment that the burners will operate in. In ABT's contractual proposal, Section 6.4, Part C - Division C3 it states *"There are no environmental limitations to the coal burners."* Under the Explanatory Comment you further state, *"The reason for stating that there are no environmental limitations to the coal burners is that the stainless steel castings and plate facing the fire, ASTM 297 Gr He or 309 will not deteriorate at temperatures of at least 2,000 °F. Consequently, ABT does not consider operation of its design in your boiler to have any environmental limitations. The conditions are such that no material will operate anywhere near its limit. In fact, ABT has placed no such limitation on any retrofit ABT has done."*

You must have been aware of IPSC's concern about high temperatures at the burner front since we paid an extra \$40,800 for a material upgrade to 253MA on burner components due to heat concerns. We specified and paid for two (2) thermocouples to be installed on each burner for temperature monitoring even when you assured us none were needed.

The OEM burners in our Unit 1 were upgraded from a 25-inch long, 309 SS tip to a 33-inch long, higher grade cast tip to prevent thermal degradation of the nozzle tips. This was done only after six years of operation. For your nozzle tips to fail within two years of startup is unacceptable especially given your contractual warrantee of 48 months for workmanship and quality of the coal nozzle tips (refer to Section 4.1 of ABT's proposal).

3. Coal-Nozzle Tip

In the subject letter, you state that, "We advised in the meeting that the temporary repairs that IPSC wanted to implement would not resolve the barrel overheating and nozzle cracking problem. ABT explained that it would be necessary to extend the carbon/stainless steel weld point further from the furnace by replacing a section of the carbon steel barrel with a stainless steel barrel."

Stainless-to-Carbon Steel Weld Location

A comparison of the distance from the centerline of the wall tubes to the tip-to-carbon steel transition between the ABT design and the upgraded OEM nozzles is within 1 inch. You imply in your April 10, 2006 letter that you are just beginning to understand that burner fronts with large throats can cause overheating in the barrel. Please keep in mind that both our units have been running with the same coal and similar loads over the past two years. Unit 1 burners have not experienced the thermal damage witnessed in the ABT burners on Unit 2. In fact, Unit 1 has been running for 14 years with similar distance from water wall tubes to the weld transition line without failure. Something in your design is not right.

Out-of-Service Cooling Air

Your subject letter (on page 3) implies that lack of cooling air flow on out of service burners could have lead to the damage witnessed in the coal-nozzle tips. If we did operate with no cooling air, you could hardly blame us since ABT did not provide us with operating guidelines for out of service flow. Out of service air flow is a system loss and was therefore one of the considerations for buying ABT burners since you claimed that cooling air was not needed. In reality, we have always used cooling air flow and the burners still failed.

Per your proposal, Section 3.6 ABT Field Services; ABT dispatched an engineer for field installation and testing support to assist during the initial stages of installation, startup, check-outs and during optimization of the new combustion equipment. At no time during this commissioning work was cooling-air flow an issue. The ABT personnel on the job stated that out-of-service cooling air was not required with the ABT design. This was consistent with ABT's claim in their proposal of no environmental limitations. On this advice IPSC left the out of service cooling air damper positions at the previous set points in the controls. Only in the April 10, 2006 ABT letter was cooling air on out of service burners a concern. Knowingly or unknowingly, ABT has misled IPSC on the ability of their burner to withstand the environment of operation.

4. Erosion

In Section 2.2 of your contractual proposal it states that; "*The segmented coal nozzle has an open design with no obstructions to wear or to collect coal,*" and in 7.2; "*In the ABT design, all wear is limited to the wear-resistant devices in the elbow. The Opti-flow system eliminates coal ropes and produces a nearly uniform fuel/air mix with axial flow downstream of the elbow. Therefore, the only erosion-prone areas will be located within the elbow.*"

Clearly, we are experiencing erosion issues that neither IPSC nor ABT anticipated. We have addressed the question of excessive coal velocities in number 1 above. The fact that we have experienced erosion-related failures in our coal barrels, nozzle tips and sweep elbows in less than two years of operation is unacceptable especially in light of the assurances you gave us as referenced in the paragraph above and the warrantee of 48 months on the nozzle tips.

Mr. Joel Vatsky
July 31, 2006
Page 4

The erosion issue gets back to design. You assert that the only wear parts will be in the x-vane diffuser yet our burners are wearing through the sweep elbows, the coal barrel and at the coal-nozzle tip. Our notes from our meeting with you and Mr. Ferrara indicate that you admit that you did not conduct a CFD model of the sweep-elbow/x-vane diffuser combination. We maintain, based on experience, that there is a flaw in this design.

IPSC would like to remind ABT that the responsibility to provide a burner design that will function properly in the operating environment of our furnaces lies with ABT not IPSC. Again, we request a favorable response to these claims by August 18, 2006.

Sincerely,

George W. Cross
President and Chief Operating Officer
Intermountain Power Service Corporation

DEW/JKH:jmj

Attachments

IP7_031189



GWC

MAY 15 2006

May 9, 2006

271 Route 202/206
P.O. Box 410
Pluckemin, NJ 07978
P 908.470.0470
F 908.470.0479

www.advancedburner.com

Mr. George W. Cross, President and Chief Operating Officer
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, Utah 84624

Subject: Intermountain Generation Station Unit 2 Low NO_x Burners, Contract 04-45606
IPSC April 24, 2006 Letter

Dear Mr. Cross:

Advanced Burner Technologies Corporation (ABT) is concerned that damage has occurred to the burners we have supplied. Although we deny IPSC claims that ABT has any responsibility, we do however remain committed to help IPSC. To this end we have been working closely with the Plant to identify the root causes that first became evident on June 27, 2005 with IPSC's Mr. J. Finlinson's email notification of the F3 burner fire.

We can understand that changes in operation (such as fuel supply) and occasionally information that can be important to the supplier may, through inadvertent oversight, not be provided to the supplier. In this case two critical items were not provided to ABT: the expected fuel change that resulted in significant increases in fuel and primary air flow, and the overheating of the original equipment burner barrels. There is no way any equipment designer can design for conditions of which they are not made aware by the owner.

The following items 1 through 5 of the subject Intermountain Power Service Corporation (IPSC) letter that describes problems identified by IPSC are as follows, with ABT responses added in bold text:

1. Erosion of the barrel just downstream of the long-sweep elbow. This has occurred on every burner and we believe it is caused by the diffuser assembly you designed and supplied that is located in the elbow.

ABT response:

The diffuser assembly, otherwise known as "x-vane", located in the elbow is a wear component, however it has worn more rapidly than the standard design we have in operation at all our other installations. ABT's proposal included supply of the standard x-vane design which eliminate the cleanout plug at the elbow's centerline; however, in early stages of the project IPSC requested a change in order to retain the existing port in the burner inlet elbow. ABT agreed to make the change but also advised IPSC that the standard x-vane as originally offered was a better, simpler, design. In any case, the accelerated wear to the x-vane assembly, and erosion of the barrel downstream of the long sweep elbow, is due to IPSC operation of their coal mills at higher flows than allowed by contract and the burner design. As stated in Proposal



2
 Cortisio
 OEM curve +
 210,000 lb/hr

Section 4.9, ...ABT will design the burners for the full load primary airflow, per mill, as per the OEM mill curves, with one mill out of service at boiler full load. The design mill primary airflow (210,000 lb/hr) for fuel injector sizing was also confirmed early in the project with J. Vatsky 9/11/03 email correspondence to P. Hailes.

10000 PA
 Flow 0000
 10000
 It did not become evident that IPSC is running the mills at much higher flows than design until October 2005. IPSC's G. Christensen 10/27/05 email correspondence advised flows are as high as 265,000 lb/hr, which is more than 25% greater than the burner design flow agreed between IPSC and ABT. ABT's S. Ferrara responded immediately with 10/28/06 email advising effects of higher operating flows by degrading performance and increasing component wear.

Based on IPSC long term records of fuels burned (Mr. G. Christensen 11/2/05 email correspondence) IPSC has operated for an extended period of time (September 2004 through April 2005) on coals having significantly lower HHV properties than allowed by ABT's design. The lower than specified HHV ($\leq 11,500$ Btu/lb) results in overfiring of burners (higher than design air and coal flows) in order to maintain full load generation on the Unit.

See Executive Summary
 Higher velocity in elbows due to toe rail (by right) causes down to 18' down

2. Erosion of burner nozzles where it divides into the six segments just prior to discharge. Every burner showed significant erosion with many having multiple holes.

ABT response:

Erosion of the burner nozzles is due to high velocities of the air/coal mixture in the nozzle, along with the higher coal loadings resulting from the lower heating value coal. This condition may be worse due to by denser coal streams being formed in the non-standard design of the x-vane assembly.

Had ABT known that IPSC intended to operate the mills at the current coal and air flows, the burner nozzles would have been designed accordingly resulting in lower nozzle velocities. ABT has not experienced nozzle erosion at any of its other installations where the mills are operating in the range for which the burner is designed.

In cases where it is known that erosive conditions exist (high velocity and/or highly abrasive fuel) ABT will apply erosion resistant materials in the fuel injector barrels as well as the inlet to the nozzles to maximize their longevity. This was not the case with IPSC as the coal was not considered to be highly abrasive and the contract defined flows result in relatively low air/coal velocity in the nozzle.

Had ABT been advised that such a fuel change and resultant mill operation was anticipated, we would have proposed the changes noted above.

3. Severe cracking and structural failure of the burner nozzle which originates from the weld of the nozzle to the burner barrel. The cracking of the nozzles was so severe on 15 of the 48 burners on a recent inspection that those 15 nozzles had to be removed and replaced.

ABT response:

This is consistent with discussions held in the November 9, 2005 meeting at the Intermountain Generating Station where ABT explained that the carbon steel burner barrels were overheating upstream of the point where carbon steel barrel is welded to the stainless steel nozzle tip. The carbon steel is expanding at a higher rate than the



stainless casting causing the casting to rip at the weld and cracks to then form in the casting.

We advised in the meeting that the temporary repairs that IPSC wanted to implement would not resolve the barrel overheating and nozzle cracking problem. ABT explained that it would be necessary to extend the carbon/stainless steel weld point further from the furnace by replacing a section of the carbon steel barrel with a stainless steel barrel. IPSC advised in the meeting that the OEM burners originally provided on the Unit had experienced the same overheating problems witnessed on the ABT nozzles and the resolution was to extend the stainless steel portion of the barrel just as ABT is recommending. IPSC advised in the meeting that based on conditions observed during the recent October 2005 outage, it would not be necessary to implement ABT's recommendation to extend the carbon/stainless steel weld point back during the April 2006 outage.

Note that this was the first time ABT was advised of this overheating condition with the OEM burners and, had this been conveyed to ABT during the bidding or design phase of the project, we would have extended the stainless steel portion of the barrel.

We have not experienced this type overheating problem on any of the ABT burner designs currently operating in the industry, which all have the carbon/stainless steel weld point in similar proximity to the furnace as is currently operating on the ABT burners at IPSC. The only time we have seen elevated temperatures on the carbon steel barrel is when the cooling secondary airflow to the burners was completely shutoff and we suspect that this may be happening at IPSC. We have suggested an investigative program to the Plant in order to determine if any operating conditions exist where insufficient cooling flow is available to the burners. In particular we believe that the compartmented windbox air control dampers may be too closed when the burner deck is out of service and have asked the Plant to investigate this. To date we have not had any response or been provided with any information.

4. Erosion of the ceramic lined long-sweep elbow and x-vane diffuser.

ABT response:

The ceramic lined long sweep elbows are original boiler equipment and were not replaced by ABT during the Low NOx Burner retrofit. The erosion of the x-vane diffuser is discussed in Item 1 above and is a result of IPSC operating the coal mills at primary air and coal flows much higher than allowed by the contract.

The x-vanes are replaceable components and are expected to wear over a period of years. ABT has an on-going development project to identify the latest wear-resistant materials so that we can select those materials that best fit the specific fuel properties and flow conditions for each project. At the design fuel and flow conditions specified by the IPSC project, the x-vane assemblies supplied by ABT would last many years prior to needing replacement. The fuel and flow conditions that IPSC has been recently operating at, and has defined for the future, would require a change to material selection of ABT's x-vanes, at an increased cost, in order to minimize the type wear IPSC is experiencing of this component. Further the burner barrels would have to be lined and the nozzles replaced with new ones designed for the actual flows now being utilized.



5. One burner (F3) was completely replaced because it was damaged in a burner fire on June 25, 2005. After inspecting the damaged burner, we believe the fire was caused by a hole eroded in the burner barrel just after the elbow. We believe the hole allowed coal to enter the inner air sleeve and eventually catch on fire damaging the burner.

ABT response:

Due to the extent of fire damage on F3 burner, it was not possible to determine the cause although based on the photos provided by IPSC it seems to have started either in the coal pipe or at the burner inlet. We noted that the coal pipe upstream of the burner, where the pipe passes through the floor grating, in the area of the coal pipe shutoff valve also showed evidence of fire, leading us to question whether the valve was only partly open.

As noted in J. Finlinson's 6/27/05 email, the IPSC operators were starting up the other Unit on June 25, 2005 at the time the fire started on F3 burner and therefore did not notice the high temperature alarms (well over 1600°F). It is not known how long the fire went unnoticed by the operators, however operator action to take the burner out of service would have prevented permanent damage to the burner components. F3 burner is the only one of 48 burners on the unit that suffered permanent damage from fire in over 2 years of operation. This being the case, it can only be concluded that the F3 incident is due to some type of operational malfunction rather than due to design defect in the burner.

The subject April 24, 2006 letter notes that IPSC "purchased the materials necessary to temporarily repair the burners." IPSC's letter also states "we are now requesting the following remedial actions from ABT according to the contract:"

1. With no additional IPSC reimbursement, ABT should make the necessary modifications to their design to solve all the problems we have experienced with the burners as outlined in this letter and to otherwise meet all the specifications of the contract.

ABT response:

The ABT burners are designed to the conditions of the contract and the problems experienced are due solely to IPSC operating conditions being outside those specified. This type of operation has voided the ABT "Guarantees and Warranties" as stated in Proposal Q03013, Section 4.9 (Contract Article III: Part C). ABT has already made the necessary design modifications to meet the new operating conditions provided by IPSC and has provided the Plant with a proposal in November 2005.

2. With no additional IPSC reimbursement, ABT should supply the necessary materials and manpower to install those design changes on all 48 of the IGS Unit 2 burners. This work should be done on the next Unit 2 major outage scheduled for the Spring of 2008.

ABT response:

ABT has already proposed to supply replacement fuel injectors for all 48 of the IGS Unit 2 burners and, as noted above, has designed these to the new conditions provided by IPSC. IPSC shall install the ABT supplied materials at IPSC cost. ABT's offer made during the November 9, 2005 meeting remains to supply the new fuel injectors to IPSC at a discount. We offer the discount as a good will gesture to work with IPSC and resolve the unexpected problems amicably.



As a further good will gesture, ABT will maintain the November 2005 price if we receive the Purchase Order and initial payment by June 15, 2006 for delivery by December 2006.

3. ABT should reimburse IPSC for the burner purchased to replace the fire damaged F3 burner. We believe the fire was the direct result of an ABT design flaw that allowed rapid erosion of the burner barrel.

ABT response:

Damage to the F3 burner is due solely to operator inaction to control room alarms, allowing a burner fire to progress for long period rather than removing the burner from service to prevent permanent damage. The ABT design is not flawed and the rapid erosion problem is due to IPSC operating the burners at flow conditions outside the contract specifications.

4. ABT should reimburse IPSC for the materials purchased from ABT to repair the burners during the April 2006 Unit 2 outage.

ABT response:

During the November 9, 2005 meeting, ABT advised that the fuel injectors would require redesign to support operation at the higher flow rates. ABT also presented the new design arrangement during the meeting, and proposed to supply forty-eight fuel injectors for installation during the April 2006 outage. IPSC advised at that time that they were only interested in implementing temporary repairs during the April 2006 outage and intended to purchase the replacements designed for the new conditions for the next major outage. The cost for materials to make the temporary repairs will not be reimbursed by ABT to IPSC.

To summarize: the damage that has occurred is a direct result of changes in Plant operation (fuel and mill conditions) and failure of IPSC to inform ABT of the original burner barrel overheating problem that could have been addressed in the initial design phase.

AT remains committed to support IPSC in resolving these issues and had provided a proposal to do so as soon as we were advised of the actual operating conditions.

Please contact Sal Ferrara at 908-470-0721 to discuss any question you have on this matter.

Sincerely yours,

Joel Vatsky
President and CEO

Cc: Sal Ferrara

MEMORANDUM

INTERMOUNTAIN POWER SERVICE CORPORATION

TO: George Cross
FROM: Dennis Killian
DATE: May 30, 2006
SUBJECT: Response to Condition of Unit 2 Burners

It is obvious after seeing the state of the Unit 2 burners that we need a plan for their future repair or replacement. Right now, we are documenting the damage to each of the burners with pictures and drawings to use in the design review process or for legal recourse reasons. We will also send out a burner tip for metallurgical and failure analysis.

The weaknesses of the ABT burners seems to be with erosion around the diffuser and at the tip and with structural failure (possibly thermal stresses) at the tip. What we are doing with the diffuser should solve the erosion in the burner barrel for now but, we still have doubts about the long term. The add-on falsies will buy us time with the tip erosion but, they do nothing to solve the inherent design flaw that allows such rapid erosion. We will replace nozzles too broken to install the falsies with straight nozzles similar to what is on Unit 1. We believe these repairs will allow us to operate safely for another two years.

We learned from the review of the B&W burners that even B&W did not respect the amount of radiant heat on burners that large. It took a finite element analysis from an outside consultant we hired for them to incorporate the necessary design changes in the second iteration of Unit 1 burners that have allowed them to operate this long. We may need to do the same thing with the ABT burners.

If nothing else, it might be possible to incorporate the strengths of both the B&W burners and the ABT burners in our own hybrid design. It appears possible to install the B&W conical diffuser, ceramic lined barrel and stainless steel straight tip with the ABT registers. We would probably lose some of the NOx reduction but, with the Unit 2 OFA we should still be able to meet the current WEPCO limits. They should work about the same as the current burners on Unit 1.

Before we go that direction, we should give ABT a chance to review their design and make it right with us. However; we need to be careful to not become a research facility for ABT. It is obvious they do not understand long sweep elbows or burners this large.

We might also want to look at other combustion staging tips available from some of the other after market suppliers or from B&W.

Since we will be budgeting for the next Unit 2 outage this summer, we should have a plan together by July or August.

Based on past experience, I think it is very unlikely that ABT would pay for all or any of the repair or modification costs without legal action. If legal action is pursued, the contract states that "No component shall last less than four (4) years before requiring rebuild, restoration, or replacement". The guarantee that they supplied us with their proposal and that was made part of the contract (Division C2 of Contract) actually stated a 6-8 year guarantee for the life of the nozzle. Those parts of the contract are very plain and clear and should give us a solid footing to pursue legal recourse.

For their defense they would probably use the velocity numbers that we gave them in an email to say that they designed for a lower coal flow velocity than what is currently on Unit 2. We would counter that by saying they should have done their own velocity calculations based on the stoichiometry and BTU throughput we had in the contract and that the numbers we supplied were only intended to verify that their calculations were comparable to our actual operating experience. It would improve our legal position if we can prove through finite element analysis that the nozzles are failing from thermal stresses.

ABT is not a large company (see attached Dun & Bradstreet Report) with only 14 employees and very few tangible assets (leased 3200 sq. ft. facility). However; their contract required Professional Liability insurance with a \$2,500,000 limit which might provide enough promise of return to make a lawsuit worthwhile.

We will prepare a letter to ABT notifying them of the failures and putting them on official notice that we are holding them financially responsible to provide and install the necessary reparations in the future. While we are shooting for the moon, we should also ask for reimbursement for the F3 burner we

purchased and for the repair parts we are installing this outage.

In the meantime, We will proceed with our own design review and failure analysis as if everything depends on us because in reality it probably will.

If you have any further questions concerning this matter, please contact Jerry Hintze.

JKH:jkh

Attachments

Mike Alley
Will Lovell
Dean Wood
Garry Christensen
Aaron Nissen
Phil Hailes
Nancy Bennett

April 24, 2006

Mr. Joel Vatsky
Advanced Burner Technologies
P.O. Box 410
271 Route 202/206
Pluckemin, NJ 07978

Dear Mr. Vatsky:

Request for Repair of Intermountain Generating Station Unit 2 Burners

In March 2004, we installed 48 of your Opti-Flow Low NO_x Burners in Unit 2 at the Intermountain Generating Station under Contract 45606. Since that time, we have experienced numerous problems with the burners. Among the most important identified to date are the following:

1. Erosion of the burner barrel just downstream of the long-sweep elbow. This has occurred on every burner and we believe it is caused by the diffuser assembly you designed and supplied that is located in the elbow.
2. Erosion of the burner nozzles where it divides into the six segments just prior to discharge. Every burner showed significant erosion with many having multiple holes.
3. Severe cracking and structural failure of the burner nozzle which originates from the weld of the nozzle to the burner barrel. The cracking of the nozzles was so severe on 15 of the 48 burners on a recent inspection that those 15 nozzles had to be removed and replaced.
4. Erosion of the ceramic lined long-sweep elbow and X-vane diffuser.
5. One burner (F3), was completely replaced because it was damaged in a burner fire on June 25, 2005. After inspecting the damaged burner, we believe the fire was caused by a hole eroded in the burner barrel just after the elbow. We believe the hole allowed coal to enter the inner air sleeve and eventually catch on fire damaging the burner.

The contract you signed with us on September 12, 2003 contained several clauses pertaining to the failures that we have experienced. For example, Division F2, Article 5, Paragraph "g" states:

"Experience based and verified wear-life shall be quoted within the bid for all burner components. No component shall last less than four (4) years before requiring rebuild, restoration, or replacement."

IP7_031198

Mr. Joel Vatsky
April 24, 2006
Page 2

Also, Division F2, Article 5, Paragraph "f" states:

"The burner assemblies shall be fabricated of quality material sufficient to withstand the significant thermal stresses occurring within the windbox as a result of both radiant and convective heating. Any deformation causing malfunction of register assemblies or misdirection of flow through the burner within the period of guaranteed operability shall be repaired at the earliest possible opportunity and charged to Contractor."

Due to the need for continued operation of IGS Unit 2, we have purchased the materials necessary to temporarily repair the burners. However; we are now requesting the following remedial actions from ABT according to the terms of the contract:

1. With no additional IPSC reimbursement, ABT should make the necessary modifications to their design to solve all of the problems we have experienced with the burners as outlined in this letter and to otherwise meet all of the specifications of the contract.
2. With no additional IPSC reimbursement, ABT should supply the necessary materials and manpower to install those design changes on all 48 of the IGS Unit 2 burners. This work should be done on the next Unit 2 major outage scheduled for the spring of 2008.
3. ABT should reimburse IPSC for the burner purchased to replace the fire-damaged F3 burner. We believe the fire was the direct result of an ABT design flaw that allowed rapid erosion of the burner barrel.
4. ABT should reimburse IPSC for the materials purchased from ABT to repair the burners during our April 2006 Unit 2 outage.

If you have any questions concerning this matter, please contact Jerry Hintze at (435) 864-6460.

Sincerely,

George W. Cross
President and Chief Operations Officer

JKH:jmj

cc: Garry Christensen
Phil Hailes
Will Lovell
Mike Alley
Robert Rees
Nancy Bennett

IP7_031199

INTERMOUNTAIN POWER SERVICE CORPORATION

April 24, 2006

Mr. Joel Vatsky
Advanced Burner Technologies
P.O. Box 410
271 Route 202/206
Pluckemin, NJ 07978

Dear Mr. Vatsky:

Request for Repair of Intermountain Generating Station Unit 2 Burners

In March 2004, we installed 48 of your Opti-Flow Low NO_x Burners in Unit 2 at the Intermountain Generating Station under Contract 45606. Since that time, we have experienced numerous problems with the burners. Among the most important identified to date are the following:

1. Erosion of the burner barrel just downstream of the long-sweep elbow. This has occurred on every burner and we believe it is caused by the diffuser assembly you designed and supplied that is located in the elbow.
2. Erosion of the burner nozzles where it divides into the six segments just prior to discharge. Every burner showed significant erosion with many having multiple holes.
3. Severe cracking and structural failure of the burner nozzle which originates from the weld of the nozzle to the burner barrel. The cracking of the nozzles was so severe on 15 of the 48 burners on a recent inspection that those 15 nozzles had to be removed and replaced.
4. Erosion of the ceramic lined long-sweep elbow and X-vane diffuser.
5. One burner (F3), was completely replaced because it was damaged in a burner fire on June 25, 2005. After inspecting the damaged burner, we believe the fire was caused by a hole eroded in the burner barrel just after the elbow. We believe the hole allowed coal to enter the inner air sleeve and eventually catch on fire damaging the burner.

The contract you signed with us on September 12, 2003 contained several clauses pertaining to the failures that we have experienced. For example, Division F2, Article 5, Paragraph "g" states:

"Experience based and verified wear-life shall be quoted within the bid for all burner components. No component shall last less than four (4) years before requiring rebuild, restoration, or replacement."

Mr. Joel Vatsky
April 24, 2006
Page 2

Also, Division F2, Article 5, Paragraph "f" states:


"The burner assemblies shall be fabricated of quality material sufficient to withstand the significant thermal stresses occurring within the windbox as a result of both radiant and convective heating. Any deformation causing malfunction of register assemblies or misdirection of flow through the burner within the period of guaranteed operability shall be repaired at the earliest possible opportunity and charged to Contractor."

Due to the need for continued operation of IGS Unit 2, we have purchased the materials necessary to temporarily repair the burners. However, we are now requesting the following remedial actions from ABT according to the terms of the contract:

1. With no additional IPSC reimbursement, ABT should make the necessary modifications to their design to solve all of the problems we have experienced with the burners as outlined in this letter and to otherwise meet all of the specifications of the contract.
2. With no additional IPSC reimbursement, ABT should supply the necessary materials and manpower to install those design changes on all 48 of the IGS Unit 2 burners. This work should be done on the next Unit 2 major outage scheduled for the spring of 2008.
3. ABT should reimburse IPSC for the burner purchased to replace the fire-damaged F3 burner. We believe the fire was the direct result of an ABT design flaw that allowed rapid erosion of the burner barrel.
4. ABT should reimburse IPSC for the materials purchased from ABT to repair the burners during our April 2006 Unit 2 outage.

If you have any questions concerning this matter, please contact Jerry Hintze at (435) 864-6460.

Sincerely,



George W. Cross
President and Chief Operations Officer

 JKH:jmj

cc: Garry Christensen
Phil Hailes
Will Lovell
Mike Alley
Robert Rees
Nancy Bennett

IP7_031201



GWC

MAY 15 2006

May 9, 2006

271 Route 202/206
P.O. Box 410
Pluckemin, NJ 07978
P 908.470.0470
F 908.470.0479

www.advancedburner.com

Mr. George W. Cross, President and Chief Operating Officer
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, Utah 84624

Subject: Intermountain Generation Station Unit 2 Low NO_x Burners, Contract 04-45606
IPSC April 24, 2006 Letter

Dear Mr. Cross:

Advanced Burner Technologies Corporation (ABT) is concerned that damage has occurred to the burners we have supplied. Although we deny IPSC claims that ABT has any responsibility, we do however remain committed to help IPSC. To this end we have been working closely with the Plant to identify the root causes that first became evident on June 27, 2005 with IPSC's Mr. J. Finlinson's email notification of the F3 burner fire.

We can understand that changes in operation (such as fuel supply) and occasionally information that can be important to the supplier may, through inadvertent oversight, not be provided to the supplier. In this case two critical items were not provided to ABT: the expected fuel change that resulted in significant increases in fuel and primary air flow, and the overheating of the original equipment burner barrels. There is no way any equipment designer can design for conditions of which they are not made aware by the owner.

The following items 1 through 5 of the subject Intermountain Power Service Corporation (IPSC) letter that describes problems identified by IPSC are as follows, with ABT responses added in bold text:

1. Erosion of the barrel just downstream of the long-sweep elbow. This has occurred on every burner and we believe it is caused by the diffuser assembly you designed and supplied that is located in the elbow.

ABT response:

The diffuser assembly, otherwise known as "x-vane", located in the elbow is a wear component, however it has worn more rapidly than the standard design we have in operation at all our other installations. ABT's proposal included supply of the standard x-vane design which eliminate the cleanout plug at the elbow's centerline; however, in early stages of the project IPSC requested a change in order to retain the existing port in the burner inlet elbow. ABT agreed to make the change but also advised IPSC that the standard x-vane as originally offered was a better, simpler, design. In any case, the accelerated wear to the x-vane assembly, and erosion of the barrel downstream of the long sweep elbow, is due to IPSC operation of their coal mills at higher flows than allowed by contract and the burner design. As stated in Proposal



Section 4.9, ...ABT will design the burners for the full load primary airflow, per mill, as per the OEM mill curves, with one mill out of service at boiler full load. The design mill primary airflow (210,000 lb/hr) for fuel injector sizing was also confirmed early in the project with J. Vatsky 9/11/03 email correspondence to P. Hailes.

It did not become evident that IPSC is running the mills at much higher flows than design until October 2005. IPSC's G. Christensen 10/27/05 email correspondence advised flows are as high as 265,000 lb/hr, which is more than 25% greater than the burner design flow agreed between IPSC and ABT. ABT's S. Ferrara responded immediately with 10/28/06 email advising effects of higher operating flows by degrading performance and increasing component wear.

Based on IPSC long term records of fuels burned (Mr. G. Christensen 11/2/05 email correspondence) IPSC has operated for an extended period of time (September 2004 through April 2005) on coals having significantly lower HHV properties than allowed by ABT's design. The lower than specified HHV ($\leq 11,500$ Btu/lb) results in overfiring of burners (higher than design air and coal flows) in order to maintain full load generation on the Unit.

2. Erosion of burner nozzles where it divides into the six segments just prior to discharge. Every burner showed significant erosion with many having multiple holes.

ABT response:

Erosion of the burner nozzles is due to high velocities of the air/coal mixture in the nozzle, along with the higher coal loadings resulting from the lower heating value coal. This condition may be worse due to by denser coal streams being formed in the non-standard design of the x-vane assembly.

Had ABT known that IPSC intended to operate the mills at the current coal and air flows, the burner nozzles would have been designed accordingly resulting in lower nozzle velocities. ABT has not experienced nozzle erosion at any of its other installations where the mills are operating in the range for which the burner is designed.

In cases where it is known that erosive conditions exist (high velocity and/or highly abrasive fuel) ABT will apply erosion resistant materials in the fuel injector barrels as well as the inlet to the nozzles to maximize their longevity. This was not the case with IPSC as the coal was not considered to be highly abrasive and the contract defined flows result in relatively low air/coal velocity in the nozzle.

Had ABT been advised that such a fuel change and resultant mill operation was anticipated, we would have proposed the changes noted above.

3. Severe cracking and structural failure of the burner nozzle which originates from the weld of the nozzle to the burner barrel. The cracking of the nozzles was so severe on 15 of the 48 burners on a recent inspection that those 15 nozzles had to be removed and replaced.

ABT response:

This is consistent with discussions held in the November 9, 2005 meeting at the Intermountain Generating Station where ABT explained that the carbon steel burner barrels were overheating upstream of the point where carbon steel barrel is welded to the stainless steel nozzle tip. The carbon steel is expanding at a higher rate than the



stainless casting causing the casting to rip at the weld and cracks to then form in the casting.

We advised in the meeting that the temporary repairs that IPSC wanted to implement would not resolve the barrel overheating and nozzle cracking problem. ABT explained that it would be necessary to extend the carbon/stainless steel weld point further from the furnace by replacing a section of the carbon steel barrel with a stainless steel barrel. IPSC advised in the meeting that the OEM burners originally provided on the Unit had experienced the same overheating problems witnessed on the ABT nozzles and the resolution was to extend the stainless steel portion of the barrel just as ABT is recommending. IPSC advised in the meeting that based on conditions observed during the recent October 2005 outage, it would not be necessary to implement ABT's recommendation to extend the carbon/stainless steel weld point back during the April 2006 outage.

Note that this was the first time ABT was advised of this overheating condition with the OEM burners and, had this been conveyed to ABT during the bidding or design phase of the project, we would have extended the stainless steel portion of the barrel.

We have not experienced this type overheating problem on any of the ABT burner designs currently operating in the industry, which all have the carbon/stainless steel weld point in similar proximity to the furnace as is currently operating on the ABT burners at IPSC. The only time we have seen elevated temperatures on the carbon steel barrel is when the cooling secondary airflow to the burners was completely shutoff and we suspect that this may be happening at IPSC. We have suggested an investigative program to the Plant in order to determine if any operating conditions exist where insufficient cooling flow is available to the burners. In particular we believe that the compartmented windbox air control dampers may be too closed when the burner deck is out of service and have asked the Plant to investigate this. To date we have not had any response or been provided with any information.

4. Erosion of the ceramic lined long-sweep elbow and x-vane diffuser.

ABT response:

The ceramic lined long sweep elbows are original boiler equipment and were not replaced by ABT during the Low NOx Burner retrofit. The erosion of the x-vane diffuser is discussed in Item 1 above and is a result of IPSC operating the coal mills at primary air and coal flows much higher than allowed by the contract.

The x-vanes are replaceable components and are expected to wear over a period of years. ABT has an on-going development project to identify the latest wear-resistant materials so that we can select those materials that best fit the specific fuel properties and flow conditions for each project. At the design fuel and flow conditions specified by the IPSC project, the x-vane assemblies supplied by ABT would last many years prior to needing replacement. The fuel and flow conditions that IPSC has been recently operating at, and has defined for the future, would require a change to material selection of ABT's x-vanes, at an increased cost, in order to minimize the type wear IPSC is experiencing of this component. Further the burner barrels would have to be lined and the nozzles replaced with new ones designed for the actual flows now being utilized.



5. One burner (F3) was completely replaced because it was damaged in a burner fire on June 25, 2005. After inspecting the damaged burner, we believe the fire was caused by a hole eroded in the burner barrel just after the elbow. We believe the hole allowed coal to enter the inner air sleeve and eventually catch on fire damaging the burner.

ABT response:

Due to the extent of fire damage on F3 burner, it was not possible to determine the cause although based on the photos provided by IPSC it seems to have started either in the coal pipe or at the burner inlet. We noted that the coal pipe upstream of the burner, where the pipe passes through the floor grating, in the area of the coal pipe shutoff valve also showed evidence of fire, leading us to question whether the valve was only partly open.

As noted in J. Finlinson's 6/27/05 email, the IPSC operators were starting up the other Unit on June 25, 2005 at the time the fire started on F3 burner and therefore did not notice the high temperature alarms (well over 1600°F). It is not known how long the fire went unnoticed by the operators, however operator action to take the burner out of service would have prevented permanent damage to the burner components. F3 burner is the only one of 48 burners on the unit that suffered permanent damage from fire in over 2 years of operation. This being the case, it can only be concluded that the F3 incident is due to some type of operational malfunction rather than due to design defect in the burner.

The subject April 24, 2006 letter notes that IPSC "purchased the materials necessary to temporarily repair the burners." IPSC's letter also states "we are now requesting the following remedial actions from ABT according to the contract:"

1. With no additional IPSC reimbursement, ABT should make the necessary modifications to their design to solve all the problems we have experienced with the burners as outlined in this letter and to otherwise meet all the specifications of the contract.

ABT response:

The ABT burners are designed to the conditions of the contract and the problems experienced are due solely to IPSC operating conditions being outside those specified. This type of operation has voided the ABT "Guarantees and Warranties" as stated in Proposal Q03013, Section 4.9 (Contract Article III: Part C). ABT has already made the necessary design modifications to meet the new operating conditions provided by IPSC and has provided the Plant with a proposal in November 2005.

2. With no additional IPSC reimbursement, ABT should supply the necessary materials and manpower to install those design changes on all 48 of the IGS Unit 2 burners. This work should be done on the next Unit 2 major outage scheduled for the Spring of 2008.

ABT response:

ABT has already proposed to supply replacement fuel injectors for all 48 of the IGS Unit 2 burners and, as noted above, has designed these to the new conditions provided by IPSC. IPSC shall install the ABT supplied materials at IPSC cost. ABT's offer made during the November 9, 2005 meeting remains to supply the new fuel injectors to IPSC at a discount. We offer the discount as a good will gesture to work with IPSC and resolve the unexpected problems amicably.



As a further good will gesture, ABT will maintain the November 2005 price if we receive the Purchase Order and initial payment by June 15, 2006 for delivery by December 2006.

3. ABT should reimburse IPSC for the burner purchased to replace the fire damaged F3 burner. We believe the fire was the direct result of an ABT design flaw that allowed rapid erosion of the burner barrel.

ABT response:

Damage to the F3 burner is due solely to operator inaction to control room alarms, allowing a burner fire to progress for long period rather than removing the burner from service to prevent permanent damage. The ABT design is not flawed and the rapid erosion problem is due to IPSC operating the burners at flow conditions outside the contract specifications.

4. ABT should reimburse IPSC for the materials purchased from ABT to repair the burners during the April 2006 Unit 2 outage.

ABT response:

During the November 9, 2005 meeting, ABT advised that the fuel injectors would require redesign to support operation at the higher flow rates. ABT also presented the new design arrangement during the meeting, and proposed to supply forty-eight fuel injectors for installation during the April 2006 outage. IPSC advised at that time that they were only interested in implementing temporary repairs during the April 2006 outage and intended to purchase the replacements designed for the new conditions for the next major outage. The cost for materials to make the temporary repairs will not be reimbursed by ABT to IPSC.

To summarize: the damage that has occurred is a direct result of changes in Plant operation (fuel and mill conditions) and failure of IPSC to inform ABT of the original burner barrel overheating problem that could have been addressed in the initial design phase.

AT remains committed to support IPSC in resolving these issues and had provided a proposal to do so as soon as we were advised of the actual operating conditions.

Please contact Sal Ferrara at 908-470-0721 to discuss any question you have on this matter.

Sincerely yours,

Joel Vatsky
President and CEO

Cc: Sal Ferrara

INTERMOUNTAIN POWER SERVICE CORPORATION

April 24, 2006

Mr. Joel Vatsky
Advanced Burner Technologies
P.O. Box 410
271 Route 202/206
Pluckemin, NJ 07978

Dear Mr. Vatsky:

Request for Repair of Intermountain Generating Station Unit 2 Burners

In March 2004, we installed 48 of your Opti-Flow Low NO_x Burners in Unit 2 at the Intermountain Generating Station under Contract 45606. Since that time, we have experienced numerous problems with the burners. Among the most important identified to date are the following:

1. Erosion of the burner barrel just downstream of the long-sweep elbow. This has occurred on every burner and we believe it is caused by the diffuser assembly you designed and supplied that is located in the elbow.
2. Erosion of the burner nozzles where it divides into the six segments just prior to discharge. Every burner showed significant erosion with many having multiple holes.
3. Severe cracking and structural failure of the burner nozzle which originates from the weld of the nozzle to the burner barrel. The cracking of the nozzles was so severe on 15 of the 48 burners on a recent inspection that those 15 nozzles had to be removed and replaced.
4. Erosion of the ceramic lined long-sweep elbow and X-vane diffuser.
5. One burner (F3), was completely replaced because it was damaged in a burner fire on June 25, 2005. After inspecting the damaged burner, we believe the fire was caused by a hole eroded in the burner barrel just after the elbow. We believe the hole allowed coal to enter the inner air sleeve and eventually catch on fire damaging the burner.

The contract you signed with us on September 12, 2003 contained several clauses pertaining to the failures that we have experienced. For example, Division F2, Article 5, Paragraph "g" states:

"Experience based and verified wear-life shall be quoted within the bid for all burner components. No component shall last less than four (4) years before requiring rebuild, restoration, or replacement."

Mr. Joel Vatsky
April 24, 2006
Page 2

Also, Division F2, Article 5, Paragraph "f" states:

"The burner assemblies shall be fabricated of quality material sufficient to withstand the significant thermal stresses occurring within the windbox as a result of both radiant and convective heating. Any deformation causing malfunction of register assemblies or misdirection of flow through the burner within the period of guaranteed operability shall be repaired at the earliest possible opportunity and charged to Contractor."

Due to the need for continued operation of IGS Unit 2, we have purchased the materials necessary to temporarily repair the burners. However; we are now requesting the following remedial actions from ABT according to the terms of the contract:

1. With no additional IPSC reimbursement, ABT should make the necessary modifications to their design to solve all of the problems we have experienced with the burners as outlined in this letter and to otherwise meet all of the specifications of the contract.
2. With no additional IPSC reimbursement, ABT should supply the necessary materials and manpower to install those design changes on all 48 of the IGS Unit 2 burners. This work should be done on the next Unit 2 major outage scheduled for the spring of 2008.
3. ABT should reimburse IPSC for the burner purchased to replace the fire-damaged F3 burner. We believe the fire was the direct result of an ABT design flaw that allowed rapid erosion of the burner barrel.
4. ABT should reimburse IPSC for the materials purchased from ABT to repair the burners during our April 2006 Unit 2 outage.

If you have any questions concerning this matter, please contact Jerry Hintze at (435) 864-6460.

Sincerely,



George W. Cross
President and Chief Operations Officer

 JKH:jmj

cc: Garry Christensen
Phil Hailes
Will Lovell
Mike Alley
Robert Rees
Nancy Bennett


IP7_031208

MEMORANDUM

INTERMOUNTAIN POWER SERVICE CORPORATION

TO: George W. Cross

Page 1 of 3

FROM: Dennis K. Killian 

DATE: April 10, 2006

SUBJECT: Response to Condition of Unit 2 Burners

It is obvious after seeing the state of the Unit 2 burners that we need a plan for their future repair or replacement. Right now, we are documenting the damage to each of the burners with pictures and drawings to use in the design review process or for legal recourse reasons. We will also send out a burner tip for metallurgical and failure analysis.

The weaknesses of the ABT burners seem to be with erosion around the diffuser and at the tip and with structural failure (possibly thermal stresses) at the tip. What we are doing with the diffuser should solve the erosion in the burner barrel for now but, we still have doubts about the long term. The add-on falsies will buy us time with the tip erosion but, they do nothing to solve the inherent design flaw that allows such rapid erosion. We will replace nozzles too broken to install the falsies with straight nozzles similar to what is on Unit 1. We believe these repairs will allow us to operate safely for another two years.

We learned from the review of the B&W burners that even B&W did not respect the amount of radiant heat on burners that large. It took a finite element analysis from an outside consultant we hired for them to incorporate the necessary design changes in the second iteration of Unit 1 burners that have allowed them to operate this long. We may need to do the same thing with the ABT burners.

If nothing else, it might be possible to incorporate the strengths of both the B&W burners and the ABT burners in our own hybrid design. It appears possible to install the B&W conical diffuser, ceramic lined barrel, and stainless steel straight tip with the ABT registers. We would probably lose some of the NO_x reduction but, with the Unit 2 OFA we should still be able to meet the current WEPCO limits. They should work about the same as the current burners on Unit 1.

IP7_031209

Before we go that direction, we should give ABT a chance to review their design and make it right with us. However, we need to be careful to not become a research facility for ABT. It is obvious they do not understand long sweep elbows or burners this large.

We might also want to look at other combustion staging tips available from some of the other after market suppliers or from B&W.

Since we will be budgeting for the next Unit 2 outage this summer, we should have a plan together by July or August.

Based on past experience, I think it is very unlikely that ABT would pay for all or any of the repair or modification costs without legal action. If legal action is pursued, the contract states that "No component shall last less than four (4) years before requiring rebuild, restoration, or replacement." The guarantee that they supplied us with their proposal and that was made part of the contract (Division C2 of Contract) actually stated a 6-8 year guarantee for the life of the nozzle. Those parts of the contract are very plain and clear and should give us a solid footing to pursue legal recourse.

For their defense they would probably use the velocity numbers that we gave them in an email to say that they designed for a lower coal flow velocity than what is currently on Unit 2. We would counter that by saying they should have done their own velocity calculations based on the stoichiometry and BTU throughput we had in the contract and that the numbers we supplied were only intended to verify that their calculations were comparable to our actual operating experience. It would improve our legal position if we can prove through finite element analysis that the nozzles are failing from thermal stresses.

ABT is not a large company (see attached Dun & Bradstreet Report) with only 14 employees and very few tangible assets (leased 3,200 square foot facility). However, their contract required Professional Liability insurance with a \$2,500,000 limit which might provide enough promise of return to make a lawsuit worthwhile.

We will prepare a letter to ABT notifying them of the failures and putting them on official notice that we are holding them financially responsible for providing and install the necessary reparations in the future. While we are shooting for the moon, we should also ask for reimbursement for the F3 burner we purchased and for the repair parts we are installing this outage.

In the meantime, we will proceed with our own design review and failure analysis as if everything depends on us, because in reality it probably will.

If you have any further questions concerning this matter, please contact Jerry Hintze at extension 6460.

JKH:jmj

Attachments

cc: Mike Alley
Will Lovell
Dean Wood
Garry Christensen
Aaron Nissen
Phil Hailes
Nancy Bennett



**Small Business
Solutions**

Advanced Burner Technologies Corp

271 Rt 202 206 S
Pluckemin, NJ 07978
Phone: 908 470-0470
D-U-N-S® Number: 01-084-8534 *

Report as of: April 6, 2006**

**Included with this Company Profile Report are continuous tracking of key business changes and free Alert messages in the View My Reports/Alerts page. You can also choose to receive e-mail notifications of the important changes.
IMPORTANT NOTE: You will not receive e-mail alerts if you have opted out of receiving communications from D&B.

Company Location and Details

County:	SOMERSET
Metropolitan Statistical Area:	Middlesex-Somerset-Hunterdon, NJ
Year Started:	2001
State of Incorporation:	N/A
Number of Employees Here: *	10
Number of Employees Total:	14
Square Footage:	3,200
Bank Name:	N/A
Bank D&B D-U-N-S Number:	N/A
Related Websites:	www.advancedburner.com

Sales Information

Annual Sales: *	\$ 1,800,000
Base Sales:	\$ 1,800,000
Trend Sales:	N/A
3 Year Sales Growth:	N/A
Net Worth:	N/A

Business and Industry Information

Primary SIC: *
3433, HEATING EQUIPMENT, EXCEPT ELECTRIC
34330000, HEATING EQUIPMENT, EXCEPT ELECTRIC

Secondary SICs:
N/A

This is a: *
PRIVATE COMPANY
HEADQUARTERS Location

Officers and Executives*

President:	Joel Vatsky
-------------------	-------------

* Indicates a requirement

Find out more about this company

This report is prepared and provided for the exclusive use of Dennis Killian, .
This report may not be reproduced in whole or in part by any means of reproduction.



Decide with Confidence

Business Information Report

[Print this Report](#)Report Printed: APR 06 2006
In Date

BUSINESS SUMMARY

ADVANCED BURNER TECHNOLOGIES CORP
271 Rt 202-206 South
Pluckemin, NJ 07978This is a **headquarters** location.
Branch(es) or division(s) exist.**Mailing address:** PO Box 410
Pluckemin, NJ 07978**Telephone:** 908 470-0470**Chief executive:** JOEL VATSKY, PRESIDENT**Year started:** 1996**Management control:** 2001**Employs:** 14 (10 here)**History:** CLEAR**Financing:** SECURED**SIC:** 3433**Line of business:** Mfg.heating equipment specifically
operating as a supplier of pulverized
coal combustion equipment**D-U-N-S Number:** 01-084-8534**D&B Rating:** **1R3**
Number of employees: 1R is **10 or more**
employees.**Composite credit appraisal:** 3 is **fair**.**D&B PAYDEX®:****12-Month D&B PAYDEX: 79**When weighted by dollar amount, payments to
suppliers average 2 days beyond terms.

Based on trade collected over last 12 months.

SUMMARY ANALYSIS

D&B Rating: **1R3**
Number of employees: 1R indicates **10 or more** employees.
Composite credit appraisal: 3 is **fair**.

The 1R and 2R ratings categories reflect company size based on the total number of employees for the business. They are assigned to business files that do not contain a current financial statement. In 1R and 2R Ratings, the 2, 3, or 4 creditworthiness indicator is based on analysis by D&B of public filings, trade payments, business age and other important factors. 2 is the highest Composite Credit Appraisal a company not supplying D&B with current financial information can receive. For more information, see the D&B Rating Key.

Below is an overview of the company's rating history since 05/05/98:

D&B Rating	Date Applied
1R3	01/10/05
1R4	01/28/04
2R3	04/07/03
2R2	09/09/02
2R3	04/07/99
--	05/05/98

The Summary Analysis section reflects information in D&B's file as of April 3, 2006.

CUSTOMER SERVICE

Got a question about D&B Small Business Solutions? Need help using one of our small business services? No problem! Our dedicated team of friendly support technicians is only a mouse click or phone call away.



[Click here](mailto:sbsSupport@dnb.com) to email us with your questions at sbsSupport@dnb.com.



If you'd like to speak with one of our member support technicians directly, call toll-free 1-866-472-7362, Monday thru Friday, 7:30 AM to 7:00 PM CST.

HISTORY

The following information was reported **11/29/2005**:

Officer(s): JOEL VATSKY, PRESIDENT

DIRECTOR(S): THE OFFICER(S)

Business started 1996 by the officers. 100% of capital stock is owned by JOEL VATSKY.

JOEL VATSKY born 1943. 1974-1997 employed by Foster Wheeler Corp, Clinton, NJ. 1997-present active here.

Business address has changed from 350 Main St, Bedminster, NJ, 07921 to 271 Rt 202/206s, Pluckemin, NJ, 07978.

CORPORATE FAMILY

Click below to buy a Business Information Report on that family member.

Branches (US):

Advanced Burner Technologies Corp

Bedminster, NJ

DUNS # 79-952-7812

BUSINESS REGISTRATION

CORPORATE AND BUSINESS REGISTRATIONS REPORTED BY THE SECRETARY OF STATE OR OTHER OFFICIAL SOURCE AS OF MAR 07 2003:

The following data is for informational purposes only and is not an official record. Certified copies may be obtained from the Pennsylvania Department of State.

Registered Name: ADVANCED BURNER TECHNOLOGIES CORP.

Business type: CORPORATION
Corporation type: PROFIT
Date incorporated: JAN 07 1997
State of incorporation: PENNSYLVANIA
Filing date: JAN 07 1997
Registration ID: 2732425
Status: INACTIVE

Where filed: SECRETARY OF STATE/CORPORATIONS DIVISION, HARRISBURG, PA

Principals: SHEKELL, LAWRENCE G, CHIEF EXECUTIVE OFFICER
POLUTNIK, JOHN E, VICE PRESIDENT

OPERATIONS

11/29/2005

Description: Manufactures heating equipment, specifically operating as a supplier of pulverized coal combustion equipment (100%).

Website: www.advancedburner.com.

Has 10-20 account(s). Terms are on a contract basis. Sells to commercial concerns. Territory : International.

Employees: 14 which includes officer(s). 10 employed here.

Facilities: Leases 3,200 sq. ft. in on two floor of building.

Location: Central business section on side street.

Branches: Subject maintains a branch location Jacksonville, Florida & Chatanooga, Tennessee.

SIC & NAICS

SIC:

Based on information in our file, D&B has assigned this company an extended 8-digit SIC. D&B's use of 8-digit SICs enables us to be more specific to a company's operations than if we use the standard 4-digit code.

The 4-digit SIC numbers link to the description on the Occupational Safety & Health Administration (OSHA) Web site. Links open in a new browser window.

34330000 Heating equipment, except electric

NAICS:

333414 Heating Equipment Manufacturing, (except Electric and Warm Air Furnaces)

D&B PAYDEX

The D&B PAYDEX is a unique, dollar weighted indicator of payment performance based on up to 20 payment experiences as reported to D&B by trade references.

3-Month D&B PAYDEX: 67

When weighted by dollar amount, payments to suppliers average 18 days beyond terms.



12-Month D&B PAYDEX: 79

When weighted by dollar amount, payments to suppliers average 2 days beyond terms.



Based on trade collected over last 3 months.

Based on trade collected over last 12 months.

When dollar amounts are not considered, then approximately 95% of the company's payments are within terms.

PAYMENT SUMMARY

The Payment Summary section reflects payment information in D&B's file as of the date of this report.

Below is an overview of the company's dollar-weighted payments, segmented by its suppliers' primary industries:

	Total Rcv'd (#)	Total Dollar Amts (\$)	Largest High Credit (\$)	Within Terms (%)	Days Slow <31 31-60 61-90 90> (%)			
Top industries:								
Nonclassified	6	1,750	500	100	-	-	-	-
Trucking non-local	4	5,350	2,500	77	23	-	-	-
Whol metal	3	35,000	20,000	71	29	-	-	-
Short-trm busn credit	2	7,550	7,500	100	-	-	-	-
Mfg process controls	1	200,000	200,000	100	-	-	-	-
Air courier service	1	750	750	100	-	-	-	-
Radiotelephone commun	1	500	500	100	-	-	-	-
Arrange cargo transpt	1	250	250	100	-	-	-	-
Telephone communictns	1	50	50	100	-	-	-	-
Other payment categories:								
Cash experiences	0	0	0					
Payment record unknown	0	0	0					
Unfavorable comments	0	0	0					
Placed for collections:								
With D&B	0	0						
Other	0	N/A						
Total in D&B's file	20	251,200	200,000					

The highest **Now Owes** on file is \$15,000The highest **Past Due** on file is \$0

D&B receives over 600 million payment experiences each year. We enter these new and updated experiences into D&B Reports as this information is received.

PAYMENT DETAILS**Detailed Payment History**

Date Reported (mm/yy)	Paying Record	High Credit (\$)	Now Owes (\$)	Past Due (\$)	Selling Terms	Last Sale Within (months)
03/06	Ppt	50	0	0		2-3 mos
	Ppt-Slow 30	2,500	0	0	N15	6-12 mos
02/06	Ppt	2,500	750	0		1 mo

	Ppt	500	0	0		2-3 mos
	Ppt	250	0	0		1 mo
	Ppt	250	0	0		4-5 mos
	Ppt	250	250	0		1 mo
	Ppt	250	250	0		1 mo
	Ppt	250	0	0		6-12 mos
	Ppt	100	0	0		6-12 mos
	Ppt	50	0	0		6-12 mos
01/06	Ppt-Slow 30	20,000	0	0	1/2 10 N30	2-3 mos
12/05	Ppt	750	750	0		1 mo
	Ppt	250	100	0		1 mo
	Ppt	0	0	0		2-3 mos
11/05	Ppt	15,000	15,000	0		1 mo
05/05	Ppt	250	0	0		6-12 mos
04/05	Ppt	7,500	500	0		
02/05	Ppt	500	0	0	N30	6-12 mos
12/04	Ppt	200,000	0	0		6-12 mos

Each experience shown is from a separate supplier. Updated trade experiences replace those previously reported.

FINANCE

03/16/2005

On March 16, 2005, attempts to contact the management of this business have been unsuccessful. Outside sources confirmed operation and location.

PUBLIC FILINGS

The following Public Filing data is for information purposes only and is not the official record. Certified copies can only be obtained from the official source.

UCC FILINGS

Collateral: All Assets
Type: Original
Sec. party: POLUTNIK, JOHN E., NORTH HUNTINGTON, PA
Debtor: ADVANCED BURNER TECHNOLOGIES CORP.
Filing number: 20904456
Filed with: SECRETARY OF STATE/UCC DIVISION, TRENTON, NJ

Date filed: 03/06/2002
Latest Info Received: 04/01/2002

Collateral: All Assets
Type: Original
Sec. party: SHEKELL, LAWRENCE G, CHAMPION, PA
Debtor: ADVANCED BURNER TECHNOLOGIES CORP
Filing number: 34930959
Filed with: SECRETARY OF STATE/UCC DIVISION, HARRISBURG, PA

Date filed: 02/15/2002
Latest Info Received: 03/11/2002

Collateral: All Assets

Type: Original
Sec. party: POLUTNIK, JOHN E, NORTH HUNTINGDON, PA
Debtor: ADVANCED BURNER TECHNOLOGIES CORP
Filing number: 34930958
Filed with: SECRETARY OF STATE/UCC DIVISION, HARRISBURG, PA

Date filed: 02/15/2002
Latest Info Received: 03/11/2002

Collateral: Inventory including proceeds and products - Accounts receivable including proceeds and products - Account(s) including proceeds and products - Computer equipment including proceeds and products - and OTHERS

Type: Original
Sec. party: PNC BANK, NATIONAL ASSOCIATION, BLUE BELL, PA
Debtor: ADVANCED BURNER TECHNOLOGIES CORP.
Filing number: 20911751
Filed with: SECRETARY OF STATE/UCC DIVISION, TRENTON, NJ

Date filed: 03/07/2002
Latest Info Received: 04/01/2002

Collateral: Inventory including proceeds and products - Accounts receivable including proceeds and products - Account(s) including proceeds and products - General intangibles(s) including proceeds and products - and OTHERS

Type: Original
Sec. party: PNC BANK NATIONAL ASSOCIATION, BLUE BELL, PA
Debtor: ADVANCED BURNER TECHNOLOGIES CORP
Filing number: 34930960
Filed with: SECRETARY OF STATE/UCC DIVISION, HARRISBURG, PA

Date filed: 02/15/2002
Latest Info Received: 03/11/2002

Collateral: Accounts receivable including proceeds and products - Inventory including proceeds and products - Account(s) including proceeds and products - Computer equipment including proceeds and products - and OTHERS

Type: Original
Sec. party: PNC BANK, PHILADELPHIA, PA
Debtor: ADVANCED BURNER TECHNOLOGIES, LLC
Filing number: 2069161
Filed with: SECRETARY OF STATE/UCC DIVISION, TRENTON, NJ

Date filed: 10/05/2001
Latest Info Received: 11/05/2001

The public record items contained in this report may have been paid, terminated, vacated or released prior to the date this report was printed.

GOVERNMENT ACTIVITY

Activity summary

Borrower (Dir/Guar):	NO
Administrative debt:	NO
Contractor:	NO
Grantee:	NO
Party excluded from federal program(s):	NO

Possible candidate for socio-economic program consideration

Labor surplus area:	N/A
Small Business:	YES (2006)
8(A) firm:	N/A

The details provided in the Government Activity section are as reported to Dun & Bradstreet by the federal government and other sources.

This report is prepared and provided under contract for the exclusive use of Dennis Killian,.
This report may not be reproduced in whole or in part by any means of reproduction.

[Close](#) |  [Print](#)

INTERMOUNTAIN POWER SERVICE CORPORATION

September 6, 2005

Mr. Joel Vatsky
Advanced Burner Technologies
P.O. Box 410
271 Route 202/206
Pluckemin, NJ 07978

Dear Mr. Vatsky:

Dissatisfaction with ABT Opti-Flow Burners in IGS Unit 2

This letter is to express the dissatisfaction of Intermountain Power Service Corporation with the performance of ABT's Opti-flow burners that were installed on Intermountain's Unit 2 in the spring of 2004. We are holding ABT at least partially culpable in the recent failure of the Unit 2 F3 burner module and request ABT's assistance in resolving our concerns.


The thermowell design supplied on your burner modules precludes the use of heavy-duty thermocouples (TC's). The bend radius is too tight to allow insertion of the 1/4 inch TC's we specified. The 1/16 inch TC's supplied with the burners are failing prematurely. We are convinced that lack of instrumentation, which would have warned us of a burner fire, contributed to the failure on F3.

We are also experiencing premature wear-related failure of some of our x-vane fuel distributors and elbows at the burner inlet. These failures are unacceptable, especially in burners that are only a little over a year old.

We have suspended plans to replace burners on Unit 1 until we can get these issues resolved. We are requesting assistance from ABT in investigating the cause of these failures and in making them right.

Please contact Mr. Dean Wood at (435) 864-6464 with questions regarding these claims or to set up a plant visit to resolve these issues.

Sincerely,



George W. Cross
President and Chief Operations Officer



DEW/JKH:jmj

271 Route 202/206
P.O. Box 410
Pluckemin, NJ 07978
P 908.470.0470
F 908.470.0479

www.advancedburner.com

September 26, 2005

Mr. George W. Cross
President and Chief Operations Officer
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, Utah 84624

Subject: Letter of September 6, 2005, Attached

Dear Mr. Cross:

We have investigated the information contained in the subject letter to see if we have been in any way remiss in our continuing efforts to support the plant, or if we had not been aware of conditions at the plant. It appears that, from our perspective, there are discrepancies between the information we have and that contained in the subject letter.

However, let me assure you that it is our intent to support IPSC to the maximum extent possible, consistent with the actual conditions.

It is my understanding that the combustion performance of our burners has been excellent, with Unit 2 continuing to meet all guarantees and commitments made by ABT. We believe that the burners' reliability has been excellent, including the following conditions discussed in the subject letter.

We agree that there has been a problem with insertion of 1/4 inch thermocouples, however the 1/16 inch TC's can perform satisfactorily. Nevertheless, we are taking two actions to resolve this concern:

1. We are evaluating the possibility of using 1/8 inch TCs to eliminate any chance that the TC's tip would not seat properly in the existing tube arrangement. This is being done in the shop.
2. The replacement for F3 burner, that is now being fabricated, will have a different TC tube run that will allow the larger TC to be installed and we will make sure of that in the shop.

Regarding the concern over possible excessive wear in the X-vanes, ABT has an on-going investigation to identify the latest wear-resistant materials for possible use in the most erosion prone areas of the fuel injector. The latest materials will be used in the new X-vanes for the F3 replacement.



With specific regard to Unit 2:

The fire in burner F3 on June 25 was not a result of TC failure. The report sent to us on June 27 by IPSC stated that the TCs were reading measured tip temperatures of approximately 1600° F, and that alarms were tripped. These circumstances do not indicate any culpability on ABT's part.

What are the facts?

It should be clear that after approximately 18 months of operation, with one fire in a 48 burner unit, that there was a specific cause to that fire and it is not due to any deficiency in burner performance or design. If this fire was due to a design defect, then a large number of fires would have occurred in this time period. It is our understanding that there have been no further fires in the three months since this incident; and no previous fires that we are aware of.

As far as excessive wear on the X-vane fuel distributors (the elbows are the original equipment and were not replaced by ABT), your letter is the first we hear of this. In our discussions with plant personnel we have been told that such wear has not been occurring on other burners inspected to date. The damage to the F3 X-vanes seems, from photos provided to us, to be entirely caused by the fire that was located in the coal pipe and elbow. Perhaps some may feel that the F3 X-vane damage was also due to high wear, in addition to that caused by the fire; however, this would be difficult to determine after the fact.

*Do -75 ft/sec
says who?*

We have requested the plant to inspect the X-vanes whenever possible because we want to know if such wear is occurring. If the mills are operating within the design range the coal pipe velocities should only be in the 70-75 ft/sec range; insufficient to cause accelerated erosion. You should be aware that the X-vanes are replaceable components that are expected to wear over a period of years. The determinant of their end of life is degradation of combustion performance, not any visible loss of material. One of the major advantages of our design is that it is easily replaceable, with minimal time and labor.

Then come and see.

I trust that the actions ABT is taking to address the thermocouple issue meets with IPSC's acceptance and that the question of X-vane wear is, at least, open.

Open to inspect?

Please rest assured that, should IPSC choose to proceed with the Unit 1 burner replacement with ABT, the questions of thermocouple size and X-vane wear have been addressed in the new F3 burner configuration and would be implemented on subsequent burners.

How so?

Sincerely,

Joel Vatsky
President and CEO

Cc: Dean Wood-IPSC
Sal Ferrara-ABT

IP7_031222

From: Jerry Finlinson
To: joel@advancedburner.com; Sal Ferrara; Tarkel Larson
Date: 6/27/2005 12:03:27 PM
Subject: unit 2 ABT burner fire photos

Joel and Sal,

This past weekend, 25 June 2005, we had a burner fire one of the new unit 2 ABT burners F3. It happened during the time that we were starting up unit 1, so the unit 2 operator was over at the unit 1 control board and didn't notice the alarm from the thermocouples that we had installed in the burner. Both the coal pipe and nozzle tip thermocouple went above 1600F.

As you can see from the attached photos, damage was extensive. The inner coal pipe has melted out the bottom and there is a slag pile inside the burner. The nozzle appears OK. The burner elbow heated up cherry red and flaked off the paint. The thermocouples and temperature switch were melted. A hole is burned through the back of the burner, so we can look right through the windbox wall into the back of the burner.

We'd like you to work with us to determine the cause of the burner fire and any possible preventive measures. Also what will be required to get it repaired. Do we need to replace the burner completely, or could it be repaired in position.

Let's also address the issue with the thermowell and how to make the thermocouple readings more reliable.

I recall you saying that there had never been a burner fire in this burner design.

Thanks, Jerry

Jerry Finlinson, Engineer
Intermountain Power Service Corp
850 West Brush Wellman Rd
Delta, UT 84624
435-864-6466 fax 0776/6670
jerry-f@ipsc.com

CC: Dean Wood; Howard Hamilton; James Nelson; Jon Christensen; Phil Hailes

From: Jerry Finlinson
To: Sal Ferrara
Date: 6/30/2005 4:08:25 PM
Subject: Unit 2 ABT burner fire Elbow photos

Sal,

Thanks for the feedback. Today our mechanics removed the burner elbow from the F3 burner. I have included some photos of the elbow. It shows one side of the fuel distributor to be melted off. We'll pull another one of an see if it also shows some damage.

We had set our burner thermocouples to alarm at 1350 on the nozzle tip. Four of them are going high for a few minutes several times per day, so we are going to raise them to 1500F. We are trying to determine if it is some electrical noise or a real temperature increase. So far it seems to be real. We'll let you know if we find anything definitive.

It appears that the secondary air register assembly inside the burner is also melted on the bottom, so we'll likely require an entire new burner. Phil and Dean will work out the details with you.

Thermowell issues. At the very beginning, you designed two thermowells into the burner at our request. It was a 3/8 inch tube with a 1/4 inch thermocouple. However, your manufacturing made the thermowells with two 45 degree bends in each one as per the drawing. It was impossible to insert the 1/4 inch thermocouples around those bends. So we worked with Tarkel to order 1/16 inch diameter thermocouples. They are still difficult to insert, partly because they bend easily and are hard to push. So we are proposing to install a new straighter thermowell in to the nozzle tip. We need your assistance to determine the best routing for the thermowell, so that we can insert it without any bends.

On the coal pipe body readings some of our thermocouples have read low by 100 to 200 degF. We are theorizing that maybe the thermocouple is not bottomed in the thermowell, but are not sure.

Thanks, Jerry

Jerry Finlinson, Engineer
Intermountain Power Service Corp
850 West Brush Wellman Rd
Delta, UT 84624
435-864-6466 fax 0776/6670
jerry-f@ipsc.com

>>> "Sal Ferrara" <sal@advancedburner.com> 6/30/2005 12:18:54 PM >>>

Jerry,

Based on the pictures the fire seems to have started either in the coal pipe or at the burner inlet. Where the coal pipe penetrates the floor grating, in vicinity of the burner shutoff valve, seems to have been subject to overheating in addition to the fire damage to the back of the fuel injector.

At this point the items we would recommend investigating is the primary airflow and burner shutoff damper position history prior to and around the time either the tip or body thermocouple temperatures rose above the normal operating temperatures. We know from our testing experience in Spring 2004 that the plant experienced problems with burner shutoff valves randomly going closed while the burner was in service (this is potential for causing fire in coal pipe or fuel injector). Also see if any abnormal PA flow of shutoff damper conditions could be correlated with temperature excursions on other burners (Dean Wood mentioned in phone discussion that there are some other burners that experience repeatable high temperatures excursions @ once or twice per day).

Also at first available outage, the plant should remove an elbow on one, or several, burners that experience periodic temperature excursions to inspect ABT's elbow fuel distributor, fuel injector barrel and burner shutoff valve for signs of overheating. I do not know how your temperature alarm is configured however it would be best if triggered by a rate of temperature change, rather than a specific temperature limit. If a rate of change logic is not utilized for the alarm, then we would recommend setting the alarm point @ 100 degree F above the temperature measured during normal operation.

We are working on providing a price for complete burner replacement. If the secondary air register assembly is OK you may only need to replace the fuel injector assembly, although you most likely need an outage to pull the fuel injector and inspect the burner to determine this.

You also mentioned the thermowell and making the thermocouple reading more reliable. I am not sure what this means, since I am not aware that there has been a temperature measurement reliability issue on either the fuel injector tip or body readings. Please provide more detail on this.
Sal

-----Original Message-----

From: Jerry Finlinson [<mailto:Jerry-F@ipsc.com>]

Sent: Monday, June 27, 2005 2:03 PM

To: joel@advancedburner.com; sal@advancedburner.com; tarkel@advancedburner.com

Cc: nelsonj@compassminerals.com; Dean Wood; Howard Hamilton; Jon Christensen; Phil Hailes

Subject: unit 2 ABT burner fire photos

Joel and Sal,

This past weekend, 25 June 2005, we had a burner fire one of the new unit 2 ABT burners F3.

It happened during the time that we were starting up unit 1, so the unit 2 operator was over at the unit 1 control board and didn't notice the alarm from the thermocouples that we had installed in the burner. Both the coal pipe and nozzle tip thermocouple went above 1600F.

As you can see from the attached photos, damage was extensive. The inner coal pipe has melted out the bottom and there is a slag pile inside the burner. The nozzle appears OK. The burner elbow heated up cherry red and flaked off the paint. The thermocouples and temperature switch

were melted. A hole is burned through the back of the burner, so we can look right through the windbox wall into the back of the burner.

We'd like you to work with us to determine the cause of the burner fire and any possible preventive measures. Also what will be required to get it repaired. Do we need to replace the burner completely, or could it be repaired in position.

Let's also address the issue with the thermowell and how to make the thermocouple readings more reliable.

I recall you saying that there had never been a burner fire in this burner design.


Thanks, Jerry

Jerry Finlinson, Engineer
Intermountain Power Service Corp
850 West Brush Wellman Rd
Delta, UT 84624
435-864-6466 fax 0776/6670
jerry-f@ipsc.com

This message scanned for viruses by CoreComm

CC: Bill Morgan; Dean Wood; Howard Hamilton; Joel Vatsky; Jon Christensen; Ken Nielson; nelsonj@compassminerals.com; Phil Hailes; Tarkel Larson

Average monthly PA flow with coal flow > 34 TPH



From: "Sal Ferrara" <sal@advancedburner.com>
To: "Garry Christensen" <Garry-C@ipsc.com>
Date: 10/28/2005 8:32:59 AM
Subject: RE: The remaining pictures

Thanks Garry.

The entire fuel injector assembly can be unbolted from the burner cover plate and removed as one piece (with inner zone damper and fixed vane spinner attached). We will provide our recommendations and an arrangement drawing for discussion on design for upgrading fuel injector & elbow design to a longer wear life. The pictures and descriptions you provided are very helpful in that respect.

In response to Dean's phone question yesterday morning, the fuel injector was designed based on the OEM Mill "Present Curve" (see email attachment) for full load, with one mill out of service. Based on the curve the burner design point is 62 MCFM PA flow @ 102 MLB/hr coal flow. Operating at higher flow rates than designed will result both in degrading performance as well as increase wear.

Sal

-----Original Message-----

From: Garry Christensen [mailto:Garry-C@ipsc.com]
Sent: Thursday, October 27, 2005 5:33 PM
To: sal@advancedburner.com
Subject: The remaining pictures

Sorry about that, the remaining pictures are attached. Are the nozzles replaceable and if so can they be removed with the tip attached? Also, what other components need to be unattached?

We do want you to look into a ceramic lined coal barrel/nozzle with a different engineered tip. ie less angle and modification of the X-vane.

I hope you will be able to come out soon and sit down and discuss the issues so we can come up with a game plan and get needed parts/new equipment in time for April's outage.

This message scanned for viruses by CoreComm


CC: "Dean Wood" <Dean-W@ipsc.com>

IP7_031228

PG 896-4

Babcock & Wilcox

CONTRACT INFORMATION SHEET



THESE CURVES ARE SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION.

DRAWN BY J. NEIDERT	DATE 2-1-82	APPROVED BY RBN	DATE 2-5-82	A.O.
REL. NO. AND DATE 1 9-8-82		CONTRACT NO. 334-0614		FILE NO. RB-614

TITLE - PULVERIZER-BURNER COORDINATION CURVES - COAL (B)

CIS- 101.05


design range 10,500 to 12,100 BTU/lb
High Performance coal 11,010 BTU/lb

IP7_031229

PG 896.4

Babcock & Wilcox

CONTRACT INFORMATION SHEET



Full load
 360 TPH
 required @
 6.4 million lb/h

THESE CURVES ARE SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION			
DRAWN BY J. NEIDERT	DATE 2-1-82	APPROVED BY RND	DATE 2-5-82
REL. NO. AND DATE 1 9-8-82	CONTRACT NO. 334-0614		FILE NO. RB-614

TITLE - PULVERIZER-BURNER COORDINATION CURVES - COAL (B)

CIS- 101.05

IP7_031230

From: "Sal Ferrara" <sal@advancedburner.com>
To: "Garry Christensen" <Garry-C@ipsc.com>
Date: 10/28/2005 8:32:59 AM
Subject: RE: The remaining pictures

Thanks Garry.

The entire fuel injector assembly can be unbolted from the burner cover plate and removed as one piece (with inner zone damper and fixed vane spinner attached). We will provide our recommendations and an arrangement drawing for discussion on design for upgrading fuel injector & elbow design to a longer wear life. The pictures and descriptions you provided are very helpful in that respect.

In response to Dean's phone question yesterday morning, the fuel injector was designed based on the OEM Mill "Present Curve" (see email attachment) for full load, with one mill out of service. Based on the curve the burner design point is 62 MCFM PA flow @ 102 MLB/hr coal flow. Operating at higher flow rates than designed will result both in degrading performance as well as increase wear.

Sal

-----Original Message-----

From: Garry Christensen [mailto:Garry-C@ipsc.com]
Sent: Thursday, October 27, 2005 5:33 PM
To: sal@advancedburner.com
Subject: The remaining pictures

Sorry about that, the remaining pictures are attached. Are the nozzles replaceable and if so can they be removed with the tip attached? Also, what other components need to be unattached?

We do want you to look into a ceramic lined coal barrel/nozzle with a different engineered tip. ie less angle and modification of the X-vane.

I hope you will be able to come out soon and sit down and discuss the issues so we can come up with a game plan and get needed parts/new equipment in time for April's outage.

This message scanned for viruses by CoreComm


CC: "Dean Wood" <Dean-W@ipsc.com>

IP7_031231

PG 896-4

Babcock & Wilcox

CONTRACT INFORMATION SHEET



THESE CURVES ARE SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION.

A.O.

FILE NO.

RB-614

TITLE - PULVERIZER-BURNER COORDINATION CURVES - COAL (B)

CIS- 101.05


design range 10,500 to 12,100 BTU/lb
 High Performance coal 11,010 BTU/lb

IP7 031232

PG 896-4

Babcock & Wilcox

CONTRACT INFORMATION SHEET



THESE CURVES ARE SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION			
DRAWN BY J. NEIDERT	DATE 2-1-82	APPROVED BY RND	DATE 2-5-82
REL. NO. AND DATE 1 9-8-82	CONTRACT NO. 334-0614		FILE NO. RB-614

TITLE - PULVERIZER-BURNER COORDINATION CURVES - COAL (B)

CIS- 101.05

IP7_031233

From: "joel" <joel@advancedburner.com>
To: "Phil Hailes" <Phil-H@ipsc.com>
Date: Thu, Sep 11, 2003 12:52 PM
Subject: Re: PA Mass Flow

OK: You initially had lb/hr I did know if that was a typo or just the wrong number.

We'll use 210,00 lb/hr as the design flow for the fuel injector sizing.

Thanks,

When do you need the dwg info you asked for?

----- Original Message -----

From: "Phil Hailes" <Phil-H@ipsc.com>
To: <joel@advancedburner.com>
Sent: Thursday, September 11, 2003 2:04 PM
Subject: Re: PA Mass Flow

> 3500 lbs/min is the average rate that Unit 1 at 950 MW is running at
> today with 7 mills. What specified condition are you requesting?

>

> >>> "joel" <joel@advancedburner.com> 9/11/2003 12:08:23 PM >>>

> Phil: this number is not correct. PA flow for mills of this size is in
> the

> 100,000's lb.hr per mill.

>

> It is not an approximate value we need; but the actual quantity under
> the

> specified condition.

>

> Please recheck this.

>

> Joel

>

>

> ----- Original Message -----

> From: "Phil Hailes" <Phil-H@ipsc.com>

> To: <joel@advancedburner.com>

> Sent: Thursday, September 11, 2003 12:25 PM

> Subject: PA Mass Flow

>

>

> > At 950 MW with 7 mills, the PA mass flow is approximately 3,500
> lbs/hr

> > per mill.

> >

> > >>> "joel" <joel@advancedburner.com> 9/10/2003 1:16:18 PM >>>

> > Phil:

> >

> > We need ASAP the following:

> >

> > What is the primary air flow per mill with the boiler at full load

> with
> > 7 mills in service? This value will set our nozzle sizing..
> >
> >
> >
> > Joel Vatsky
> >
> >
> >
>
>

CC: "Onaitis, Chuck" <Chuck@advancedburner.com>, "Ferrara, Sal N."
<Sal@advancedburner.com>



P.O Box 410, 271 Route 202/206
Pluckemin, NJ 07978
Phone. 908-470-0470; FAX: 908-470-0479
www.advancedburner.com

November 19, 2003

Jamestown Board of Public Utilities
P.O. Box 700
Jamestown, New York 14702-0700

Attention: James Nelson

Reference: IPSC Contract 04-45606
Unit 2 Low NOx Burners

Dear Mr. Nelson:

Confirming our previous discussion, the ABT burners on the subject Contract are designed for a maximum throughput of 220 MBtu/hr.

Please advise should you have any other questions.

Sincerely yours,


Sal N. Ferrara
Director of Proposals & Projects

cc: Tarkel Larson/Joel Vatsky


IP7_031236

DISCLOSURE NOTICES:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
2. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
3. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
4. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
5. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
6. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
7. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
8. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.


THERMOCOUPLE
PLATE
WELD TO
VERTICAL FLUTE




DETAIL D
SCALE 1 : 12
TIP THERMOCOUPLE LOCATION




SECTION C-C
VIEW IS
03008-400-A00-D0
ONLY
BODY THERMOCOUPLE LOCATION




DETAIL E
SCALE 1 : 12
BODY THERMOCOUPLE LOCATION




SECTION F-F




C.C.W. SHOWN
C.W. OPPOSITE HAND




WALL TUBES



DETAIL G
SCALE 1 : 12



DETAIL H
SCALE 1 : 12



SECTION B-B

30" OD FLANGE
1 1/8" HOLES
20 PLACES ON
27 1/2" D.B.C.

ABT FUEL DISTRIBUTION DEVICES

ITEM	DESCRIPTION	OPERATION	STROKE
A	SPIN VANE DRIVE	IN TO OPEN	5 3/4"
B	EXISTING OIL IGNITOR		
C	ABB FIBER OPTIC FLAME SCANNER		
D	DAMPER DRIVE	IN TO OPEN	16"
E	SIGHT TUBE		
F	INNER AIR ZONE DAMPER	PUSH TO OPEN	6"
G1	TIP THERMOCOUPLE JUNCTION BOX		
G2	BODY THERMOCOUPLE JUNCTION BOX		

EST. WEIGHT: 8296.51 lb.

MATERIAL:

SIZE:

TYPE:

ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED

CUSTOMER NAME

I.P.S.C.

QUANTITY

PART NO.

CONTRACT NO.



OPTI-FLOW BURNER
IGS UNIT 3

GENERAL ARRANGEMENT

DATE: 03008-100-A00-D0

SCALE: 1.24

SHEET: 1 OF 1

CAD GENERATED DRAWING
DO NOT MANUALLY UPDATE

NAME: RJ

DATE: 10/27/2003

DRAWN: RJ

CHECKED:

ENG APPR:

MFG APPR:

G.A.

2

TOLERANCES UNLESS SPECIFIED

MACHINE WELD FABRICATED PARTS

UP TO 8" INCL

OVER 8" TO 12" INCL

OVER 12" TO 24" INCL

OVER 24" TO 48" INCL

OVER 48" TO 96" INCL

OVER 96" TO 192" INCL

OVER 192" TO 384" INCL

EST. WEIGHT: 8296.51 lb.

MATERIAL:

SIZE:

TYPE:

ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED

CUSTOMER NAME

I.P.S.C.

QUANTITY

PART NO.

CONTRACT NO.

NO.	DATE	REMARKS	BY

NO.	DATE	REMARKS	BY

NO.	DATE	REMARKS	BY

NO.	DATE	REMARKS	BY


NO.	DATE	REMARKS	BY

NO.	DATE	REMARKS	BY

NO.	DATE	REMARKS	BY

NO.	DATE	REMARKS	BY

DISCLOSURE NOTICE:
 1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCE BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCE BURNER TECHNOLOGIES IS PROHIBITED.
 2. THE STRUCTURE AND OPERATION OPTI-FLOW® FUEL DISTRIBUTION SYSTEM AND DUAL REGISTER ARE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.




REAR WALL BURNER ARRANGMENT

- NOTES:
1. CUSTOMER TO SUPPLY BURNER NUMBERS.
 2. CUSTOMER TO SUPPLY DRAWING TO SHOW ELBOW ORIENTATIONS.
 3. CUSTOMER TO SUPPLY PLATFORM ELEVATIONS.

REVISIONS		REMARKS		BY	
NO.	DATE				
<p>ADVANCED BURNER TECHNOLOGIES CORP.</p> <p>OPTI FLOW BURNER</p> <p>IGS UNIT 2</p> <p>GENERAL ARRANGEMENTS RW</p> <p>E 03008-100-A01-RW</p>					
MATERIAL:		EST WEIGHT			
SIZE:		ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED			
TYPE:		DO NOT SCALE PRINT			
CUSTOMER NAME		PLANT NAME		UNIT	
I.P.S.C.		IGS		2	

DISCLOSURE NOTICE:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCE TECHNOLOGIES CORP. AND IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF ADVANCE BURNER TECHNOLOGIES CORP.
2. THE STRUCTURE AND OPERATION OF THIS FUEL DISTRIBUTION SYSTEM AND DUAL REGISTER ARE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.



FRONT WALL BURNER ARRANGMENT

- NOTES:
1. CUSTOMER TO SUPPLY BURNER NUMBERS.
 2. CUSTOMER TO SUPPLY DRAWING TO SHOW ELBOW ORIENTATIONS.
 3. CUSTOMER TO SUPPLY PLATFORM ELEVATIONS.

REVISIONS		DATE	BY
1	ISSUED FOR CONSTRUCTION		
2	REVISED		
3	REVISED		
4	REVISED		
5	REVISED		
6	REVISED		
7	REVISED		
8	REVISED		
9	REVISED		
10	REVISED		
11	REVISED		
12	REVISED		
13	REVISED		
14	REVISED		
15	REVISED		
16	REVISED		
17	REVISED		
18	REVISED		
19	REVISED		
20	REVISED		
21	REVISED		
22	REVISED		
23	REVISED		
24	REVISED		
25	REVISED		
26	REVISED		
27	REVISED		
28	REVISED		
29	REVISED		
30	REVISED		
31	REVISED		
32	REVISED		
33	REVISED		
34	REVISED		
35	REVISED		
36	REVISED		
37	REVISED		
38	REVISED		
39	REVISED		
40	REVISED		
41	REVISED		
42	REVISED		
43	REVISED		
44	REVISED		
45	REVISED		
46	REVISED		
47	REVISED		
48	REVISED		
49	REVISED		
50	REVISED		
51	REVISED		
52	REVISED		
53	REVISED		
54	REVISED		
55	REVISED		
56	REVISED		
57	REVISED		
58	REVISED		
59	REVISED		
60	REVISED		
61	REVISED		
62	REVISED		
63	REVISED		
64	REVISED		
65	REVISED		
66	REVISED		
67	REVISED		
68	REVISED		
69	REVISED		
70	REVISED		
71	REVISED		
72	REVISED		
73	REVISED		
74	REVISED		
75	REVISED		
76	REVISED		
77	REVISED		
78	REVISED		
79	REVISED		
80	REVISED		
81	REVISED		
82	REVISED		
83	REVISED		
84	REVISED		
85	REVISED		
86	REVISED		
87	REVISED		
88	REVISED		
89	REVISED		
90	REVISED		
91	REVISED		
92	REVISED		
93	REVISED		
94	REVISED		
95	REVISED		
96	REVISED		
97	REVISED		
98	REVISED		
99	REVISED		
100	REVISED		

Features

- Excellent oxidization resistance through 2000°F
- High creep-rupture strength
- Good weldability
- Alkali salt hot corrosion resistance

Applications

- Coal burners in power boilers
- Fluidized bed combustor cyclones
- Kilns, rotary calciners
- Furnace fans and dampers
- Superheater tube hangers
- Recuperators
- Thermal oxidizers
- Radiant tubes for steel coil and aluminum annealing
- Expansion bellows
- Land based gas turbine components

Chemical Composition, %

	Min	Max
Chromium (Cr)	20.0	22.0
Nickel (Ni)	10.0	12.0
Silicon (Si)	1.40	2.00
Carbon (C)	0.05	0.10
Nitrogen (N)	0.14	0.20
Cerium (Ce)	0.03	0.08
Manganese (Mn)	—	0.80
Phosphorus (P)	—	0.040
Sulphur (S)	—	0.030
Iron (Fe)	balance	


Specifications

UNS S30815 W.Nr. 1.4893
 ASME Code Case 2033-2
 ASME Section IX P-No. 8, Group No. 2
 Use External Pressure Chart HA-6
 ASME SA-182(F45), SA-213, SA-240,
 SA-249, SA-312, SA358, SA-409, SA-479
 ASTM A167, A 182(F45), A 213, A 240,
 A 249, A 276, A 312, A 358, A 409, A 473,
 A 479, A 480, A 813 and A 814


Performance Profile

RA 253 MA is a lean austenitic heat resistant alloy with high strength and outstanding oxidation resistance. RA 253 MA obtains its heat resistant properties by advanced control of micro alloy additions. The use of rare earth metals in combination with silicon gives superior oxidation resistance to 2000°F (1090°C). Nitrogen, carbon, and a dispersion of rare earth and alkaline earth oxides combine to provide creep rupture strength comparable to the nickel alloys.

2000°F Cyclic Oxidation Testing 1900 Hours Cycled Weekly



Minimum Creep Rate 0.0001% per Hour



RA 253 MA is a registered trademark of Outokumpu Stainless.

RA 253 MA

Oxidation

RA 253 MA has exceptional oxidation resistance up to about 2000°F (1090°C). Above this temperature oxidation resistance drops off. A combination of rare earths and silicon is responsible for the high oxidation resistance of this 21%Cr alloy. The rare earths increase diffusion rate of the silicon to the scale metal interface. This promotes development of a continuous SiO₂ subscale, which in turn slows further oxide growth. Rare earth metals also improve adhesion and elasticity of the oxide scale, even under cyclic conditions. These rare earths, primarily cerium, increase the number of nucleation sites for the oxide. This results in a fine grained chromia and silica scale.

Impact Toughness

RA 253 MA, in common with other high chromium austenitics, loses room temperature toughness and ductility after long exposure to the 1100—1600°F (600—870°C) temperature range. The effect is primarily on room temperature properties. While operating in the creep-rupture range the metal will have greater ductility and toughness.

Impact Strength after 20,000 hours aging at 1652°F (900°C), Charpy values for both alloys increased from those at 10,000 hour exposure.

Aging Temperature		Charpy V-notch impact foot-pounds (joule)	
°F	°C	310S	RA 253 MA
1292	700	3 (4)	3 (4)
1472	800	3 (4)	4 (5)
1652	900	27 (36)	42 (57)

Hot Salt Corrosion

Sodium and potassium salts cause hot corrosion of heat resistant alloys. Traditionally the most resistant alloys have been considered to be those highest in nickel. Exposure in salts for heat treating high speed steel indicate that RA 253 MA may be comparable to RA600.

Grade	weight %	Nickel, Depth of intergranular attack, mils (mm)	
RA 253 MA	11	6.9	(0.18)
RA600	76	7.5	(0.19)
RA309	13	12.5	(0.32)
RA330®	35	13.8	(0.35)

Plate samples exposed 210-252 cycles in preheat salts 1300 and 1500°F (704 and 816°C), high heat salt 2200°F (1200°C), quench in 1100°F (593°C) salt.

Metallic pots for neutral heat treating salts are commonly made of RA309 or RA330. The service life of the pot is primarily determined by maintenance, not alloy. Pots must be desludged regularly. When changing pots, every bit of old spilled salt must be removed from the furnace refractory.

Carburization

RA 253 MA has only fair resistance to carburization. Service experience has shown RA309 to be slightly better.

Coupons were exposed for 15 weeks of simulated bake cycles 1700—1950°F (930-1065°C) in "green mix" used for production of carbon electrodes. Room temperature tensile tests showed the following ductility:

Alloy	UNS	Retention of Ductility (% reduction of area)
RA 253 MA	S30815	0.5
302B	S30215	nil
800H	N08810	1.4
RA330®	N08330	16.6

Sulfidation

RA 253 MA has good resistance to hot SO₂ bearing atmospheres. In other words, it resists sulfidation under oxidizing conditions. However, RA 253 MA is not resistant to reducing sulfidizing atmospheres, when sulfur is present as H₂S. Note that even though the atmosphere may be oxidizing, the partial pressure of oxygen can be extremely low under solid sulfate deposits. Local sulfidation attack under the deposit can then occur.

Test samples exposed to an atmosphere containing 13.6% SO₂ at 1850°F (1010°C) for 1860 hours exhibited the following depth of intergranular oxidation and sulfidation:

Alloy	Depth of attack mils (mm)	
RA 253 MA	8	(0.20)
RA333®	8	(0.20)
RA309	18	(0.46)
RA310	20	(0.51)
RA330	24	(0.61)

PHYSICAL PROPERTIES

Density:

0.282 pounds/cubic inch
7800 kilogram/cubic meter

Melting Range:

2500—2610°F
1370—1435°C

Permeability:

$\mu = 1.01$ at $H = 1000$ Oersted

Mean Coefficient of Thermal Expansion:

Temp. Range		Temp. Range	
°F	in/in°Fx10 ⁻⁶	°C	m/m°Cx10 ⁻⁶
68—200	9.06	20—93	16.3
68—400	9.34	20—204	16.8
68—600	9.59	20—316	17.3
68—800	9.81	20—427	17.7
68—1000	9.97	20—538	17.9
68—1200	10.14	20—649	18.3
68—1400	10.3	20—760	18.5
68—1600	10.5	20—871	18.9
68—1800	10.8	20—982	19.4

Thermal Conductivity:

Temp	Btu•ft/ft ² •hr°F	Temp	W/mK
°F		°C	
60	8.38	20	14.5
400	10.1	204	17.5
800	11.7	427	20.2
1200	13.0	649	22.5
1400	14.0	760	24.2
1800	16.6	982	28.7

Specific Heat:

Temperature		Temperature	
°F	Btu/lb•°F	°C	J/Kg•K
68	0.105	20	440
400	0.117	204	490
800	0.130	427	544
1200	0.142	649	595
1400	0.149	760	624
1800	0.164	982	687

Electrical Resistivity:

Temperature		Temperature	
°F	ohm•circ mil/ft	°C	microhm•m
68	505	20	0.84
400	622	204	1.03
800	745	427	1.24
1200	830	649	1.38
1400	851	760	1.41
1800	871	982	1.45

Elastic Properties:

Poisson's ratio, room temperature 0.31

Dynamic modulus of elasticity			
Temperature		Temperature	
°F	psi x 10 ⁶	°C	GPa
68	29.0	20	200
400	26.8	204	185
800	24.4	427	168
1200	21.7	649	150
1400	20.2	760	139
1800	17.6	982	121

The modulus values given here were determined by a method involving the speed of sound through the metal at temperature. They are for information only. Above about 1000F (540C) heat resisting alloys no longer behave in an elastic manner. That is, one cannot calculate a deflection under load using such data.

MECHANICAL PROPERTIES

Room Temperature Properties

	Specified Minimums		Typical Range	
	psi	MPa	psi	MPa
Ultimate tensile strength	87,000	600	90,000-114,000	600—800
0.2% offset yield strength	45,000	310	45,000—69,000	310-476
Elongation in 2" (50mm), %	40		42—70	
Reduction of Area, %	50		—	
Hardness, Rockwell B	—		Rb 90	
Grain Size, ASTM	—		3—6	

Charpy V-notch impact strength, room temperature, average of three tests. Annealed material.

110 foot-pound 149 Joule

RA 253 MA

Typical Short Time Elevated Temperature Tensile Properties

Note: these are typical, and not specified minimums

Test Temp		Ultimate tensile strength		0.2% Offset yield strength		Elongation	Reduction
°F	°C	psi	MPa	psi	MPa		
122	50	96,200	663	44,200	305	51	68
212	100	90,200	622	39,300	271	48	65
392	200	83,800	578	32,200	222	46	65
572	300	82,400	568	29,300	202	46	64
752	400	79,700	550	29,100	201	46	60
932	500	75,700	522	25,500	176	44	62
1112	600	69,000	476	24,200	167	43	63
1292	700	56,400	389	23,000	159	44	58
1472	800	36,900	254	21,500	148	—	76
1562	850	24,800	171	14,600	101	—	88
1652	900	18,900	130	11,600	80	—	92
1832	1000	10,800	74.5	6,200	42.7	—	97
2012	1100	9,400	64.8	4,000	27.6	—	97
2192	1200	3,700	25.5	2,000	13.8	—	99

Data 850°C and up are from a single heat, other data is an average of 2 to 5 heats.

Note: Above about 1000°F (540°C), short time tensile properties are not a suitable basis for design. At the higher temperatures metals are not elastic, and deform slowly with time. Engineering design calculations should be made on the basis of time-dependent properties, that is, on creep or rupture data.

Creep-Rupture Properties

Over 2.6 million hours of creep and rupture testing were used to generate the graphs and tables in this section. Some tests have run as long as 30,000 hours at AvestaPolarit Research Centre.

Temperature °F °C		Stress, psi (MPa), for secondary creep rate of		Average stress, psi (MPa) for rupture at indicated time		
		0.0001%/hr	0.00001%/hr	1000 hour	10,000 hour	100,000 hour
1100	593	18,000 (124)	12,000 (82.7)	32,000 (221)	22,000 (152)	15,000 (103)
1200	649	11,600 (80)	8,200 (56.5)	23,000 (159)	14,000 (96.5)	8,700 (60.0)
1300	704	7,700 (53.1)	5,700 (39.3)	16,000 (110)	8,500 (58.6)	4,600 (31.7)
1400	760	5,000 (34.5)	3,800 (26.2)	9,200 (63.4)	5,200 (35.9)	2,900 (20.0)
1500	816	3,350 (23.1)	2,550 (17.6)	6,600 (45.5)	3,750 (25.9)	2,100 (14.5)
1600	871	2,300 (15.9)	1,750 (12.1)	4,400 (30.3)	2,500 (17.2)	1,450 (10.0)
1700	927	1,500 (10.3)	1,150 (7.93)	2,750 (19.0)	1,650 (11.4)	970 (6.69)
1800	982	890 (6.14)	550 (3.79)	1,850 (12.8)	1,150 (7.93)	700 (4.83)
1900	1036	490 (3.39)	— —	1,350 (9.31)	860 (5.93)	— —
2000	1093	— —	— —	1,020 (7.03)	680 (4.69)	— —

RA 253 MA has approximately twice the strength of RA309 and RA310 in the creep-rupture range.

WELDING

General

Neither preheat nor postheat is required for welding RA 253 MA.

The chemistry of RA 253 MA welding wire and covered electrodes is balanced to contain about 4—12 Ferrite Number. This ferrite provides RA 253 MA weld fillers excellent resistance to hot cracking. In that respect, RA 253 MA behaves as do other stainless weld fillers, such as 309. The unique addition of cerium to RA 253 MA, both in the base metal and in the weld fillers, is to enhance the alloy's oxidation resistance. Cerium also makes the weld bead appear a little rough. This is characteristic of weld fillers containing rare earths and is not amenable to improvement by welding procedure. While this has not been a problem in service, a few customers prefer to weld RA 253 MA with RA333® weld fillers.

Shielded Metal Arc Welding (SMAW)

RA 253 MA-17 AC/DC titania electrodes may be used with either alternating current or with direct current. For DC welding use reverse polarity (electrode positive). Maintain the arc length as short as possible. A short arc minimizes loss of cerium through the arc and improves penetration. Starts and craters should be filled in to minimize the possibility of cracking.

All welding flux must be removed from each deposit, between passes and after the final pass. Residual welding flux may corrode the material when placed in high temperature service.

Typical SMAW Parameters suggested current ranges at 24—30 volts

	electrode diameter, inch		
	3/32	1/8	5/32
amperes	45—70	70—110	100—140

The lower end of the current range is used for out-of-position welding.

Gas Metal Arc Welding (GMAW)

Shielding gas for the spray-arc transfer mode is be 100% argon. For improved wetting and bead contour, Ar-He-CO₂ mixes, containing 80% minimum argon and no more than 1% carbon dioxide, have been used. For short-circuiting arc transfer welds we suggest 75%He 25%Ar shielding gas. Short arc welding has been done using 90%He 7-1/2%Ar 2-1/2%CO₂, or 68%Ar 30%He 2%CO₂. The lower helium gives a cooler arc and is preferred for out of position work.

Typical GMAW Parameters Spray-arc 100% argon shielding

Wire dia., inch	DCRP Current, amperes	Volts
0.035	160—210	26
0.045	180—240	27

DO NOT USE 98%Ar 2%O₂ FOR WELDING RA 253 MA. AND NEVER USE 75%Ar 25%CO₂ FOR ANY STAINLESS OR HEAT RESISTANT ALLOY WELDING.

Gas Tungsten Arc Welding (GTAW)

100% argon shielding gas is preferred for manual GTAW. Helium may be added to increase speed in automatic welding. Electrodes should be 2% thoriated tungsten (AWS EWTh-2) with direct current straight polarity (electrode negative). For good arc control, grind the electrode tip to a 30 to 60 degree point, with a small flat at the tip. Grind lines should be parallel to the electrode, not circumferential. Finish grind on a 120 grit wheel. Adjust the arc on clean scrap metal, with no scale.

Typical GTAW Parameters

2% Thoriated Gas, Tungsten Electrode diameter, inch	Direct Current Reverse Polarity (Electrode Negative) amperes	Voltage	Shielding Argon or Argon-Helium mixes, CFH
0.040	25-80	10-14	25
0.062	50-145	12-16	25
0.094	135-235	12-20	25

RA 253 MA

Submerged Arc Welding (SAW)

RA 253 MA is sub-arc welded using the neutral basic AvestaFlux® 805. This is an agglomerate type welding flux characterized by neat deposit surfaces, a smooth transition zone between parent and weld metal, easy slag removal and excellent resistance to moisture absorption during storage.

Typical SAW Parameters

Wire Dia. Inch	Direct Current, Reverse Polarity, Amperes	Voltage	Wire Stickout, inch	Travel Speed, inch/minute
0.062	225-300	29	3/4	8-12
0.094	300-400	27-32	1	16-24
0.125	400-450	27-32	1	16-24

Dissimilar Metal Welding

For joining RA 253 MA base metal to:	Suggested weld fillers either bare wire or covered electrodes
carbon steel	309
stainless grades 304, 316, or 309	RA 253 MA or 309
310	RA 253 MA
RA 353 MA	RA 353 MA
RA330, RA333, RA800H/AT, RA600, or RA601	RA333
RA 602 CA™	RA 602 CA wire or covered electrodes

FORMING

RA 253 MA may be formed, sheared, and machined. Alloying with nitrogen results in a high yield point (54,000 psi typical). For this reason, greater force is required and more spring-back may be anticipated than with 304 or 309 stainless. All traces of forming lubricants must be removed prior to welding, annealing, or use in high temperature service.

Forming at room temperature is suggested whenever possible. If hot bending is required, the workpiece should be heated uniformly throughout its section to 2000°F (1100°C), finishing above 1650°F (900°C). Overheating

or excessive hold time at starting temperature should be avoided to minimize grain growth.

No forming or bending should be performed in the low ductility range of 1200—1600°F (650—870°C). Forming in this temperature range may cause intergranular tearing in austenitic alloys.

Machining

Heat resistant austenitic alloys, such as RA 253 MA, are generally more difficult to machine than are conventional austenitic stainless steels. Alloying with nitrogen and rare earth metals causes both higher cutting forces and a more rapid tool wear during machining.

General Suggestions

- Use the most stable machine tools available. Stainless steels generate high cutting forces and large loads on the tools and the set-up.
- The set-up of the tools and the workpiece must be rigid. The workpiece must be adequately supported in order to avoid deflections by the cutting forces. Extensions on tools should be kept as small as possible. Long tool extensions and/or unstable cutting conditions severely increase the risk of vibrations and tool failure.
- Always use tools with sharp cutting edges. It is important that the cutting edge is sharp but it must also be strong enough to withstand the cutting forces. For cemented carbide tools, it is important that the edge chamfer is small enough to give a cutting edge that is effectively "sharp".
- Do not use a larger nose radius than necessary as this may cause vibrations.
- Use a depth of cut that is deep enough to let the cutting edge work below the strain hardened layer created by previous passes or operations.
- Use the correct cutting speed. A cutting speed which is too low increases the risk of built-up edge formation, tool failure and may result in a poor surface finish of the machined surface.
- Change the insert or regrind the tool at more frequent intervals than for carbon steels. A blunt cutting edge produces higher cutting forces and a thicker strain hardened layer than a sharp edge. This applies especially to high alloy stainless steels.
- When cutting fluid is used it should always be applied liberally to the cutting zone. If possible use cutting oils and emulsions with EP-additives.

Machining Data

The machining data given below represents general guidelines or starting values. These may need to be adjusted to the actual conditions of a specific machining operation. They are based on a tool life of approximately 15 minutes for cemented carbide tools and approximately 40 minutes for high speed steel tools.

Turning

longitudinal and face turning

	Cemented carbide tools		HSS tools
	Roughing	Finishing	Finishing
Cutting speed, feet/minute	295—395	395—525	46—59
Feed, inch/turn	0.012—0.024	0.002—0.012	0.002—0.008
Depth of cut, inches	0.08—0.20	0.02—0.08	0.02—0.08
Cemented carbide grade	C5, C6	C6, C7	—

Notes: Use coated cemented carbide inserts with positive chipbreaker styles. Use as small an entering angle as possible during roughing. Use cutting fluid. When roughing, SPUN and TPUN geometries may be used with good results. When face turning large workpieces use a tougher cemented carbide grade.

Drilling

twist drilling with HSS drills

Drill diameter Inch	Cutting speed foot/minute	Feed inch/revolution
1/32—1/8	16—26	0.0015
1/4	16—26	0.003
3/8	26—33	0.005
5/8	26—33	0.008
3/4	26—33	0.010
1-1/4	26—33	0.012
1-1/2	26—33	0.013

This section has been taken entirely from MACHINING GUIDELINES 253 MA® by Outokumpu Stainless.

Annealing

Solution annealing of RA 253 MA is performed by heating 1920—2100°F (1050—1150°C) for 5—20 minutes, rapid air cool or water quench. Plate is most commonly annealed about 1960—2000°F (1070—1100°C).

About 70% of residual stresses may be relieved by heating 1560—1740°F (850—950°C) for about 15 minutes at heat, air cool.

After severe cold work (more than 10-20% cold work) it is desirable to solution anneal for maximum creep rupture strength. This is appropriate for service above 1450°F (800°C).


Sources

All of the oxidation, hot salt corrosion, sulfidation and carburization data in this brochure is from Rolled Alloys' laboratory. The physical and mechanical properties, along with machining parameters, were developed by Outokumpu Stainless.

RA 253 MA

SOME APPLICATIONS


Power Plants



Coal fired power plant using a pressurized fluidized bed combustion (PFBC) boiler. RA 253 MA used for the cyclones (pictured), and gas collecting pipe for this project at American Electric Power (AEP) TIDD project in Brilliant, OH. Cyclones separate out particulate from the exhaust gases, which are fed into a gas turbine. Combustion temperatures were 1500-1600°F. RA 253 MA selected for its excellent strength and its resistance to wastage by the combined effects of oxidation, sulfidation, and abrasion.



RA 253 MA witch's hat used in a pulverized coal boiler at a U.S. paper mill to protect an ash chute coming off the boiler. RA 253 MA was selected for its resistance to oxidation, sulfidation, and abrasion resistance in the process temperatures.




RA 253 MA boiler tube separators used at a Midwestern U.S. coal fired power plant, which replaced type 309 stainless. RA 253 MA was selected because of its improved strength, oxidation, and sulfidation resistance compared to 309 stainless.


STEEL PROCESSING & HEAT TREATING

Coal Injection Lances

Small diameter RA 253 MA pipe is being used at several steel mills for the injection of pulverized and/or granulated coal into the blast furnaces. Hot air blast temperatures can vary from 1650°F to 2200°F in temperature depending on the mill. RA 253 MA is used for its excellent resistance to oxidizing/sulfidizing conditions involved in coal combustion.



RA 253 MA pipe replaced type 310 stainless steel in this recuperator system off of a zinc galvanizing line. Estimated process temperatures were 1600°F (average) and 1750°F maximum. The recuperator used 2" SCH40 pipe. 310 and 316 stainless pipe used in the front three rows, (the inlet for hot exhaust gases) of the recuperator failed from scaling in less than 1 year. RA 253 MA was installed and photos show its condition after two years in service. Most recent inspection after four years of service reported no RA 253 MA failures.




RA 253 MA radiant U-tubes mounted horizontally in a heat treat furnace. Typical operating temperature 1800°F. Exothermic atmosphere used for annealing. Tubes were fabricated with a 6" OD x 11ga wall firing leg and a 5-1/8" OD x 11ga wall exhaust leg. Picture shown after 10 months in service. RA 253 MA replaced RA330.

Wire Annealing


RA 253 MA pipe is used as muffles in the heat treatment of steel wires. RA 253 MA tested against RA330®, alloy 600, 601, and Haynes® 230®. RA 253 MA was selected based on its high performance and greater economy. Unit operates from 1650°F typically with occasional operation as high as 1900°F. Typical life has been three years before replacement.

Air Pollution Control




RA 253 MA material is used for the hot sections of this recuperative thermal oxidizer for the tubesheets and the shell. The unit destroys hydrocarbon fumes emitted in the printing industry. Operating temperatures reportedly in the 1300-1500°F range. Type 321 stainless was used for some cooler areas of the unit.

Process Industries





RA 253 MA hot air ducting is used at a US pulp and paper mill. Type 316 stainless was used previously, which failed in one year's time. Operating temperature estimated at 1940°F with some SO₂ in the air stream. This RA 253 MA unit has been in service for over three years.



RA 253 MA plate has been used to replace both cast HK and wrought 310H stainless hangers in crude heaters. RA 253 MA offers much greater stress-rupture values than 310H stainless approaching that of cast HK. Since RA 253 MA is a wrought alloy it provides greater toughness and soundness than a casting and as a result is less prone to sudden brittle failures.

Disclaimer Clause: The data and information in this printed matter are believed to be reliable. However, this material is not intended as a substitute for competent professional engineering assistance which is a requisite to any specific application. Rolled Alloys makes no warranty and assumes no legal liability or responsibility for results to be obtained in any particular situation, and shall not be liable for any direct, indirect, special, or consequential damages therefrom. This material is subject to revision without prior notice.





RA 253 MA

MIDWEST REGION:

125 West Sterns Road
Temperance, Michigan 48182-9546
800-521-0332
1-734-847-0561
Fax: 1-734-847-6917
email:sales@rolledalloys.com

CENTRAL REGION:

9944 Princeton-Glendale Road
Cincinnati, Ohio 45246
800-521-0332
email:sales@rolledalloys.com

EASTERN REGION:

30 Baker Hollow
Windsor, Connecticut 06095
800-521-0332
email:sales@rolledalloys.com

SOUTHERN REGION:

9818 E. Hardy Road
Houston, Texas 77093
800-521-0332
email:sales@rolledalloys.com

WESTERN REGION:

Harvey Titanium Ltd., Division of Rolled Alloys
291 Coral Circle Drive
El Segundo, California 90245
800-321-0909
1-310-343-6000 fax 1-310-606-9322
email:harveytisales@rolledalloys.com

CANADA:

Rolled Alloys-Canada, Inc.
151 Brunel Road - Unit 23
Mississauga Ontario Canada L4Z 2H6
800-521-0332
1-905-501-7552 fax 1-905-501-7553
email:racsales@rolledalloys.com

ENGLAND:

Walker Industrial Park
Guide, Blackburn
BB1 2QE, United Kingdom
+44-(0)1254 582 999 fax +44-(0)1254 582 666
email:blackburn@rolledalloys.co.uk

Unit 5, Priory Industrial Park
Airspeed Rd., Christchurch, Dorset
BH23 4HD, United Kingdom
+44-(0)1425 280 000 fax +44-(0)1425 280 028
email:christchurch@rolledalloys.co.uk

THE NETHERLANDS:

Rolled Alloys
Voorerf 16
4824 GN Breda, The Netherlands
+31-(0)76-548 44 44 fax +31-(0)76-542 98 88
email:sales@rolledalloys.nl

INTERNATIONAL:

Rolled Alloys International, Ltd.
14, The Oaks
Clews Road, Redditch, Worcestershire
B98 7ST, United Kingdom
+44-(0)1527-401101 fax +44-(0)1527-401013
email:hbuijsters@rolledalloys.co.uk

SINGAPORE:

Rolled Alloys International, Ltd. Singapore
10 Anson Road #24-06
International Plaza, Singapore 079903
+65-62272725 fax +65-62272735
email:railtd@pacific.net.sg

CHINA:

Rolled Alloys, Ltd.
Room 12B03, 12B Floor
Suncome Liauw's Plaza
738 Shangcheng Road, Pudong New Area
Shanghai, China 200120
+86-(0)21-5835-5329 fax +86-(0)21-5835-5339

E-mail: sales@rolledalloys.com

<http://www.RolledAlloys.com>

ISO 9001:2000
AS9100 Rev A
REGISTERED
COMPANY

ROLLED
ALLOYS
The world's heat, corrosion, titanium,
and aerospace alloy specialists.

ABT Burner Failures

April 8, 2006

Phil Hailes' Comments

Having looked at some of the burners scattered throughout the boiler, I am even more convinced by my initial conclusions as to the causes for the damage. In fact, D5 burner illustrates my point very well. So the following is just my thoughts, based on inspection of the removed burners.

Cracks progress in 3 stages. They proceed sequentially. Stage 1 is first, Stage 2 is second, and Stage 3 is third.

Stage 1: Cracking initiates approximately 6" from the nozzle-to-barrel circumferential joint, on the transition of the barrel circular geometry to the nozzle "flower pedal" geometry. This is the location that the erosive wear of the coal is the most obvious and significant. This always begins on "flower pedal" transition that are on the upper half of the burner. These cracks begin because the material is thinned at this transition point, by erosion, and possibly manufacturing. I submit that the thinned sections crack (after erosion) because of thermal stresses. Once the crack is initiated, they spread longitudinally, along the axis of the barrel, mostly forward, and sometimes rearward.

Stage 2: These cracks are strictly thermal. They progress from the Stage 1 cracks, and run circumferentially around the "flower pedal". They trend along a circumferential line at about the mid-point of the pedals. They initiate from the stress risers of the Stage 1 cracks. These ultimately cause the most obvious damage and are the ones that a casual observer, walking past the burner would notice without getting dirty. When these cracks begin, the party is over. It seems that all or most all of them have originated from a Stage 1 crack.

Stage 3: These are the cracks that initiate from the Stage 2 cracks. They run axially (for-aft) along the flower pedal, parallel to the ridges. They are a result of hoop stresses, caused by the thermal loads, I believe. These also cause more obvious damage, however, they are not as prevalent as Stage 1 and 2, since they appear later in the game, and the stress has likely been relieved significantly by the cracking of Stage 2.

The above conclusions are based on directional crack propagation, sequential A-to-B cracks, and material erosion indications. The first thing to fail is the eroded area of the "flower pedals". They fail first from coal erosion. Once the cracking starts, then the cracks begin to propagate throughout the nozzle.

In summary, it's erosion for a little bit, then thermal takes over and destroys everything. I suppose that if the erosion problems hadn't occurred, perhaps the flower pedal wouldn't have been destroyed. That being said, 70 F to 2700 F is definitely a source of thermal stress, no matter how you cut it.....maybe they would have come apart anyway.



Standard Specification for Steel Castings, Iron-Chromium and Iron-Chromium-Nickel, Heat Resistant, for General Application¹

This standard is issued under the fixed designation A 297/A 297M; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope

1.1 This specification covers iron-chromium and iron-chromium-nickel alloy castings for heat-resistant service. The grades covered by this specification are general purpose alloys and no attempt has been made to include heat-resisting alloys used for special production application.

NOTE—For heat-resisting alloys used for special product application, reference should be made to Specifications A 351/A 351M, A 217/A 217M, and A 447/A 447M.

1.2 The values stated in either inch-pound units or SI units are to be regarded separately as standard. Within the text, the SI units are shown in brackets. The values stated in each system are not exact equivalents; therefore, each system must be used independently of the other. Combining values from the two systems may result in nonconformance with the specification.

2. Referenced Documents

2.1 ASTM Standards:

A 217/A 217M Specification for Steel Castings, Martensitic Stainless and Alloy, for Pressure-Containing Parts, Suitable for High-Temperature Service²

A 351/A 351M Specification for Castings, Austenitic, Austenitic-Ferritic (Duplex), for Pressure-Containing Parts²

A 370 Test Methods and Definitions for Mechanical Testing of Steel Products³

A 447/A 447M Specification for Steel Castings, Chromium-Nickel-Iron Alloy (25-12 Class), for High-Temperature Service²

A 781/A 781M Specification for Castings, Steel and Alloy, Common Requirements, for General Industrial Use²

3. General Conditions for Delivery

3.1 Material furnished to this specification shall conform to the requirements of Specification A 781/A 781M, including any supplementary requirements that are indicated in the purchase order. Failure to comply with the general requirements of Specification A 781/A 781M constitutes nonconformance with this specification. In case of conflict between the requirements of this specification and Specifica-

tion A 781/A 781M, this specification shall prevail.

4. Ordering Information

4.1 The inquiry and order should include or indicate the following:

4.1.1 A description of the casting by pattern number or drawing (dimensional tolerances shall be included on the casting drawing),

4.1.2 Grade of steel,

4.1.3 Options in the specification, and

4.1.4 The supplementary requirements desired including the standards of acceptance.

5. Process

5.1 Alloys shall be made by the following processes: electric-arc, electric-induction, or other approved processes.

6. Heat Treatment

6.1 Castings for heat-resistant service may be shipped in the as-cast condition without heat treatment. If heat treatment is required, the treatment shall be established by mutual agreement between the manufacturer and the purchaser and shall be so specified in the inquiry, contract, or order.

7. Chemical Composition

7.1 Alloys shall conform to the requirements as to chemical composition prescribed in Table 1.

8. Repair by Welding

8.1 The composition of the deposited weld metal shall be similar to the composition of the casting. All weld repairs shall be subjected to the same inspection standards as the casting.

8.2 Castings with major weld repairs shall be heat treated in accordance with Section 6.

8.3 Weld repairs shall be considered major when the depth of the cavity after preparation for repair exceeds 20 % of the actual wall thickness, or 1 in. [25 mm], whichever is smaller, or when the extent of the cavity exceeds approximately 10 in.² [65 cm²].

8.3.1 When Supplementary Requirement S7 is specified on the purchase order, or inquiry, major weld repairs shall be subject to the prior approval of the purchaser.

8.4 All other weld repairs shall be considered minor and may be made at the discretion of the manufacturer without prior approval of the purchaser.

¹ This specification is under the jurisdiction of ASTM Committee A-1 on Steel, Stainless Steel, and Related Alloys and is the direct responsibility of Subcommittee A01.18 on Castings.

Current edition approved Dec. 15, 1993. Published April 1994. Originally published as A 297 - 46 T. Last previous edition A 297/A 297M - 89.

² Annual Book of ASTM Standards, Vol 01.02.

³ Annual Book of ASTM Standards, Vol 01.03.

TABLE 1 Chemical Requirements

Grade	Type	Composition, %							
		Carbon	Manganese, max	Silicon, max	Phosphorus, max	Sulfur, max	Chromium	Nickel	Molybdenum, max ^A
HF	19 Chromium, 9 Nickel	0.20-0.40	2.00	2.00	0.04	0.04	18.0-23.0	8.0-12.0	0.50
HH	25 Chromium, 12 Nickel	0.20-0.50	2.00	2.00	0.04	0.04	24.0-28.0	11.0-14.0	0.50
HI	28 Chromium, 15 Nickel	0.20-0.50	2.00	2.00	0.04	0.04	26.0-30.0	14.0-18.0	0.50
HK	25 Chromium, 20 Nickel	0.20-0.60	2.00	2.00	0.04	0.04	24.0-28.0	18.0-22.0	0.50
HE	29 Chromium, 9 Nickel	0.20-0.50	2.00	2.00	0.04	0.04	26.0-30.0	8.0-11.0	0.50
HT	15 Chromium, 35 Nickel	0.35-0.75	2.00	2.50	0.04	0.04	15.0-19.0	33.0-37.0	0.50
HU	19 Chromium, 39 Nickel	0.35-0.75	2.00	2.50	0.04	0.04	17.0-21.0	37.0-41.0	0.50
HW	12 Chromium, 60 Nickel	0.35-0.75	2.00	2.50	0.04	0.04	10.0-14.0	58.0-62.0	0.50
HX	17 Chromium, 66 Nickel	0.35-0.75	2.00	2.50	0.04	0.04	15.0-19.0	64.0-68.0	0.50
HC	28 Chromium	0.50 max	1.00	2.00	0.04	0.04	26.0-30.0	4.00 max	0.50
HD	28 Chromium, 5 Nickel	0.50 max	1.50	2.00	0.04	0.04	26.0-30.0	4.0-7.0	0.50
HL	29 Chromium, 20 Nickel	0.20-0.60	2.00	2.00	0.04	0.04	28.0-32.0	18.0-22.0	0.50
HN	20 Chromium, 25 Nickel	0.20-0.50	2.00	2.00	0.04	0.04	19.0-23.0	23.0-27.0	0.50
HP	26 Chromium, 35 Nickel	0.35-0.75	2.00	2.50	0.04	0.04	24-28	33-37	0.50

^A Castings having a specified molybdenum range agreed upon by the manufacturer and the purchaser may also be furnished under these specifications.

SUPPLEMENTARY REQUIREMENTS

The following supplementary requirements shall not apply unless specified in the purchase order. A list of standardized supplementary requirements for use at the option of the purchaser is included in Specification A 781/A 781M. Those which are ordinarily considered suitable for use with this specification are given below. Others enumerated in A 781/A 781M may be used with this specification upon agreement between the manufacturer and purchaser.

S1. Magnetic Particle Examination

S2. Radiographic Examination

S3. Liquid Penetrant Examination

S4. Ultrasonic Examination

S5. Examination of Weld Preparation

S6. Certification

S7. Prior Approval of Major Weld Repairs

S8. Marking

S9. Tension Test

S9.1 One tension test shall be made from material representing each heat. The bar from which the test specimen is taken shall be heat treated in production furnaces to the same procedure as the castings it represents. The results shall conform to the requirements specified in Table 2.

S9.2 Test bars shall be poured in separately cast keel blocks similar to Fig. 3 of Test Methods and Definitions A 370 or Fig. 1 of Specification A 447/A 447M.

S9.3 Tension test specimens may be cut from heat-treated castings; or from as-cast castings if no heat treatment is specified for the castings, instead of from test bars when agreed upon between the manufacturer and the purchaser.

S9.4 Test specimens shall be machined to the form and dimensions of the standard round 2-in. [50-mm] gage length specimen shown in Fig. 6 of Test Methods and Definitions A 370 and shall be tested in accordance with Test Methods and Definitions A 370.

S9.5 If the results of the mechanical tests for any heat do not conform to the requirements specified, the castings may be re-heat treated and re-tested, but may not be solution treated or re-austenitized more than twice.

S9.6 If any test specimen shows defective machining or develops flaws, it may be discarded and another specimen substituted from the same heat.

TABLE 2 Tensile Requirements

Grade	Type	Tensile Strength, min		Yield Point, min		Elongation in 2 in. [50 mm], min, % ^A
		ksi	[MPa]	ksi	[MPa]	
HF	19 Chromium, 9 Nickel	70	485	35	240	25
HH	25 Chromium, 12 Nickel	75	515	35	240	10
HI	28 Chromium, 15 Nickel	70	485	35	240	10
HK	25 Chromium, 20 Nickel	65	450	35	240	10
HE	29 Chromium, 9 Nickel	85	585	40	275	9
HT	15 Chromium, 35 Nickel	65	450	4
HU	19 Chromium, 39 Nickel	65	450	4
HW	12 Chromium, 60 Nickel	60	415
HX	17 Chromium, 66 Nickel	60	415
HC	28 Chromium	55	380
HD	28 Chromium, 5 Nickel	75	515	35	240	8
HL	29 Chromium, 20 Nickel	65	450	35	240	10
HN	20 Chromium, 25 Nickel	63	435	8
HP	26 Chromium, 35 Nickel	62.5	430	34	235	4.5

^A When ICI test bars are used in tensile testing as provided for in this specification, the gage length to reduced section diameter ratio shall be 4 to 1.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, 1916 Race St., Philadelphia, PA 19103.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, 1916 Race St., Philadelphia, PA 19103.

of
n
n
n

rial repre-
ecimen is
es to the
sults shall

cast keel definitions

at-treated
atment is
ars when
urchaser.

form and age length definitions

Methods

y heat do
tings may
e solution

hining or specimen

GWC

MAY 15 2006

May 9, 2006

271 Route 202/206
P.O. Box 410
Pluckemin, NJ 07978

P 908.470.0470
F 908.470.0479

www.advancedburner.com

Mr. George W. Cross, President and Chief Operating Officer
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, Utah 84624

Subject: Intermountain Generation Station Unit 2 Low NO_x Burners, Contract 04-45606
IPSC April 24, 2006 Letter

Dear Mr. Cross:

Advanced Burner Technologies Corporation (ABT) is concerned that damage has occurred to the burners we have supplied. Although we deny IPSC claims that ABT has any responsibility, we do however remain committed to help IPSC. To this end we have been working closely with the Plant to identify the root causes that first became evident on June 27, 2005 with IPSC's Mr. J. Finlinson's email notification of the F3 burner fire.

We can understand that changes in operation (such as fuel supply) and occasionally information that can be important to the supplier may, through inadvertent oversight, not be provided to the supplier. In this case two critical items were not provided to ABT: the expected fuel change that resulted in significant increases in fuel and primary air flow, and the overheating of the original equipment burner barrels. There is no way any equipment designer can design for conditions of which they are not made aware by the owner.

The following items 1 through 5 of the subject Intermountain Power Service Corporation (IPSC) letter that describes problems identified by IPSC are as follows, with ABT responses added in bold text:

1. Erosion of the barrel just downstream of the long-sweep elbow. This has occurred on every burner and we believe it is caused by the diffuser assembly you designed and supplied that is located in the elbow.

ABT response:

The diffuser assembly, otherwise known as "x-vane", located in the elbow is a wear component, however it has worn more rapidly than the standard design we have in operation at all our other installations. ABT's proposal included supply of the standard x-vane design which eliminate the cleanout plug at the elbow's centerline; however, in early stages of the project IPSC requested a change in order to retain the existing port in the burner inlet elbow. ABT agreed to make the change but also advised IPSC that the standard x-vane as originally offered was a better, simpler, design. In any case, the accelerated wear to the x-vane assembly, and erosion of the barrel downstream of the long sweep elbow, is due to IPSC operation of their coal mills at higher flows than allowed by contract and the burner design. As stated in Proposal



Section 4.9, ...ABT will design the burners for the full load primary airflow, per mill, as per the OEM mill curves, with one mill out of service at boiler full load. The design mill primary airflow (210,000 lb/hr) for fuel injector sizing was also confirmed early in the project with J. Vatsky 9/11/03 email correspondence to P. Hailes.

It did not become evident that IPSC is running the mills at much higher flows than design until October 2005. IPSC's G. Christensen 10/27/05 email correspondence advised flows are as high as 265,000 lb/hr, which is more than 25% greater than the burner design flow agreed between IPSC and ABT. ABT's S. Ferrara responded immediately with 10/28/06 email advising effects of higher operating flows by degrading performance and increasing component wear.

Based on IPSC long term records of fuels burned (Mr. G. Christensen 11/2/05 email correspondence) IPSC has operated for an extended period of time (September 2004 through April 2005) on coals having significantly lower HHV properties than allowed by ABT's design. The lower than specified HHV ($\leq 11,500$ Btu/lb) results in overfiring of burners (higher than design air and coal flows) in order to maintain full load generation on the Unit.

2. Erosion of burner nozzles where it divides into the six segments just prior to discharge. Every burner showed significant erosion with many having multiple holes.

ABT response:

Erosion of the burner nozzles is due to high velocities of the air/coal mixture in the nozzle, along with the higher coal loadings resulting from the lower heating value coal. This condition may be worse due to by denser coal streams being formed in the non-standard design of the x-vane assembly.

Had ABT known that IPSC intended to operate the mills at the current coal and air flows, the burner nozzles would have been designed accordingly resulting in lower nozzle velocities. ABT has not experienced nozzle erosion at any of its other installations where the mills are operating in the range for which the burner is designed.

In cases where it is known that erosive conditions exist (high velocity and/or highly abrasive fuel) ABT will apply erosion resistant materials in the fuel injector barrels as well as the inlet to the nozzles to maximize their longevity. This was not the case with IPSC as the coal was not considered to be highly abrasive and the contract defined flows result in relatively low air/coal velocity in the nozzle.

Had ABT been advised that such a fuel change and resultant mill operation was anticipated, we would have proposed the changes noted above.

3. Severe cracking and structural failure of the burner nozzle which originates from the weld of the nozzle to the burner barrel. The cracking of the nozzles was so severe on 15 of the 48 burners on a recent inspection that those 15 nozzles had to be removed and replaced.

ABT response:

This is consistent with discussions held in the November 9, 2005 meeting at the Intermountain Generating Station where ABT explained that the carbon steel burner barrels were overheating upstream of the point where carbon steel barrel is welded to the stainless steel nozzle tip. The carbon steel is expanding at a higher rate than the



stainless casting causing the casting to rip at the weld and cracks to then form in the casting.

We advised in the meeting that the temporary repairs that IPSC wanted to implement would not resolve the barrel overheating and nozzle cracking problem. ABT explained that it would be necessary to extend the carbon/stainless steel weld point further from the furnace by replacing a section of the carbon steel barrel with a stainless steel barrel. IPSC advised in the meeting that the OEM burners originally provided on the Unit had experienced the same overheating problems witnessed on the ABT nozzles and the resolution was to extend the stainless steel portion of the barrel just as ABT is recommending. IPSC advised in the meeting that based on conditions observed during the recent October 2005 outage, it would not be necessary to implement ABT's recommendation to extend the carbon/stainless steel weld point back during the April 2006 outage.

Note that this was the first time ABT was advised of this overheating condition with the OEM burners and, had this been conveyed to ABT during the bidding or design phase of the project, we would have extended the stainless steel portion of the barrel.

We have not experienced this type overheating problem on any of the ABT burner designs currently operating in the industry, which all have the carbon/stainless steel weld point in similar proximity to the furnace as is currently operating on the ABT burners at IPSC. The only time we have seen elevated temperatures on the carbon steel barrel is when the cooling secondary airflow to the burners was completely shutoff and we suspect that this may be happening at IPSC. We have suggested an investigative program to the Plant in order to determine if any operating conditions exist where insufficient cooling flow is available to the burners. In particular we believe that the compartmented windbox air control dampers may be too closed when the burner deck is out of service and have asked the Plant to investigate this. To date we have not had any response or been provided with any information.

4. Erosion of the ceramic lined long-sweep elbow and x-vane diffuser.

ABT response:

The ceramic lined long sweep elbows are original boiler equipment and were not replaced by ABT during the Low NOx Burner retrofit. The erosion of the x-vane diffuser is discussed in Item 1 above and is a result of IPSC operating the coal mills at primary air and coal flows much higher than allowed by the contract.

The x-vanes are replaceable components and are expected to wear over a period of years. ABT has an on-going development project to identify the latest wear-resistant materials so that we can select those materials that best fit the specific fuel properties and flow conditions for each project. At the design fuel and flow conditions specified by the IPSC project, the x-vane assemblies supplied by ABT would last many years prior to needing replacement. The fuel and flow conditions that IPSC has been recently operating at, and has defined for the future, would require a change to material selection of ABT's x-vanes, at an increased cost, in order to minimize the type wear IPSC is experiencing of this component. Further the burner barrels would have to be lined and the nozzles replaced with new ones designed for the actual flows now being utilized.

5. One burner (F3) was completely replaced because it was damaged in a burner fire on June 25, 2005. After inspecting the damaged burner, we believe the fire was caused by a hole eroded in the burner barrel just after the elbow. We believe the hole allowed coal to enter the inner air sleeve and eventually catch on fire damaging the burner.

ABT response:

Due to the extent of fire damage on F3 burner, it was not possible to determine the cause although based on the photos provided by IPSC it seems to have started either in the coal pipe or at the burner inlet. We noted that the coal pipe upstream of the burner, where the pipe passes through the floor grating, in the area of the coal pipe shutoff valve also showed evidence of fire, leading us to question whether the valve was only partly open.

As noted in J. Finlinson's 6/27/05 email, the IPSC operators were starting up the other Unit on June 25, 2005 at the time the fire started on F3 burner and therefore did not notice the high temperature alarms (well over 1600°F). It is not known how long the fire went unnoticed by the operators, however operator action to take the burner out of service would have prevented permanent damage to the burner components. F3 burner is the only one of 48 burners on the unit that suffered permanent damage from fire in over 2 years of operation. This being the case, it can only be concluded that the F3 incident is due to some type of operational malfunction rather than due to design defect in the burner.

The subject April 24, 2006 letter notes that IPSC "purchased the materials necessary to temporarily repair the burners." IPSC's letter also states "we are now requesting the following remedial actions from ABT according to the contract:"

1. With no additional IPSC reimbursement, ABT should make the necessary modifications to their design to solve all the problems we have experienced with the burners as outlined in this letter and to otherwise meet all the specifications of the contract.

ABT response:

The ABT burners are designed to the conditions of the contract and the problems experienced are due solely to IPSC operating conditions being outside those specified. This type of operation has voided the ABT "Guarantees and Warranties" as stated in Proposal Q03013, Section 4.9 (Contract Article III: Part C). ABT has already made the necessary design modifications to meet the new operating conditions provided by IPSC and has provided the Plant with a proposal in November 2005.

2. With no additional IPSC reimbursement, ABT should supply the necessary materials and manpower to install those design changes on all 48 of the IGS Unit 2 burners. This work should be done on the next Unit 2 major outage scheduled for the Spring of 2008.

ABT response:

ABT has already proposed to supply replacement fuel injectors for all 48 of the IGS Unit 2 burners and, as noted above, has designed these to the new conditions provided by IPSC. IPSC shall install the ABT supplied materials at IPSC cost. ABT's offer made during the November 9, 2005 meeting remains to supply the new fuel injectors to IPSC at a discount. We offer the discount as a good will gesture to work with IPSC and resolve the unexpected problems amicably.

5/9/2006



As a further good will gesture, ABT will maintain the November 2005 price if we receive the Purchase Order and initial payment by June 15, 2006 for delivery by December 2006.

3. ABT should reimburse IPSC for the burner purchased to replace the fire damaged F3 burner. We believe the fire was the direct result of an ABT design flaw that allowed rapid erosion of the burner barrel.

ABT response:

Damage to the F3 burner is due solely to operator inaction to control room alarms, allowing a burner fire to progress for long period rather than removing the burner from service to prevent permanent damage. The ABT design is not flawed and the rapid erosion problem is due to IPSC operating the burners at flow conditions outside the contract specifications.

4. ABT should reimburse IPSC for the materials purchased from ABT to repair the burners during the April 2006 Unit 2 outage.

ABT response:

During the November 9, 2005 meeting, ABT advised that the fuel injectors would require redesign to support operation at the higher flow rates. ABT also presented the new design arrangement during the meeting, and proposed to supply forty-eight fuel injectors for installation during the April 2006 outage. IPSC advised at that time that they were only interested in implementing temporary repairs during the April 2006 outage and intended to purchase the replacements designed for the new conditions for the next major outage. The cost for materials to make the temporary repairs will not be reimbursed by ABT to IPSC.

To summarize: the damage that has occurred is a direct result of changes in Plant operation (fuel and mill conditions) and failure of IPSC to inform ABT of the original burner barrel overheating problem that could have been addressed in the initial design phase.

AT remains committed to support IPSC in resolving these issues and had provided a proposal to do so as soon as we were advised of the actual operating conditions.

Please contact Sal Ferrara at 908-470-0721 to discuss any question you have on this matter.

Sincerely yours,

Joel Vatsky
President and CEO

Cc: Sal Ferrara



▪ **Mill Performance:**

Air Flow: The low NO_x burners will be designed to slave to the mills' operation in that the fuel injector will be sized to follow the mills' primary air flow characteristic. Consequently, ABT will design the burners for the full load primary air flow, per mill, as per the OEM mill curves, with one mill out of service at boiler full load. Primary air flow must reduce as mill load decreases. PA flow will be determined during pre-retrofit testing defined in this proposal Section 2.4.

Coal/PA Flow Balance: The balance between coal pipes within a given mill is to be within $\pm 10\%$ of the mean for that mill. (ABT recognizes that this is difficult to accomplish on all mills. Consequently, we will accept one of the eight mills being outside this range, to maximum of $\pm 15\%$).

- **Fineness:** 99.5% < 50 Mesh and 70% < 200 mesh; all mills simultaneously.
- **Coal Properties:** Western U.S. bituminous:
HHV > 11,500 Btu/lb; N₂ $\leq 1.2\%$; FC/VM ≤ 1.2 ; Ash $\leq 12\%$

4.10 Burner Load Variation

The nominal burner heat input at boiler full load with one mill out of service, is approximately 192 Mbtu/hr.

The ABT low NO_x burner's flame will remain stable at a load greater than 220 MBtu/hr, and less than 95 MBtu/hr.

Maximum secondary air flow at 220 MBtu per hour and 15% excess air, with 10% OFA flow will be no less than 124,240 lb/hr.

Minimum secondary air flow will be determined by balancing the burner stoichiometry against the overfire airflow necessary to maintain minimum NO_x. Note that 45% load is below the steam temperatures control range listed on the B&W summary performance sheet.

4.11 Ash Patterns

The low NO_x system shall not increase or adversely alter the pattern of ash deposits on the furnace walls or high temperature superheater tubing such that existing soot blowing and/or steam de-superheating sprays cannot maintain tube cleanliness or steam temperatures. Furthermore, the burners shall not cause increased buildup of slag deposits around the burner openings (i.e., eyebrows).



- NO_x shows only a slight dependence on BZLR for boilers with ABT low NO_x burners. The BZLR for Intermountain is similar to Deseret, which show NO_x emissions of 0.35. This data indicates that a NO_x level of 0.33 is attainable for Intermountain at 15% excess air and OFA ports closed.

7
12

2.2 Opti-Flow™ Low NO_x Burner:

ABT's Opti-Flow™ low NO_x burner generates a very bright, intense flame that does not look like the classical low NO_x flame: its intensity is more akin to that of classical turbulent burners. Yet, the NO_x levels are typically more than 35 percent lower than those generated by competitors' low NO_x burners that ABT has replaced firing bituminous coal and more than 40% lower than those firing PRB. This NO_x reduction result has been attained without any additional UBC penalty.

The Opti-Flow™ low NO_x flame stabilization nozzle is the key element of the fuel injector for attaining excellent flame stability along with minimum NO_x. Excellent flame stability is achieved by incorporating external flame stabilizers surrounding each nozzle segment. The segmented coal nozzle has an open design with no obstructions to wear or to collect coal. Nearly uniform fuel distribution around the burner nozzle circumference is also obtained, which provides significant aid in attaining minimum NO_x and UBC simultaneously. Pressure drop is minimal and there are no components in the coal path that would be subject to wear, coal accumulation, or coking.

linear

18-9
C-9

Advanced Burner Technologies utilizes high quality stainless steels for all parts of the fuel injector that face the furnace, as well as stainless steel castings for all complex parts. The result is high reliability and excellent longevity of the burners.

linear

ABT's Opti-Flow™ dual register is an innovative design that provides the operator with the flexibility of optimizing inner and outer zone swirl values, and the air flow split between the inner and outer zones independently of swirl. This is accomplished with a manually adjustable inner air damper and represents a significant improvement over other dual register designs. A fixed vane swirler is attached to the outer barrel of the fuel injector to impart swirl to the inner air zone.

In order to be most effective, any low NO_x burner must operate in an external environment that provides proper conditions needed for optimal combustion at each burner. There are two operational areas that are extremely important for best burner performance with minimum flame length:

- a) Known and accurately controlled primary air flow along with other sources of air which enter the fuel injector: such as auxiliary air and seal air. ABT has sized the fuel injector proposed here based on the PA flow contained in the OEM mill curves for Intermountain Unit 2. This primary air flow must be verified during pre-retrofit testing.

PA

C2

8

From: "Sal Ferrara" <sal@advancedburner.com>
To: "Garry Christensen" <Garry-C@ipsc.com>
Date: 10/28/2005 8:32:59 AM
Subject: RE: The remaining pictures

Thanks Garry.

The entire fuel injector assembly can be unbolted from the burner cover plate and removed as one piece (with inner zone damper and fixed vane spinner attached). We will provide our recommendations and an arrangement drawing for discussion on design for upgrading fuel injector & elbow design to a longer wear life. The pictures and descriptions you provided are very helpful in that respect.

In response to Dean's phone question yesterday morning, the fuel injector was designed based on the OEM Mill "Present Curve" (see email attachment) for full load, with one mill out of service. Based on the curve the burner design point is 62 MCFM PA flow @ 102 MLB/hr coal flow. Operating at higher flow rates than designed will result both in degrading performance as well as increase wear.

Sal *L so they know that there is wear.*

-----Original Message-----

From: Garry Christensen [mailto:Garry-C@ipsc.com]
Sent: Thursday, October 27, 2005 5:33 PM
To: sal@advancedburner.com
Subject: The remaining pictures

Sorry about that, the remaining pictures are attached. Are the nozzles replaceable and if so can they be removed with the tip attached? Also, what other components need to be unattached?

We do want you to look into a ceramic lined coal barrel/nozzle with a different engineered tip. ie less angle and modification of the X-vane. I hope you will be able to come out soon and sit down and discuss the issues so we can come up with a game plan and get needed parts/new equipment in time for April's outage.


This message scanned for viruses by CoreComm

CC: "Dean Wood" <Dean-W@ipsc.com>

IP7_031263

CONTRACT INFORMATION SHEET

INTERMOUNTAIN POWER PROJECT
STEAM GENERATOR UNITS 1-4
PROJECT FILE 9255.62.3401
IPA CONTRACT 2010N



THESE CURVES ARE SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION.

DRAWN BY
J. NEIDERT

DATE
2-1-82

APPROVED BY
R. H. P.

DATE
2-5-82

A.O.

REL. NO. AND DATE 1 9-8-82

CONTRACT NO.

334-0614

FILE NO.


RB-614

TITLE - DR 150752-RIGOR COORDINATION CURVES - COAL (B)

CIS- 101.05

IP7_031264

Average monthly PA flow with coal flow > 34 TPH



From: "joel" <joel@advancedburner.com>
To: "Phil Hailes" <Phil-H@ipsc.com>
Date: Thu, Sep 11, 2003 12:52 PM
Subject: Re: PA Mass Flow

OK: You initially had lb/hr I did know if that was a typo or just the wrong number.

We'll use 210,00 lb/hr as the design flow for the fuel injector sizing.

Thanks,

When do you need the dwg info you asked for?

----- Original Message -----

From: "Phil Hailes" <Phil-H@ipsc.com>
To: <joel@advancedburner.com>
Sent: Thursday, September 11, 2003 2:04 PM
Subject: Re: PA Mass Flow

> 3500 lbs/min is the average rate that Unit 1 at 950 MW is running at
> today with 7 mills. What specified condition are you requesting?

>
> >>> "joel" <joel@advancedburner.com> 9/11/2003 12:08:23 PM >>>
> Phil: this number is not correct. PA flow for mills of this size is in
> the
> 100,000's lb.hr per mill.

>
> It is not an approximate value we need; but the actual quantity under
> the
> specified condition.

> Please recheck this.

> Joel

> ----- Original Message -----

> From: "Phil Hailes" <Phil-H@ipsc.com>
> To: <joel@advancedburner.com>
> Sent: Thursday, September 11, 2003 12:25 PM
> Subject: PA Mass Flow

> > At 950 MW with 7 mills, the PA mass flow is approximately 3,500
> lbs/hr
> > per mill.

> > >>> "joel" <joel@advancedburner.com> 9/10/2003 1:16:18 PM >>>
> > Phil:

> > We need ASAP the following:

> > What is the primary air flow per mill with the boiler at full load

12

> with
>> 7 mills in service? This value will set our nozzle sizing..
>>
>>
>>
>> Joel Vatsky
>>
>>
>>
>
>

CC: "Onaitis, Chuck" <Chuck@advancedburner.com>, "Ferrara, Sal N." <Sal@advancedburner.com>

IP7_031267



Executive Summary and Philosophy

Advanced Burner Technologies Corporation is pleased to offer this proposal to Intermountain Power Service Corporation to supply and install state-of-the-art low NO_x burners for the Delta Unit #2 boiler. The specification lists several western bituminous coals, none of which, either singly or in the combinations specified, present any problem for ABT. The NO_x guarantee is 0.33 lb/MBtu is based upon what we understand to be the worst coal, SUFCO, which currently yields NO_x of about 0.45. Consequently, the NO_x will be reduced by at least 25% under equivalent operating conditions: 15% excess air and no overfire air flow. With 10% OFA flow, NO_x will be reduced to about 0.29 and with 20% to <0.25.

These values are based upon actual field experience with boilers of various sizes firing fuels ranging from lignite to PRB to eastern and western bituminous coal, as well as bit/PRB mixtures; and equipped with ABT's low NO_x burners only or these burners plus our OFA system. Consequently, we have a very high degree of confidence that these values can be attained in operation at Delta #2.

Under contract to ABT, Airflow Sciences Corporation will perform CFD models of the windboxes. This will enable us to optimize the secondary air distributions within the compartmented windbox design.

This proposal includes complete mechanical and electrical installation of all ABT supplied equipment. ABT's installation partner is Maintenance Enterprises, Inc., whose General Manager, Mike Simonds, has worked with ABT on several low NO_x conversions. These conversions include the turn-key supply and installation of low NO_x burners and overfire air systems at two 540 MW Kentucky Utilities boilers and installation of our burners on another 500MW unit at Deseret Generation & Transmission Coop in Vernal Utah. MEI, under Mr. Simonds' direction, will do an exemplary job of installing the ABT equipment.

We have the utmost confidence that the guarantees we have offered will be met.

Joel Vatsky, President
Advanced Burner Technologies Corp

C4

Jul-03

coal sampled May 2003

Weighted Totals

<u>Mine</u>	sampled	% of Total	% Na2O	HGI	Softening	HHVC Btu/lb	% H2O	% Ash	% Volatile	% Fixed Carbon	% Sulfur
	Total Tonnage				Temp						
Genwall Resources	27,501.08	5.81	2.04	45.5	2,148	12,426	6.95	8.51	39.04	45.50	0.67
Skyline (Product B) trucks	0.00	0.00	0.97	43.7	2,137	12,562	5.51	6.51	43.20	44.78	0.40
SUFCO (Product A)	195,613.19	41.35	2.96	42.4	2,122	11,292	8.37	11.06	37.57	43.00	0.39
Andalex	64,932.12	13.73	1.12	42.1	2,237	12,084	5.65	10.07	37.27	47.01	0.60
Andalex AMQ	0.00	0.00	0.84	39.1	2,277	11,981	6.64	9.44	34.78	49.14	0.56
West Ridge Resources	47,378.20	10.01	1.16	46.4	2,200	12,848	5.75	7.46	37.06	49.73	1.13
West Ridge Resources spc	27,929.48	5.90	0.94	45.9	2,234	13,069	5.22	7.07	37.53	50.18	1.18
Coastal-Dugout	26,777.20	5.66	0.48	40.4	2,357	11,977	5.80	11.45	35.72	47.03	0.68
Arch-Dugout (product B)	82,943.41	17.53	1.37	41.7	2,217	11,826	6.49	10.82	36.38	46.31	0.56
Arch (spot)	0.00	0.00	0.49	39.3	2,299	11,959	6.22	10.96	33.66	49.16	0.71
Totals	473,074.68	100.00	1.94	42.91	2,184	11,860	6.99	10.16	37.25	45.60	0.60

IP7_031269

CS

14

15

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

5. Burner Design: Burners provided for use at IGS shall adhere to the following provisions:
- a. Within the design phase of the Work, Contractor shall review all operational impacts on associated equipment and systems such as fans, pulverizers, dampers, etc. Any concerns regarding operating limitations or increase power demands noted within the modeling/design phase shall immediately be brought to the attention of the IPSC Contract Administrator.
 - b. Burner design and fabrication methodologies shall emphasize speed and ease of installation. The burner nozzles shall interface directly with the existing burner line flanges.
 - c. Burners shall be provided with combustion air flow sensors providing individual burner air flow indication in each annulus on each burner. Pre-wired panels, signal transducers, and displays shall be provided for displaying flow for each burner locally. Terminals shall be designed and provided within each panel for routing signals remotely. IPSC will have the responsibility to route the flow signals from the local panels to the control room if desired.
 - d. Burners shall provide for local manual air balance control, both between registers within each burner and between burners within a row. The registers shall remain operable under all operating conditions for at least the durations noted in Division C2, Burner and Scanner Performance Guarantees.
 - e. Temperature sensors installed at two (2) locations on each burner shall be provided and routed to a local cold-junction box at each burner level. The sensors shall be located in accordance with the direction of Contractor to identify and track the hottest temperatures occurring at the burner in both the in-service and out-of-service condition. Individual burner temperatures shall be provided at the local cold-junction boxes. Termination space shall be provided within the local cold-junction boxes for continuation of the circuits remotely for indication, monitoring, and alarm within the plant data acquisition system by IPSC as desired.
 - f. **The burner assemblies shall be fabricated of quality material sufficient to withstand the significant thermal stresses occurring within the windbox as a result of both radiant and convective heating.** Any deformation causing malfunction of register assemblies or misdirection of flow through the burner within the period of guaranteed operability shall be repaired at the earliest possible opportunity and charged to Contractor.

Cb

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

-
- g. Experience-based and verified wear-life shall be quoted within the bid for all burner components. No component shall last less than four (4) years before requiring rebuild, restoration, or replacement.
 - h. Burners shall be designed to operate continuously by IPSC without detrimental effects on boiler performance and steam side flexibility, within the ranges of carbon monoxide, unburned carbon, nitrogen oxides, and excess air specified in Division C2, Burner and Scanner Performance Guarantees.
 - i. Burners shall be designed for installation within the existing burner openings without pressure part modifications, unless clearly noted otherwise within the Proposal.
 - j. Burners shall be designed such that stable flame ignition occurs at the nozzle discharge.
 - k. Burners shall be designed for continuous operation with preheated air at an air heater outlet temperature of 750°F. This does not account for radiant and other heating sources.
 - l. Burners shall be equipped with an aspirated observation/viewing port to permit inspection of the flame. If necessary for flame diagnostics and adjustment, multiple observation doors shall be furnished. Doors shall be designed to permit observation during any load condition. Contractor (ABT) shall include one (1) port per burner assembly with observation glass to view flame. Each port will be equipped with purge air connection and ball valve should the need arise to purge the view pipe.
 - m. Burners shall include, and shall be provided with, new seal/cooling air piping and fittings, including a ball valve, from the burner connection to the header piping.
 - n. Air register operating mechanisms, joints, seals, slides, and linkages shall not be subject to binding from poor design, differential expansion, or from the accumulation of fly ash and shall remain operational without internal lubrication.
 - o. Air flow volume adjustment within each zone of the burner shall not be controlled with the same device controlling air swirl or spin within any air zone.
 - p. Burners shall be capable of stable operation continuously from 45 percent to 115 percent of rated BTU output of the burner without supplemental fuels.
6. Flame Detection System Design: The flame scanning system shall, as a minimum, include the following provisions:

17

PART C- DIVISION C2

BIDDING DOCUMENTS - PROPOSAL SCHEDULE

1. Proposal is hereby made to furnish and deliver to IPSC Unit 2 Low NOx Burners, F.O.B. IPSC dock, full freight allowed in accordance with Specifications 45606, the following:

- a. Burner and Scanner Performance: The new burners shall provide for a continuous boiler operation of 6,900,000 pounds/hour output, 1,005°F superheat and 1,005°F reheat temperature under all operating conditions. Bidders shall state the following burner and scanner performance guarantees and submit with the bid package:

BURNER AND SCANNER PERFORMANCE GUARANTEES	
Maximum Burner Nox and CO Production Under All Modes of Operation:	NOx=0.33 ^{lb} /mbtu CO=200 ppm
Maximum Burner BTU Throughput:	> 220 MBtu/hr
Burner and Scanner System Temperature Tolerance and Thermal Degradation Life:	Burner Tip=2000°F Scanner Electronic=140°F
Time Within Which Burner Register Assembly Shall Remain Fully Operable By Hand:	Past Guarantee Period
Combustion Zone Stability (Ignition Location/Stability, Flame Shape/Color):	Bright Flame in throat
Ash Deposition (At Burner Throat, OFA Ports, and Superheat Pendants):	Burner Throats & SH No add'l from current
Maximum Burner Out-Of-Service Cooling Air Requirements (CFM Per Compartment):	Scanners= 15 SCFM at 10"W.C.
Minimum In-Service Air Flow With Associated Emissions (Assuming 10 Percent Total Overfire Air Flow):	See Proposal Sec. 4
Maximum In-Service Air Flow With Associated Emissions (Assuming 10 Percent Total Overfire Air Flow):	See Proposal Sec. 4
Maximum Wear Life of Primary Air/Coal Path Components (Minimum Four (4) Years):	Nozzles: 6-8 yrs.* Fuel Dist. 4-6 yrs.*

C8



resulted in a significant improvement. The RMS value was reduced to 13% of the mean - an improvement of 4.62 over the baseline. Existing elbow-based fuel injectors that contain conical diffusers suffer from fuel imbalances of 36% RMS. In this case, the Opti-Flow™ system yields a 3 to 1 improvement in fuel distribution.

Severe fuel imbalance can result in the following problems:

- High-unburned carbon
- Long flames
- Flame instability problems.
- NO_x control problems

Not uniform - that's the problem

The significant improvement in fuel distribution provided by the Opti-Flow™ system will correct these problems to the extent that they are caused by fuel imbalance within the coal nozzles. Other fuel distributors cause coal "ropes" to impact on the coal nozzle and, thereby, reduce the nozzle's usable life. In the ABT design, all wear is limited to the wear-resistant devices in the elbow

*Begin
P. 7
C-2
Wear*

The Opti-Flow™ system eliminates coal ropes and produces a nearly uniform fuel/air mix with axial flow downstream of the elbow. Therefore, the only erosion-prone areas will be located within the elbow. These areas will be lined with erosion-resistant materials and will be easily replaceable when necessary. A further advantage of this fuel distribution system is that, when used in conjunction with the Opti-Flow™ segmented nozzle, NO_x can be reduced compared to existing nozzles used for tangential firing.

The Opti-Flow™ Fuel Distribution System consists of:

1. The existing coal elbow with ABT's distributor vane package installed to break the coal rope formed in the fuel piping. All surfaces, including the leading edges are protected with ceramic tile.
2. A ceramic device at the coal elbow inlet will be used in conjunction with distributor vanes for equalizing coal flow to the tip.

7.3 IMPLICATION FOR FIELD RESULTS

Within a flame of a low NO_x burner, poor fuel distribution around the nozzle's circumference results in degraded emissions and efficiency performance. Optimal combustion - minimum NO_x and minimum unburned carbon, simultaneously - occurs when the circumferential fuel distribution is uniform (assuming primary air and secondary air distribution are also uniform). When this condition exists, the environment surrounding all fuel particles is the same and, therefore, results in uniform combustion conditions.



Delete: "In the event the burner supplier does not provide for the installation— penalty clause applies."

Change boxed clause to read: "For delivery of all burner —— components contract price". Delete last sentence.

Delete remainder of Section 2.

ABT anticipates shipments to the IPP job site will begin in early January, prior to installation contractor arrival on site. In case of early shipments, IPP would be responsible for off loading and storage of equipment.

6.4 PART C - DIVISION C3

Bidding Documents - Additional bid

- 1 b. There are no normally recommended or required spares. However, the plant may choose to have our fuel injector assembly (barrel & nozzle) on site in the event that a burner might be damaged by some external cause.
- g. There are no environmental limitations to the coal burners
- h. The coal burners will slave to the mills. There are no special modes of operation.
- i. There are no special maintenance requirements. ABT suggests that, fly ash be cleaned from adjustable register components at the commencement of an outage if the boiler is to be water cleaned.
- j. There are no required boiler modifications to accommodate the new burners.

6.5 DIVISION E1, GENERAL CONDITIONS

Article 5: Fabrication drawings and burner design calculations will not be supplied however will be available at the fabrication shop, or at our engineering office, for reference during visits by IPSC.
Drawings anticipated for delivery to IPSC include:

- a. General Arrangement Drawings showing equipment arrangement.
- b. Field Installation Drawings.
- c. Instruction manuals for supplied equipment.

DIVISION C3

BIDDING DOCUMENTS - ADDITIONAL BID INFORMATION

LIMITATIONS	
Component Description	Material Limitation, °F
Those shielded from furnace radiation, set back from furnace opening, and exposed to maximum windbox temperature, i.e., register sleeve dampers, register backplate, windbox coverplate, fuel injector barrel, elbow flatback and fuel distributors:	750

Explanatory Comment: The reason for stating that there are no environmental limitations to the coal burners is that the stainless steel castings and plate facing the fire, ASTM 297 Gr HE or 309 will not deteriorate at temperatures of at least 2000°F. ABT has never measured tip temperatures above 1600°F, in pre-NSPS furnaces that have input per plan levels as high as 2.3MBTu/hr/ft² and Furnace Exit Gas Temperatures or 2400°F and firing Eastern bituminous coals. These are a good deal higher than Intermountain and generate higher gas temperatures.

Consequently, ABT does not consider operation of its design in IPSC's boiler to have any environmental limitations: The conditions are such that no material will operate anywhere near its limit. In fact, ABT has placed no such limitations on any retrofit ABT has done.

- h. Available and recommended modes of operation for both the flame detection system and the burner system.

ABT will not require any special modes of operation in that the existing burner controls should not require changes. Burners will be setup during optimization (at 100 percent MCR) which will begin with components at predetermined positions similar to the follow example:

PREDETERMINED POSITIONS	
Burner Secondary Air Sleeve Dampers (SAD):	80 Percent Open
Burner Outer Air Registers Spin Vanes:	40 Percent Open
Burner Inner Air Sleeve Damper:	20 Percent Open

Following start-up these components are used to control the shape and ignition point of the flame, which in turn controls NO_x, O₂ distribution and CO emissions. The final settings are tabulated and provided to the customer for future

Additional Clarification to Spec. 45606

6.4 Part C-Division 3

- 1g. Bid form, Spec Page C-2, submitted with our proposal listed the max. and min. limitations of our offered equipment as being 2000° F and 140° F for the "Burner Tip" and "Scanner Electronic", respectively. Our design for specific components is based on their expected temperature exposure with the following limitations:

<u>Component Description</u>	<u>Material Limitation, ° F</u>
Those exposed to direct furnace radiation, i.e. flow divider, spin vanes, throat casting, register front cone, fuel injector tip and flame stabilizers.	2000
Those semi-shielded from furnace radiation i.e. fixed vane spinner and inner zone damper perforated plate.	1600
Those shielded from furnace radiation, set back from furnace opening, and exposed to maximum windbox temperature, i.e. register sleeve dampers, register backplate, windbox coverplate, fuel injector barrel, elbow flatback and fuel distributors.	750

Explanatory Comment: The reason we stated that there are no environmental limitations to the coal burners is that the stainless steel castings and plate facing the fire, ASTM 297 Gr HE or 309 will not deteriorate at temperatures of at least 2000 F. We have never measured tip temperatures above 1600 F, in pre-NSPS furnaces that have input per plan levels as high as 2.3MBtu/hr/ ft² and Furnace Exit Gas Temperatures of 2400F and firing Eastern bituminous coals. These are a good deal higher than Intermountain and generate higher gas temperatures.

Consequently, we do not consider that operation of our design in your boiler to have any environmental limitations: the conditions are such that no material will operate anywhere near its limit. In fact we have placed no such limitations on any retrofit we have done.

- 1h. We will not require any special modes of operation in that the existing burner controls should not require changes. Burners will be setup during optimization (at 100% MCR) which will begin with components at predetermined positions similar to the following example:

Burner Secondary Air Sleeve Dampers (SAD)	80% Open
Burner Outer Air Registers Spin Vanes	40% Open
Burner Inner Air Sleeve Damper	20% Open

C12



3.0 Scope of Supply

Following is the scope of supply offered by ABT for the project.

3.1 Opti-Flow™ Low NO_x Burners

Forty-eight (48) Opti-Flow™ low NO_x burner modules with the following features.

- ABT's fuel distribution system consisting of silicon carbide and ceramic tile-lined components that will be installed in the existing ceramic tile-lined sweep elbow.
- A straight fuel injector with a cast HE tip for thermal resistance and long life.
- An inner air zone with a manually operated sliding damper for inner versus outer air flow distribution control and a stationary fixed vane spinner.
- A manually operated sleeve damper for total burner secondary air flow control and burner air flow balancing.
- Manually operated outer zone, axial spin vanes.
- **Materials will be ASTM297 grade HE castings, 309 SS (in high heat affected areas), 304 SS, and carbon steel where appropriate.**
- Burner front windbox cover plate.
- New windbox/burner adapter ring.

Note: ABT has found that some windbox front plates can be warped, resulting in a variation in distance between the windbox plate and the waterwall throat. To provide an easier installation, ABT is providing a seal ring that will slide into the existing windbox opening and allow easier fit-up by compensating for windbox to waterwall variations. The seal ring would be field welded to the windbox (the register front plate comes from the factory bolted to the seal ring.)

- Two thermocouples, each with terminal connection head mounted on burner front plate, for plants use in remote monitoring of burner tip and barrel temperatures.
- Plug-in design requiring no modifications to the windbox, waterwalls or existing burner support rails.
- Burner seal ring to attach to the existing burner throat seal plate.
- All gaskets, nuts, bolts and washers required for field assembly.
- Burner flame view port with purge air connection and ball valve assembly.

3.2 Flame Scanner Systems

ABT offers a replacement flame scanner system, including scanners, amplifiers and connection cables. The base scope includes supply of an IRIS system. Option for supply of an ABB system is also offered that, if selected, would result in a price adder of the amount listed in proposal Section 5.

1 C13

23

Spec. 45606

PART C - DIVISION C3**BIDDING DOCUMENTS - ADDITIONAL BID INFORMATION**

1. **Bid Submittal Requirements:** Information supplied in submittals shall include, but not be limited to, the following:
- a. Schedule showing the cost of replacement parts for both the burner components and the flame detection system, including a pricing index for calculating cost of individual replacement parts through the year 2010.
 - b. A recommended spare parts list with current pricing and normal delivery schedule.
 - c. Location, name, and telephone number of the nearest service technicians for both burners, burner instrumentation, and the flame detection systems.
 - d. Analysis of fail-safe modes of operation of the flame detection system, including component self-diagnostics and alarming.
 - e. Dimensional drawings as required for bid analysis and evaluation.
 - f. Burner and lighter materials of construction and applicable temperature tolerance.
 - g. Environmental limitations of burner and scanner hardware, including both airborne contaminants and heat.

The Proposal form in Part C, Division C2, Bidding Documents - Proposal Schedule, that was submitted with Proposal, listed the maximum and minimum limitations of offered equipment as being 2000°F and 140°F for the "Burner Tip" and "Scanner Electronic", respectively. The design for specific components is based on expected temperature exposure with the following limitations:

LIMITATIONS	
Component Description	Material Limitation, °F
Those exposed to direct furnace radiation, i.e., flow divider, spin vanes, throat casting, register front cone, fuel injector tip and flame stabilizers:	2000
Those semi-shielded from furnace radiation, i.e., fixed vane spinner and inner zone damper perforated plate:	1600

C3-1

C14

IP7_031278



4.0 Guarantees and Warranties

4.1 Workmanship and Quality:

ABT shall warrant the workmanship and quality of the supplied parts from the start-up date for a period of 12 months and 48 months for coal nozzle tips. ABT will supply a replacement for any supplied part which suffers a catastrophic failure due to design or workmanship flaws. IPSC will provide complete access to any supplied part that fails, including removal of any equipment that prevents access to the part to be replaced or repaired and removal and reinstallation of any complete ABT-supplied assemblies that cannot be repaired in-situ.

Changes to the appearance and dimensions of any part will be considered failures only if guaranteed emissions are affected to the extent that the unit is out of compliance and readjustment of burner operating parameters fails to return the emission to within guarantee level; and there are no changes to other equipment, operating methods, or fuel supply which could result in changes to the emissions.

The following requirements apply to both the material warranty and the below listed guarantees:

- Primary air flows shall be within $\pm 5\%$ of the mill manufacturer's design primary air flow vs. coal flow curve
- Mills will not be operated at full load with more than one burner out of service.

4.2 Reliability

The Opti-Flow™ fuel injector components will prevent coal layout and dropout as well as the potential resultant coking inside the fuel injector during normal start-up and operation. Failures caused by other equipment are excluded, for example: mill and control system problems, igniters, or failed/stuck burner shut-off valves.

4.3 Pressure Drop

4.3.1 Fuel Injector

The pressure drop across the new fuel injector, as measured between the inlet flange and the furnace, at the respective elevation, will be no greater than with the existing burner. The new fuel injectors will not limit boiler load.

4.3.2 Secondary Air

Windbox pressure will not exceed 2" W.C., with overfire air ports (to be supplied by others) open

1 C15

25

5.0 Pricing & Schedule

5.1 Pricing: Pricing for base scope is provided on bid form "Bid Pricing Sheet".

5.1.1 Option: Adder to Supply ABB Flame Scanners per Section 3.2...\$ 55,385.00

All prices include freight, FOB Delta, Utah.

Pricing quoted is subject to acceptance within 120 days of date of quotation.

5.2 Payment Schedule

- 20% - Invoice Upon Award
- 20% - Upon submittal of burner general arrangement drawings.
- 20% - Upon commencement of burner fabrication
- 30% - Upon receipt of the equipment at the job site in good condition *
- 10% - Upon successful start-up**

Payment Terms - Net 30 days from date of ABT invoice. Payments made later than 30 after date of invoice will incur 1.5% per month interest charge.

* Early material shipment to be acceptable, with equipment storage by IPSC. The 30% payment upon receipt of equipment shall be prorated based on percent of major material items delivered.

** Retention applies to Low NO_x equipment supply only. Installation and sub-supplier equipment and services are excluded from retention.

5.3 Delivery Schedule

The following schedule is based upon an award date of September 5, 2003.

- | | |
|---|----------|
| a) Award - | 9/5/03 |
| b) Burner Drawings for Review and Initial Procurement - | 11/03/03 |
| c) Commence Fabrication | 12/01/03 |
| d) Commence Equipment Shipment | 01/09/04 |
| e) Complete Equipment Shipment | 02/13/04 |
| f) Commence Outage (see Appendix 4 for installation schedule) | 02/28/04 |
| g) Start-up | 3/24/04 |
| h) Optimization Complete | 4/07/04 |
| i) Guarantee Testing Complete | 4/13/04 |

5.4 Recommended Spare Parts

ABT does not recommend any spares associated with the fuel injector or burner register assemblies as there is low risk of failure and our customers have not seen the need for stocking any of the associated parts. The longest lead parts are castings, for which we maintain the patterns, that can be supplied within 1-2 weeks.

Reference Appendix A-2 of this proposal for Flame Scanner System recommended spares lists.

C16

INTERMOUNTAIN POWER SERVICE CORPORATION

CONTRACT 04-45606

and

SPECIFICATIONS 45606

for

UNIT 2 LOW NO_x BURNERS

CONTRACT ISSUED TO:

**ADVANCED BURNER TECHNOLOGIES
350 MAIN STREET, SUITE 5
BEDMINSTER, NJ 07921**

CONTRACT ADMINISTRATOR: JAMES NELSON

BUYER: NANCY C. BENNETT

INTERMOUNTAIN POWER SERVICE CORPORATION

CONTRACT 04-45606

and

SPECIFICATIONS 45606

for

UNIT 2 LOW NOx BURNERS

CONTRACT ISSUED TO:

**ADVANCED BURNER TECHNOLOGIES
350 MAIN STREET, SUITE 5
BEDMINSTER, NJ 07921**

CONTRACT ADMINISTRATOR: JAMES NELSON

BUYER: NANCY C. BENNETT

CONTRACT AGREEMENT

THIS CONTRACT AGREEMENT, entered into this 17th day of September 2003, between the **INTERMOUNTAIN POWER SERVICE CORPORATION (IPSC)**, a nonprofit organization under contract to the Intermountain Power Agency (IPA), a political subdivision of the state of Utah, organized and existing under the Interlocal Co-Operation Act, Title 11, Chapter 13, Utah Code Annotated 1953, as amended, and **Advanced Burner Technologies (ABT)**, a Corporation, with its principal office in Bedminster, New Jersey, hereinafter called the (Contractor),

WHEREAS, IPSC has prepared specifications and other Contract Documents for **Unit 2 Low NOx Burners** as detailed in the Contract Documents (the Work), and has requested proposals from bidders to perform the Work;

WHEREAS, Contractor has submitted to IPSC a Proposal in accordance with the terms of this Contract Agreement; and

WHEREAS, IPSC has determined and declared Contractor to be the lowest and best, regular responsible bidder for the said Work, subject to execution of this Contract Agreement;

AGREEMENTS: In consideration of the compensation to be paid to Contractor, and of the mutual terms and conditions contained herein, IPSC for itself and its successors, and Contractor for itself and its permitted successors and assigns, hereby agree as follows:

ARTICLE I: Contractor shall perform in accordance with the provisions of this Contract Agreement, including the Contract Documents identified in Article III hereof.

ARTICLE II: Contractor will be paid for its performance under this Contract Agreement in accordance with the provisions of the Contract Documents, including those provisions in the Article entitled "Limitation of Liability; Responsible Party" in Part E, Division E1, General Conditions.

ARTICLE III: The term Contract Documents means and includes all of the following:

<u>PART</u>	<u>DIVISION</u>	<u>TITLE</u>
A	A1	Notice Inviting Proposals
B	B1	Instructions to Bidder
	B2	Supplementary Instructions to Bidders
C		<u>Bidding Documents</u>
	C1	Proposal, No. Q03013
	C1	Labor, Material, and Performance Bond
	C2	Proposal Schedule
	C3	Additional Bid Information
	C4	Comments, Exceptions, Additions, and Cost Summary
	C5	Contractor's Exceptions
D	D1	Contract Documents Description
E	E1	General Conditions
	E2	Additional General Conditions
F		<u>Detailed Specifications</u>
	F1	Special Conditions
	F2	Detailed Requirements

Attachments

Attachment 1 - Scanner, Lighter and Fuel Specifications, and Outline Drawings
Attachment 2 - Fuel Oil Analysis Report
Attachment 3 - General Coal Properties
Attachment 4 - FD Fan Performance
Attachment 5 - PA Fan Performance
Attachment 6 - Existing Burner General Layout
Attachment 7 - Secondary Air Duct and Windbox Drawings
Attachment 8 - As Fired Coal Sample Analyses - IPSC Fuels Lab

The foregoing Contract Documents, and the documents identified in Part D "Contract Documents Description," are an integral part of this Contract Agreement and are hereby incorporated as part of this Contract Agreement as if fully restated herein. The above listed Contract Documents shall prevail over other information submitted with Contractor's Proposal.

ARTICLE IV: This Contract Agreement, including the Contract Documents, constitutes the entire Agreement of the parties hereto with respect to the Work and other subjects addressed herein, and supersedes all prior oral communications or written documents.

WHEREFORE, IPSC and Contractor execute this Contract Agreement as of the date stated in the first introductory paragraph.

INTERMOUNTAIN POWER SERVICE CORPORATION

850 West Brush Wellman Road
Delta, UT 84624-9546

By: George W. Cross
George W. Cross
President and Chief Operations Officer

9/16/03
Date

ADVANCED BURNER TECHNOLOGIES

350 Main Street, Suite 5
Bedminster, NJ 07921

By: Paul Votaw
Title: President

Sept 12, 2003
Date

TABLE OF CONTENTS**SPECIFICATIONS**

<u>PART</u>	<u>DIV</u>	<u>TITLE</u>	<u>PAGE NUMBER</u>
A	A1	Notice Inviting Proposals	A1-1
B	B1	Instructions to Bidders	B1-1 thru B1-2
	B2	Supplementary Instructions to Bidders	B2-1 thru B2-4
C		<u>Bidding Documents</u>	
	C1	Bidder's Bond	C1-1
	C1	Proposal	C1-2
	C1	Labor, Material, and Performance Bond	C1-3 thru C1-4
	C2	Proposal Schedule	C2-1 thru C2-3
	C3	Additional Bid Information	C3-1 thru C3-3
D	D1	Contract Documents Description	D1-1
E	E1	General Conditions	E1-1 thru E1-8
	E2	Additional General Conditions	E2-1 thru E2-2
F		<u>Detailed Specifications</u>	
	F1	Special Conditions	F1-1 thru F1-5
	F2	Detailed Requirements	F2-1 thru F2-6

Attachments

Attachment 1 - Scanner, Lighter and Fuel Specifications, and Outline Drawings

Attachment 2 - Fuel Oil Analysis Report

Attachment 3 - General Coal Properties

Attachment 4 - FD Fan Performance

Attachment 5 - PA Fan Performance

Attachment 6 - Existing Burner General Layout

Attachment 7 - Secondary Air Duct and Windbox Drawings

Attachment 8 - As Fired Coal Sample Analyses - IPSC Fuels Lab

PART A - DIVISION A1

NOTICE INVITING PROPOSALS

The Intermountain Power Service Corporation (IPSC) invites sealed bids for furnishing and delivering **Unit 2 Low NOx Burners** in accordance with **Specifications 45606**, available in the Purchasing Section, Intermountain Power Service Corporation, 850 West Brush Wellman Road, Delta, Utah 84624-9546.

Proposals shall be submitted on IPSC's bidding forms. All Proposals shall be filed with the Buyer at the above address on or before **August 25, 2003**.

Each Proposal shall be accompanied by a certified or cashier's check payable to Intermountain Power Agency (IPA), or a Surety Bond payable to IPA, IPSC, and the City of Los Angeles Department of Water and Power (LADWP) in the amount of \$50,000 as a guarantee that the bidder shall execute the proposed Contract Agreement if awarded.

Proposals shall be subject to acceptance within, and irrevocable for, a period of one hundred and twenty (120) calendar days after date of bid opening.

IPSC reserves the right to reject any and all Proposals.

Contractor shall furnish a Performance Bond equal to 10 percent of the estimated Contract amount, and shall keep the Performance Bond in place at all times thereafter until all obligations under the Contract have been discharged.

In the performance of any contract awarded, the bidder shall not discriminate in employment practices against any employee or applicant for employment because of race, religion, national origin, ancestry, sex, age, or physical disability.

Dated: Aug. 8, 2003

Nancy C. Bennett
Nancy C. Bennett, Buyer
Intermountain Power Service Corporation

PART B - DIVISION B1

INSTRUCTIONS TO BIDDERS

1. **Form, Signature, and Delivery of the Proposals:** The bidder's Proposal shall be made on the yellow copy of the Bidding Documents. The Specifications printed on white paper shall be retained by the bidder.

The bidder's name, address, and the date shall be stated in the Proposal. The Proposal shall be signed by the person authorized to bind the bidder.

The Proposal shall be enclosed in a sealed envelope, plainly marked in the upper left-hand corner with the name and address of the bidder. The envelope shall bear the words "Proposal for," followed by the Specification Number, the title of the Specifications, and the date and hour of bid opening.

If the Proposal is mailed, it shall be addressed as follows:

Purchasing Section
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, UT 84624-9546

If the Proposal is sent by messenger, it shall be delivered to the Administration Building, Intermountain Power Service Corporation, 850 West Brush Wellman Road, Delta, Utah.

2. **Interpretations and Addenda:** Should a bidder find discrepancies or omissions in the plans, specifications, or other documents, or should there be doubt as to their true meaning, the bidder shall submit to the Buyer a written request for an interpretation or clarification thereof. A request for addenda, interpretation, or clarification shall be delivered to the Buyer marked "Request for Interpretation" and must be received by the Buyer in time to permit a reasonable response before the date of opening bids. Any interpretation of, or change in the documents will be made only by addendum issued to each person to whom Specifications have been issued and will become a part of any contract awarded. IPSC will not be responsible for or bound by any other explanations or interpretations.
3. **Correspondence:** All inquiries or correspondence to IPSC prior to award of Contract shall be addressed to the Buyer.
4. **Changes or Alternatives:** The bidder shall not change any wording in the documents. Any explanations or alternatives offered shall be submitted in a letter attached to the front of the Bidding Documents. Alternatives which do not substantially comply with IPSC's Specifications cannot be considered. Language of negation or limitation of any rights, remedies, or warranties provided by law will not be considered part of the Proposal. Bids offered subject to conditions or limitations may be rejected.

DIVISION B1

INSTRUCTIONS TO BIDDERS

5. Specified Materials or Equivalent: Whenever any particular material or process is specified by a patent or proprietary name, by a trade or brand name, of a manufacturer, such wording is used for the purpose of describing the material or process, fixing the standard of quality required, and shall be deemed to be followed by the words "or equivalent." The bidder may offer any material or process which shall be the equivalent of that so specified, but the bidder must identify the equivalent offered.
6. Language: Everything submitted by the bidder shall be written in the English language.
7. Sales or Use Taxes: Prices quoted by the bidder shall not include any applicable sales or use taxes or Federal Excise Taxes.
8. Duties: Prices quoted by the bidder shall include all applicable duties.
9. Award of Contract: Award of Contract will be made to the lowest and best, regular responsible bidder. The determination as to which is the lowest and best, regular responsible bidder may be made on the basis of the lowest ultimate cost of the services, materials, equipment, or other Work in place and use. The right is reserved to reject any or all Proposals.

Within thirty (30) calendar days after the date of award of Contract, Contractor shall sign the Contract supplied by IPSC. The Contract will be effective upon execution by IPSC. Award of Contract is subject to execution of IPSC's form of Contract Agreement and other Contract Documents.

10. Comparison of Bids: For the purpose of comparing bids, it will be assumed that the quantity of forty-eight (48) burners and scanners will be required.
11. Bidder's Bond: The Proposal shall be accompanied by a certified check or a cashier's check issued by a responsible bank, payable in the state of Utah to the order of Intermountain Power Agency, in an amount of \$50,000. A surety bond payable to IPA, IPSC, and LADWP in a like amount will be accepted in lieu of a check.
12. Performance Bond: Within thirty (30) calendar days after date of award of Contract, Contractor shall furnish a Performance Bond, payable to IPA, IPSC, and LADWP equal to 10 percent of the estimated amount of the Contract.
13. Calculation of the Bonds: The estimated amount of the Proposal for the Bidder's Bond, or of the Contract for the Performance Bond, will be considered to be the price, including freight charges, quoted by the bidder in the Proposal Schedule, times the assumed quantity under the Comparison of Bids in Article 10 of this Division.

PART B - DIVISION B2**SUPPLEMENTARY INSTRUCTIONS TO BIDDERS**

1. **Required Delivery and Installation Schedule:** The Unit 2 outage is currently scheduled to begin Saturday, February 28, 2004. The target completion date for returning all systems to IPSC Operations control is Wednesday, March 24, 2004. Each bidder shall prepare and provide, with each bid package, a proposed installation plan showing project progress on a daily basis beginning with initial equipment delivery and ending with job site clean up and exit.
 - a. All bidders shall provide a guaranteed installation schedule as part of the proposed installation plan submitted with each bid package.
 - b. The proposed installation plan shall be developed to ensure completion of all Work inside the boiler within a maximum of twenty-six (26) days. This twenty-six (26) day period shall include four (4) days for installation of the boiler internal scaffolding by a separate contractor and three (3) days for removal of the same.
 - c. Work not requiring the unit to be off-line, such as mobilization, staging, boiler enclosure structural access work, demobilization, etc., shall be clearly identified on the proposed installation plan and can be coordinated outside this outage window, with approval from the IPSC Contract Administrator. Mobilization into the burner levels of the boiler enclosure, as well as material and equipment access and removal will require careful coordination due to the volume of work ongoing throughout the boiler. Crane access will require close coordination.
 - d. The bidders shall provide a schedule of costs associated with an IPSC scheduled delay of the outage start date in one (1) week increments up to one (1) month. These costs shall be based on notification from IPSC one (1) month prior to the scheduled outage start dates. A second schedule of costs shall be based on notification from IPSC one (1) week prior to the scheduled outage start dates.
 - e. Unless otherwise noted in these Specifications, IPSC facilities and equipment shall not be used in support of this Work. To prevent delays, caused by equipment breakdown, Contractor shall provide spare tools and equipment at IPP job site in reasonable quantities in anticipation of equipment failures.
 - f. The proposed installation plan, submitted with the bid package, shall be the basis for development of the approved installation plan forming a part of the eventual Contract governing this Work. The approved installation plan shall be used as the basis for instituting mid-outage resource corrections and for calculating any liquidated damage charges associated with completion of the Scope of Work.

DIVISION B2

SUPPLEMENTARY INSTRUCTIONS TO BIDDERS

- g. The proposed installation plan shall include detailed information regarding each task within the Contract Scope of Work, including:

DETAILED INFORMATION FOR PROPOSED INSTALLATION PLAN
Equipment and Material Delivery
Equipment Mobilization and Assembly
Manpower Loading Throughout Contract
Windbox Access Provisions Complete
Burner Removal By Row
Interface Modifications Complete (If Any)
Burners in Position
Burners Welded Out
Burner Flow and Temperature Instrumentation Complete
Windbox Restoration Complete
External Instrumentation Boxes Mounted, Wired, and Tubed
Windbox Insulation Complete
Material and Equipment Removed From Boiler and Stowed
Area Cleaned and Restored

- h. The proposed installation plan, to be included as part of the submitted bid, shall include estimates of all required on-site services, with clear identification of each request for service to be provided by IPSC. The estimates shall include power service requirements for running all electrical equipment and compressed air requirements. Authorization for connection to and use of requested power, compressed air, or other on-site services must be coordinated and approved by the IPSC Contract Administrator.
- i. At least two (2) months prior to mobilization to IPP plant site, Contractor shall provide a detailed material "laydown plan" for coordination of area utilization and access. The laydown plan shall address staging and temporary storage requirements for all associated materials and equipment in order to minimize interference with ongoing plant operations and outage Work.

DIVISION B2

SUPPLEMENTARY INSTRUCTIONS TO BIDDERS

This laydown plan shall be submitted to and approved by the IPSC Contract Administrator prior to receiving any Contract materials, equipment, or craft personnel on site for the outage Work.

2. **Incentives and Liquidation Damage:** For incomplete delivery to the IPP job site by 12:00 pm, noon, Mountain Standard Time (MST) on Monday, February 23, 2004, Contractor shall be assessed 1 percent in liquidated damages calculated as a percent of the Contract price.

ABT anticipates shipments to the IPP job site will begin in early January, prior to installation contractor arrival on site. In case of early shipments, IPSC will be responsible for off loading and storage of equipment.

For delivery of all burner and scanner components to the IPP job site at least three (3) weeks ahead of the Unit 2 outage start date identified above, the bidder will be awarded a 1 percent bonus calculated as a percent of the Contract price.

3. **Applicable Codes and Standards:** The Work performed within these Specifications shall adhere to the applicable portions of the latest published revision of the following codes and standards:

CODES AND STANDARDS
ASME - American Society of Mechanical Engineers
NBIC - National Board Inspection Code
AWS - American Welding Society
OSHA - Occupational Safety and Health Administration
ASNT - American Society for Nondestructive Testing
Contractor's Utah Jurisdiction Approved R Stamp Program

4. **Safety:** Contractor shall be responsible to provide and manage an acceptable safety program.
- Contractor shall provide a full-time safety representative. The safety representative shall act as the point of contact for all safety-related issues and may be assigned additional duties.
 - Contractor shall provide copies of written safety policies/plans to the IPSC Contract Administrator one (1) month prior to beginning Work, including, but not

DIVISION B2

SUPPLEMENTARY INSTRUCTIONS TO BIDDERS

limited to, Respiratory Protection, Confined Space, and Hazardous Communications.

- c. Prior to flame cutting or welding in any location, Contractor shall first obtain a Hot Work Permit. The permit will be coordinated by the IPSC Contract Administrator or designee. The permit lists mandatory safety precautions, which shall be taken before, during, and after hot work.
 - d. Contractor shall ensure its employees perform Work in accordance with all applicable federal, state, and local safety and health regulations. The IPSC Safety Section personnel will periodically monitor the Work site. If violations are noted, the violations will be reported to Contractor's on-site supervisor and the IPSC Contract Administrator for appropriate action.
5. Flame Scanning System Training: The bidder shall include provisions for two (2) on-site training classes for a duration of not less than one (1) ten-hour day each. Classes shall be conducted with training sets of the installed hardware to allow for full simulation of the calibration, tuning, diagnostics, and repair procedures. Classes shall be conducted for up to thirty (30) people per class.
6. Documentation: Nine (9) copies of all hard-copy documentation shall be supplied for all equipment supplied under the Contract. Where possible, electronic documentation may be provided, in addition to or in lieu of, hard-copy documentation. Electronic documents shall be text .pdf, picture .jpg, or vector .dwg files.

Documentation provided by Contractor shall include, but not be limited to, the following as applicable:

DOCUMENTATION
Equipment Description
Dimensional Drawings
Installation Instructions
Operating Instructions
Maintenance and Trouble-Shooting Guidelines
Parts List and Bill of Materials
Recommended Spare Parts

PART C - DIVISION C1**BIDDING DOCUMENTS****BIDDER'S BOND**

(Not necessary when certified or cashier's check accompanies bid. See below*.)

SURETY BOND

We, the undersigned Principal and Surety, acknowledge ourselves jointly and severally bound to Intermountain Power Agency (IPA) and Intermountain Power Service Corporation (IPSC) of the state of Utah, and the City of Los Angeles Department of Water and Power (LADWP), in the sum of _____ Dollars (\$_____), to be paid to IPA if the attached Proposal shall be accepted and the proposed Contract awarded to said bidder, and said bidder shall fail to execute the Contract and Bond for the faithful performance thereof; otherwise this obligation to be void.

Dated: August 22, 2003

Firm Name: Advanced Burner Technologies Corp.

350 Main Street, Suite 5, Bedminster, NJ 07921NJ

By: 

(Signature)**

(Surety): _____

By: _____

(Signature)

*When the bidder is submitting a check in lieu of a Bond, the check must be made payable to Intermountain Power Agency, must either be certified by a responsible bank or be a cashier's check issued by a responsible bank, and must be payable in the state of Utah.

If check is submitted herewith, state check number 16010201 and amount \$ 50,000.00

**See Form, Signature, and Delivery of the Proposals, Division B1

NOTE: All signatures above must be written in ink.

PROPOSAL


The undersigned hereby proposes to furnish and deliver **Unit 2 Low NOx Burners** to the Intermountain Power Service Corporation in accordance with **Specifications 45606**.

The undersigned agrees, upon the acceptance of this Proposal: (a) to execute IPSC's form of Contract (including the Contract Agreement and other Contract Documents identified in said Specifications) for furnishing and delivering the items and services embraced in the accepted Proposal, (b) to perform its obligations under the Contract at the prices stated in the accompanying Proposal Schedule, and (c) to furnish a Performance Bond conditioned upon the faithful performance of the Contract.

The undersigned furthermore agrees that, in case of failure to execute such Contract Agreement and provide the necessary Performance Bond, the check or Bidder's Bond accompanying this Proposal, and the monies payable thereon, shall be forfeited to and remain the property of Intermountain Power Agency.

The undersigned declares under penalty of perjury that this Proposal is genuine, is not a sham or collusive, and is not made in the interest or in behalf of any person or entity not herein named. The undersigned further declares under penalty of perjury that the bidder has not directly or indirectly induced or solicited any other bidder to submit a sham bid, or any other person, firm, or corporation to refrain from bidding. The undersigned also declares under penalty of perjury that the bidder has not in any manner sought by collusion to secure for itself an advantage over any other bidder.

I declare under penalty of perjury under the laws of the state of Utah that the foregoing is true and correct.

Date: August 22, 20 03
Bidder: Advanced Burner Technologies Corp.
Address: 350 Main Street, Suite 5
Bedminster, NJ 07921
Signed By: 
(Authorized Signature)
Print Name: ~~Joe K. Ferrara~~ Sal Ferrara
Title: Director of Proposals & Projects

* 50% Performance Bond for construction 10% Retention for equipment performance.

LABOR, MATERIAL, AND PERFORMANCE BOND

1. Know all persons by these presents, that

(Insert Contractor's name and address or legal title)

as Principal, hereinafter called Contractor, and

as Surety, hereinafter called Surety, are held and firmly bound unto Intermountain Power Agency, Intermountain Power Service Corporation, hereinafter called IPSC, and the City of Los Angeles Department of Water and Power, as Obligees, in the amount of _____ Dollars (\$_____) for the payment whereof Contractor and Surety bind themselves, their heirs, executors, administrators, successors and assigns, jointly and severally, firmly by these presents.

2. WHEREAS, Contractor has by written agreement dated _____, 20____, entered into a Contract Agreement with IPSC for **Unit 2 Low NOx Burners** in accordance with Contract No. **04-45606** which Contract is attached hereto and by reference made a part hereof, and is hereinafter referred to as the Contract.

NOW, THEREFORE,

3. THE CONDITION OF THIS OBLIGATION is such that, if Contractor shall promptly and faithfully perform said Contract, and shall promptly make payment to all claimants for labor and material used or supplied for use in the performance of the Contract, then this obligation shall be null and void; otherwise, it shall remain in full force and effect.
4. Whenever Contractor shall be, and declared by IPSC to be, in default under the Contract, IPSC having performed IPSC's obligations thereunder, the Surety may promptly remedy the default, or shall promptly:
- a. Complete the Contract in accordance with its terms and conditions, or
 - b. Obtain a bid or bids for submission to IPSC for completing the Contract in accordance with its terms and conditions, and upon determination by IPSC and Surety of the lowest and best, regular responsible bidder acceptable to IPSC, arrange for a Contract between such bidder and IPSC, and make available as work progresses (even though there should be a default or a succession of defaults under the Contract or Contracts of Completion arranged under this paragraph) sufficient funds to pay the cost of completion less the balance of the Contract price, but not exceeding the amount of the Bond. The term "balance of

the Contract price," as used in this paragraph, shall mean the total amount payable to Contractor under the Contract and any amendments thereto, less the amount previously paid to Contractor.

5. Upon failure of Contractor to timely pay laborers and material men, Surety agrees to discharge such obligation in an amount not exceeding the sum set forth above and also, in case suit is brought upon this Bond, a reasonable attorney's fee to be fixed by the court. This Bond shall inure to the benefit of any and all persons named in Title 14, Chapter 2, Utah Code, as amended, so as to give a right of action to such persons or their assigns in any suit brought upon this Bond.
6. No right of action shall accrue on this Bond to or for the use of any person or corporation other than named herein, or the heirs, executors, administrators, or successors and assigns of the Obligees, except as provided by statutory or regulatory provisions relating to Contractor's bonds upon public and private contracts, the provisions of which are made a part hereof as a supplemental description of Surety's obligations herein.
7. Surety hereby waives notice of any change orders or extensions of time made by IPSC in accordance with the terms of the Contract.

8. SIGNED AND SEALED this _____ day of _____, 20____ AD

In the presence of: _____
(Principal)

(Seal)

(Witness)

(Title)

(Seal)

(Surety)

(Witness)

(Title)

PART C- DIVISION C2**BIDDING DOCUMENTS - PROPOSAL SCHEDULE**

1. Proposal is hereby made to furnish and deliver to IPSC Unit 2 Low NOx Burners, F.O.B. IPSC dock, full freight allowed in accordance with Specifications 45606, the following:

- a. Burner and Scanner Performance: The new burners shall provide for a continuous boiler operation of 6,900,000 pounds/hour output, 1,005°F superheat and 1,005°F reheat temperature under all operating conditions. Bidders shall state the following burner and scanner performance guarantees and submit with the bid package:

BURNER AND SCANNER PERFORMANCE GUARANTEES	
Maximum Burner Nox and CO Production Under All Modes of Operation:	NOx=0.33 ^{lb} /mbtu CO=200 ppm
Maximum Burner BTU Throughput:	> 220 MBtu/hr
Burner and Scanner System Temperature Tolerance and Thermal Degradation Life:	Burner Tip=2000°F Scanner Electronic=140°F
Time Within Which Burner Register Assembly Shall Remain Fully Operable By Hand:	Past Guarantee Period
Combustion Zone Stability (Ignition Location/Stability, Flame Shape/Color):	Bright Flame in throat
Ash Deposition (At Burner Throat, OFA Ports, and Superheat Pendants):	Burner, Throats & SH No add'l from current
Maximum Burner Out-Of-Service Cooling Air Requirements (CFM Per Compartment):	Scanners= 15 SCFM at 10"W.C.
Minimum In-Service Air Flow With Associated Emissions (Assuming 10 Percent Total Overfire Air Flow):	See Proposal Sec. 4
Maximum In-Service Air Flow With Associated Emissions (Assuming 10 Percent Total Overfire Air Flow):	See Proposal Sec. 4
Maximum Wear Life of Primary Air/Coal Path Components (Minimum Four (4) Years):	Nozzles: 6-8 yrs. ⁺ Fuel Dist. 4-6 yrs. +

DIVISION C2

BIDDING DOCUMENTS - PROPOSAL SCHEDULE

- b. In support of the stated guarantees, the bidder shall provide clear commitments in the following areas:

CLEAR COMMITMENTS	
The Nature of Remedial Efforts That Will Occur to Achieve Guaranteed Performance in Each Area	
The Approximate or Typical Time Frame Associated with Resolution of Each of the Stated Performance Guarantees	
The Company or Organization Expected to Provide the Applicable Resources Associated with the Remedial Work (Modifications, Testing, and Operational)	
The Ultimate Monetary Compensation Offered by the Original Equipment Manufacturer (OEM)	

2. Prices: The price or prices shall be according to the following bid pricing sheet:

BID PRICING SHEET	
Bid Price to Purchase Forty-Eight (48) Low NOx Burners, Per Specifications, Without Scanners:	\$ 2,237,415.00
Bid Price to Purchase Forty-Eight (48) Scanners and Ancillary Hardware, Per Specifications:	\$ 157,130.00
Bid Price to Install Forty-Eight (48) Burners and Associated Flame Detection Systems:	\$ 1,473,130.00
TOTAL BID PRICE:	\$ 3,867,675.00

3. Cash Terms: A discount for prompt payment is offered of 0% percent for Contract payments made within 30 calendar days after date of acceptance or delivery and receipt of invoice.
4. Taxes: The foregoing quoted prices are exclusive of all applicable sales and use taxes.
5. Manufacturer: Advanced Burner Technologies and IRIS or ABB (option)
6. Location of Point of Manufacture: USA

DIVISION C2

BIDDING DOCUMENTS - PROPOSAL SCHEDULE

-
7. Brand and Catalog Number or Other Designation: OPTI-FLOWTM
Low NOx Burner, IR-P532/S552 or SafeflameTM DFS
8. Form of Business Organization: The bidder shall state below the form of its business organization.
9. Bidder is a: Corporation, organized under the laws of the state of NJ.
(Corporation, Partnership, Limited Partnership, Individual)
- If a partnership, the bidder shall state below the names of the partners. If a corporation, the bidder shall state below the names of the president and of the secretary.
-
10. Person to Contact: Should IPSC desire information concerning this Proposal, please contact:
- Name: Sal Ferrara Telephone No: 908-470-0721
- Address: 350 Main Street, Suite 5, Bedminster, NJ 07921
- (If different, the address of bidder's chief executive office is:) _____
-

PART C - DIVISION C3**BIDDING DOCUMENTS - ADDITIONAL BID INFORMATION**

1. **Bid Submittal Requirements:** Information supplied in submittals shall include, but not be limited to, the following:
 - a. Schedule showing the cost of replacement parts for both the burner components and the flame detection system, including a pricing index for calculating cost of individual replacement parts through the year 2010.
 - b. A recommended spare parts list with current pricing and normal delivery schedule.
 - c. Location, name, and telephone number of the nearest service technicians for both burners, burner instrumentation, and the flame detection systems.
 - d. Analysis of fail-safe modes of operation of the flame detection system, including component self-diagnostics and alarming.
 - e. Dimensional drawings as required for bid analysis and evaluation.
 - f. Burner and lighter materials of construction and applicable temperature tolerance.
 - g. Environmental limitations of burner and scanner hardware, including both airborne contaminants and heat.

The Proposal form in Part C, Division C2, Bidding Documents - Proposal Schedule, that was submitted with Proposal, listed the maximum and minimum limitations of offered equipment as being 2000°F and 140°F for the "Burner Tip" and "Scanner Electronic", respectively. The design for specific components is based on expected temperature exposure with the following limitations:

LIMITATIONS	
Component Description	Material Limitation, °F
Those exposed to direct furnace radiation, i.e., flow divider, spin vanes, throat casting, register front cone, fuel injector tip and flame stabilizers:	2000
Those semi-shielded from furnace radiation, i.e., fixed vane spinner and inner zone damper perforated plate:	1600

DIVISION C3

BIDDING DOCUMENTS - ADDITIONAL BID INFORMATION

LIMITATIONS	
Component Description	Material Limitation, °F
Those shielded from furnace radiation, set back from furnace opening, and exposed to maximum windbox temperature, i.e., register sleeve dampers, register backplate, windbox coverplate, fuel injector barrel, elbow flatback and fuel distributors:	750

Explanatory Comment: The reason for stating that there are no environmental limitations to the coal burners is that the stainless steel castings and plate facing the fire, ASTM 297 Gr HE or 309 will not deteriorate at temperatures of at least 2000°F. ABT has never measured tip temperatures above 1600°F, in pre-NSPS furnaces that have input per plan levels as high as 2.3MBTu/hr/ft² and Furnace Exit Gas Temperatures or 2400°F and firing Eastern bituminous coals. These are a good deal higher than Intermountain and generate higher gas temperatures.

Consequently, ABT does not consider operation of its design in IPSC's boiler to have any environmental limitations: The conditions are such that no material will operate anywhere near its limit. In fact, ABT has placed no such limitations on any retrofit ABT has done.

- h. Available and recommended modes of operation for both the flame detection system and the burner system.

ABT will not require any special modes of operation in that the existing burner controls should not require changes. Burners will be setup during optimization (at 100 percent MCR) which will begin with components at predetermined positions similar to the follow example:

PREDETERMINED POSITIONS	
Burner Secondary Air Sleeve Dampers (SAD):	80 Percent Open
Burner Outer Air Registers Spin Vanes:	40 Percent Open
Burner Inner Air Sleeve Damper:	20 Percent Open

Following start-up these components are used to control the shape and ignition point of the flame, which in turn controls NO_x, O₂ distribution and CO emissions. The final settings are tabulated and provided to the customer for future

reference. During normal operation, following optimization, further adjustments should not be necessary unless a significant change in fuel supply characteristics occurs.

In no case has ABT required any customer to modify normal procedures to accommodate its burners; however, as noted in the guarantee section, ABT does require good fuel balance in the coal pipes, accurate primary air flow measurement and control, and that the primary air flow decrease as mill load decreases. ABT does not consider these to be "special modes of operation"; rather good operation.

- i. Recommended maintenance requirements for the burners and flame detection system.
- j. Required boiler modifications for accommodation of the new hardware.
- k. Installation and performance history of the burners and flame detection system.
- l. Recommended spare parts for all hardware or software provided.
- m. Proposed installation plan, including recommended methods of installation for maximizing both installation productivity and operating reliability.

PART C - DIVISION C4**COMMENTS, EXCEPTIONS, ADDITIONS, AND COST SUMMARY**

The following is a list of comments, exceptions, additions, and cost summary to Specifications 45606 which shall be incorporated as part of the Contract Documents in Contract 04-45606.

1. Exception/Change: ABT Payment of Schedule:

ABT 5.2 PAYMENT SCHEDULE	
20 Percent	Burner material on order.
10 Percent	Upon Submittal of burner and flame detection system and general arrangement drawings.
30 Percent	Upon commencement of burner fabrication.
30 Percent	Upon receipt of all burners on the job site. (Note: Early shipment is acceptable with storage at IPP job site.)
10 Percent	Upon completion of start-up and adjustment of burners.

2. Addition: The following feature shall also be included:

ABT 3.1 OPTI-FLOW LOW NOx BURNERS
Ratchet-type actuators are to be provided for moving the sleeve damper and spin vane ring. In addition, the dual-handle control features for both the damper and spin vane ring are to be retained.

3. Addition: IPSC selects the ABB scanner with noted exceptions (see Addition 4, below); include with that selection, Option 2 and Option 5.

ABT A2-2 ABB		
Option 2	Safe Flame Sensor Module Communication Server (SMCS)	Cost: \$10,000
Option 5	Safe Flame DFS (recommended spare parts)	Cost: \$11,288

DIVISION C4

COMMENTS, EXCEPTIONS, ADDITIONS, AND COST SUMMARY

4. Addition: The following will be provided for in the Contract:

ABT A2-2 ABB, Pages 1 and 2	
ABB has quoted sixteen (16) amplifier enclosures to be located at the burner with front-access chassis. IPSC requires location of the amplifiers and enclosures near the control room to minimize boiler washdown damage. IPSC requires the chassis to be rear-access with (2) cabinets of 24-inch depth containing eight (8) chassis, rather than the twenty-six (26) called-out. This will require increasing the cable runs from 50 feet to approximately 500 feet.	
IPSC intends to provide local-indication, at the burner, for a flame intensity value. IPSC will provide the instrumentation for this local-indication requirement.	

5. Cost Summary: The total cost of the Contract to supply burners and options is:

COST SUMMARY	
Item	Cost
Burners:	\$2,237,415
ABB Scanners:	\$ 212,515
Option 2 (SMCS):	\$ 10,000
Option 5 (Parts):	\$ 11,288
Performance Bond:	\$ 15,000
Professional Liability Premium:	\$ 60,000
Total Cost:	\$2,546,218

September 12, 2003

50 Main Street, Suite 5
Bedminster, NJ 07921

P 908.470.0470

F 908.470.0479

www.advancedburner.com

Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, Utah 84624

Attention: Nancy C. Bennett, C.P.M.

Reference: Contract 04-45606 -Unit 2 Low NOx Burners

Dear Ms. Bennett:

Advanced Burner Technologies thanks you for your valuable order. Enclosed are three (3) original contracts with our signature on page 3 of the "Contract Agreement" form. With these executed documents, we acknowledge receipt of this contract and confirm our agreement based on the following clarifications to the contract document:

Part F - Division F1 - Article 6b. Commercial General Liability

Line 8, strike "\$8 million", replace with "\$2.5 million"

Division C4 - Comments, Exceptions, Additions, and Cost Summary - 1. ABT 5.2

Invoices will be issued in advance of achieving milestones, this is to insure immediate issue of payment upon achieving milestone.

Explanation: This is offered in place the "20% Invoice Upon Award" stated in ABT's proposal.

Division C4 - Comments, Exceptions, Additions, and Cost Summary - 2. ABT 3.1

2nd line, delete the words "for both the damper and".

Explanation: The sleeve damper will be controlled via single handle.

Division C4 - Comments, Exceptions, Additions, and Cost Summary - 5. Cost Summary


Delete "Performance Bond" and amount "\$15,000".

Revise "Total Cost" to read "\$2,531,218".

Explanation: The performance bond was offered on "Installation" however we understand from these contract documents that installation is excluded from the contract. 10% retention is to be held until successful performance testing, in place of a performance bond on equipment.

Please acknowledge IPSC's agreement with these clarifications to the contract documents with signature in space provided below and return with one original IPSC executed contract.

We again thank you for your valuable order and look forward to providing you with a Quality Engineered and Manufactured System, with an on time delivery.

By: 
George W. Cross

President and Chief Operations Officer

Date: 9/16/03

Sincerely yours,


Sal N. Ferrara

IP7_031306

IP7_031307



Executive Summary and Philosophy

Advanced Burner Technologies Corporation is pleased to offer this proposal to Intermountain Power Service Corporation to supply and install state-of-the-art low NO_x burners for the Delta Unit #2 boiler. The specification lists several western bituminous coals, none of which, either singly or in the combinations specified, present any problem for ABT. The NO_x guarantee is 0.33 lb/MBtu is based upon what we understand to be the worst coal, SUFCO, which currently yields NO_x of about 0.45. Consequently, the NO_x will be reduced by at least 25% under equivalent operating conditions: 15% excess air and no overfire air flow. With 10% OFA flow, NO_x will be reduced to about 0.29 and with 20% to <0.25.

These values are based upon actual field experience with boilers of various sizes firing fuels ranging from lignite to PRB to eastern and western bituminous coal, as well as bit/PRB mixtures; and equipped with ABT's low NO_x burners only or these burners plus our OFA system. Consequently, we have a very high degree of confidence that these values can be attained in operation at Delta #2.

Under contract to ABT, Airflow Sciences Corporation will perform CFD models of the windboxes. This will enable us to optimize the secondary air distributions within the compartmented windbox design.

This proposal includes complete mechanical and electrical installation of all ABT supplied equipment. ABT's installation partner is Maintenance Enterprises, Inc., whose General Manager, Mike Simonds, has worked with ABT on several low NO_x conversions. These conversions include the turn-key supply and installation of low NO_x burners and overfire air systems at two 540 MW Kentucky Utilities boilers and installation of our burners on another 500MW unit at Deseret Generation & Transmission Coop in Vernal Utah. MEI, under Mr. Simonds' direction, will do an exemplary job of installing the ABT equipment.

We have the utmost confidence that the guarantees we have offered will be met.

A handwritten signature in black ink, reading "Joel Vatsky".

Joel Vatsky, President
Advanced Burner Technologies Corp



Table of Contents

	Section-Page
Executive Summary	i
1.0 Introduction.....	1-1
1.1 Background.....	1-1
1.2 NO _x Control Philosophy.....	1-1
1.3 Opti-Flow™ Low NO _x Burner.....	1-2
1.4 Analytical Evaluation.....	1-2
2.0 Technical Discussion.....	2-1
2.1 Boiler Comparisons and ABT Experience.....	2-1
2.2 The Opti-Flow™ Low NO _x Burner.....	2-5
2.2.1 Fuel Injector for Intermountain Unit 2	2-6
2.2.2 ABT Opti-Flow™ Dual Register with Fuel Injector.....	2-6
2.3 Analytical Evaluations.....	2-6
2.4 Testing.....	2-7
2.5 ABT Support Personnel.....	2-7
3.0 Scope of Work.....	3-1
3.1 Opti-Flow™ Low NO _x Burners.....	3-1
3.2 Flame Scanner Systems.....	3-1
3.3 Individual Secondary Air Flow Measurement.....	3-2
3.4 Flow Modeling.....	3-2
3.5 Drawings and Operating Manuals.....	3-3
3.6 ABT Field Support Services.....	3-3
3.7 Mechanical & Electrical Installation	3-3
4.0 Guarantees and Warranties.....	4-1
4.1 Workmanship and Quality.....	4-1
4.2 Reliability.....	4-1
4.3 Pressure Drop.....	4-1
4.3.1 Fuel Injector.....	4-1
4.3.2 Secondary Air.....	4-1
4.4 NO _x	4-2
4.5 CO.....	4-3
4.6 Excess Air.....	4-3
4.7 Unburned Carbon Expressed as Loss on Ignition.....	4-3
4.8 Boiler Performance.....	4-3
4.9 Mill and Fuel Conditions.....	4-3
4.10 Ash Patterns.....	4-4
4.11 Remedies for NO _x , CO and LOI Exceeding Guarantee Values.....	4-4
4.11.1 Financial Remedies.....	4-5



4.12	Vendor Equipment.....	4-5
5.0	Pricing & Schedule.....	5-1
5.1	Pricing.....	5-1
5.2	Payment Schedule.....	5-1
5.3	Delivery Schedule.....	5-1
5.4	Recommended Spare Parts.....	5-1
6.0	Exceptions and Clarifications.....	6-1
7.0	The Opti-Flow™ Low NO _x Firing System.....	7-1
7.1	Opti-Flow™ Low NO _x Burner.....	7-1
7.2	Opti-Flow™ Fuel Distributors.....	7-4
7.3	Implications for Field Results.....	7-5
A-1	Drawings	
A-2	IRIS & ABB - Flame Scanner Systems	
A-3	Eastern Instruments - Burner Airflow Measuring System	
A-4	MEI - Installation	

IP7_031311



1.0 Introduction

1.1 Background

Intermountain Power Service Corporation (IPSC) Unit 2 is a B&W pulverized coal, supercritical boiler rated at 6,900,000 pounds of steam per hour. This unit fires western bituminous coal using 48 OEM dual register low NO_x burners. NO_x emissions typically range between 0.4 and 0.45 lb/10⁶ Btu at full load as a function of coal source, with one mill out of service.

Advanced Burner Technologies (ABT) has developed a novel, highly effective low NO_x burner that has demonstrated NO_x levels in the 0.35 – 0.40 range on several large boilers firing bituminous coals, including western coal. Approximately 10,000 MW of large utility boilers have been converted to ABT's Opti-Flow™ burner design. These units range in capacity from 70 to 720 MW. In addition, ABT has implemented a novel OFA system along with its low NO_x burner, to obtain minimum NO_x without performance or operational problems. Fuels range from lignite to high sulfur bituminous coal.

Intermountain Unit 2 has a moderate burner zone liberation rate (BZLR) of approximately 300,000 Btu/hr-ft². For this furnace burning western bituminous coal, ABT would expect operating NO_x levels at full load to be in the range of 0.30 - 0.35 lb/10⁶ Btu with a retrofit of 48 Opti-Flow™ low NO_x burners and one mill out of service; with overfire air port closed.

1.2 NO_x Control Philosophy

Advanced Burner Technologies utilizes the following considerations for attaining minimum NO_x levels while minimizing the potential for adverse furnace effects.

1. Utilize a highly effective low NO_x burner that achieves minimum NO_x emissions without overfire air.
2. Balance coal flows to the burners to eliminate very high coal flow regions that generate high LOI and CO, and very low coal flow regions that generate high NO_x.
3. Eliminate poor windbox distribution of secondary air caused by stratifications and recirculation zones that exacerbate the burner balancing problems caused by poor coal line distribution.

Note: It is ABT's experience that minimum NO_x, CO and LOI cannot be attained without addressing the fuel and air imbalances that exist in most boilers.

NO_x is generated by two different processes; fuel bound nitrogen and thermal NO_x. Thermal NO_x formation is promoted by high furnace temperatures (i.e. BZLR), which convert atmospheric nitrogen to NO_x. Intermountain Unit 2 has a moderate BZLR and



thermal NO_x generation is an issue, with this furnace heat release. However, the ABT Opti-Flow™ fuel injector produces a flame that efficiently reduces fuel bound nitrogen compounds to N₂, as well as minimizing thermal NO_x formation. The Technical Discussion section contains a more complete discussion of the furnace parameters and its relationship to NO_x.

1.3 Opti-Flow™ Low NO_x Burner

The heart of the Opti-Flow™ low NO_x burner is a fuel injector that improves reliability and performance as compared to more conventional fuel injectors. The combination of the new fuel injector and a suitable low NO_x dual register, results in a low NO_x burner that attains at least 35 percent lower NO_x levels than the conventional designs of low NO_x burners it has replaced.

The Opti-Flow™ low NO_x, flame stabilization nozzle is the key element of the fuel injector for attaining excellent flame stability along with minimum NO_x. Excellent flame stability is achieved due to external flame stabilizers surrounding each segment. Nearly uniform fuel distribution around the burner nozzle circumference is obtained, which provides significant aid in attaining minimum NO_x and UBC simultaneously. *Not 7-3 happening*

Advanced Burner Technologies utilizes high quality stainless steels for all parts of the fuel injector that face the furnace, as well as stainless steel castings for all complex parts. The result is high reliability and excellent longevity of the burners. *2.2*

ABT's Opti-Flow™ dual register is an innovative design that provides the operator with the flexibility of optimizing: inner and outer zone swirl values and the air flow split between the inner and outer zones independently of swirl. This is accomplished with a manually adjustable inner air damper and represents a significant improvement over other dual register designs. A fixed vane swirler is fixed to the outer barrel of the fuel injector to impart swirl to the inner air zone.

1.4 Analytical Evaluations

CFD (Computational Fluid Dynamics) is an analytical tool that aids in the design of air delivery systems. CFD allows us to evaluate alternatives and provide an optimized system without modifying the system after installation. Air supply systems in a boiler are so complex it is impossible to optimize a system using conventional duct design techniques. Consequently CFD analysis is utilized for the following:

- Optimize air flow distribution to the burners within the existing wind-boxes.
- Minimize pressure loss in ducts

For Intermountain Unit 2, a primary area of investigation is CFD modeling of the wind-box air flow. Airflow Sciences Corporation (ASC) will develop a model of the wind-box and secondary air ducts, in order to evaluate the air flow distribution to the



burners within the windboxes and the air flow to each individual burner. The results will be used to design any turning vanes, baffles or other distribution devices to improve air flow within the ducts and windboxes.

Note, that this B&W boiler uses compartmented windboxes that do not act as true plenums. Consequently, secondary air flow is not uniformly distributed to the burners within the windbox; and it has been ABT's experience that these windbox flows can be unstable.

ABT has a means of eliminating the instability and minimizing burner-to-burner secondary air imbalances by converting each compartment into a nearly true plenum. The cost for this is very moderate and it's effectiveness has been shown in the field on a 560 MW B&W boiler.

11/11/2000 10:00:00 AM

IP7_031315



2.0 Technical Discussion

The NO_x emission from any given boiler is a function of several variables:

- Furnace size relative to full load heat input: The larger the furnace for a given heat input, the lower the temperatures will be. Therefore, thermal NO_x will be lower. This parameter, Burner Zone Liberation Rate, is expressed as Q/BZS.
- Fuel Parameters: The fuel constituents which have the largest impact on NO_x are N₂, HHV, and FC/M.
- Burner Design: The design of the burner produces the largest effect on both combustion and NO_x emissions. Very low NO_x levels can only be attained with a highly effective low NO_x burner.

To determine the NO_x level a boiler is capable of generating with a given low NO_x burner, a comparison is made of that boiler with a unit that has similar BZLR, fuel parameters, and the same burner design.

2.1 Boiler Comparisons and ABT Experience

Burner Zone Liberation Rate (BZLR) is the ratio of heat input to the furnace (Q) to the Burner Zone Surface (BZS). The following calculation of BZLR is summarized below:

$$Q = w_f [\text{HHV} + (\# \text{ air} / \# \text{ fuel}) (0.248) (T_a - 80)]$$

Where: w_f = fuel flow (lb/hr) and T_a = secondary air temperature

$$\text{BZS} = 2 (\text{WD} + \text{WH} + \text{HD})$$

(The BZS is the six-sided box that surrounds the burners.)

Where: W = unit width, D = unit depth, H = wall height from the hopper knuckle to 10' above the top burner level.

For Intermountain, using the design coal analysis:

$$Q = 9038 \times 10^6 \text{ Btu/hr}$$

$$\text{BZS} = 29,566 \text{ ft}^2$$

$$\text{BZLR} = Q/\text{BZS} = 305,700 \text{ Btu/hr/ft}^2$$

ABT considers NO_x emissions of 0.30 - 0.35 lb/10⁶ Btu with western bituminous coal to be attainable with the Opti-Flow™ low NO_x burner, with OFA ports closed. Our




experience with the Opti-Flow™ burner on a boiler with similar BZLR firing western bituminous coal has demonstrated that a NO_x level of 0.35 lb/10⁶ Btu is attainable.

Figure 2-1 compares NO_x levels as a function of BZLR for several cases:

- OEM low NO_x burners (B&W and Foster Wheeler) firing bituminous coal for three (3) boilers. The data indicate that there is little difference between the B&W and FW low NO_x burners of that early vintage.
- Data for Deseret Bonanza Unit one which has a BZLR similar to that for Intermountain. In addition, this boiler fires a western bituminous coal with characteristics similar to the coal(s) fired at Intermountain.

Figure 2.1 Low NO_x Burner Comparison
NO_x vs. Burner Zone Liberation Rate



Shown in Figure 2-1 is data for the following six boilers firing lignite, PRB and bituminous coal:

Deseret, Bonanza Unit 1: A 440 MW Foster Wheeler boiler, firing western bituminous coal similar to the worst Intermountain coal, was retrofitted in May 1997 with 20 Opti-Flow low NO_x burners. NO_x emissions before the retrofit, with the original Foster Wheeler low NO_x burners, were typically in the 0.55 to 0.6 range. After the retrofit, with the ABT low NO_x fuel injectors and dual register modifications, NO_x is approximately 0.35. In 2001, three of the five mills were replaced with larger units and the new mill's burners were upgraded to handle the higher capacity. The boiler now produces 500 MW with no increase in NO_x or detrimental impacts to boiler performance. Burner coking and fires have been eliminated, as have burner eyebrows and furnace slag.

Deseret Contact: Dan Howell 435-781-5718

AEP/SWEPCO, Welsh #1: A 560 MW B&W boiler with 42 burners (NO_x with OEM dual register low NO_x burners was ~0.38). Unit was retrofitted with ABT Opti-Flow Mark I burners in the fall of 1999; initially no OFA ports were installed. Operating with one top burner deck out of service, NO_x was typically in the 0.20 to 0.22 range.

In the fall of 2001, ABT's OFA system was installed at Welsh #1. With the OFA ports open, NO_x has been reduced to the 0.16 – 0.17 range with all mills in service. It is apparent that significant coal line imbalances exist at Welsh #1; these imbalances limit the degree of NO_x reduction that can be achieved, since they result in high CO emissions. Although the unit was designed for operation with 19% excess air, it must currently operate with approximately 25% excess air in order to control CO. Minimizing these coal line imbalances will allow operation at near design excess O₂ or below and reduce the NO_x to the 0.15 level.

AEP/SWEPCO, Pirkey #1: A 700 MW B&W boiler firing Texas lignite (NO_x with OEM dual register low NO_x burners was ~ 0.36 to 0.38). The unit was completely retrofitted with 56 ABT Opti-Flow Mark II Low NO_x burners and OFA system in the fall of 2001. NO_x emissions, with the OFA ports closed, have been lowered to approximately 0.22. Operation of the OFA system has been very successful in that the boiler can operate continuously at full load with NO_x emissions of ~ 0.15 lb/10⁶ Btu with one mill out of service (normal operation).

AEP Contact: Kent Randall 318-673-3813 Welsh & Pirkey Plants

Kentucky Utilities, Ghent #3 and #4: Two 540 MW FW boilers firing Kentucky bituminous coal. NO_x emissions of 0.55 to 0.7 without OFA and about 0.45 with OFA ports open were attained with the OEM low NO_x burners and OFA system. ABT replaced all 24 fuel injectors, with the Opti-Flow Mark I design, upgraded the FW dual registers and supplied a new OFA system to each boiler. Unit #3 was converted in the fall of 1998 and Unit #4 in the fall of 1999. NO_x was reduced to about 0.40 while firing Eastern bituminous coal and 0.23 for PRB coal, with OFA ports closed; and to 0.3 and 0.18 respectively with OFA ports open. Currently, NO_x is about 0.3 firing a 50/50 blend of E. bituminous and PRB with OFA ports closed.

The walls of these boilers are coated with refractory to maintain furnace temperatures and to attain design steam temperatures (low steam temperatures resulted from an OEM boiler design problem). Prior to the retrofit, there were frequent heavy slag falls from the walls; however not a single slag fall has been observed following the retrofit.

Ghent Contact: Steve Nix 502-347-4152

Allegheny Energy, Harrison #1, 2 and 3: Three 660 MW FW boilers that are of pre-NSPS design with very hot, tight furnaces firing a highly slagging, eastern bituminous coal. All units were upgraded by replacing the fuel injector with the ABT design, while maintaining the existing FW dual registers. NO_x emissions have been reduced from the 0.55 to 0.6 range to below 0.45 without overfire air. The furnaces are clean

with no evidence of any operating or performance problems, due to the new low NO_x burners. Unburned carbon is in the same range as before the retrofit.

Harrison Contact: Dean Hedrick 304-584-2350

Tyrone Unit#3/ Green River Unit #3: These are 70 MW B&W boilers each originally with eight turbulent burners firing Eastern bituminous coal. Tyrone was started up in fall 2001 and Green River in spring 2002.

NO_x has been reduced from about 0.8 to below 0.35 lb/10⁶ Btu without OFA. There was no increase in UBC and no deterioration in boiler performance or efficiency.

Tyrone Contact: Tom Moore 859-879-3501

Green River Contact: Tom Troost 270-757-3113

JEA St. John Unit #1: A 660 MW Foster Wheeler boiler that fires a blend containing 20% petroleum coke and 80% bituminous coal with 28 burners; more petroleum coke is fired in this boiler than any other pulverized coal boiler in the U.S. In addition, Colombian coal is fired in this blend, which makes it an even more difficult fuel since this coal is commonly known to be difficult to burn.

In early 2003, St. Johns Unit 1 was completely retrofitted with 28 Opti-Flow™ LNB's and similar windbox/secondary air modifications. Preliminary burner tuning has shown that NO_x has been reduced by over 20% for Unit 1; further reduction in NO_x is anticipated once additional burner tuning is completed.

Excellent flame stability has also been attained with the retrofit of Opti-Flow™ burners for Unit 1. In fact, the petroleum coke blend can now be fired in the lower rows of burners without flame stability problems. Excellent flame stability is also maintained as load is reduced from 670 MW to 380 MW, with only one mill out of service (normal operating practice with these boilers). Prior to the retrofit of Opti-Flow™ burners, this turndown could not be achieved with only one mill out of service. To date, ABT is the first to demonstrate the ability to cofire petroleum coke in a wall-fired boiler with an advanced low NO_x burner that maintains such excellent flame stability and NO_x reduction.

St. Johns Contact: Bob Branning 904-665-8806

Of particular note from the data shown in Figure 2-1 are the following:

- Opti-Flow™ low NO_x burners result in a relatively flat BZLR curve by minimizing thermal NO_x formation.
- At the high BZLR values of Deseret, Ghent, and Harrison, the Opti-Flow™ burner NO_x level is at least 35% lower than the OEM's low NO_x burners.



- NO_x shows only a slight dependence on BZLR for boilers with ABT low NO_x burners. The BZLR for Intermountain is similar to Deseret, which show NO_x emissions of 0.35. This data indicates that a NO_x level of 0.33 is attainable for Intermountain at 15% excess air and OFA ports closed.

2
w

2.2 Opti-Flow™ Low NO_x Burner:

ABT's Opti-Flow™ low NO_x burner generates a very bright, intense flame that does not look like the classical low NO_x flame: its intensity is more akin to that of classical turbulent burners. Yet, the NO_x levels are typically more than 35 percent lower than those generated by competitors' low NO_x burners that ABT has replaced firing bituminous coal and more than 40% lower than those firing PRB. This NO_x reduction result has been attained without any additional UBC penalty.

The Opti-Flow™ low NO_x flame stabilization nozzle is the key element of the fuel injector for attaining excellent flame stability along with minimum NO_x. Excellent flame stability is achieved by incorporating external flame stabilizers surrounding each nozzle segment. The segmented coal nozzle has an open design with no obstructions to wear or to collect coal. Nearly uniform fuel distribution around the burner nozzle circumference is also obtained, which provides significant aid in attaining minimum NO_x and UBC simultaneously. Pressure drop is minimal and there are no components in the coal path that would be subject to wear, coal accumulation, or coking.

Wear
1.2

Advanced Burner Technologies utilizes high quality stainless steels for all parts of the fuel injector that face the furnace, as well as stainless steel castings for all complex parts. The result is high reliability and excellent longevity of the burners.

But not the injector

Wear
1.3
1.2

ABT's Opti-Flow™ dual register is an innovative design that provides the operator with the flexibility of optimizing inner and outer zone swirl values, and the air flow split between the inner and outer zones independently of swirl. This is accomplished with a manually adjustable inner air damper and represents a significant improvement over other dual register designs. A fixed vane swirler is attached to the outer barrel of the fuel injector to impart swirl to the inner air zone.

Carbon Steel injector suffers creep.

In order to be most effective, any low NO_x burner must operate in an external environment that provides proper conditions needed for optimal combustion at each burner. There are two operational areas that are extremely important for best burner performance with minimum flame length:

- a) Known and accurately controlled primary air flow along with other sources of air which enter the fuel injector: such as auxiliary air and seal air. ABT has sized the fuel injector proposed here based on the PA flow contained in the OEM mill curves for Intermountain Unit 2. This primary air flow must be verified during pre-retrofit testing.

PA Flame
4.9

Ref: Email Sal Ferrara 10/28/05
Subject: RE: The remaining picture.
To: Larry Christensen



b) PA/coal flows between burners must be as balanced as possible. Significant imbalances in either PA or coal flows will yield:

- Longer flames on some burners.
- High NO_x from the burner with low fuel flow
- High UBC from the burner with high fuel flow
- High windbox pressure caused by an attempt to force an excessive amount of air to the high fuel burners.

This problem is generated by both unequal coal pipe lengths (resistance) and external mill stratifications. ABT's experience is that the proper use of adjustable coal pipe orifices can alleviate this problem to a considerable degree.

2.2.1 Fuel Injector for Intermountain Unit 2

The key components of the fuel injector include:

- a) Fuel Distribution System: Flow enhancing fuel distribution system yields nearly uniform coal distribution at the burner nozzle. Uniform coal distribution helps to minimize NO_x and prevent significant increase in unburned carbon. This will be shop installed into the existing ceramic lined sweep elbows.
- b) Low NO_x Opti-Flow™ Segmented Burner Tip: Cast stainless steel open coal nozzle with integral external flame stabilizers promotes internal fuel staging reactions which result in minimum NO_x, yet provide extremely stable, bright flames.

2.2.2 New ABT Opti-Flow Dual Registers with Fuel Injector

ABT's complete dual register, described in detail in Section 7, will be installed in combination with our fuel injector. The improvements in air flow control and operability will amplify the fuel injector's ability to control NO_x. Minimum NO_x with optimal flame shape should then be attainable. The ABT dual register design provides the following:

- Optimized secondary air flow to the burners (nearly equal total air/coal ratios) accomplished by adjustment of individual burner dampers.
- Independent control of secondary air swirls and flow distribution within the burner.

2.3 Analytical Evaluations

Airflow Sciences Corp (ASC) will develop a CFD model of Intermountain's burner windboxes and duct work. ABT's experience is that the B&W compartmented



windboxes, with air flow control by louvered dampers, is inherently unstable. This modeling will identify regions where turning vanes and baffles will be needed to optimize flow to the burners, while minimizing pressure drop.

2.4 Testing

IPSC will contract the following testing and analytical services that will be witnessed by ABT's service personnel:

- Pre-retrofit testing will be conducted within three weeks following contract award to verify the primary air flow to the inlet of all of the mills. These tests will be conducted with one mill out of service and three mill loads: maximum, 70% and 40%. Maximum mill load corresponds to boiler full load with one mill out of service.

Isokinetic coal samples will be taken to evaluate the coal pipe balance. Those mills that have balance worse than $\pm 10\%$ from the mean will need to be balanced.

- A short boiler Baseline Test program will be performed in order to develop baseline data. Emissions and boiler performance data will be taken over the control range of the boiler with all mills in service.
- Emissions testing will be conducted immediately following start-up of the new combustion system. If not currently installed, during the outage the plant should install taps in the flue, upstream of the air heater. Probes will be placed in each tap for a complete grid. NO_x, O₂, and CO will be sampled during the start-up and burner optimization period after the outage. Unburned carbon will be sampled in the same manner as done for the baseline. Start-up, optimization and operational testing are expected to take no more than four weeks.

2.5 ABT Support Personnel

Lead ABT personnel, having > 20 years experience, that would support the Intermountain project are:

<u>Name</u>	<u>Location</u>	<u>Phone No.</u>
George Schiazza-Lead Service Engineer	Jacksonville, FL	904-272-8923
Tarkel Larson-Service & Sales Manager	Chattanooga, TN	423-899-8918
Sal Ferrara-Proposal & Project Manager	Bedminster, NJ	908-470-0721
Chuck Onaitis-Engineering Manager	Bedminster, NJ	908-470-0722

IP7_031323



3.0 Scope of Supply

Following is the scope of supply offered by ABT for the project.

3.1 Opti-Flow™ Low NO_x Burners

Forty-eight (48) Opti-Flow™ low NO_x burner modules with the following features.

- ABT's fuel distribution system consisting of silicon carbide and ceramic tile-lined components that will be installed in the existing ceramic tile-lined sweep elbow.
- A straight fuel injector with a cast HE tip for thermal resistance and long life.
- An inner air zone with a manually operated sliding damper for inner versus outer air flow distribution control and a stationary fixed vane spinner.
- A manually operated sleeve damper for total burner secondary air flow control and burner air flow balancing.
- Manually operated outer zone, axial spin vanes.
- Materials will be ASTM297 grade HE castings, 309 SS (in high heat affected areas), 304 SS, and carbon steel where appropriate.
- Burner front windbox cover plate.
- New windbox/burner adapter ring.

Note: ABT has found that some windbox front plates can be warped, resulting in a variation in distance between the windbox plate and the waterwall throat. To provide an easier installation, ABT is providing a seal ring that will slide into the existing windbox opening and allow easier fit-up by compensating for windbox to waterwall variations. The seal ring would be field welded to the windbox (the register front plate comes from the factory bolted to the seal ring.)

- Two thermocouples, each with terminal connection head mounted on burner front plate, for plants use in remote monitoring of burner tip and barrel temperatures.
- Plug-in design requiring no modifications to the windbox, waterwalls or existing burner support rails.
- Burner seal ring to attach to the existing burner throat seal plate.
- All gaskets, nuts, bolts and washers required for field assembly.
- Burner flame view port with purge air connection and ball valve assembly.

3.2 Flame Scanner Systems

ABT offers a replacement flame scanner system, including scanners, amplifiers and connection cables. The base scope includes supply of an IRIS system. Option for supply of an ABB system is also offered that, if selected, would result in a price adder of the amount listed in proposal Section 5.



Both ABB and Iris have extensive experience and success with their systems. ABT's burner design is easily adaptable to either system. Our burner flame shape and intensity allow for reliable flame scanning. In this case we do not have preference of one scanner system over the other. Experience lists and detailed scope of supply for both systems are included in Appendix A-2 of this proposal.

Fifteen (15) man-days, 8 hr/day, of flame scanner system startup and operational testing time and two (2) man-days, 10 hr/day, hands-on training time for plant personnel is included in the pricing for supply of either system.

3.3 Individual Secondary Air Flow Measurement

Each burner assembly will be equipped with an Eastern Instruments (EI) DPU-Differential Pressure System. Four (4) VAP³™/PA Pitots will be positioned equally around the circumference of the burner register. Shop installed tubing will connect pitots to fittings mounted on the burner module's front plate. Eight (8) NEMA 4 cabinets, one for each burner elevation, will be supplied with factory installed differential pressure transmitters and root valves. Tubing between cabinets and burner modules will be supplied and field installed. Local indication will be displayed at the transmitter cabinets where terminals will also be provided for the plant's use, should indication in the control room be desired.

We selected the EI system for our burners for its durable, accurate, and maintenance-free design. The VAP³™/PA with its reverse sensors is designed to operate in heavy particulate environments where dust and granular residue may be present. Also, due to its unique Velocity Averaging™ and Parallel Plate™ patented design, the VAP can be installed in locations where random flow distribution may be present. More detail on features of the VAP is provided in Appendix A-3 of this proposal.

Four (4) man-days of EI startup and hands-on training time for plant personnel is included in supply of the EI measuring system.

3.4 Flow Modeling

In order to achieve balanced airflow to the burners, CFD modeling is required. ABT will subcontract to Airflow Sciences Corporation (ASC) to develop a model for the secondary air duct and burner windboxes. The model will be utilized to evaluate the air flow distribution to the burners. The results will be used to design any turning vanes, baffles or other distribution devices needed to improve airflow within the ducts and windboxes.

Materials (typically carbon steel baffle plates and turning vanes) will be supplied and installed where necessary as depicted by the model.



3.5 Drawings and Operating Manuals

Documentation of the proposed equipment and materials, including arrangement drawings, field installation, and operating instructions will be supplied to IPSC in the format, quantities and time frame requested. Fabrication drawings would be available for IPSC's review in our office, or at the respective fabrication shops.

3.6 ABT Field Services

ABT will dispatch an engineer for field installation and testing support to assist during the initial stages of installation, startup check-out and during optimization of the new combustion system. Included in this proposal are a total of 40 man-days of ABT technical service support for erection, start-up, optimization and operational testing. Should additional service time be requested by IPSC, it would be billed at \$1000.00 per eight (8) hour day and time over 8 hours will be billed at a rate of \$187.00/hour. Travel and living expenses associated with additional ABT support services would be billed at cost.

3.7 Mechanical and Electrical Installation

ABT will subcontract erection services to Maintenance Enterprises Inc (MEI). Firm prices associated with the installation is entered on the bid form "Bid Pricing Sheet". Appendix A-4 contains conditions and schedule associated with MEI's proposal for the installation scope of work.

2025/03/10 14:00:00

IP7_031327



4.0 Guarantees and Warranties

4.1 Workmanship and Quality:

4.1

ABT shall warrant the workmanship and quality of the supplied parts from the start-up date for a period of 12 months and 48 months for coal nozzle tips. ABT will supply a replacement for any supplied part which suffers a catastrophic failure due to design or workmanship flaws. IPSC will provide complete access to any supplied part that fails, including removal of any equipment that prevents access to the part to be replaced or repaired and removal and reinstallation of any complete ABT-supplied assemblies that cannot be repaired in-situ.

Changes to the appearance and dimensions of any part will be considered failures only if guaranteed emissions are affected to the extent that the unit is out of compliance and readjustment of burner operating parameters fails to return the emission to within guarantee level; and there are no changes to other equipment, operating methods, or fuel supply which could result in changes to the emissions.

The following requirements apply to both the material warranty and the below listed guarantees:

- Primary air flows shall be within $\pm 5\%$ of the mill manufacturer's design primary air flow vs. coal flow curve
- Mills will not be operated at full load with more than one burner out of service.

4.2 Reliability

The Opti-Flow™ fuel injector components will prevent coal layout and dropout as well as the potential resultant coking inside the fuel injector during normal start-up and operation. Failures caused by other equipment are excluded, for example: mill and control system problems, igniters, or failed/stuck burner shut-off valves.

4.3 Pressure Drop

4.3.1 Fuel Injector

The pressure drop across the new fuel injector, as measured between the inlet flange and the furnace, at the respective elevation, will be no greater than with the existing burner. The new fuel injectors will not limit boiler load.

15

4.3.2 Secondary Air

Windbox pressure will not exceed 2" W.C., with overfire air ports (to be supplied by others) open



Note: ABT will supply appropriate secondary air duct and windbox turning vanes and baffles to minimize secondary air mal-distributions to the windboxes and instabilities within each windbox.

4.4 NO_x

ABT guarantees that NO_x will not exceed 0.33 lb/10⁶ Btu, with overfire air ports closed, at the design excess air of Section 4.6 and 100% MCR.

ABT predicts that NO_x with OFA ports open, with a flow of 20% of the total combustion air, will be less than 0.25 lb/MBtu.

NO_x is a function of several fuel variables, primary among them is fixed carbon to volatile matter (FC/VM) ratio and % fuel-bound nitrogen. Figure 4.1 represents the change in NO_x guarantee parametrically in FC/VM against fuel nitrogen content as lb. N₂/10⁶ Btu.

Note: The guarantee point represents the fuel properties specified in Section 4.9: 1.2% N₂ and 11.500 Btu/lb corresponds to 1.04 lb N₂/10⁶Btu.




Figure 4.1 Change in NO_x vs. Fuel Properties



Short-term periodic exceedances will be permitted provided the NO_x level returns below the guaranteed level after the unit stabilizes. This is necessary to accommodate potential NO_x variations during rapid load changes and while mills are coming in and out of service.

NO_x performance testing should be performed with both the CEMs and the economizer exit grid in operation. If the low NO_x system fails as indicated by CEMs but is within guarantee by the economizer exit test instruments, the latter shall govern and the CEMs shall be recalibrated against the test instruments.

4.5 CO

CO will not exceed an average of 200 ppm, with overfire air ports closed, at the boiler excess air as specified in Section 4.6 over boiler steam temperature control range, provided the fuel/mill conditions of Section 4.9 are met and that secondary air flows in each duct are steady and approximately equal (flow variations caused by plugged or unbalanced air pre-heaters are to be minimized).

4.6 Excess Air

The full load boiler excess air level at the burners will not exceed 15%. ABT will have the option of recommending a minimum O₂, across the respective boilers' steam temperature control range, at which NO_x, CO and LOI guarantees are simultaneously achieved, without deteriorating boiler performance.

4.7 Unburned Carbon Expressed as Loss On Ignition

LOI will not exceed the values obtained in pre-outage baseline testing; with overfire air ports closed with no more than 5% leakage/cooling air flow. This LOI level is guaranteed provided the conditions of Sections 4.6 and 4.9 are met; and the post retrofit LOI is sampled and measured using the same methods as in the pre-retrofit testing.

4.8 Boiler Performance

Boiler performance will not be deteriorated from the performance obtained during the baseline tests. Commercially acceptable variations in individual measured data will be acceptable (i.e., super heat temperature $\pm 10^{\circ}$ F, etc.).

Boiler efficiency will not be lower than the baseline measurements, corrected for excess air and fuel conditions.

4.9 Mill and Fuel Conditions

The above guarantees are predicated on the following:



▪ **Mill Performance:**

Air Flow: The low NO_x burners will be designed to slave to the mills' operation in that the fuel injector will be sized to follow the mills' primary air flow characteristic. Consequently, ABT will design the burners for the full load primary air flow, per mill, as per the OEM mill curves, with one mill out of service at boiler full load. Primary air flow must reduce as mill load decreases. PA flow will be determined during pre-retrofit testing defined in this proposal Section 2.4.

2.2
Air-7
Chart

Coal/PA Flow Balance: The balance between coal pipes within a given mill is to be within $\pm 10\%$ of the mean for that mill. (ABT recognizes that this is difficult to accomplish on all mills. Consequently, we will accept one of the eight mills being outside this range, to maximum of $\pm 15\%$).

- **Fineness:** $99.5\% < 50$ Mesh and $70\% < 200$ mesh; all mills simultaneously.
- **Coal Properties:** Western U.S. bituminous:
HHV $> 11,500$ Btu/lb; N₂ $\leq 1.2\%$; FC/VM ≤ 1.2 ; Ash $\leq 12\%$

4.10 Burner Load Variation

The nominal burner heat input at boiler full load with one mill out of service, is approximately 192 Mbtu/hr.

The ABT low NO_x burner's flame will remain stable at a load greater than 220 MBtu/hr, and less than 95 MBtu/hr.

Maximum secondary air flow at 220 MBtu per hour and 15% excess air, with 10% OFA flow will be no less than 124, 240 lb/hr.

Minimum secondary air flow will be determined by balancing the burner stoichiometry against the overfire airflow necessary to maintain minimum NO_x. Note that 45% load is below the steam temperatures control range listed on the B&W summary performance sheet.

Unless we
actually
know it at
that level.
Then it
comes
apart

4.11 Ash Patterns

The low NO_x system shall not increase or adversely alter the pattern of ash deposits on the furnace walls or high temperature superheater tubing such that existing soot blowing and/or steam de-superheating sprays cannot maintain tube cleanliness or steam temperatures. Furthermore, the burners shall not cause increased buildup of slag deposits around the burner openings (i.e., eyebrows).



4.12 Remedies for NO_x , CO and LOI Exceeding the Guarantee Values

ABT is offering a low NO_x combustion system consisting of state-of-the-art low NO_x burners. Since there are no technical combustion remedies currently available to correct a failure to meet specific combustion guarantees (if there were ABT would have included them within the original design) specific remedies are proposed.

Although we expect to meet the offered guarantees, we are proposing the following remedies in the event that NO_x/LOI/CO levels are not attainable.

4.12.1 Financial Remedies

a) NO_x Remedy

In the event that the NO_x guarantee is exceeded during the performance test and there are no combinations of burner adjustments that reduce the NO_x level to within the guarantee value, ABT will be permitted to adjust excess O₂ to reduce the NO_x level to within the guarantee level, provided the requirements of Sections 4.8 and 4.10 are simultaneously met (i.e., no deterioration of boiler performance or ash patterns).

Liquidated Damage for NO_x: In the event the NO_x guarantee is not attainable ABT shall pay a liquidated damage of \$50,000 per 0.01lbNO_x/10⁶ Btu

b) LOI Remedy

In the event that the UBC guarantee is exceeded during the performance test, ABT will be permitted to readjust the firing system to reduce UBC to within guarantee levels. If there are no operational remedies and the criterion for the mills' fineness, performance, and coal are being met, ABT will pay a liquidated damage of \$25,000/ 0.1% UBC in the fly ash.

c) CO Remedy

In the event that the CO guarantee is exceeded during the performance test, or as a result of the NO_x remedies of 4.9.1, ABT will pay a liquidated damage according to the following formula:

CO L.D. (\$) = 100 [Meas. CO – Guar CO] , where CO is in ppm corrected to 3% O₂.

4.13 Vendor Equipment

ABT will pass-through to IPSC the guarantees and warranties for vendor-supplied equipment the Vendors offer to ABT.

IP7_031333

5.0 Pricing & Schedule

5.1 Pricing: Pricing for base scope is provided on bid form "Bid Pricing Sheet".

5.1.1 Option: Adder to Supply ABB Flame Scanners per Section 3.2... **\$ 55,385.00**

All prices include freight, FOB Delta, Utah.

Pricing quoted is subject to acceptance within 120 days of date of quotation.

5.2 Payment Schedule

20% - Invoice Upon Award

20% - Upon submittal of burner general arrangement drawings.

20% - Upon commencement of burner fabrication

30% - Upon receipt of the equipment at the job site in good condition *

10% - Upon successful start-up**

Payment Terms - Net 30 days from date of ABT invoice. Payments made later than 30 after date of invoice will incur 1.5% per month interest charge.

* Early material shipment to be acceptable, with equipment storage by IPSC. The 30% payment upon receipt of equipment shall be prorated based on percent of major material items delivered.

** Retention applies to Low NO_x equipment supply only. Installation and sub-supplier equipment and services are excluded from retention.

5.3 Delivery Schedule

The following schedule is based upon an award date of September 5, 2003.

a) Award -	9/5/03
b) Burner Drawings for Review and Initial Procurement -	11/03/03
c) Commence Fabrication	12/01/03
d) Commence Equipment Shipment	01/09/04
e) Complete Equipment Shipment	02/13/04
f) Commence Outage (see Appendix 4 for installation schedule)	02/28/04
g) Start-up	3/24/04
h) Optimization Complete	4/07/04
i) Guarantee Testing Complete	4/13/04

5.4 Recommended Spare Parts

ABT does not recommend any spares associated with the fuel injector or burner register assemblies as there is low risk of failure and our customers have not seen the need for stocking any of the associated parts. The longest lead parts are castings, for which we maintain the patterns, that can be supplied within 1- 2 weeks.

Reference Appendix A-2 of this proposal for Flame Scanner System recommended spares lists.

IP7_031335



6.0 EXCEPTIONS AND CLARIFICATIONS

6.1 PART A DIVISION A1: NOTICE

1. Bid Validity:

Bid Validity: 120 days required

Delivery, February 23, 2004

Release, September 5, 2003



24 weeks

Delivery will delay day by day for each day contract release extends beyond 9/5/03.

2. Performance Bond

A construction performance bond in the amount of 50% of the installation cost shall be supplied, if requested, the cost of which is approximately \$15,000.00. This bond will terminate upon successful completion of the installation and customer acceptance.

Instead of a 10% performance bond for equipment, ABT requests that IPSC use 10% retention to be released upon successful performance testing of the boiler.

6.2 PART B - DIVISION B1: INSTRUCTIONS TO BIDDERS

9. Award of Contract:

If ABT is awarded this contract we would commence design work immediately, not upon execution of the contract by IPSC.

12. Performance Bond:

Please see comment 2, Section

6.3 DIVISION B2, SUPPLEMENTARY INSTRUCTIONS TO BIDDERS

Article 2: Incentives and Liquidated Damages

2nd Paragraph: Change to read: For completion — Contractor will be awarded \$50,000 per day bonus.

3rd Paragraph: Change to read: For incomplete — will be assessed \$50,000 per day of delay.

A701 Add'l Notes
pages.

Additional Clarification to Spec. 45606

6.4 Part C-Division 3

- 1g. Bid form, Spec Page C-2, submitted with our proposal listed the max. and min. limitations of our offered equipment as being 2000° F and 140° F for the "Burner Tip" and "Scanner Electronic", respectively. Our design for specific components is based on their expected temperature exposure with the following limitations:

<u>Component Description</u>	<u>Material Limitation, ° F</u>
Those exposed to direct furnace radiation, i.e. flow divider, spin vanes, throat casting, register front cone, fuel injector tip and flame stabilizers.	2000
Those semi-shielded from furnace radiation i.e. fixed vane spinner and inner zone damper perforated plate.	1600
Those shielded from furnace radiation, set back from furnace opening, and exposed to maximum windbox temperature, i.e. register sleeve dampers, register backplate, windbox coverplate, fuel injector barrel, elbow flatback and fuel distributors.	750

Explanatory Comment: The reason we stated that there are no environmental limitations to the coal burners is that the stainless steel castings and plate facing the fire, ASTM 297 Gr HE or 309 will not deteriorate at temperatures of at least 2000 F. We have never measured tip temperatures above 1600 F, in pre-NSPS furnaces that have input per plan levels as high as 2.3MBtu/hr/ft² and Furnace Exit Gas Temperatures or 2400F and firing Eastern bituminous coals. These are a good deal higher than Intermountain and generate higher gas temperatures.

Consequently, we do not consider that operation of our design in your boiler to have any environmental limitations: the conditions are such that no material will operate anywhere near its limit. In fact we have placed no such limitations on any retrofit we have done.

- 1h. We will not require any special modes of operation in that the existing burner controls should not require changes. Burners will be setup during optimization (at 100% MCR) which will begin with components at predetermined positions similar to the following example:

Burner Secondary Air Sleeve Dampers (SAD)	80% Open
Burner Outer Air Registers Spin Vanes	40% Open
Burner Inner Air Sleeve Damper	20% Open

Following start-up these components are used to control the shape and ignition point of the flame, which in turn controls NOx, O2 distribution and CO emissions. The final settings are tabulated and provided to the customer for future reference. During normal operation, following optimization, further adjustments should not be necessary unless a significant change in fuel supply characteristics occurs.

In no case have we required any customer to modify normal procedures to accommodate our burners. However, as noted in the guarantee section, we do require good fuel balance in the coal pipes, accurate primary air flow measurement and control and that the Primary air flow decrease as mill load decreases. We do not consider these to be "special modes of operation"; rather good operation.

4.9



Delete: "In the event the burner supplier does not provide for the installation— penalty clause applies:"

Change boxed clause to read: "For delivery of all burner —— components contract price". Delete last sentence.

Delete remainder of Section 2.

ABT anticipates shipments to the IPP job site will begin in early January, prior to installation contractor arrival on site. In case of early shipments, IPP would be responsible for off loading and storage of equipment.

6.4 PART C - DIVISION C3

*— Ref Additional Inserted
pages 2 pages ahead.*

Bidding Documents - Additional bid

- 1 b. There are no normally recommended or required spares. However, the plant may choose to have our fuel injector assembly (barrel & nozzle) on site in the event that a burner might be damaged by some external cause.
- g. There are no environmental limitations to the coal burners
- h. The coal burners will slave to the mills. There are no special modes of operation.
- i. There are no special maintenance requirements. ABT suggests that, fly ash be cleaned from adjustable register components at the commencement of an outage if the boiler is to be water cleaned.
- j. There are no required boiler modifications to accommodate the new burners.

10
1

6.5 DIVISION E1, GENERAL CONDITIONS

Article 5: Fabrication drawings and burner design calculations will not be supplied however will be available at the fabrication shop, or at our engineering office, for reference during visits by IPSC.
Drawings anticipated for delivery to IPSC include:

- a. General Arrangement Drawings showing equipment arrangement.
- b. Field Installation Drawings.
- c. Instruction manuals for supplied equipment.



Article 13: Add at end of paragraph, "In no event shall Contractor be liable, whether in contract, tort (including negligence), warranty, strict liability, or any other legal theory, for any indirect or consequential damages, such as, but not limited to: cost of capital; loss of anticipated profits or revenue; loss of use or increased expense of using equipment or plant; loss of power or production; cost of purchased or replacement power or production; or claims of customers for loss of power or production."

6.6 DIVISION E2, ADDITIONAL GENERAL CONDITIONS

Article 1: ABT's offer is based on Warranty and Guarantee conditions as written in Section 4 of the Proposal.

6.7 DIVISION F1, DETAILED SPECIFICATIONS - SPECIAL CONDITIONS

Article 3: Delivery

Add: Notwithstanding the above, IPSC agrees to accept early delivery of burners if ABT's shop is ready to ship. Burners will be stored indoors at the site and unloaded by IPSC.

Article 6: General ABT Clarification on Insurance

The following clarifications to specific portions of this article are made regarding our current insurance coverage which has been satisfactory to all our customers' requirements. We therefore have not included additional premiums, associated with higher limits, in our pricing for this proposal. Should our current limits be unacceptable to IPSC, and we must raise them for an IPSC contract, the difference in ABT's premium would be added and billed to IPSC at cost.

Article 6a: Workers Compensation/Employers Liability: (revised requirements) beginning on 4th line, strike words beginning with "Voluntary" through end of this sentence.

Beginning 11th line, strike words beginning with "waiver of subrogation" through the end of this paragraph.

Article 6b: Commercial General Liability: (revised requirements)

Line 5 and 7 strike "\$5 million", replace with "\$2 million",

Line 6, strike words "and be specific for the contract",

Line 9, strike 'IPSC's', replace with "standard",

Beginning on Line 10, strike the words "or an endorsement of the policy acceptable to IPSC"

Strike all of subparagraphs "(2)", "(3)", and "(5)".

Article 6c: Commercial Automobile Liability: (revised requirements)
Next to last line, strike words "as required" and replace with "revised requirements"

Article 6d: Professional Liability: (revised requirements)
2nd line strike words "with Contractual Liability included,"
4th line strike "\$5 million", replace with "\$1 million",
Beginning on 5th line strike the entire sentence beginning with
"Evidence", replace with "Such insurance may be an endorsement to
the Commercial General Liability Policy without separate aggregate."

Article 6e: Other Conditions: (revised requirements)
Strike entire subparagraph (1)
In subparagraph (2) Line 2 insert the word "revised" between the
words "these" and "insurance".

6.8 DIVISION F2, DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

Article 5e: ABT supply includes two thermocouples, each with its own terminal block head mounted on the burner windbox cover plate. The heads will have a removable cover for IPP access to terminals for remote temperature indication of fuel injector tip and barrel.

Article 5l: ABT supply includes one port per burner assembly with observation glass to view flame. Each port will be equipped with purge air connection and ball valve should the need arise to purge the view pipe.



7.0 The Opti-Flow™ Low NO_x Firing System

Advanced Burner Technologies' Opti-Flow™ low NO_x burner, which contains the fuel injector and dual register, is installed as a "plug-in" module. The existing burner throat opening in the water wall is used, as are the present support rails. In addition, we maintain the same opening in the windbox. No pressure part modifications or windbox modifications are required. All components are shop installed including the airflow elements, associated tubing and fittings.

ABT has developed an elbow-based fuel distribution system, which yields nearly uniform distribution of coal at the burner tip. These components are installed in the existing ceramic lined sweep elbow. All of the wear surfaces of these components are protected with ceramic wear materials.

Since its conception, ABT has constantly striven to produce a better Low NO_x combustion system. We consider all aspects of the system from combustion products (low NO_x, CO, & LOI), the effects on the furnace (slagging, fouling, and water wall corrosion), and the cost both from the purchase price to the O&M budget. We take seriously comments from the customer, the installation labor, and operational difficulties. As part of this effort, we have continually simplified the burner, both the register and the fuel injector.

*We have
Non-uniform
distribution
at the coal
tip -
7.1*

7.1 Opti-Flow™ Low NO_x Burner

a) Fuel Injector Sub-Assembly

The fuel injector, a novel ABT Opti-flow™ design with a segmented nozzle and a fuel distributor, is made from highly wear resistant ceramic components, mounted in the elbow.

There are no internal devices in the fuel injector, other than the flow distribution devices in the elbow, that could cause coal layout or require periodic maintenance.

The components and their functions are briefly described as follows:

- Flow Distributor: A fuel distribution device in the elbow breaks the rope formed in the coal piping in order to provide uniform fuel distribution at the nozzle. A more complete discussion, "Opti-Flow™ Distribution System for Elbow-Based Fuel Injectors", is contained in section 7.2.
- Opti-Flow™ Low NO_x Flame Stabilization Nozzle: This is the key element for attaining excellent flame stability and minimum NO_x. Figure 7.1, shows the segmented coal nozzle, which has an open design with no obstructions to collect coal. Pressure drop is low, and there are no components in the coal path that are subject to wear, coal accumulation or coking. Excellent flame

7.0



stability is achieved due to the external flame stabilizers surrounding each segment.

- Inner Air Zone Swirler: This fixed vane swirler is attached to the outer barrel of the fuel injector. The position of the swirler is fixed and no adjustments are required.

A schematic of the Opti-Flow™ dual register is shown in Figure 7-2.




Figure 7.1 Opti-Flow™ Coal Nozzle

b) Opti-Flow™ Dual Register Assembly




Figure 7.2 Opti-Flow™ Dual Register Assembly

Key features of the Opti-Flow™ dual register sub-assembly include:



- Sleeve Damper: Air flow to each burner is controlled by a manually operated sleeve damper. This damper is used to balance the air flow between burners. The vanes are manually adjustable from the burner front to optimize the secondary air swirl in the outer zone.
- Inner Air Zone Damper: The sleeve damper is axially adjustable to vary the ratio of airflow between the inner air zone and the outer air zone. This is a manual adjustment made during optimization.

Mechanically the damper is very simple. Because of its smaller size and weight, it rides on two stainless steel rods and is actuated by a push/pull rod. It is welded to the actuator rod to prevent any cocking of the sleeve.

- Outer Spin Vanes: The vanes are manually adjustable from the burner front to optimize the secondary air swirl in the outer zone. The actuator is two manually operated push/pull rods, which translate a "bull ring", moving linkages which rotating all of the spin vanes. This system has no components subject to binding by ash deposits and has little hysteresis.
- Low pressure drop register: The register has been designed for low pressure drop by the addition of turning vanes in the outer air zone and lower velocities in the spin vane section.
- Burner front plate flange: Flange adjusts to accommodate distortions in the windbox plate and it allows the burner throat casting to be located in the throat, regardless of furnace wall or windbox location. The bolted joint can be convenient, in the future, for removal of the burner module for maintenance.



7.2 Opti-Flow™ Fuel Distributor

Unbalanced fuel distribution leaving the coal nozzle tip and the resultant operating problems are caused by similar deficiencies in all pulverized fuel injectors. Coal is separated from its carrier (primary) air inside the inlet device, be it scroll, elbow, or 90° turning head, resulting in "roping" of the coal inside the primary stream. Redistributing the "rope" downstream of the inlet has been an inherent problem with burner designs. ABT's method of improving fuel distribution consists of a system of several interrelated components.

Advanced Burner Technologies has developed an elbow-based fuel distribution system, which yields nearly uniform distribution of coal at the burner nozzle's exit. This system reduces the fuel imbalance that occurs in standard elbow-based fuel injectors by a factor of approximately 4.5 to 1; and by over 3 to 1 as compared to other types of burner inlets (i.e., scrolls or t-type heads). Figure 7-3 illustrates the results of our two-phase physical flow modeling with a standard 90°-flatback elbow. The distribution system is also designed to accommodate sweep elbows.

Doesn't happen

Problems. Unseen wear.




Figure 7.3 Comparison of Open Elbow and Opti-Flow™ Distribution

Baseline testing was performed with an open elbow and fuel nozzle in order to determine the uncontrolled distribution of particles at the outlet of the nozzle. A seven-point collection matrix was used: six points around the circumference and one collection point on the axis. As expected, the fuel distribution was severely unbalanced with an RMS value of 60% of the mean. The Opti-Flow™ modifications



resulted in a significant improvement. The RMS value was reduced to 13% of the mean - an improvement of 4.62 over the baseline. Existing elbow-based fuel injectors that contain conical diffusers suffer from fuel imbalances of 36% RMS. In this case, the Opti-Flow™ system yields a 3 to 1 improvement in fuel distribution.

Severe fuel imbalance can result in the following problems:

- High-unburned carbon
- Long flames
- Flame instability problems.
- NO_x control problems

*Erosion patterns on
the nozzle tip indicate
that there is not
uniform flow.*

The significant improvement in fuel distribution provided by the Opti-Flow™ system will correct these problems to the extent that they are caused by fuel imbalance within the coal nozzles. Other fuel distributors cause coal "ropes" to impact on the coal nozzle and, thereby, reduce the nozzle's usable life. In the ABT design, all wear is limited to the wear-resistant devices in the elbow.

The Opti-Flow™ system eliminates coal ropes and produces a nearly uniform fuel/air mix with axial flow downstream of the elbow. Therefore, the only erosion-prone areas will be located within the elbow. These areas will be lined with erosion-resistant materials and will be easily replaceable when necessary. A further advantage of this fuel distribution system is that, when used in conjunction with the Opti-Flow™ segmented nozzle, NO_x can be reduced compared to existing nozzles used for tangential firing.

The Opti-Flow™ Fuel Distribution System consists of:

1. The existing coal elbow with ABT's distributor vane package installed to break the coal rope formed in the fuel piping. All surfaces, including the leading edges are protected with ceramic tile.
2. A ceramic device at the coal elbow inlet will be used in conjunction with distributor vanes for equalizing coal flow to the tip.

7.3 IMPLICATION FOR FIELD RESULTS

Within a flame of a low NO_x burner, poor fuel distribution around the nozzle's circumference results in degraded emissions and efficiency performance. Optimal combustion - minimum NO_x and minimum unburned carbon, simultaneously - occurs when the circumferential fuel distribution is uniform (assuming primary air and secondary air distribution are also uniform). When this condition exists, the environment surrounding all fuel particles is the same and, therefore, results in uniform combustion conditions.



However, in practical operation, there are several conditions both external and internal to the fuel injector that precludes uniform fuel distribution. As a result, this prevents uniform air/fuel (stoichiometric) conditions within any flame from being attained.

Externally, non-uniform fuel flow inside the coal pipe, upstream of the fuel injector's inlet, causes imbalances further downstream within the fuel injector.

Internally, all burners, regardless of inlet type, develop unbalanced coal flow that yields wide variations in stoichiometry within the flame. Stratification that causes high fuel flow will result in very low stoichiometric zones in the flame. On the other hand, stratification that causes low fuel flow will result in very high stoichiometric zones in the flame. The former generates high-unburned carbon levels; the latter generates high NO_x levels.

Since both unburned carbon and NO_x generation are non-linear functions of oxygen availability (stoichiometry), the high and low stoichiometric portions of the flame do not compensate each other for their respectively high NO_x/low UBC and low NO_x/high UBC levels. The consequence of this effect is that the unbalanced flame generates NO_x and UBC levels that can be significantly higher than anticipated.

Table 7-1 compares the minimum and maximum relative fuel flows of the Base-Std OEM design and the Opti-Flow™ design to perfectly balanced conditions. The resultant local flame stoichiometries and relative effects on NO_x and UBC levels are also tabulated.

TABLE 7-1
Standard vs. Opti-Flow™ Burner:
Effect of Fuel Imbalance on Relative NO_x & UBC

Condition	Fuel Flow (Relative)		Local Flame Stoichiometry	Relative NO _x	Relative UBC
Base-Std	Min.	0.61	1.97	>>1.0	<1.0
	Max.	1.59	0.75	<1.0	>>1.0
Opti-Flow™	Min.	0.90	1.33	1.0+	1.0-
	Max.	1.22	0.98	1.0-	1.0+
Perfect Balance	1.0		1.2*	1.0	1.0

*Assumes 20% excess air operation (stoichiometry = 1.2)



Based upon these comparisons, it is reasonable to predict that, all other operating parameters and conditions being equal, the Opti-Flow™ low NO_x fuel injector will produce lower NO_x and lower Unburned Carbon than a standard burner.


Field retrofits on large utility boilers have confirmed this analysis: NO_x has been reduced 40% below the levels attained with the OEM's burner, while unburned carbon has not been increased.

DISCLOSURE NOTICES

1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR WHOLE, WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.

2. THE STRUCTURE AND OPERATION OF THE OPTI-FLOW FUEL DISTRIBUTION SYSTEM AND DUAL REGISTER ARE THE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.

4" FIELD APPLIED INSULATION & LAGGING



INSTALLATION INSTRUCTIONS

- 1 REMOVE ELBOW-SHIP TO SHOP FOR INSTALATION OF
- 2 REMOVE EXISTING BURNER AND FLANGE RING
- 3 REMOVE EXISTING SEAL RING AT FURNACE WALL
- 4 INSTALL NEW BURNER ASSEMBLY, CENTER IN THROAT LEVEL, AND LOCATE END OF THROAT AT CL OF LAST
- 5 SHIM BETWEEN SUPPORT BAR AND EXISTING RAILS
- 6 SEAL WELD INSTALATION RING TO WINDBOX
- 7 INSTALL SEAL RING AND WELD TO WALLBOX
- 8 INSTALL IGNITERS AND MAIN FLAME SCANNER
- 9 REINSTALL REWORKED ELBOW

UNLESS SPECIFIED

WELD FABRICATIONS
1. 20"
2. 22"
3. 24"
4. 26"

IS NOT TO EXCEED 125

WRP CORNERS

SCALE PRINT

CAD GENERATED DRAWING
DO NOT MANUALLY UPDATE

APPROVALS DATE

DRAWN GCO 11/15/02

CHECKED

ADVANCED BURNER TECHNOLOGIES

350 MAIN STREET, SUITE 3
BIRMINGHAM, AL 35202

Phone: 205-419-8470
Fax: 205-419-8470
www.abt.com

INTERMOUNTAIN POWER SERVICE CORPORATION

ABT PROPOSAL NUMBER Q02003

SIZE B DWG NO. Q03013-10

REV 1

CAD FILE

IP7_031350

IP7_031351

IP7_031352

IRIS

SYSTEMS INC.

1701 W. Northwest Highway, Grapevine, TX, 76051
Tel: 972-539-0889 Fax: 972-539-6379

Wednesday, August 20, 2003

Advanced Burner Technologies
350 Main Street, Suite 5
Bedminster, NJ 07921

Attention: Sal N. Ferrara

Subject: IPSC Unit 2, Low NOx Burners
ABT proposal # Q03013
IPSC Spec 45606

We are pleased to submit the following proposal per your inquiry.

I would like to point out a special additional value we are providing on this project. We propose to provide, included in the pricing for this project: *an extended warranty of three years from shipping or two years from startup*. In addition, please know that IRIS provides a 100% guarantee in discrimination.

Since you are buying new burners, this should allow you to properly sight the scanners. This is based upon the burner design allowing room for proper sighting. In turn, this will allow you to detect both the main flame and the igniter using only one scanner. Our pricing is based upon 48 loops. If, for any reason, you decide that you need to include an additional scanner per burner, you would need to double the hardware pricing.

The IRIS flame scanners are network capable. IRIS has its own software called Flame Tools, which will allow you to calibrate and adjust the scanners remotely, along with trending, cataloging, and graphing. This software is included in our pricing. The flame scanners are capable of communicating in all versions of Modbus.

IRIS scanners only require 5 CFM over furnace pressure for cooling air.

We would like to submit the following breakdown in scope of supply.

<u>Item 1</u>	<u>Description</u>	<u>Qty.</u>
IR-P532	Dual IR/UV controllers (AC, 120 Vac)	24
IR-S552	Infrared viewing heads	48
 <u>Item 2</u>	 <u>Description</u>	 <u>Qty.</u>
Burner Front Amplifier Cabinet	Each cabinet comes with breaker, fuses and flame light indication for (4) main flame scanners. Each cabinet will accommodate two IR-P532s. Scanner cabinets will be mounted in the same location as the existing cabinets.	8

IP7_031353

Item 3	Description	Qty.
Scanner Mounting Kits	Each kit includes cooling air Y and shut off valve, and adapter plate	48

Item 4	Description	Qty.
Detector Cable	4 conducted braided shielded cabling is required for our scanners. Exact runs for cabling is known however the <u>price per foot</u> is \$ 1.96. For pricing purpose we assumed 50 ft per scanner.	48

Item 5	Description	Qty.
Start-up Services	A. Per your specifications; <u>first trip, two weeks</u> (five-day week, 8 hour days), travel and expenses included. B. Per your specifications: <u>Second Trip, One week</u> (five-day week, 8 hour days), travel and expenses included C. Per your specifications: <u>Two onsite train classes</u> , (for the duration of not less than 10 hours total.)	N/A

(Any additional service required, please see our attached field service rate schedule.)

Option (adder to base price)	Description	Qty.
Recommended Spare Parts	We recommend (2) IR-P532 and (2) IR-S552	4

The price for (2) IR-P532 & (2) IR-S552 is.....\$ 9,500.00

All prices are good for 120 days.

FOB: Delta, Utah

Freight: Included (except freight for spares will be pre-paid and billed at cost)

Terms: Net 30

Lead time: 4-6 weeks

I would like very much to provide a presentation. That would allow me to answer in person any questions or concerns you may have. At your convenience, please contact me to set up a date and time. I look forward to hearing from you, and once again, thank you for allowing me to provide this quote.

Highest regards,

Walter F. Collins
Diamond Systems / IRIS
1701 W Northwest HWY
Grapevine, TX 76051
(972) 539-0889
Fax (972) 539-6379

FIELD SERVICE RATE SCHEDULE

	<u>Field Service Engineer</u>	<u>Project/Software Engineer</u>
Per Day Rate	\$1020.00	\$1300.00
Per Hour Rate	\$127.50	\$ 162.50
Time and One-Half	\$191.25	\$ 243.75
Double Time	\$255.00	\$ 325.00

1. Time and one-half applies to all work performed after 8 hours per day or on Saturday.
2. Double time applies to all work performed on Sundays, holidays, and work after 12 continuous hours.
3. DSI personnel are not required to work more than 12 hours in any 24-hour period.
4. All weekday travel time is chargeable per the above notes. (time and one-half maximum)
5. All weekend travel time is chargeable per the above notes.
6. Eight-hour minimum charge for all one-day service calls with four-hour minimum per day thereafter.
7. Offshore (at sea, platform) rates are an additional \$100 per day.
8. Field Service time, if put on "hold", at job-site or hotel, will be charged at the regular daily rate plus expenses.

DSI Holidays:

New Year's Day	President's Day	Memorial Day
Day before Independence Day	Independence Day	Labor Day
Thanksgiving Day	Day after Thanksgiving	Christmas Eve Day
Christmas Day	New Year's Day	

Workday Defined:

The above charges are for a normal eight-hour day with time and one-half charged for Saturdays, and time over eight (8) hours for a weekday; Sundays, holidays and work after twelve (12) continuous hours will be charged at double time. In addition the travel and living expenses will be billed at cost. DSI will supply receipt and documentation for the substantiation of reasonable travel and living expenses. These shall include (1) air travel receipt, if used, (2) hotel receipt, if used, and (3) car rental receipt, if used. No other receipts for living expenses will be furnished unless specifically requested by the purchaser in writing prior to the start of the assignment.

Time Sheets:

Before the work commences, satisfactory arrangements must be made with DSI to review and sign Daily Time Sheets. It is suggested that customer submit a written document to DSI stating whether the customer or their authorized representative will be signing the time sheets. Disputes of any nature should be immediately reported, in writing, to DSI. Approval and acceptance of the work will be assumed, if no arrangements have been made to sign the time sheets, and invoicing will be submitted accordingly. Once signed, the time card is considered as acceptance of the work performed.

Travel Expenses:

Airfare	At cost
Auto Rental	At cost
Mileage	(.35/mile)
Tolls	At cost
Parking	At cost

Living Expenses:

Motels and meals, etc..	At cost
-------------------------	---------

Copies of travel and living expense receipts will be submitted with the field service invoice.

Terms of Payment:

Field Service Invoices are due and payable upon receipt.

ALLEGHENY POWER ALBRIGHT, WV	STEAM GENERATOR, RILEY STOKER CORP. TWELVE (12) BURNER, LOW NOX, BURNING PULVERIZED COAL, NATURAL GAS, & #2 OIL FRONT WALL FIRED
AMERICAN ELECTRIC POWER CO PICWAY STATION	STEAM GENERATOR, 16 RILEY LOW NOX, BURNERS, TYPE 90 CCV, #3A. NATURAL GAS & PULVERIZED COAL
AMERICAN ELECTRIC POWER CO COSHOCOTON, OHIO	STEAM GENERATOR, 16 RILEY LOW NOX, BURNERS, TYPE 90 CCV, #3A. NATURAL GAS & PULVERIZED COAL
BOARD OF PUBLIC UTILITIES NEARMAN CREEK PLANT KANSAS CITY, KANSAS	STEAM GENERATOR, PULVERIZED COAL, NATURAL GAS, RILEY STOKER "TURBO" UNIT, 18 BURNERS OPPOSED FIRED
CENTRAL ILLINOIS LIGHT & POWER CO EDWARDS STATION PEORIA, IL	STEAM GENERATOR, RILEY STOKER, SIXTEEN BURNER IN FRONT WALL, BURNERS ARE FOSTER WHEELER LOW NOX TYPE BURNING PULVERIZED COAL WITH #2 OIL IGNITORS.
CENTRAL ILLINOIS LIGHT & POWER CO EDWARDS STATION PEORIA, IL	16 IRIS MODEL S506 UV, 16 IRIS MODEL S512 IR VIEWING HEADS c/w MODEL P522 SIGNAL PROCESSORS.
COLORADO UTE ELECTRIC ASSOC. HAYDEN STATION	STEAM GENERATOR, 18 BURNERS, FRONT FIRED, PULVERIZED COAL WITH GAS ELECTRIC IGNITION
COMMONWEALTH ELECTRIC CO SANDWICH STATION, MA	STEAM GENERATOR, UNIT 1, FOSTER-WHEELER OPPOSED FIRED, 48 BURNERS (3 PER CELL), #6 OIL.
CRISP COUNTY POWER CORP GEORGIA	STEAM GENERATOR, PULVERIZED COAL NATURAL GAS, B & W, 4 BURNERS
DIDCOT POWER STATION OXFORDSHIRE, UK	3 STEAM GENERATOR WITH 48 BURNERS EACH, GAS/OIL/COAL, B&W LOW NOX GAS ADDED. FRONT AND REAR FIRED, WITH 48 P520, S506 UV & Eexd HOUSING
ENTERGY WATERFORD STATION KILLONA, NY UNITS 1 & 2	18 BURNERS EACH GAS AND OIL FIRED. 72 IRIS MODEL S550 DUAL UV/IR VIEWING HEADS c/w MODEL P520 SIGNAL PROCESSORS AND HARDWARE.
FAIRCHILD AIR FORCE BASE SPOKANE, WASHINGTON	STEAM GENERATORS, UNITS 1, 2 & 3 RILEY STOKER UNITS FIRING OIL AND PULVERIZED COAL
GULF STATES UTILITIES SABINE STATION	STEAM GENERATORS, UNITS 1 & 2 C.E. TILTING TANGENTIAL CORNER FIRED UNITS, 24 BURNERS FIRING NATURAL GAS
GULF STATES UTILITIES NELSON STATION	STEAM GENERATOR, UNIT 1, C.E. TILTING TANGENTIAL CORNER FIRED NATURAL GAS
GULF STATES UTILITIES NELSON COAL #2 WESTLAKE, LOUISIANA	STEAM GENERATOR, C.E. TILTING TANGENTIAL CORNER FIRED UNIT, PULVERIZED COAL, 24 BURNERS
IOWA/ILLINOIS GAS & ELECTRIC DAVENPORT	STEAM GENERATOR, C.E. CORNER FIRED WITH RILEY LOW NOX BURNERS. PULVERIZED COAL & NATURAL GAS. 16 MAIN BURNERS. TWENTY-EIGHT GAS IGNITORS. IRIS 500 WITH FIBER OPTIC LIGHT GUIDES. IRIS 300 FOR IGNITER DETECTION.

IOWA PUBLIC SERVICE NEAL STATION #1 SERGEANT BLUFF, IOWA	STEAM GENERATOR, FOSTER-WHEELER, TWENTY-FOUR (24) BURNERS, OPPOSED FIRING, PULVERIZED COAL AND NATURAL GAS, WITH GAS ELECTRIC IGNITORS.
MIDWEST POWER CO NEAL STATION #2 SERGEANT BLUFF, IOWA	STEAM GENERATOR, SIXTEEN (16) BURNERS, FOSTER-WHEELER, PULVERIZED COAL, NATURAL GAS & #2 OIL.
MONTANA-DAKOTA UTILITIES CO. OTTERTAIL STATION, SD	STEAM GENERATOR, HONEYWELL IAC 24 BURNERS, OIL AND PULVERIZED COAL, IRIS MODEL P520'S, 12 S512 AND 12 S512E'S WITH FIBER OPTICS ON IGNITORS, IRIS P520 ON THE AUX BOILER.
NEW ENGLAND POWER CO. SALEM HARBOR #1	STEAM GENERATOR, 16 LOW NOX RILEY BURNERS, TYPE CCV, PULVERIZED COAL & #6 OIL. IRIS P520 WITH INFRARED VIEWING HEADS.
NEW ENGLAND POWER CO. SALEM HARBOR #2	STEAM GENERATOR, 12 LOW NOX RILEY BURNERS, TYPE CCV, PULVERIZED COAL & #6 OIL. IRIS P520 WITH INFRARED VIEWING HEADS.
NEW ENERGY CORPORATION SOUTH BEND, INDIANA	STEAM GENERATOR, RILEY "TURBO" UNIT FIRING PULVERIZED COAL, #6 OIL AND NATURAL GAS, WASTE FUEL
PACIFIC GAS & ELECTRIC CO CONTRA COSTA	STEAM GENERATOR, 24 LOW NOX TODD BURNERS, NATURAL GAS AND #6 OIL
PENNSYLVANIA POWER & LIGHT CO SUNBURY 2	STEAM GENERATOR, 12 LOW NOX RILEY BURNERS TYPE CCV, PULVERIZED COAL AND #2 OIL IGNITORS.
PENNSYLVANIA POWER & LIGHT CO SUNBURY 3	SAME AS SUNBURY 3.
PENNSYLVANIA POWER & LIGHT CO MARTINS CREEK	SAME AS SUNBURY 3.
PENNSYLVANIA POWER & LIGHT CO MARTINS CREEK	SAME AS SUNBURY 3.
SIGECO A.B. BROWN STATION MT. VERNON, IN	24 BURNERS COAL FIRED. IRIS MODEL S552 IR VIEWING HEADS c/w MODEL P520 SIGNAL PROCESSORS FLAMETOOLS SOFTWARE
SIGECO F.B. CULLEY STATION NEWBURGH, IN	24 BURNERS COAL FIRED. IRIS MODEL S550 UV/IR VIEWING HEADS c/w MODEL P520 SIGNAL PROCESSORS FLAMETOOLS SOFTWARE
TAIWAN POWER COMPANY	24 IRIS MODEL S552 IR VIEWING HEADS c/w MODEL P520 SIGNAL PROCESSORS
TENNESSEE EASTMAN CO KINGSFORD, TENNESSEE	STEAM GENERATOR, TWELVE (12) BURNERS, LOW NOX, FRONT WALL MOUNTED, BURNING PULVERIZED COAL, NATURAL GAS & #2 OIL.
TODD COMBUSTION INC. CONED HUDSON AVE. NEW YORK	16 TODD VARIFLAME LOW NOX GAS/OIL BURNERS IRIS MODEL 500'S

TODD COMBUSTION INC. PACIFICORP. GADSBY #1 & #2	2 UNITS 6 TODD VARIFLAME LOW NOX GAS FUTURE OIL BURNERS IRIS P520'S
TRI-STATE G & E CRAIG STATION CRAIG, CO UNITS 1, 2, & 3	120 B&W DUAL REGISTER BURNERS 120 IRIS MODEL S550 DUAL UV/IR VIEWING HEADS c/w MODEL P522 SIGNAL PROCESSORS.
ULTASYSTEMS FOR ROANOKE VALLEY PROJECT. WELDON, NC	STEAM GENERATOR, SIXTEEN (16) LOW NOX BURNERS, BURNING PULVERIZED COAL, NATURAL GAS & #2 OIL.
WISCONSIN POWER & LIGHT CO. ROCK RIVER STATION BELOIT, WI	STEAM GENERATORS, (3) BABCOCK & WILCOX, FOUR BURNERS FIRING PULVERIZED COAL.
BLACK HAWK STATION	STEAM GENERATORS (3), BABCOCK & WILCOX, FOUR BURNERS EACH FIRING NATURAL GAS.
WORSLEY ALUMINA STATION AUSTRALIA	12 P520 WITH 12 S552



SYSTEMS INC.

1701 W. Northwest Highway, Grapevine, TX, 76051

Tel: 972-539-0889

Fax: 972-539-6379

IRIS REFERENCES

1. Entergy, Louisiana Station - John Mallot - (225)354-4075
2. Central Louisiana Elect Co., Dolet Hills Station - Marty Eveans - (318) 484-7494
3. Tri-State Generation, Craig Plant, - Mark Linke - (970) 824-4411
4. Tucson Electric Power Co., Irvington Station - Scott Gurinave - (520) 745-3224
5. Entergy, Lynch and Lake Catherine, - Jeff Williams - (800)264-2535 or 0044
6. Reliant, Houston, Fred Cortez - (713) 945-7713
7. TXU, Valley Plant, Stewart Rake - (903)965-5116
8. City of Austin, Decker Creek Plant, Vance Zimmerman - (512) 505-7333, CE Unit
9. AEP/ West TX Utilities, Michael Rowell - (915) 674-7248
10. City Public Service of San Antonio, Bob Knight - (210)353-3669, CE Unit
11. AEP/Dallas, Ben Crawford - (214) 777-1406
12. City of Lafayette, Jamie Webb (337) 291-5760 Buddy Hudson (S&L) - (337)291-5779
13. AEP/Southwestern Electric, Knox Lee Plant , Scott Mankins (903)643-2651, CE Unit

If you should need additional references, please give me a call.

IP7_031360



August 19, 2003

ABB Inc.
Proposal No. U030304A Rev. 1

Mr. Sal Ferrara
Advanced Burner Technologies
350 Main Street, Suite 5
Bedminster, New Jersey 07921

Dear Mr. Ferrara,

ABB Inc. is pleased to offer our SafeFlame™ DFS Scanner System for use on your Low Nox Burner. We propose our SafeFlame™ visible light fiber optic scanner for monitoring the pulverized coal and class I oil lighters on forty eight (48) opposing wall fired low NOx burners. The proposed scanner is an extremely rugged field proven device with nominally 11,000 in operation around the world today. A description of the scanner system is provided in Attachment 1.

The proposed flame scanners are mounted in 2" ridged guide pipes. ABB has included with this proposal packing glands that can be welded to the new burner front plate. This will allow for removal and/or adjustment of the scanner guide pipe position in the burner.

Dimensional drawings of the flame scanner, guide pipe, and chassis are attached.

The hardware proposed below is for installation of the SafeFlame DFS electronics on each burner deck. A window kit is installed in each chassis enclosure to allow for visual access to scanner status without having to open the NEMA 4 enclosure.

BASE OFFER – SINGLE SCANNER PER BURNER

ITEM	QTY	DESCRIPTION
1	48	SafeFlame™ Fiber Optic Flame Scanner: <ul style="list-style-type: none">• Cast aluminum housing• Visible light photodiode board assembly• 9 degree viewing angle lens• High Temperature fiber optic cable• ¼ turn stainless steel electrical quick disconnect on scanner



2	48	2" Ridged scanner guide pipe mounting assemblies <ul style="list-style-type: none">• Stainless steel centering tip• 2" schedule 40 pipe• Cast aluminum cooling/purge air manifold
3	48	Guide pipe packing gland: <ul style="list-style-type: none">• For use with 3" NPT burner front plate opening• Holds and seals 2" scanner guide pipe
4	48	Flame scanner connector cable assembly: <ul style="list-style-type: none">• ¼ turn stainless steel connectors, one end• 50 foot scanner wire pigtail length• ½" NPT connection for installation in liquidtight conduit• Connector connection potted
5	16	SafeFlame™ DFS front access chassis each consisting of: <ul style="list-style-type: none">• Three (3) DFS sensor modules• Two (2) blank module• One (1) 115 VAC DFS power supply module• One (1) front access 19" wide rack mount DFS chassis
6	16	SafeFlame DFS chassis enclosure: <ul style="list-style-type: none">• NEMA 4 construction• Door window kit• DFS chassis (item 5) factory mounted
7	9	SafeFlame™ DFS Instruction Manuals
8	15	Man-days, (8) hours/day, for startup & testing
9	2	Man-days, (10) hours/day, for plant training



AVAILABLE OPTIONS

Option 1

ABB Inc. Technical Services Support is available in addition to support that is already included for start-up, testing, and on-site training. Additional support services would be at the prevailing rates at time of service. 2003 service rates as detailed in Attachment 2.

The home office for all ABB scanner service engineers is out of the ABB Windsor, CT offices. The contact for scheduling service is John Iovino, 860-285-6784. Mr. Iovino coordinates scheduled and emergency service based on available personnel at the time of service.

Option 2

The SafeFlame™ Sensor Module Communication Server (SMCS) is available as an option. This 19" rack mount device is a MODBUS slave that interfaces directly to a plant DCS system and allows real time scanner data to be downloaded into the DCS system via an RS-232 or RS-485 MODBUS port. This allows scanner data to be presented to operating personnel using existing DCS monitors and displays. The SMCS is not required for normal scanner setup or operation and does not replace the dry flame contacts used for safety in the Burner Management System. Refer to Attachment 1 for a scanner network configuration.

Each SMCS can be connected to a maximum of 6 SafeFlame™ DFS chassis therefore; four SMCS would be required for this installation. The SMCS would be mounted in four of the DFS chassis NEMA 4 enclosures located in each of the boiler corners.

The price for four (4) optional SMCS is:

\$10,000 USD

(Ten Thousand US Dollars)

Option 3

The SMCS offered in option 3 has a digital output that can be connected to a Personal Computer rather than the DCS system. As an option, ABB offers a personal computer based data trending and data archiving software package, called *Flame Explorer*, which can be used with one or more SMCS. This package can be used to assist plant personnel in initial setup of the scanners and monitoring during routine operation. This optional software package is \$2,250 for a single client seat license.

The SafeFlame DFS modules can be programmed locally using the faceplate pushbuttons and display. The *Flame Explorer* software is not required for tuning the scanner system, rather it is only a tool to make tuning easier.

Option 4



If the scanners are properly located, redundant flame scanners should not be required for reliable flame detection. (see notes and clarifications below). However, if redundant scanners are desired the modified scope and pricing is:

ITEM	QTY	DESCRIPTION
1	96	SafeFlame™ Fiber Optic Flame Scanner: <ul style="list-style-type: none">• Cast aluminum housing• Visible light photodiode board assembly• 9 degree viewing angle lens• High Temperature fiber optic cable• ¼ turn stainless steel electrical quick disconnect on scanner
2	96	2" Ridged scanner guide pipe mounting assemblies <ul style="list-style-type: none">• Stainless steel centering tip• 2" schedule 40 pipe• Cast aluminum cooling/purge air manifold
3	96	Guide pipe packing gland: <ul style="list-style-type: none">• For use with 3" NPT burner front plate opening• Holds and seals 2" scanner guide pipe
4	96	Flame scanner connector cable assembly: <ul style="list-style-type: none">• ¼ turn stainless steel connectors, one end• 50 foot scanner wire pigtail length• ½" NPT connection for installation in liquidtight conduit• Connector connection potted
5	32	SafeFlame™ DFS front access chassis each consisting of: <ul style="list-style-type: none">• Three (3) DFS sensor modules• Two (2) blank module• One (1) 115 VAC DFS power supply module• One (1) front access 19" wide rack mount DFS chassis
6	16	SafeFlame DFS chassis enclosure: <ul style="list-style-type: none">• NEMA 4 construction• Door window kit• Two (2) DFS chassis (item 5) factory mounted
7	9	SafeFlame™ DFS Instruction Manuals

The price for the material detailed in the option 4 furnished upon request.



Option 5

Safe Flame DFS Spare Parts are offered at a 25% discount if purchased on the same purchase order as the flame scanner system. The major spare parts and quantities recommended for the base scanner system is shown in Table 1 along with the list price and 25% discounted price. The scanner head delivery is typically less than 5 weeks with the rest of the components in stock, available for next day delivery.

Table 1 – Scanner System Spare Parts

Quantity	Item Description	Part Number	Per Unit List Price	Unit Price 25% off list price	Total Price
4	Visible Light Scanner	C10-922XX-LP	\$1,710.00	\$1,282.50	\$5,130.00
6	Cable/Connector Assembly	C10-97252	\$291.00	\$218.25	\$1,309.50
4	DFS Sensor Module Assembly	C86-94639	\$1,010.00	\$757.50	\$3,030.00
3	DFS Power Supply	C86-80741	\$800.00	\$600.00	\$1,800.00
6	4 amp pico fuses	C32-32012	\$4.20	\$3.15	\$18.90
Total =					\$11,288

Price escalation on flame scanner replacement parts through 2010 is nominally 1% per year. In addition the recommend spare parts, a detailed parts list is in Attachment 4.

NOTES AND CLARIFICATIONS

1. ABB experience on multiple air zone, wall fired coal burners has been that the coal flame flicker frequency is much stronger in the inner air zone vs. any outer air zones. Since background flicker frequencies do not change with the inner or outer air zone scanner locations, any increases in measured flame flicker frequency improve the overall scanner performance and makes the flame detection more robust. Therefore, ABB recommends the flame scanners be installed in the inner air zone.
2. The selection of one visible light scanner fiber optic scanner for both oil and coal flame detection is based on the premise that; the oil flame shape and "color" does not change dramatically during the transition between oil flame with no primary air (PA) flow to oil flame with primary air flow. ABB has observed on some coal burners with center mounted



oil lighters a dramatic change in the oil flame when PA is introduced. The oil flame changed from a standard, turbulent oil flame, to a "gas like" laminar flow flame. When a change like this occurs a visible light scanner is not the best choice for the oil lighter. When this occurs a second, UV flicker scanner, should be added for oil flame detection. Based on phone discussion between yourself and our Product Manager, Jim Niziolek, this oil flame shape does not occur with the Advanced Burner Technologies Design and therefore, a single scanner for both oil and coal will suffice for this application.

3. For this application ABB would recommend a nominal scanner purge airflow of 20 SCFM at 3 IN-WC static pressure. The purge/cooling air specification for the existing ABB FLAMON UW scanners calls for 15 SCFM at 10 IN-WC above furnace pressure. On past FLAMON to SafeFlame fiber optic scanner retrofits the existing purge air system has been more than sufficient to keep the scanners cool and the existing fans have not been changed. Therefore, if the existing scanner air system provides clean purge air it should not need to be replaced with the 48 scanner system. ABB would however, like the opportunity to review the existing scanner fan specifications to insure the capacity is sufficient.
4. Detailed temperature specifications for the flame scanner fiber cable, scanner head, and electronics is in Attachment 1.
5. Ten time per second the DFS sensor module runs system diagnostics from the scanner head photodiode to the microprocessor A/D converter. In the unlikely event a problem is detected the flame relays in that sensor module will de-energize and a fault will be indicated on the face of the scanner sensor module. These diagnostics include:
 - 5.1. ROM memory (on power up)
 - 5.2. RAM memory (on power up)
 - 5.3. Positive power supply low
 - 5.4. Negative power supply low
 - 5.5. A/D failure
 - 5.6. Sensor positive supply short
 - 5.7. Sensor negative power supply short
 - 5.8. Input signal high
 - 5.9. No input signal
 - 5.10. Frequency over range
6. The highest background flicker frequencies are created from opposed wall lighters during initial start-up of the boiler. As coal is introduced into the boiler the background flicker decreases to 0 Hz. The SafeFlame DFS Sensor module has two flame relays. If desired, one flame relay can be set with trip points commensurate with the background conditions observed during start-up while the other can be adjusted for conditions observed during normal coal operation. In this fashion the scanner system will provide the flame discrimination required while allowing the system to be as forgiving as possible to firing system perturbations or flame shape changes.



7. There are no specific routine maintenance requirements. Scanner maintenance is basic:
 - 7.1. As needed – If scanner intensity drops within 10% of the trip point, the scanner should be removed and the lens cleaned. If clean purge air is supplied to the scanner, this cleaning may not be needed except as a preventative measure after an extended outage.
 - 7.2. During outages
 - 7.2.1. If burner work is to be performed removed scanner to avoid mechanical damage
 - 7.2.2. Inspect and clean lenses if necessary after and extended outage
 - 7.2.3. Periodically blow dirt and dust from electronics
 - 7.2.4. Periodically check tightness of all terminations
8. One or more of the following technical personnel will supply support to the proposed scanner system design:

Jim Niziolek	Product Manager	860-285-6775	27 years experience
Paul Chase	Chief Engineer, Scanners	860-285-6762	35 years experience
Bill Clark	Production/Quality Manager	860-285-9402	25 years experience
Arnie Piellucci	Project Engineer	860-285-6871	25 years experience

EXCLUSIONS

The following items are not included as part of this offer and are the responsibility of others.

- Mounting, installation, and wiring of new hardware
- Connection of the scanner flame outputs to the BMS system
- Scanner cooling air system piping
- Guide pipe installation in burner
- BMS system changes

REFERENCE LIST

A list of user contacts is in Attachment 3.

DELIVERY

Standard delivery is 10-12 weeks ARO. Expedited delivery may be available depending on shop loading at time of order.



TERMS

Payment terms are net 30 from invoice. Invoices to be issued upon shipment.

Standard ABB Inc. Terms and Conditions apply and are attached.

Pricing quoted is subject to acceptance within 120 days of date of quotation.

Prices include shipping (except freight for spares will be pre-paid & billed at cost).

I thank you for this opportunity to quote our SafeFlame™ DFS System for your coal fired application. If you have any questions on this offer or other questions regarding the scanner system hardware, please feel free to call me at 860-285-6895 or our Product Manager, Jim Niziolek at 860-285-6775.

Respectfully Submitted,

Sam Good
Proposal Specialist

ABB Inc
2 Waterside Crossing
Suite 200
Windsor, CT 06095

**ATTACHMENT 2
2003 DOMESTIC FIELD SERVICES RATES**

ABB Inc. Utility Automation Service is pleased to offer site technical assistance at the following rates and conditions of payment.

The services described above are offered at the per diem rate of \$1360 per normal work day. A normal work day is defined as the first eight (8) hours worked during any day from Monday to Friday. A minimum charge of eight (8) hours is applicable for every normal work day commencing from the initial travel day to the purchaser's site and ending on the final travel day at the conclusion of the site assignment. Initial and final travel time is billable at the normal work day rate, regardless of what day of the week or what time of the day the travel actually occurs. Eight (8) hours will be billable per normal work day even if the field service engineer is directed or requested to stand by locally. The overtime rate is 1.5 times the normal work day rate or \$255 per hour. Overtime is defined as any work performed in excess of eight (8) hours during any work day and all hours worked on Saturdays and Sundays. The overtime rate applies to all work performed except Sundays, New Year's Day, Memorial Day, Independence Day, Thanksgiving Day and Christmas Day. Two (2) times the normal work day rate or \$340 per hour applies to all hours worked on Sundays and those specific holidays.

For extended assignments, i.e., durations in excess of three (3) months, the service engineer shall be entitled to home leave every five (5) weeks. Home leave shall include four (4) days off, i.e., two working days and two weekend days. All travel and living expenses, as well as, other miscellaneous expenses, will be billed at actual cost. These costs shall include airfare, meals, car rental, hotel, etc.

Payment shall be 30 days upon receipt of invoice. Invoicing shall be on a monthly basis. This offer is valid for a period of sixty (60) days from this date. ABB Inc. "General Terms and Conditions of Sale" apply to this offering. A copy is attached to this document.

ABB Inc. requires a minimum of thirty (30) days advance notice of actual dates for which service is required in order to assure that appropriate resources are allocated and assigned. ABB Inc. will make every reasonable effort to accommodate accelerated needs, schedule changes and to respond to emergency "on demand" requests for site service.

ATTACHMENT 3
REFERENCE LIST FOR ABB INC. SAFE FLAME™ DFS FLAME SCANNER SYSTEMS

<u>Contact</u>	<u>Utility and Plant(s)</u>	<u>Application/Fuel</u>
Kevin Williams 563-262-2888	MidAmerican Energy Louisa Installed 2002	B&W Opposed Wall Coal w/oil & gas lighters
Jim Parsons 816-556-2162	Kansas City Power and Light Iatan Installed 2000	B&W Opposed Wall Coal with oil lighters
Jack Dabbs 770-854-4441 x464	Georgia Power Plant Wansley Installed 2001	T-Fired Coal
Ron Wolfe 270-844-6035	Western Kentucky Energy Greene #2 Installed 2001	B&W Opposed Wall Coal w/oil lighters
Ed Hutchins 405-553-5245	Oklahoma Gas & Elec. Mustang/Horseshoe Lake Installed 1999 and 2000	Wall, T-Fired, GT Gas
Art Bocchino or Bill Smith 319-262-3588	Muscatine Power and Water Unit 8 Installed 2000	Cyclone, TFired Coal
Travis Ray 970-229-1697	Platte River Power Authority Installed 2000	T-Fired Coal
Richard Winkler 314-554-4214	Ameren Sioux Plant Installed 1999	Cyclone Coal
Gary Dove 505-537-4119	Phelps Dodge Units 7 & 8 (1x1 and 3x3) Installed 1998	Wall Gas
Ross Childs	Western Resources, Gordon Evans Unit 2	Wall

316-291-8666	Installed 1998	Gas/Oil
Mario Amaya 210-978-3629	CPS San Antonio, Victor Braunig 1,2, 3 Installed 1998	T-Fired Gas/Oil
Grant Numberg 918-581-0842	P.S. Oklahoma Northeastern Station Installed 1996, 1997	T-Fired Coal
Jim Clark 516-391-6123	Long Island Lighting Co. Barrett Station Installed 1994, 1997	T-Fired Oil/Gas
Brad Zimmerman 701-873-2571	Montana-Dakota Utilities Coyote Station Installed 1997	Cyclone Coal
Gary Hausman 610-498-6247	Pennsylvania P&L Martins Creek Installed 1995	T-Fired Oil/Gas
Harold Edwards 913-331-4700	Western Resources Lawrence Station Installed 1994	T-Fired Coal/Gas
Mickey Kinney 816-325-7516	Independence P&L Blue Valley Station Installed 1994	T-Fired Coal/Oil/Gas
Stan Saska 860-848-6018	Northeast Utilities Montville Station Installed 1994	T-Fired Oil
Frank Lyter 610-774-6046	Pennsylvania P&L Brunner Island Installed 1993, 1994	T-Fired Coal

11/15/02

IP7_031372

ABB INC.
Utility Plant Automation
2 Waterside Crossing
Suite 200
Windsor, CT. 06095
Fax: (860) 285-6999

ATTACHMENT 4 - Spare Parts Listing for SafeFlame Fiber Optic DFS Scanner Systems
Plant: Intermountain Power
Proposal Number U030304

Description	Part No.	Unit Price
Head Assy (wide viewing angles)	C10-97248	\$ 226.00
Collimator Tube	C65-91960	\$ 78.00
Body (wide viewing angles)	C63-97311	\$ 99.00
Lens (Visible Light)	C35-90398	\$ 26.00
Spacer (9840475)	C65-91966	\$ 14.00
Lens Barrel Assembly (9 degree)	C10-97326	\$ 291.00
Mounting Plate	C52-91948	\$ 40.00
Compression Spring (wide viewing angles)	C68-10317	\$ 13.00
Jam Nut	C08-95061	\$ 1.60
Plug	C65-91967	\$ 62.00
Fiber Optic Cable, hi temp 110"	C99-94501	\$ 244.00
Scanner Flex Hose, 72"	C64-97256	\$ 126.00
Housing Electronics Card Visible Light (Replaces C87-92525 & C10-97261)	C10-24112	\$ 490.00
Electrical Connector Gasket	C69-97363	\$ 3.55
Connector/Cable assembly, 50 ft	C10-97252-50	\$ 352.00
Connector w/pre-wired header Replaces (C36-92130)	C36-92146	\$ 72.00
Protector Plate	C63-97260	\$ 18.00
Screws 8-32x0.19 (bag of 5)	C08-95192	\$ 5.20
Sensor Module Assembly	C86-94639	\$ 1,010.00
Sensor Relay/Board	C86-94644	\$ 870.00
Display Board	C86-94612	\$ 175.00
Power Supply 110/220Vac	C86-80741	\$ 800.00
Fuse 4 Amp	C32-32012	\$ 4.20

IP7_031373

**SAFE FLAME™ DFS FIBER OPTIC SCANNERS FOR:
WALL FIRED OR TILTING TANGENTIAL FIRED COAL BOILERS**

SAFE FLAME™ DFS TECHNOLOGY

Flame Scanners are a crucial part of a boiler's safety system. Their primary function is to identify potentially dangerous "flame out" conditions where ignition has ceased and continued addition of fuel could cause an explosion. Because of the flame scanner importance, they must be extremely reliable and rugged.

Safe Flame™ technology has been reliably in use since 1982 with over eleven thousand (11,000) scanners installed. Safe Flame™ DFS is the newest generation of this technology. It incorporates the speed and precision of digital signal processing, which makes it the finest flame scanner available.

SAFE FLAME™ DFS FLAME SCANNER SYSTEM DESCRIPTION

All Safe Flame™ DFS Flame Scanner Systems have four major components.

1. Flame scanner mounting hardware which is affixed to the burner front
2. Flame scanner head, which mounts on the burner/windbox. The scanner head converts the light energy from the burner flames into electrical signals.
3. A quick disconnect electrical connector/cable assembly transmits the analog scanner signal to a flame scanner electronics chassis. If the chassis is located more than 100 feet from the scanner head a local junction box is used for spicing to flame scanner extension cable.
4. The Safe Flame™ DFS Scanner Chassis holds the system power supply and the microprocessor based DFS flame sensor modules. The electrical signal from each flame scanner head is monitored and analyzed by a DFS Flame Sensor Module, which determines if the flame scanner is seeing a stable flame. Flame safety contacts, analog outputs, and digital outputs are all made available to the boiler operators from terminal strips on the backplane of the Safe Flame™ DFS chassis.

A typical scanner installation is shown in Figure 1.

FLAME SCANNER FOR PULVERIZED COAL FIRING

The recommended ABB Inc. flame scanner for pulverized coal applications is the Safe Flame™ visible light, through the windbox fiber optic scanner. On wall-fired boilers where flame discrimination is required, a wide viewing angle lens is used. A ridged guide pipe is supplied for penetration into the wall-mounted burner. On a tilting tangential fired unit a narrow viewing

angle lens is used to discriminate warm up oil guns and prove coal fireball flame. On tilting tangential fired units the scanner guide pipe is flexible to allow the scanner to tilt up and down with the corner burners. All other scanner and system components are the same.




Figure 1 – Typical Flame Scanner Installation

FLAME SCANNERS FOR CYCLONE BURNER

For cyclone burners the ABB SafeFlame™ wall mounted fiber optic flame scanner is recommended. Cyclone burners are notorious for the extreme temperatures on and immediately adjacent to the burners making scanner survival difficult, even for the most rugged scanners. To accommodate these high temperatures the SafeFlame™ wall mount fiber optic scanner uses a high temperature fiber optic cable to allow the scanner electronics to be removed away from the cyclone. Fiber cables are available in 110' or 360' (30 foot) lengths.

THROUGH THE WINDBOX FIBER OPTIC FLAME SCANNER ASSEMBLY

The ABB Inc. Safe Flame™ through the windbox fiber optic flame scanner is a rugged, high temperature flame scanner designed for use on coal and/or oil wall fired boilers. This multi-fuel scanner reliably discriminates individual burner flames over background radiation and detects unstable operation and flame out conditions.

The scanner is a visible light scanner and is available with different viewing angles to accommodate the firing of pulverized coal, oil or a combination of both fuels. The purpose for fiber cable is to allow the focusing lens to be brought closer to the burner front allowing an unobstructed field of view for the scanner. On wall-fired boilers this allows the scanner optics to focus on the near field burner flame while averaging out the light pulsations created from background flames. This combination of fiber optics and lensing provides unsurpassed flame discrimination capabilities. On tangential fired boilers, a narrow viewing angle lens is used to allow the scanner to look deep into the furnace, providing strong fireball flame flicker frequency even at low load operation. As with all Safe FlameTM scanners, the Fiber Optic Flame Scanner has been ruggedly designed for years of reliable service in the power plant environment. Refer to Figure 2.




Figure 2 – Safe FlameTM Wall Fired Fiber Optic Scanner

The scanner stainless steel optical head houses a lens assembly that couples the light energy from an oil or coal flame into a high temperature fiber optic cable. Refer to Figure 3. The fiber optic cable assembly consists of a fiber bundle encapsulated in a 3/8" stainless steel over-braid flex jacket. The fiber optic cable is installed in a 1/2 inch outer stainless steel flex hose and 1/2 inch schedule 40 pipe connected to a rugged cast aluminum housing. The fiber optic cable is terminated at a photodiode/electronics card mounted in the aluminum housing. The scanner stainless steel optical head assembly is rated for 900 °F (480 °C) operation, whereas the signal conditioning aluminum housing is rated at 140 °F (60 °C).

All scanners are supplied with a standard length fiber optic cable. Changing the length of the flex hose and the ridged pipe sets the overall length of the scanner assembly. No special length fiber cable is required as excess fiber cable is simply coiled inside the aluminum housing. This makes scanner spare parts compatible between plants.




Figure 3 - Details of Scanner Head

The fiber optic cable transmits the light from the optical head to a photodiode/electronics card, which converts the collected light energy into an electrical flame signal. The photodiode circuit has a dynamic light range of 10^5 that makes the scanner very sensitive to combustion flame throughout the entire operating range of the burner.

Refer to Figure 4 for a typical installation in a coal-fired wall burner. Refer to Figure 5 for a tilting tangential fired burner installation.




Figure 4 - Typical Fiber Optic Scanner Installation - Wall Fired Burner

Installation of the Fiber Optic Flame Scanner is accomplished by inserting the scanner down the flexible or ridged guide pipe, which is installed through the burner windbox. Once installed in the guide pipe the scanner head has excellent visual access to the combustion flame. The end of the guide pipe has a cooling air inlet tee for purge/cooling air. Nominally 30 SCFM at 6" WG is recommended to keep the guide pipe free and clear of slag or ash and keep the scanner head cool.




Figure 5 – Typical Fiber Optic Scanner Installation – T-Fired Burner

WALL MOUNTED FIBER OPTIC SCANNER

As noted above, the SafeFlame™ wall mounted fiber optic scanner is recommended for cyclone burners due to the high temperature at the cyclone. This scanner uses the same fiber optic cable, lens, electronics board, and connector as the through the windbox scanner allowing for compatibility of spare parts. An optional 30-foot fiber optic cable is available for those installations where it is desirable to remote the electronics even further from the cyclone. Refer to Figure 6.




Figure 6 -Wall Mount Fiber Optic Scanner for Cyclones

FLAME SCANNER ELECTRICAL CONNECTOR/CABLE ASSEMBLY

For ease of maintenance all Safe Flame scanner heads have a bayonet style 5-pin connector. To insure long-term reliability the electrical connections are potted at the factory. Standard cable lengths from the connector are 8', 25', 50', and 100'. The other end of the cable (or "pigtail") has bare wires for connection to scanner extension wire in a junction box, or connection to a Safe Flame™ chassis. Where the cable exits the connector there is a 1/2" FNPT thread so the "pigtail" can be installed in liquid tight, flexible electrical conduit.

SAFE FLAME™ DFS ELECTRONICS CHASSIS

All Safe Flame scanner heads produce an analog current signal that is input into a remotely mounted Safe Flame™ DFS Electronic chassis. The chassis can be mounted up to 5,000 feet from the flame scanner. The DFS chassis holds the power supply, the scanner Sensor Modules, an optional 2/4 logic module, and the field terminal strips for system I/O. The scanner system AC power, flame scanner input signals, sensor module flame contacts, analog, and serial outputs signals are all distributed through the chassis backplane and are available on the field terminal

strips. Each scanner heads requires one DFS Sensor Module and one chassis can support up to four DFS Sensor Modules.

A four-channel rear DFS Electronics Chassis is illustrated in Figure 7. It can be seen that four DFS Sensor Modules, an optional 2/4 Logic Module and a Power Supply Module are "plugged" into a 19" rack with a back plane. The setup is designed to be modular to ease serviceability by technicians.




Figure 7 - Safe Flame™ DFS Rear Access, 4 Channel Chassis

Safe Flame DFS scanner chassis are available in front access or rear access design. With the rear access design the chassis is 19" rack mounted with field terminations at the rear of the chassis. A front access chassis is twice as high (10.5"), panel mounted, with access to the field terminations from the front of the chassis. The field terminals face the front and are covered by an aluminum fold down door. One either side plate is a 3" diameter opening for wire feed to the terminals. Refer to Figures 8 and 9 for photos of a rear and front access chassis.

OPERATION

The Safe Flame™ DFS Sensor Module is self-checking 10 times per second, from initial power "on" through normal operation. If no faults are detected, the previously programmed user trip points are loaded in from non-volatile memory and normal operation begins. If any failures are detected, a fault condition is generated.




Figure 8 – Rear Access Safe Flame DFS Chassis




Figure 9 –Front Access Safe Flame DFS Chassis

The scanner head transmits the flame signal to the microprocessor in the DFS Sensor Module. The Sensor Module examines the flame signal two thousand (2,000) times a second, measuring the flame intensity and flame flicker frequency. The measured intensity and flicker frequency are compared to user programmed trip points. If both the intensity and frequency exceed their respective trip points, flame is proven and the flame relay is energized. The flame scanner trip

points are determined during initial system tuning and programmed using easy to follow prompts. Sophisticated proprietary software is used to extract the flame flicker frequency and intensity information.

If either the measured flame flicker frequency or the measured intensity drops below the programmed trip points for more than the user settable time-delay period, the flame relay (and the TTL flame signal) will de-energize indicating a flame failure.

A second relay is provided on the DFS Sensor Module. A hardware jumper sets the function of this relay. It can be used as a second, independently programmed flame relay, or can be used as a fault relay. If the relay is used for fault indication it will be energized whenever the system is working correctly. If any system fault is detected the relay is de-energized and both a fault code and a short message are displayed on the front panel. If used as a second flame relay it will be energized when the flicker frequency and intensity both exceed the second set of trip points programmed into the DFS Sensor Module.

An optional 2/4 Module is available for installation in the DFS chassis. This module has 2 relays that are output to the back plane terminal strips. If two of the four DFS Sensor Modules in the chassis are proving flame one of the relays will energize. This relay output is typically used for fireball flame monitoring control logic on tilting tangential fired boilers. The second relay is a fault relay and is normally energized. If any DFS Sensor Module in the chassis goes into a fault mode this relay will de-energize as an operator warning.

SENSOR MODULE COMMUNICATION SERVER (OPTION)

Each DFS sensor module has an RS-232 output that carries over 25 pieces of information on the scanner. Function settings, fault status, operating parameters, and channel identifiers are all available through this serial output. A connector on each DFS chassis has all 4 RS-232 signals from each Sensor Module in the chassis.

The Safe FlameTM Sensor Module Communication Server (SMCS) is a sample hold digital multiplexor that can be connected via ribbon cables to six DFS chassis. Once per second the SMCS samples each DFS Sensor Module and stores all data available on the serial line.

A switch selectable serial output on the SMCS (RS-232 or RS-485) is configured as a MODBUS® slave and can be plugged into a DCS, BMS, or personal computer. MODBUS® commands are issued from the host to selectively download data for operator display. If a personal computer is used, ABB Inc. offers a data display, trending, and programming package called *Flame Explore* for use with Safe Flame DFS scanner system.

A typical SMCS configuration is shown in Figure 10.




Figure 10 - SMCS Configuration

FLAME EXPLORER SOFTWARE (OPTION)

ABB Inc. offers an optional flame scanner data trending and archiving software package that runs on a personnel computer connected to one or more SMCS. This package, called *Flame Explorer*, can be used to assist plant personnel in initial setup of the scanner system and monitoring during routine operation. The package can be used on a single SMCS (up to 24 scanners) using the RS-232 output or can be used with multiple SMCS daisy chained together using the RS-485 output.

Flame Explorer allows the user to trend in real time, the two measure parameters (DC intensity and Flicker Frequency) for each scanner. One to four scanners can be displayed simultaneously and are selected using simple drop down boxes. Data from any or all of the scanners can be archived using a simple channel selection sheet. Although the software is not required for scanner set-up, it can be used to remotely configure each scanner or a group of scanners. An ID password installed in the software and a hardware jumper on the Safe Flame DFS sensor module locks out programming capability to keep unqualified personnel from adjusting the flame scanners. Figures 11 and 12 show some of the screens available with *Flame Explorer*.




Figure 11 – Trend graph for one flame scanner




Figure 12 – Trend graph from four flame scanners

GENERAL SPECIFICATIONS**Safe Flame™ DFS Chassis and Power Supply**

- Environmental: 0 to 60°C (32°F to 140°F) non-condensing
- Chassis Input Voltage: 120/240 (+10%) VAC @ 45 to 65 Hz
- Power Input Protection: Metal oxide varistor/input circuit breaker/fuse
- Chassis Mounting Position: Restricted to horizontal position, canted position prohibited

Safe Flame™ DFS Sensor Module

- Environmental: 0 to 60 °C (32 °F to 140 °F) non-condensing
- Microprocessor: Motorola MC68HC11E1FN (2M Hz)
- A/D Converter: 12 bit, 2000 Hz sample rate w/10μ second settling time
- Visual Outputs: 10 Element LED Bar and
4 Character Alpha-Numeric Display
- Contact Outputs: Qty 2, Form C
- Contact Rating Switched Load: 2 A Maximum
500 V Maximum
100 VA Maximum
- Contact Rating Inrush Current: 20 A for 10 microseconds
4 A for 10 seconds
2 A for 100 seconds
- TTL Outputs: Qty 3, Open Collector
- Digital Output: RS-232, VT100 Terminal Compatible
- Analog outputs: Qty 2, Isolated 4-20 ma, non-isolated 0-1 ma
- Digital Output: RS-232, VT100 Terminal Compatible
- Analog outputs: Qty 2, Isolated 4-20 ma, non-isolated 0-1 ma

Safe Flame™ DFS 2/4 and Chassis Fault Module (optional)

- Environmental: 0 to 60 °C (32 °F to 140 °F) non-condensing
- Contact Outputs: Qty 2, Form C
- Contact Rating Switched Load: 2 A Maximum
500 V Maximum
100 VA Maximum
- Contact Rating: Inrush Current: 20 A for 10 microseconds
4 A for 10 seconds
2 A for 100 seconds

Through The Windbox Fiber Optic Flame Scanner

- Electronics Ambient Temp: -18 to 60° C (0 to 140 °F)
- Fireside Scanner Head Temp: 482° C (900 °F)
- Nominal length: 33 to 126"
- Max Diameter: 5"
- Purge/Cooling air: 30 SCFM @ 6" wg
- Mounting: Twist lock to end of 2" guide pipe
- Electrical Supply: +/- 15 Vdc, nominally 100 ma
- Output: 0 to 2 ma
- Dynamic light range: 10⁵ fixed
- Connector: Stainless Steel ¼ turn connector with ½" NPT
- Photodiode: Visible light or Infrared
- Photodiode Response Range: Visible light - 450 to 700 nm, Infrared - 700 to 1100 nm
- Fuels: Oil, Coal or any combination of the two

Wall Mount Fiber Optic Flame Scanner (Cyclones)

- Electronics Ambient Temp: -18 to 60° C (0 to 140 °F)
- Fiber Optic Cable Max Temp: 482° C (900 °F)
- Lens O-ring Max. temp: -54 to 232° C (-65 to 450° F)
- Nominal length: -54 to 232° C (-65 to 450° F)
- Fiber cable length: 110" or 360"
- Purge/Cooling air: 6-10 SCFM
- Mounting: 1" cam groove
- Electrical Supply: +/- 15 Vdc, nominally 100 ma
- Output: 0 to 2 ma
- Dynamic light range: 10⁵ fixed
- Connector: Stainless Steel ¼ turn connector with ½" NPT
- Photodiode: Visible light or Infrared
- Photodiode Response Range: Visible light - 450 to 700 nm, Infrared - 700 to 1100 nm
- Fuels: Oil, Coal or any combination of the two

Contact


For additional information, pricing, and delivery contact your local ABB representative or:

ABB Inc.
Utility Plant Automation
2 Waterside Crossing
Suite 200
Windsor, CT. 06095

Mr. Jim Niziolek
Product Manager, Boiler Sensors
Phone: 860-285-6775
E-mail: james.m.niziolek@us.abb.com

ITEM NO.	QTY.	PART NUMBER	DRAWING NO.	DESCRIPTION
1	1	C13-94588	D-28-B-1181	FRONT ACCESS CHASSIS SUB-ASSEMBLY
2	1	C86-88741	B232855-B14	POWER SUPPLY MODULE
3	1	C86-88742	B232855-B15	2/4 FLAME AND FAULT ALARM MODULE
4	1	C86-84639	B232855-B16	SENSOR MODULE
5	1	C86-88739	D232856-B85	BLANK MODULE
6	1	C86-92834	B232856-B38	DATA PLATE

* SEE NOTE 3
** SEE MODULE SELECTION
TABLE FOR QUANTITY.



SEE NOTES NO. 1 & 2

SEE NOTE 4

CHASSIS PART NO. & BLANK MODULE SELECTION TABLE									
TYPE	ASSEMBLY PART NO.	REC'D ITEM NO.	SLOT LOCATION	QTY	ITEM 4	SLOT LOCATION	QTY	ITEM 5	SLOT LOCATION
1	C13-94588	1	5	4	1,2,3,4	NONE	NONE	NONE	NONE
2	C13-94588-228	1	5	4	1,2,3,4	NONE	NONE	NONE	NONE
3	C13-94587	0	---	4	1,2,3,4	1	5	---	---
4	C13-94587-228	0	---	4	1,2,3,4	1	5	---	---
5	C13-94588	0	---	3	1,2,3	2	4,5	---	---
6	C13-94588-228	0	---	3	1,2,3	2	4,5	---	---
7	C13-94588	0	---	2	1,2	3	3,4,5	---	---
8	C13-94588-228	0	---	2	1,2	3	3,4,5	---	---
9	C13-94539	0	---	1	1	4	2,3,4,5	---	---
10	C13-94539-228	0	---	1	1	4	2,3,4,5	---	---
11	C13-94511	1	5	3	1,2,3	1	4	---	---
12	C13-94511-228	1	5	3	1,2,3	1	4	---	---

NOTES

- FOR BACK PANEL MOUNT (INSTEAD OF RACK MOUNTING AS SHOWN) (A) (2) VERTICAL PROFILE, ELMA #68-173-36, (B) MAXIM SCREWS, ELMA #68-173-36, (C) 3/4" HEX NUTS ELMA #1887-59, MOUNTING KIT PART NO. C13-94824.
- REAR PROFILE MOUNTING HOLES SAME AS FRONT PROFILE (ITEM NO. 3).
- IF BLANK MODULES ARE REQUIRED SEE THE BLANK MODULE SELECTION TABLE ABOVE FOR ITEMS 4, 5 AND 6 QUANTITIES AND LOCATIONS.
- UNLESS SPECIFIED OTHERWISE, A TYPE 1 CHASSIS, P/N C13-94586, IS THE STANDARD FRONT ACCESS CHASSIS SUPPLIED FOR USE ON TANGENTIAL FIRED BOILERS.
- SWITCH ON POWER SUPPLY PC BOARD ENABLES 115V OR 230V OPERATION.
- CENTER DATA PLATE ON INSIDE COVER SO INFORMATION CAN BE READ WITH COVER DOWN.

REF. ENG.


EXTERNAL CONNECTION DIAG. FRONT TERMINALS - D-28-B-8118

SAFE FLAME™ OFS
FINAL CHASSIS ASSEMBLY FRONT ACCESS

THIS DRAWING IS THE PROPERTY OF
ABB
HARTFORD, CONNECTICUT U.S.A. 06183

DATE: 11/1/88
DRAWN BY: J. J. JONES
CHECKED BY: J. J. JONES
APPROVED BY: J. J. JONES

CE, TUV, OR CSA
SENSITIVE



IP7_031390

VAP³™ Designed by Bob Brandt for

EP EASTERN INSTRUMENTS

VAP³™ /PA



Industrial Velocity Averaging Parallel Plate Pitot for Heavy Particulate Applications

The VAP³™ airflow measurement system is ideal for either new or retro-fit industrial applications where the air-stream is heavily laden with particulate. When inserted to traverse a duct or conduit, the VAP³™ provides an accurate, differential pressure output signal allowing for precise airflow measurement or control of your process.

Due to its unique Velocity Averaging and Parallel Plate patented design, with all pressure sensing holes facing away from the direction of flow, the VAP³™ can be installed in locations where heavy particulate and random flow distribution is present. Each VAP³™ probe has multiple differential pressure sensing ports, specifically

located to provide a full traverse of the duct. For larger ducts, an array of probes with differential pressure lines separately manifolded, can be installed to ensure a fully averaged airflow sampling. The VAP³™ primary flow sensor is erosion and corrosion resistant, capable of withstanding process temperatures from -40 to 700°F. The VAP³™ probe is constructed from a single piece series 6063 aluminum extrusion with a Teflon hard anodized metallurgical bond applied, yielding a surface hardness of Rockwell 65C. The VAP³™ is ideally designed for primary and secondary airflow in a power plant where fly ash carryover is present.

The Technology

To accurately measure the randomly distributed airflow through a duct, the VAP³™ patented dual chamber design (Figure 1) incorporates a multi-sensing point configuration; patent #5,402,687. The VAP³™ generates a differential signal with the high pressure (P_H) ports located on the trailing edge and the low pressure (P_L) ports located on the parallel surfaces, normal to the flow. Existing duct insertion flow measurement technology cross-sectional area designs create vortices, which tend to allow particulate buildup on the trailing edge surfaces. The VAP³™ cross-section design generates negligible vortices, allowing air to flow without turbulence across the surface of the VAP³™, ensuring no particulate buildup where the sensing ports are located (Figure 2).

In existing multipoint Pitot configurations, dramatic measurement errors can occur when random flow distribution of

airflow is found within the duct. For example, a 37% difference in air velocity across the duct will exhibit an error of 7% in flow measurement output. To achieve the highest level of accuracy, each point of measurement's differential pressure should be individually square rooted within the differential pressure formula, whereas in existing multipoint Pitot technologic, the sum of the differential pressures is square rooted by nature of using a single differential pressure transmitter. The patented VAP³™ velocity averaging design compensates for this phenomenon; patent #5,753,825. By specifically shaping the inside of the high pressure ports, it reduces the exit coefficient, allowing the air to escape out of the measurement chamber easier than air enters. Therefore the varying high pressures entering the multiple ports of the chamber are more equalized, negating error. Now using the example above, a 37% offset in velocity variation across a duct yields only a 1/2% error.




Figure 1




Figure 2

IP7_031391

VAP³™ /PA

Industrial Velocity Averaging Parallel Plate Pitot for Heavy Particulate Applications

Product Features

Primary Flow Element. The VAP³™ provides a differential pressure signal output linear to flow, therefore there are no correction factors required in order to linearize the output signal. Accuracy is within $\pm 1\%$ (linearity and repeatability).

Velocity Averaging Technology. Through the use of patented specially shaped high pressure ports, the VAP³™ averages the extreme flow distribution to minimize pressure averaging error.

No Air Straighteners Required. The VAP³™ flow measurement system is designed to measure the normal vector of both the high and low pressure components thus negating the effects of airflow pitch and yaw up to 30°, which are found in highly turbulent flow locations.

Measures Accurately Independent of Velocity Changes. High and low pressure ports are located so that their associated pressure gradients do not vary with changes in velocity.


Durable Materials of Construction. The VAP³™ is constructed from extruded 6063 series aluminum with a final process Teflon hard anodized coating, yielding a durable surface hardness of Rockwell 65C.

Basic Installation. Each VAP³™ probe can be inserted into the duct utilizing a pre-fabricated weld on insertion port. When multiple probes are needed within the duct, the high and low pressure sensing ports can each be manifolded together.

Negligible Pressure Loss. Due to the streamline, narrow cross-section of the Parallel Plate Pitot design, the VAP³™ will not restrict the airflow, therefore there will be minimal, if not negligible pressure drop across the measurement area.


In Duct Sensors are Passive. There are no active, electronic components or moving parts that are installed within the air stream, therefore eliminating maintenance costs and ensuring reliability.

Installation




For Rectangular and Square Duct			
Y	Minimum QTY	Y	Minimum QTY
6" to 8"	1	38" to 60"	4
10" to 26"	2	62" to 116"	5
28" to 36"	3	118" +	Consult Factory

For Circular Duct	
D	Minimum QTY
6" to 18"	2
20" to 116"	3



Product Drawing with Dimensional Chart



Typical Flow Equations

$$Q_{PA} = 1097 \times A_p \times \left(\frac{\Delta P^{0.465}}{\rho^{0.5}} \right) \quad \text{where } A_p \approx 1.0 \times A_{Duct} \quad (A_p \text{ based on typical approach values in a 12" ID duct})$$

EP EASTERN INSTRUMENTS


416 LANDMARK DRIVE • WILMINGTON, NC 28412

Tel: 910-392-2490 • Fax: 910-392-2123

www.easterninstruments.com

IP7_031392

IP7_031393



Maintenance Enterprises, Inc
a Crown Enterprises Company

ADVANCED BURNER TECHNOLOGIES

**Installation of Low NOx Burners,
& Turning Vanes**

**Intermountain Power
Unit #3**

MEI Proposal # M-1912-MS


ORIGINAL

IP7_031394

TABLE OF CONTENTS

- I Pricing Page**
- II Safety (3 Years) & Insurance**
- III P-3 Schedule**
- IV Subcontractor List**
- V T & M Rates**
- VI Stamps "R", "S", "U"**
- VII Exceptions**
- VIII Clarifications**

IP7_031396



Maintenance Enterprises, Inc
a Crown Enterprises Company

August 20, 2003

Mr. Sal Ferrara
Project Manager
Advanced Burner Technologies
350 Main Street
Suite 5
Bedminster, New Jersey 07921

**RE: Intermountain Power Service Corp. – Unit #2
Low NO_x Project – Installation of 48 New Burners & Turning Vanes
MEI Proposal #M-1912-MS**

Dear Sal:

MEI is pleased to submit a lump sum bid in regard to the above-mentioned work. This bid is based on no ACM and/or lead paint. We have priced this bid based upon working one (1) ten hour shift, seven (7) days a week for two (2) weeks pre-outage. The outage is to be worked at one (1) ten (10) hour shift, seven (7) days a week, for twenty-eight (28) days.

Included in this bid is the following:

- Supervision
- Labor
- Pick-up trucks
- Welding supplies
- Two forklifts
- 3-8-pack welding machines
- Tool trailer
- Office trailer

Maintenance Enterprises, Inc. 703 E. Gardena Blvd. Gardena, CA 90248
Tel. (310) 329-0004 Fax. (310) 329-0006
www.Crownenterprises.com

IP7_031397

Mr. Sal Ferrara
August 20, 2003
Page Two

- Lunch trailer
- Equipment & tools
- QC supervisor
- Safety supervisor
- Insulation contractor
- Electrical contractor
- Port-A-Johns
- Telephones

Items to be supplied by ABT:

- Construction drawings
- All materials
- ABT representative as needed

Items to be supplied by Intermountain Power:

- Electricity – 480 3 phase/110 – 20 AMP
- Drinking water
- Service air to 90psi
- Location to place tool trailer
- Two telephone hook-ups (bills to be paid by MEI)
- Trash dumpsters
- Metal dumpsters

There is no state, federal, city, or county taxes in this bid.

This contract is contingent up acceptance by all parties.

If you should have any questions, please do not hesitate to contact me at your convenience.

Sincerely,




Mike Simonds
General Manager
Enc

Maintenance Enterprises, Inc. 703 E. Gardena Blvd. Gardena, CA 90248
Tel. (310) 329-0004 Fax. (310) 329-0006
www.Crownenterprises.com

IP7_031398

IP7_031399



Maintenance Enterprises, Inc.

A Crown Enterprises company

SAFETY INFORMATION

January 1, 2003

Number of OSHA Recordable Cases2000	4
2001	3
2002	3
Number of Lost Time Cases2000	0
2001	1
2002	0
Number of Lost Work Days2000	0
2001	1
2002	0
Number of Fatalities2000	0
2001	0
2002	0
Number of Manhours Worked2000	290,366
2001	1,089,167
2002	450,544
Total OSHA Recordable Incident Rate2000	2.76
2001	0.55
2002	1.33
Lost Time Incident Rate2000	0.00
2001	0.18
2002	0.00
Worker's Compensation Experience Modifier2000	0.58
2001	0.74
2002	0.70

IP7_031400

RECORD. CERTIFICATE OF LIABILITY INSURANCE		OP ID GB MAINT-1	DATE (MM/DD/YY) 11/04/02
Hibernia Rosenthal 411 Colonial Drive Baton Rouge LA 70896-6068 Phone: 225-381-8812 Fax: 225-381-8510		THIS CERTIFICATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND CONFERS NO RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE DOES NOT AMEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE POLICIES BELOW.	
INSURED Maintenance Enterprises, Inc. c/o Crown Enterprises, Inc. Debbie Dabadie PO Box 120 White Castle LA 70788		INSURERS AFFORDING COVERAGE INSURER A: Steadfast Insurance Co. INSURER B: Steadfast Insurance Co. INSURER C: Zurich American Insurance Co. INSURER D: INSURER E: Firemans Fund Insurance Co.	

COVERAGES

THE POLICIES OF INSURANCE LISTED BELOW HAVE BEEN ISSUED TO THE INSURED NAMED ABOVE FOR THE POLICY PERIOD INDICATED. NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THIS CERTIFICATE MAY BE ISSUED OR MAY PERTAIN, THE INSURANCE AFFORDED BY THE POLICIES DESCRIBED HEREIN IS SUBJECT TO ALL THE TERMS, EXCLUSIONS AND CONDITIONS OF SUCH POLICIES. AGGREGATE LIMITS SHOWN MAY HAVE BEEN REDUCED BY PAID CLAIMS.						
INSR LTR	TYPE OF INSURANCE	POLICY NUMBER	POLICY EFFECTIVE DATE (MM/DD/YY)	POLICY EXPIRATION DATE (MM/DD/YY)	LIMITS	
A	GENERAL LIABILITY	BOG9307179-00	11/01/02	11/01/03	EACH OCCURRENCE	\$ 1,000,000.
	<input checked="" type="checkbox"/> COMMERCIAL GENERAL LIABILITY				FIRE DAMAGE (Any one fire)	\$ 100,000
	<input type="checkbox"/> CLAIMS MADE <input checked="" type="checkbox"/> OCCUR				MED EXP (Any one person)	\$ 5,000.
	<input checked="" type="checkbox"/> Pollution				PERSONAL & ADV INJURY	\$ 1,000,000.
	GENL AGGREGATE LIMIT APPLIES PER:				GENERAL AGGREGATE	\$ 2,000,000.
	<input type="checkbox"/> POLICY <input type="checkbox"/> PROJECT <input type="checkbox"/> LOC				PRODUCTS - COMPROP AGG	\$ 2,000,000.
C	AUTOMOBILE LIABILITY	BAP9307177-00	11/01/02	11/01/03	COMBINED SINGLE LIMIT (Ea accident)	\$ 1,000,000
	<input type="checkbox"/> ANY AUTO				SOOPLY INJURY (Per person)	\$
	<input type="checkbox"/> ALL OWNED AUTOS				SOOPLY INJURY (Per accident)	\$
	<input type="checkbox"/> SCHEDULED AUTOS				PROPERTY DAMAGE (Per accident)	\$
	<input type="checkbox"/> TRD AUTOS				AUTO ONLY - EA ACCIDENT	\$
	<input type="checkbox"/> OWNED AUTOS				OTHER THAN EA ACC	\$
					AUTO ONLY: AGG	\$
I	EXCESS LIABILITY	EOG9307186-00	11/01/02	11/01/03	EACH OCCURRENCE	\$ 5000000
	<input checked="" type="checkbox"/> OCCUR <input type="checkbox"/> CLAIMS MADE				AGGREGATE	\$ 5000000
	<input type="checkbox"/> DEDUCTIBLE					\$
	<input checked="" type="checkbox"/> RETENTION \$ 10000					\$
	WORKERS COMPENSATION AND EMPLOYMENT LIABILITY				WC STATUTORY LIMITS	OTHER
					E.L. EACH ACCIDENT	\$
					E.L. DISEASE - EA EMPLOYEE	\$
					E.L. DISEASE - POLICY LIMIT	\$
	OTHER	MXI97851593	11/10/02	11/10/03	Per Item	500,000
	Rent/Leased Equip				Per Occur	1,000,000

DESCRIPTION OF OPERATIONS/LOCATIONS/VEHICLES/EXCLUSIONS ADDED BY ENDORSEMENT/SPECIAL PROVISIONS

Policies include Blanket Waiver of Subrogation, Additional Insureds and 30 day Notice of Cancellation where required by written contract.

DATE HOLDER	<input checked="" type="checkbox"/>	ADDITIONAL INSURED; INSURER LETTER:	BLANK-1	CANCELLATION
SAMPLE				SHOULD ANY OF THE ABOVE DESCRIBED POLICIES BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, THE ISSUING INSURER WILL ENDEAVOR TO MAIL <u>30</u> DAYS WRITTEN NOTICE TO THE CERTIFICATE HOLDER NAMED TO THE LEFT, BUT FAILURE TO DO SO SHALL IMPOSE NO OBLIGATION OR LIABILITY OF ANY KIND UPON THE INSURER, ITS AGENTS OR REPRESENTATIVE. AUTHORIZED REPRESENTATIVE

IP7_031401

ACORD. CERTIFICATE OF INSURANCE

DATE JAN/98
08-06-98

PRODUCER

LCTA - SIF
P.O. Box 1709
Baton Rouge, LA 70821-1709

THIS CERTIFICATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND CONFERS NO RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE DOES NOT AMEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE POLICIES BELOW.

COMPANIES AFFORDING COVERAGE

COMPANY
A LA Commerce & Trade Assoc.-SIF

INSURED

Maintenance Enterprises, Inc.
P.O. Box 120
White Castle, LA 70788

COMPANY
B

COMPANY
C

COMPANY
D

COVERAGES

THIS IS TO CERTIFY THAT THE POLICIES OF INSURANCE LISTED BELOW HAVE BEEN ISSUED TO THE INSURED NAMED ABOVE FOR THE POLICY PERIOD INDICATED. NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THIS CERTIFICATE MAY BE ISSUED OR MAY PERTAIN, THE INSURANCE AFFORDED BY THE POLICIES DESCRIBED HEREIN IS SUBJECT TO ALL THE TERMS, EXCLUSIONS AND CONDITIONS OF SUCH POLICIES. LIMITS SHOWN MAY HAVE BEEN REDUCED BY PAID CLAIMS.

CO LTR	TYPE OF INSURANCE	POLICY NUMBER	POLICY EFFECTIVE DATE (MM/DD/YY)	POLICY EXPIRATION DATE (MM/DD/YY)	LIMITS
	GENERAL LIABILITY <input type="checkbox"/> COMMERCIAL GENERAL LIABILITY <input type="checkbox"/> CLAIMS MADE <input type="checkbox"/> OCCUR <input type="checkbox"/> OWNER'S & CONT PROT				GENERAL AGGREGATE \$ PRODUCTS-COMP/OP AGG \$ PERSONAL & ADV INJURY \$ EACH OCCURRENCE \$ FIRE DAMAGE (Any one fire) \$ MED EXP (Any one person) \$
	AUTOMOBILE LIABILITY <input type="checkbox"/> ANY AUTO <input type="checkbox"/> ALL OWNED AUTOS <input type="checkbox"/> SCHEDULED AUTOS <input type="checkbox"/> HIRED AUTOS <input type="checkbox"/> NON-OWNED AUTOS				COMBINED SINGLE LIMIT \$ BODILY INJURY (Per person) \$ BODILY INJURY (Per accident) \$ PROPERTY DAMAGE \$
	GARAGE LIABILITY <input type="checkbox"/> ANY AUTO				AUTO ONLY - EA ACCIDENT \$ OTHER THAN AUTO ONLY: EACH ACCIDENT \$ AGGREGATE \$
	EXCESS LIABILITY <input type="checkbox"/> UMBRELLA FORM <input type="checkbox"/> OTHER THAN UMBRELLA FORM				EACH OCCURRENCE \$ AGGREGATE \$
A	WORKERS COMPENSATION AND EMPLOYERS' LIABILITY THE PROPRIETOR/PARTNERS/EXECUTIVE OFFICERS ARE: <input type="checkbox"/> INCL <input type="checkbox"/> EXCL	10536	01-01-98	Continuous until Cancelled	STATUTORY LIMITS EACH ACCIDENT \$ 1,000,000 DISEASE - POLICY LIMIT \$ 1,000,000 DISEASE - EACH EMPLOYEE \$ 1,000,000
	OTHER				

DESCRIPTION OF OPERATIONS/LOCATIONS/VEHICLES/SPECIAL ITEMS

Excess Carrier: National Union Fire Insurance Company of Louisiana

CERTIFICATE HOLDER

SAMPLE

CANCELLATION

SHOULD ANY OF THE ABOVE DESCRIBED POLICIES BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, THE ISSUING COMPANY WILL ENDEAVOR TO MAIL 30 DAYS WRITTEN NOTICE TO THE CERTIFICATE HOLDER NAMED TO THE LEFT, BUT FAILURE TO MAIL SUCH NOTICE SHALL IMPOSE NO OBLIGATION OR LIABILITY OF ANY KIND UPON THE COMPANY, ITS AGENTS OR REPRESENTATIVES.

AUTHORIZED REPRESENTATIVE

William H. Cormier


ACORD 25-S (3/93)

CORD 25-S (3/93)

IP7_031402

IP7_031403

IP7_031404



Start Date 18FEB04 07:00
 Finish Date 28MAR04 16:59
 Data Date 18FEB04 07:00
 Run Date 20AUG03 10:52




1912

Sheet 1 of 5

Intermountain Power - Delta, Utah
 Lo-NOx Burner Replacement

Date	Revision	Checked	Approved



Start Date: 18FEB04 07:00

Finish Date: 28MAR04 1659

Date Date: 18FEB04 07:00

Run Date: 20AUG03 10:02

Sheet 2 of 5

Intermountain Power - Delta, Utah

Lo-NOx Burner Replacement


1912



Early Bar

Progress Bar

Date	Revision	Checked	Approved

© Primavera Systems, Inc.



Start Date	16FEB04 07:00		Early Bar
Finish Date	26MARD04 15:59		Progress Bar
Date Date	16FEB04 07:00		
Run Date	20AUG03 10:52		

1912

Sheet 4 of 5

Intermountain Power - Delta, Utah

Lo-NOx Burner Replacement

[illegible]


IP7_031409

SUBCONTRACTORS

Drexal Power - Electrical

Petro-Chem – Insulation

IP7_031411



Maintenance Enterprises, Inc
a Crown Enterprises Company

TIME & MATERIAL RATE SCHEDULE

Intermountain Power – Delta, UT
August 20, 2003

	<u>ST</u>	<u>OT</u>
Project Manager	60.41	82.31
Superintendent	48.60	65.90
Planner/Scheduler	55.42	75.60
Cost Engineer	38.27	54.04
Quality Control	40.66	55.08
Supervisor/General Foreman	41.11	54.48
Safety	40.66	55.08
Timekeeper	22.64	31.28
Working Foreman	39.11	52.48
Material Control	31.49	43.60
“AA” Welder	37.11	50.48
“A” Welder	34.01	46.22
“B” Welder	29.37	39.84
“A” Pipe Fitter	32.46	44.10
“B” Pipe Fitter	29.37	39.84
“A” Boilermaker	30.92	41.97
“B” Boilermaker	27.82	37.71
“A” Rigger	30.92	41.97
“B” Rigger	27.82	37.71
Helper	23.17	31.32
Fire watch/Hole Watch	18.53	24.93
Labor	18.53	24.93

NOTE: The Above Rates Are Valid For (Six) 6 Months.

Overtime/Holiday Pay:

- All hours worked over eight (8) hours each day are considered overtime.
- All hours worked on Saturday, Sunday or holidays are considered overtime.
- Contractor's normal workweek is a sixty (60) hour week [six (6) ten (10) hour shifts]...However, Contractor is receptive to any work day/work week required for a specific job, based upon prior mutual agreement.
- When a twelve (12) hour shift is requested by client, Contractor shall be paid for crew mealtime (i.e., receive twelve (12) hours pay for eleven and one-half (11-1/2) hours worked).

Standby Time:

- If the crew is not able to work as scheduled during any shift or is delayed for any reason beyond their control, a minimum of four (4) hours up to a maximum of ten (10) hours per day will be charged in accordance with the above rates to a maximum of sixty (60) hours per week.

Travel Time:

- Travel time required to move tools and equipment from point of origin to jobsite and return.
- Travel time by air or ground transport when approved in advance by the client. Travel time is automatically considered "COMPANY APPROVED" for any emergency call out of 72 hours or less notice and will apply to traveling both to and from the jobsite.
- Travel time is actual elapsed time from point of origin to jobsite and return to a maximum of eight (8) hours per day and will be charged at the above Straight Time rates.

Transportation:

- Vehicles for transportation to and from jobsite, charged at cost plus ten percent (10%), if required.
- Air travel versus use of ground transportation is subject to Client's prior concurrence.
- Ground transportation will be charged portal to portal at thirty two (32) cents per mile for employee owned vehicles.

Per Diem:

- At MEI's option, the rate will be \$75.00 U.S. Dollars per day per person OR \$20.00 U.S. Dollars per day per person plus, lodging will be charged at cost plus ten percent (10%). Per Diem will be charged Monday through Sunday regardless of the work schedule, unless prior agreements have been made to supercede this agreement. Per Diem will only be charged on employee's traveling over 50 miles from their legal residence.

M.E.I. Owned Equipment:

- Equipment rates include maintenance and costs associated with ownership and furnishing of such equipment.
- Weekly/Monthly rates are based on seven days around the clock operation.
- Fuel will be invoiced at cost plus ten percent (10%) if supplied by MEI.
- Pickup will be invoiced at \$50.00 per day.

Personal Protective Equipment:

- Included in the labor rates will be: safety glasses, hardhats, monogoggles, ear protection and gloves.
- Any special safety equipment such as fresh air, etc. will be furnished at cost plus ten percent (10%).

Materials:

- All materials will be charged at cost plus ten percent (10%).

Consumables:

- All consumables will be charged at cost plus ten percent (10%).

Small Tools:

- Tool trailer will be charged at \$35.00 per hour.
- See attached list for tools included with tool trailer. All other tools will be charged at cost plus ten percent (10%).

Subcontracts:

- Actual cost plus ten percent (10%).
- All fuel will be charged at cost plus ten percent (10%).

Third Party Equipment Rental:

- Actual cost plus ten percent (10%).

Freight:

- Freight for tool trailers, equipment, and any materials will be charged cost plus ten percent (10%) (Round trip).

Welding Procedures:

- All specialized procedures not currently in MEI's database will be charged at cost plus ten percent (10%).

Welder Testing:

- All welders having to be qualified to the new procedures will be charged at cost plus ten percent (10%), test time at above straight time rates, and mileage at \$.32 per mile.

IP7_031415

**THE NATIONAL BOARD
OF
BOILER & PRESSURE VESSEL INSPECTORS**

Certificate of Authorization



This is to certify that

**MAINTENANCE ENTERPRISES, INC.
52410 CLARK ROAD
WHITE CASTLE, LOUISIANA 70788**

*is authorized to use the "R" SYMBOL in accordance with the
provisions of the National Board.*

The scope of Authorization is limited as follows:

**REPAIRS AND/OR ALTERATIONS AT THE ABOVE LOCATION
AND EXTENDED FOR FIELD REPAIRS AND/OR
ALTERATIONS CONTROLLED BY THIS LOCATION**

CERTIFICATE NUMBER: R-845

ISSUE DATE: MAY 30, 2002

EXPIRATION DATE: SEPTEMBER 20, 2005

Executive Director

A handwritten signature in dark ink, appearing to read 'R. L. Tamm', written over a horizontal line.

NB 243 Rev. 2

IP7_031416



CERTIFICATE OF AUTHORIZATION

This certificate accredits the named company as authorized to use the indicated symbol of the American Society of Mechanical Engineers (ASME) for the scope of activity shown below in accordance with the applicable rules of the ASME Boiler and Pressure Vessel Code. The use of the Code symbol and the authority granted by this Certificate of Authorization are subject to the provisions of the agreement set forth in the application. Any construction stamped with this symbol shall have been built strictly in accordance with the provisions of the ASME Boiler and Pressure Vessel Code.

COMPANY:

**MAINTENANCE ENTERPRISES, INC.
52410 CLARK ROAD
WHITE CASTLE, LOUISIANA 70788**

SCOPE:

**MANUFACTURE AND ASSEMBLY OF POWER BOILERS AT THE ABOVE
LOCATION AND FIELD SITES CONTROLLED BY THE ABOVE LOCATION**

**AUTHORIZED: JUNE 4, 2002
EXPIRES: JULY 27, 2005
CERTIFICATE NUMBER: 29,190**

**CHAIRMAN OF THE BOILER
AND PRESSURE VESSEL COMMITTEE**

DIRECTOR, ACCREDITATION AND CERTIFICATION



CERTIFICATE OF AUTHORIZATION

This certificate accredits the named company as authorized to use the indicated symbol of the American Society of Mechanical Engineers (ASME) for the scope of activity shown below in accordance with the applicable rules of the ASME Boiler and Pressure Vessel Code. The use of the Code symbol and the authority granted by this Certificate of Authorization are subject to the provisions of the agreement set forth in the application. Any construction stamped with this symbol shall have been built strictly in accordance with the provisions of the ASME Boiler and Pressure Vessel Code.

COMPANY:

**MAINTENANCE ENTERPRISES, INC.
52410 CLARK ROAD
WHITE CASTLE, LOUISIANA 70788**

SCOPE:

**MANUFACTURE OF PRESSURE VESSELS AT THE ABOVE LOCATION AND
FIELD SITES CONTROLLED BY THE ABOVE LOCATION**

**AUTHORIZED: JUNE 4, 2002
EXPIRES: JULY 27, 2005
CERTIFICATE NUMBER: 31,222**

**CHAIRMAN OF THE BOILER
AND PRESSURE VESSEL COMMITTEE**

DIRECTOR, ACCREDITATION AND CERTIFICATION



IP7_031419

EXCEPTIONS

Part B – Division B2 – Paragraph 2 – Incentives and Liquidation Damages

Early Completion:

For completion of installation of the burner and scanner systems, contractor will be awarded \$25,000 per day for up to two (2) days, with a maximum possible bonus of \$50,000.

Late Completion:

Liquidation damages for failure to complete insulation of all burner and scanner system components will be assessed at \$100,000 per day, up to a possible total of ten (10) days delay of \$1,00,000.

We feel this section should be removed or realigned equally.

IP7_031421

CLARIFICATIONS

1. Job bid on standard rates, not prevailing wages
2. No ACM or lead paint
3. No federal, state or city taxes
4. Payment is net 30 days, billed once per month
5. Bond based upon 50% of insulation cost
6. Job bid on seven (7) days per week, ten (10) hours per day for six (6) weeks
7. Use of air pre-heaters electric hoist
8. No materials included. ABT to supply
9. No P-3 Planner included however, our office will up-date the schedule weekly if necessary
10. One (1) hour orientation included
11. No start-up support in bid
12. One (1) full-time safety man on site
13. One (1) full-time QC on site
14. No R-1 Form
15. No A-I
16. Bid bond by ABT

PART D - DIVISION D1

CONTRACT DOCUMENTS DESCRIPTION

The Contract Agreement, together with the documents listed in Article 3 thereof, the Reference Specifications, any other documents listed below, and such of Contractor's Proposal documents as are expressly agreed to by IPSC shall constitute the Contract (the Contract). Said Documents are complementary and require complete and finished Work. Anything shown or required of Contractor in any one or more of said documents shall be as binding as if contained in all of said documents. Contractor shall not be allowed to take advantage of any error, discrepancy, omission, or ambiguity in any document, but shall immediately report to the President and Chief Operations Officer, in writing, any such matter discovered. The President and Chief Operations Officer will then decide or correct the same and the decision will be final.

PART E - DIVISION E1

GENERAL CONDITIONS

1. **Definitions:** The following words shall have the following meanings:
 - a. **Bidder:** The person, firm, or corporation adopting and submitting a Proposal under these Specifications.
 - b. **Buyer:** The Purchasing Agent for IPSC.
 - c. **Contract Administrator:** The IPSC employee designated by the President and Chief Operations Officer with primary responsibility for administration of the Contract, or other representatives designated by the Contract Administrator acting within the limits of their authority.
 - d. **Contractor:** The person, firm, or corporation to whom the Contract is awarded.
 - e. **Directed, Required, Approved, etc.:** The words *directed, required, approved, permitted, ordered, designated, prescribed, instructed, acceptable, accepted, satisfactory*, or similar words shall refer to actions, expressions, and prerogatives of the Contract Administrator unless otherwise expressly stated.
 - f. **Gallon:** Liquid volume of 231 cubic inches at 60 degrees Fahrenheit.
 - g. **IGS:** Intermountain Generating Station located at 850 West Brush Wellman Road, Delta, Utah 84624.
 - h. **IPA:** Intermountain Power Agency, the owner of Intermountain Power Project, and a political subdivision of the state of Utah, organized and existing under the Interlocal Co-operation Act, Title 11, Chapter 13, Utah Code Annotated 1953, as amended.
 - i. **IPP:** Intermountain Power Project, consisting of Intermountain Generating Station, Intermountain Railcar, Intermountain Converter Station, Adelanto Converter Station, Intermountain AC Switchyard and associated transmission lines, microwave stations, and support facilities.
 - j. **IPSC:** Intermountain Power Service Corporation, a nonprofit corporation, furnishing personnel to support the Operating Agent in the performance of operation and maintenance.
 - k. **Operating Agent, or LADWP:** The City of Los Angeles Department of Water and Power which is responsible for operation and maintenance for IPP.

DIVISION E1

GENERAL CONDITIONS

-
- l. President and Chief Operations Officer: The President and Chief Operations Officer of IPSC, or other representatives designated by the President and Chief Operations Officer acting within the limits of their authority.
 - m. Reference Specifications: Those bulletins, standards, rules, methods of analysis or tests, codes, and specifications of other agencies, engineering societies, or industrial associations referred to in these Specifications. These refer to the latest edition, including amendments published and in effect at the date of the Invitation for Proposal, unless specifically referred to by edition, volume, or date. Unless the context otherwise requires, Reference Specifications also include all amendments published or adopted after the date of the Invitation for Proposal.
 - n. Subcontractor: A person, firm, or corporation, other than Contractor and employees thereof, who supplies labor, services or materials for a portion of the Work to be performed by Contractor under the Contract.
 - o. Ton: The short ton of 2,000 pounds.
 - p. Work: The services, materials, equipment, and other performance identified in these Specifications and other Contract Documents to be provided by Contractor.
2. Materials and Work: All Work shall comply with these Specifications. All materials used or supplied, and all equipment furnished, shall be new and unused, but this requirement shall not preclude the use of recycled materials in the manufacturing processes. All Work shall be done by qualified workers in a thorough and workmanlike manner that would pass without objection in both Contractor's trade and IPA's and IPSC's industry. Materials, equipment, workmanship, and other Work not definitely specified, but incidental to and necessary for the Work, shall conform to the best commercial practice for the type of Work in question and be of a quality that passes without objection in Contractor's trade and IPA's and IPSC's industry.
3. Nondiscrimination: The applicable provisions of Executive Order No. 11246 of September 24, 1965, and Bureau of Land Management regulations, and all other applicable governmental regulations pertaining to nondiscrimination in employment in the performance of contracts, are incorporated herein by reference, and made a part hereof as if they were fully set forth herein. During the performance of the Contract, Contractor shall not discriminate in its employment practices against any employee or applicant for employment because of the employee's or applicant's race, religion, national origin, ancestry, sex, age, or physical disability. All subcontracts awarded under or pursuant to the Contract shall contain a like nondiscrimination provision.
4. Governing Law; Venue: The Contract shall be governed by the substantive laws of the state of Utah, regardless of any rules on conflicts of laws or choice of law that would otherwise cause a court to apply the laws of any other state or jurisdiction. Any action,

DIVISION E1

GENERAL CONDITIONS

in law or in equity, concerning any alleged breach of or interpretation of the Contract, or concerning any tort in relation to the Contract or incidental to performance under the Contract, shall be filed only in the state or federal courts located in the state of Utah.

5. Patents and Intellectual Property: Contractor shall fully indemnify and, at the election of IPA, defend IPA, IPSC, and the Operating Agent against any and all liability, whatsoever, by reason of any alleged infringement of any intellectual property rights (including, but not limited to, patents, copyrights, trademarks, or trade secrets) on any article, process, method, or application used in any designs, plans, drawings, or specifications provided under the Contract, or by reason of Contractor's manner of performance under the Contract, or by reason of use by IPA, IPSC, or the Operating Agent of any article, process, or material specified by Contractor.

All drawings shall be delivered to and be the property of IPSC. IPSC shall be entitled to use the Drawings and the information contained therein for the construction, operation, maintenance, repair, alteration, improvement, and expansion of IPP facilities. Drawings anticipated for delivery to IPSC include: (a) General Arrangement Drawings showing equipment arrangement; (b) Field Installation Drawings; and (c) Instruction Manuals for supplied equipment.

6. Contractor's Address and Legal Service: The address given in the Proposal shall be considered the legal address of Contractor and shall be changed only by advance written notice to IPSC. Contractor shall supply an address to which certified mail can be delivered. The delivery of any written communication to Contractor personally, or delivery to such address, or the depositing in the United States Mail, registered or certified with postage prepaid addressed to Contractor at such address, shall constitute a legal service thereof.

7. Assignment of Contract Prohibited: Contractor shall not assign or otherwise attempt to dispose of the Contract, or any rights hereunder, or of any monies due or to become due hereunder, unless authorized by the prior written consent of the President and Chief Operations Officer. The Contract, and Contractor's rights hereunder (including rights of collection) are nonassignable without the President and Chief Operations Officer's prior written consent. No right or claim can be asserted against IPA, IPSC, or the Operating Agent, in law or equity, by any person, by reason of any assignment or disposition unless so authorized.

If Contractor, without such prior written consent, purports to assign or dispose of the Contract, or any right or interest hereunder, IPSC may at its option terminate the Contract. Such termination shall relieve and discharge IPA, IPSC, and the Operating Agent from any and all liability, duties, and obligations to Contractor, and to any assignee or transferee thereof.

8. Quality Assurance: IPSC has the right to subject any or all materials, services, equipment, or other Work furnished and delivered under the Contract to rigorous

DIVISION E1

GENERAL CONDITIONS

inspection and testing. (Unless otherwise specifically provided in the Contract with respect to specific materials, services, equipment, or other Work, IPSC has no duty to inspect, test, or specifically accept.) Before offering any material, services, equipment, or other Work for inspection, testing, delivery, or acceptance, Contractor shall eliminate all items or portions which are defective or do not meet the requirements of these Specifications. If any items or portions are found not to meet the requirements of these Specifications, the lot, or any faulty portion thereof, may be rejected. Only the Contract Administrator may accept any material, service, equipment, or other Work as complying with these Specifications on behalf of IPSC.

IPSC may inspect and reject materials, services, equipment, or other Work tendered or purchased under the Contract at any reasonable location IPSC may choose (including, but not limited to, points of origin, while in transit to IPSC, IPSC specified receiving points, IPSC storage sites, or any point of use or installation). Inspection can include any testing that IPSC deems necessary or convenient to determine compliance with these Specifications. The expense of any initial tests will be borne by IPSC. All expenses of subsequent or additional tests will be charged against Contractor when due to failure of first-offered materials, services, equipment, or other Work to comply with these Specifications.

The fact that the materials, services, equipment, or other Work have or have not been inspected, tested, or accepted by IPSC, whether voluntarily or as required by any specific provision in the Contract, shall not relieve Contractor of responsibility in case of later discovery of nonconformity, flaws, or defects, whether patent or latent.

9. Extra Work, Reduced Work, and Change Orders by IPSC: IPSC reserves the right at any time before final acceptance of the entire Work to order Contractor to furnish or perform extra Work, or to make changes altering, adding to, or deducting from the Work, without invalidating the Contract. Changes shall not be binding upon either IPSC or Contractor unless made in writing in accordance with this Article.

Changes will originate with the President and Chief Operations Officer who will transmit to Contractor a written request for a Proposal covering the requested change, setting forth the changed Work in detail, and including any required supplemental plans or specifications. Upon receipt of such request, Contractor shall promptly submit in writing to the President and Chief Operations Officer a Proposal offering to perform such change, a request for any required extension of time caused by such change, and an itemized statement of the cost or credit for the proposed change. Failure of Contractor to include a request for extension of time in the Proposal shall constitute conclusive evidence that such extra Work or revisions will entail no delay and that no extension of time will be required.

If Contractor's Proposal is accepted by IPSC, a written change order will be issued by the President and Chief Operations Officer stating that the extra Work or change is authorized and granting any required adjustments of the Contract price and of time of

DIVISION E1

GENERAL CONDITIONS

completion. If Contractor's Proposal is rejected by IPSC, then IPSC may order the additional or changed Work from other vendors.

Additional Work or changes pursuant to the change order shall be performed in accordance with the terms and conditions of these Specifications. No extra Work shall be performed or change made unless pursuant to such written change order, and no claim for an addition to the Contract price shall be valid unless so ordered.

Notwithstanding anything in the preceding paragraphs to this Article, IPSC may issue a written order reducing the Scope of Work without issuing a request for Proposal. Any such reduction in the Scope of Work shall be effective upon issuance. Reductions ordered by IPSC shall constitute partial terminations and shall reduce the price to be paid.

10. Changes at Request of Contractor: Changes may be made to facilitate the Work of Contractor. Such changes may only be made without additional cost to IPSC, without extension of time, and pursuant to written permission from the President and Chief Operations Officer. Permission for such changes shall be requested in writing by Contractor to the President and Chief Operations Officer.
11. Time is of the Essence and Extensions of Time: Time is of the essence to the Contract. Delivery and other performance of Work must be completed within the times and by the dates specified. Time for delivery or other performance of Work shall not be extended except as provided in this Article. Failure to deliver or otherwise perform Work within the times and by the dates specified shall constitute a default and be grounds for IPSC to immediately terminate the Contract.

If Contractor makes a timely written request in accordance with this Article, the time for delivery or other performance of Work will be extended by a period of time equivalent to any delay in the whole Work which is: (a) authorized in writing by the President and Chief Operations Officer, (b) caused solely by IPSC, or (c) due to unforeseeable causes (such as war, strikes, or natural disasters) and which delay is beyond the control and without the fault or negligence of Contractor and subcontractors.

Contractor shall promptly notify the President and Chief Operations Officer in writing at both the beginning and ending of any delay, of its cause, its effect on the whole Work, and the extension of time claimed. Failure of Contractor to provide such written notices and to show such facts shall constitute conclusive evidence that no excusable delay has occurred and that no extension of time is required.

The President and Chief Operations Officer will ascertain the facts and the extent of the delay and will extend the time for delivery when the findings of fact justify such an extension. The President and Chief Operations Officer's determination will be final and conclusive.

DIVISION E1

GENERAL CONDITIONS

IPSC will be responsible for granting extensions of time as herein provided, but will not otherwise be responsible in any manner or liable to any extent for damage directly or indirectly suffered by Contractor as a result of any delay.

12. Protests and Claims: If Contractor considers any demand of the President and Chief Operations Officer to be outside of the requirements of the Contract, or considers any amount of payment, or any record, ruling, or other act, omission, or determination by the President and Chief Operations Officer to be unreasonable, Contractor shall promptly deliver to the President and Chief Operations Officer a written statement of the protest and of the amount of compensation or nature of accommodation, if any, claimed.

Upon written request by the President and Chief Operations Officer, Contractor shall provide access to all records containing any evidence relating to the protest or claim.

Upon review of the protest, claim, and evidence, the President and Chief Operations Officer will promptly advise Contractor in writing of the final decision which will be binding on all parties.

The requirements of this Article shall be in addition to, and shall not be construed as waiving claims provisions of the Statutes of the state of Utah. Contractor is deemed to have waived and does waive all claims for extensions of time and for compensation in addition to the Contract price except for protests and claims made and determined in accordance with this Article.

13. Limitation of Liability; Responsible Party: It is understood and agreed that IPA shall be the sole party or person liable to Contractor for payments under or pursuant to the Contract, and for any breaches, defaults, or for any torts in the performance of or in relation to the Contract by IPA, IPSC, or the Operating Agent, or any officers, agents, or employees thereof. Contractor hereby expressly covenants and agrees that no suit shall be brought by Contractor against IPSC, or the Operating Agent, or their, or IPA's officers, agents, or employees, or any of the purchasers of power from IPA, but that all rights or remedies that Contractor may have or that may arise under or in relation to the Contract shall be asserted by Contractor solely against IPA. Without limiting the foregoing provisions of this Article, Contractor shall have no right against any of the foregoing (including IPA) to assert or recover, in contract or in tort, damages or losses in the nature of consequential damages, incidental damages, or punitive or exemplary damages. In no event shall Contractor be liable, whether in contract, tort (including negligence), warranty, strict liability, or any other legal theory, for any indirect or consequential damages, such as, but not limited to: cost of capital; loss of anticipated profits or revenue; loss of use or increased expense of using equipment or plant; loss of power or production; cost of purchased or replacement power or production; or claims of customers for loss of power or production.

14. Independent Contractor: Contractor shall perform all Work as an independent contractor in the pursuit of its independent calling. Contractor is not an employee,

DIVISION E1

GENERAL CONDITIONS

agent, joint venturer, partner, or other representative of IPA, IPSC, or the Operating Agent and shall be under the control of IPSC only to provide the Work requested and not as to the means or manner by which the Work is to be accomplished. Contractor has no authority to act for, bind, or legally commit IPA, IPSC, or the Operating Agent in any way.

15. Drug Policy: Contractor shall submit a current copy of its drug policy for review. IPP facilities are a drug free and zero tolerance workplace. Contractor's employees and its subcontractors' employees, who are to perform Work or otherwise be at the IPP facilities, shall participate in a drug testing program prior to arrival, and at any additional time(s) during the Contract as IPSC may request.
16. Security and Safety Compliance: Contractor and its employees, agents, representatives, and/or subcontractors, while performing Work on IPP premises, or who are otherwise on IPP premises, shall fully comply with all security, fire prevention, and safety rules and procedures in force at IPP. IPSC has the right (but not duty) to make periodic and random inspections of the persons, and of their respective property, upon entering, at any time while on, and when departing any IPP facility. Such persons subject to inspection include Contractor, any subcontractor, and their respective employees, agents, and representatives. Property subject to inspection includes, but is not limited to, vehicles, clothing, toolboxes, lunch boxes, any other carrying case, tools or equipment, and anything contained therein. If violations are noted, the violations will be reported to Contractor's on-site supervisor and the Contract Administrator for appropriate action.

All Contractor's employees will be given security identification badges by IPSC and those badges shall be displayed each day to allow admittance on IPP premises. Contractor's employees who do not have security identification badges in their possession, will not be allowed on site unless signed in by the Contract Administrator. All security identification badges shall be returned to the Security Contractor when the employee terminates their work at this site. All Contractor's vehicles will also receive parking stickers from the Security Contractor allowing entrance on IPP premises. Temporary badges and parking stickers are available for intermittent Contractor employees and vehicles.

Contractor shall have access on IPP premises between the hours of 7:00 am to 7:00 pm Monday through Friday. Access may be allowed on weekends or at other times with the approval of the Contract Administrator.

Contractor will be directed to specified areas for parking vehicles and equipment by the Contract Administrator. Certain areas of IPP premises are restricted to IPSC vehicles only. Exceptions to the parking restriction will be made on an as needed basis through Contractor's respective Contract Administrator. Contractor shall make its employees, agents, representatives, and/or subcontractors aware of all areas that are subject to restricted parking.

DIVISION E1

GENERAL CONDITIONS

Contractor agrees, warrants, and represents that: (a) it is familiar with the risks of injury associated with the Work and otherwise being on IPP premises, (b) has reviewed the Work to be performed, (c) has inspected the IPP Work site with an IPSC representative, and (d) has determined that no unusual or peculiar risk of harm exists with regard to the Work to be performed on IPP premises. Contractor further agrees that it shall, at all times, provide on IPP premises, a competent supervisor(s) familiar with IPSC's and the industry's safety standards to ensure compliance with all federal, state, and local regulations pertaining to safety (including, but not limited to, Federal and State OSHA, as said regulations relate to the Work to be performed under the Contract). Although IPSC assumes no responsibility to oversee or supervise the Work, IPSC reserves the right to review safety programs and practices and to make recommendations to Contractor. No such review or recommendation by IPSC shall impose any liability or responsibility on IPSC, or relieve Contractor from providing a safe working environment and complying with all legal requirements.

Contractor shall comply with IPSC's safety and equipment requirements prior to starting the Work. Worker protective clothing, which includes, but is not limited to, hardhats, safety glasses, safety shoes, gloves, respirators, earplugs, safety harnesses, and face shields shall be provided by Contractor.

Prior to starting the Work, all of Contractor's personnel shall attend a safety orientation taught by a representative of IPSC. At Contractor's option and subject to IPSC approval, a supervisor of Contractor may attend the orientation taught by IPSC, and then present the orientation to the remainder of Contractor's personnel. In that case, a roll shall be provided to IPSC which lists each person who received the orientation and the date it was received.

17. Nonexclusive: This is a nonexclusive Contract. IPSC reserves the right to obtain services, materials, equipment, or other Work from other vendors or suppliers.

PART E - DIVISION E2

ADDITIONAL GENERAL CONDITIONS

1. **Guarantee:** Contractor guarantees and warrants for a minimum period of one (1) year after delivery, and for such longer period as may be specified by the applicable statute of limitations, that all materials, services, equipment, and other Work furnished are free from defects and otherwise conform to the terms of the Contract, including, but not limited to, the Article entitled "Materials and Work" in Part E, Division E1, General Conditions.

Contractor shall repair or replace, as IPSC may direct, all defective materials, services, equipment, or other Work. Such repair or replacement shall be F.O.B. at such destination as IPSC may direct (contract delivery point, point of installation, point of consumption, etc.). IPSC's right to demand repair or replacement is in addition to any other remedies that may be available for breach of the foregoing guarantee and warranty.

Contractor shall, for the protection and benefit of IPA, IPSC, and LADWP, obtain guarantees conforming to the foregoing two (2) paragraphs from each of its vendors and subcontractors with respect to their materials, services, equipment, or other portion of the Work. Such guarantees from vendors and subcontractors shall be in addition to, and not in lieu of, Contractor's own guarantees.

2. **Payment:** Payment will be made within thirty (30) calendar days after delivery and receipt of the invoice in the form directed by IPSC.
3. **Work Slips and Invoices:** Contractor shall furnish Work slips suitable for recording (e.g., - the weight of concentrated sulfuric acid in tons), at the time of each delivery. IPSC may direct the form of Work slips to be used. Accuracy of completed Work slips shall be subject to verification by IPSC, who will retain the original copies.

At the expiration of each calendar month during which material or other Work is delivered, Contractor shall render an invoice and copies of signed Work slips (e.g., - the total weight of acid) delivered during said month.

Invoices shall be submitted in duplicate to Accounts Payable, Intermountain Power Service Corporation, 850 West Brush Wellman Road, Delta, Utah 84624-9546. All letters pertaining to invoices shall be addressed to the foregoing address.

IPSC may direct the form of invoice to be used. All invoices shall show the Contract number, release number, or other identification of each delivery covered by the invoice. In all cases, the amount of the applicable sales tax or use tax shall be separately stated on the invoice.

4. **Regulations, Permits, Licenses, and Warrants:** Contractor shall comply with all applicable federal, state, and local regulations including, but not limited to, Federal and State OSHA, as said regulations relate to the Contract, Contractor's performance, or

DIVISION E2

ADDITIONAL GENERAL CONDITIONS

Contractor's trade. In addition, Contractor shall ensure that all permits, licenses, and warrants relating to the Contract, Contractor's performance, and Contractor's trade be acquired.

5. Letters to IPSC: All inquiries relating to these Specifications prior to award of Contract shall be addressed to the Buyer.

After award of Contract, all letters pertaining to performance of the Contract (other than invoice) shall be addressed as follows:

Mr. George W. Cross
President and Chief Operations Officer
Intermountain Power Service Corporation
850 West Brush Wellman Road
Delta, UT 84624-9546

Attention: James Nelson
Contract Administrator

Regarding **Contract No: 04-45606**

PART F - DIVISION F1

DETAILED SPECIFICATIONS - SPECIAL CONDITIONS

1. **General:** Under the terms of the Contract, Contractor shall furnish and deliver **Unit 2 Low NOx Burners** ordered by IPSC beginning with date stated in the first introductory paragraph of the Contract Agreement (hereinafter called the Contractual Period).
2. **Quantity:** IPSC agrees to purchase **forty-eight (48) Low NOx Burners and Associated Flame Detection Systems** during the Contractual Period.
3. **Delivery:** Contractor shall make deliveries only upon receipt of releases issued by the Buyer or a duly authorized representative. IPSC reserves the right to specify in said releases the amounts and dates of deliveries at the locations described in the Proposal Schedule.

Notwithstanding the above, IPSC agrees to accept early delivery of burners if ABT's shop is ready to ship. Burners will be stored indoors at the site and unloaded by IPSC.

4. **Printed Documents:** All printed documents, including drawings and instruction books, if applicable, shall be in the English language. All units of measurement shall be in the English foot-pound-second system.
5. **Indemnity Clause:** Contractor undertakes and agrees to indemnify, hold harmless, and at the option of the IPA, defend IPA, IPSC, LADWP, and any and all of their boards, officers, agents, representatives, employees, assigns, and successors in interest from and against any and all suits and causes of action, claims, charges, costs, damages, demands, expenses (including, but not limited to, reasonable attorneys' fees and cost of litigation), judgments, civil fines and penalties, liabilities or losses of any kind or nature, including, but not limited to, violations of regulatory law, breach of contract, death, bodily injury or personal injury to any person, including Contractor's employees and agents, or damage or destruction to any property of either party hereto, or of third persons, arising in any manner by reason of or incident to the performance of the Contract on the part of Contractor, or Contractor's officers, agents, employees, or subcontractors of any tier, except as may be caused by the sole negligence of IPA, IPSC, LADWP, or their boards, officers, agents, representatives, or employees.
6. **Insurance Requirements:** Prior to the start of the Work, but not later than thirty (30) calendar days after date of award of Contract, Contractor shall furnish IPSC evidence of coverage from insurers acceptable to IPSC and in a form acceptable to IPSC Insurance Analyst. Such insurance shall be maintained by Contractor and at Contractor's sole cost and expense.

Such insurance shall not limit or qualify the liabilities and obligations of Contractor assumed under the Contract. IPA, IPSC, or LADWP shall not, by reason of any of their inclusion under these policies or otherwise, incur liability to the insurance carrier for payment of the premium for these policies.

DIVISION F1

SPECIAL CONDITIONS

Any insurance carried by IPA, IPSC, or LADWP which may be applicable is and shall be deemed excess insurance, and Contractor's insurance is and shall be primary for all purposes despite any provision in Contractor's policies to the contrary.

Should any portion of the required insurance be on a "Claims Made" policy, Contractor shall, prior to the policy expiration date following completion of the Work, provide evidence that the "Claims Made" policy has been renewed or replaced with the same limits and terms and conditions of the expiring policy at least for the Contract under which the Work was performed.

Note: General ABT Clarification on Insurance: Should ABT's current limits be unacceptable to IPSC and ABT must raise the insurance limits for the Contract, the difference in ABT's premiums would be added and billed to IPSC at cost.

- a. Workers' Compensation/Employer's Liability: Workers' Compensation Insurance covering all of Contractor's employees in accordance with the laws of all states in which the Work is to be performed and including Employer's Liability Insurance, and as appropriate, Broad Form All States Endorsement. The limit for Employer's Liability coverage shall be not less than \$1 million each accident and shall be a separate policy if not included with Workers' Compensation coverage. Evidence of such insurance shall be a certificate to the policy providing for a thirty (30) calendar days prior written notice of cancellation or nonrenewal of a continuous policy to IPSC, by receipted delivery.
- b. Commercial General Liability: Commercial General Liability with Blanket Contractual Liability, Products and Completed Operations, Broad Form Property Damage, Premises and Operations, Independent Contractors, and Personal Injury coverages included. Such insurance shall provide coverage for total limits actually arranged by Contractor, but not less than \$2 million Combined Single Limit. Should the policy have an aggregate limit, such aggregate limits should not be less than \$8 million. Umbrella or Excess Liability coverages may be used to supplement primary coverages to meet the required limits. Evidence of such coverages shall be on IPSC's Additional Insured Endorsement Form, on an endorsement of the policy acceptable to IPSC, or a complete copy of the coverage and exclusions portions of the policy. The evidence of coverage should provide for the following:
 - (1) To include IPA, IPSC, LADWP, and their officers, agents, and employees as additional insured with the Named Insured for the activities and operations under and in connection with the Contract.
 - (2) That the insurance is primary and not contributing with any other insurance maintained by IPA, IPSC, or LADWP.

DIVISION F1

SPECIAL CONDITIONS

- (3) That the policy shall not be subject to cancellation, change in coverage, reduction of limits or nonrenewal of a continuous policy, except after written notice to IPSC, by receipted delivery, no less than thirty (30) calendar days prior to the effective date thereof.
- (4) A description of the coverages included under the policy.
- c. Commercial Automobile Liability: Commercial Automobile Liability covering the use of owned, nonowned, hired, and leased vehicles for total limits actually arranged by Contractor, but not less than \$1 million Combined Single Limit. Such insurance shall include Contractual Liability coverage. The method of providing evidence of insurance and requirements for additional insureds, primary insurance, notice of cancellation, and Severability-of-Interest shall be the same revised requirements in the Commercial General Liability Section of terms and conditions.
- d. Professional Liability: Contractor shall provide Professional Liability Insurance covering Contractor's liability arising from errors and omissions made directly or indirectly during the execution and performance of the Contract and shall provide coverage of \$2.5 million Combined Single Limit. Such insurance shall be an endorsement to the Commercial General Liability Policy without separate aggregate.

The policy shall not be subject to cancellation, change in coverage, reduction of limits, or nonrenewal of a continuous policy, except after written notice to IPSC, by receipted delivery, not less than thirty (30) calendar days prior to the effective date thereof.
- e. Other Conditions: Contractor shall be responsible for all subcontractors' compliance with these revised insurance requirements. The foregoing remedies in subsection (1) shall be available to IPSC against Contractor for any failure by any subcontractor to maintain and provide the required insurance.
- 7. Transportation: All shipments of hazardous materials under the Contract or in connection herewith shall be handled in accordance with current U.S. Department of Transportation regulations and all other applicable federal, state, and local laws and regulations.
- 8. Material Safety Data Sheets: Contractor shall furnish IPSC with a Material Safety Data Sheet (MSDS) for all hazardous materials furnished under the Contract, used, stored, or transported on or near IPP premises in connection with the Contract. The MSDS shall be furnished to IPSC on, or prior to, the date of the first delivery, use, storage, or transportation of the materials or equipment. If these Specifications require that Contractor furnish instruction books, the MSDS shall also be included in such books.

9. Contract Termination:

- a. For Convenience or Security: IPSC reserves the right, by giving twenty (20) calendar days prior written notice (or such longer notice as IPSC may select) to Contractor, to terminate the whole or any part of the Contract at IPSC's convenience, whether or not Contractor is in default. IPSC also reserves the right to terminate the Contract, effective immediately upon notice, for purposes of security or safety of IPP facilities, persons who work at IPP facilities, or the public. In the event of termination for convenience, security, or safety, IPA will pay Contractor reasonable and proper direct costs of termination (if, however, Contractor's Proposal includes cancellation charges, payment for termination costs shall not exceed the cancellation charges set forth therein). Contractor shall, after consultation with IPSC, take all reasonable steps to minimize the costs related to termination. Contractor shall provide IPSC with an accounting of costs claimed, including adequate supporting information and documentation and IPSC may, at its expense, audit the claimed costs and supporting information and documentation.
- b. For Breach: IPSC may terminate the whole or any part of the Contract effective immediately upon notice, in the event Contractor is in material default, and without right on the part of Contractor to claim any termination costs. This right to terminate is in addition to, and not in lieu of, any other remedy provided in the Contract or otherwise provided by law or equity.
- c. Limitation of Liability: In no event shall termination of this Contract, or any portion thereof, whether for convenience, security, safety, breach, or otherwise, constitute the basis for or result in any claim by Contractor for consequential or incidental damages (including loss of anticipated profits or other economic damages) or punitive damages, and Contractor hereby releases IPA, IPSC, and LADWP, and their officers, directors, employees, agents, and representatives, from any and all such claims or liability.

10. Suspension of Work: IPSC reserves the right to suspend and reinstate execution of the whole or any part of the Contract and the Work without invalidating the provisions of the Contract. In the event the Work is suspended, Contractor will be reimbursed for actual direct unavoidable costs that it reasonably incurs as a result of the suspension. Claims for such cost reimbursement shall be submitted by invoice. Contractor shall use all reasonable means to minimize such costs, and shall allow IPSC to audit costs claimed. Contractor shall, upon request by IPSC, provide a projection of costs it anticipates to incur during any suspension, or continuation of suspension, contemplated by IPSC. In no event shall suspension constitute the basis for, or result in, any claim for consequential or incidental damages (including loss of anticipated profits or other economic damages) or punitive damages, and Contractor hereby releases IPA, IPSC, and LADWP, and their officers, directors, employees, agents, and representatives, from any and all such claims or liability.

DIVISION F1

SPECIAL CONDITIONS

11. No Waiver: No breach, noncompliance, or other failure to perform (collectively "breach") by Contractor, or any subcontractor, or of any Work shall be deemed waived unless expressly waived in writing by the President and Chief Operations Officer. No waiver by IPSC of any one breach shall be deemed to waive any other prior, concurrent, or subsequent breach. No exercise, or failure to exercise, or delay in exercising any particular remedy by IPSC shall be deemed a waiver or preclude IPSC from subsequently invoking that remedy for that breach or any other breach. All remedies granted to IPSC in the Contract, or by law or equity, are cumulative and may be exercised in any combination or order.

PART F - DIVISION F2**DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS**

1. **General:** The Scope of Work for the Contract includes the design, procurement, fabrication, delivery, installation, and start-up of burners at IGS Unit 1 and Unit 2. The burners in Unit 2 are to be replaced during the Spring 2004 Outage. The outage is scheduled to begin February 28, 2004. All replacement burner materials must be on-site at IGS no later than February 13, 2004.
2. **Existing Equipment:** The existing burners are B&W Dual Register, Phase 5 Pulverized Coal Burners. The existing Bailey Control System Flamon® Type UM and UW flame scanning hardware shall be replaced with the new burners as a part of these Specifications. The existing lighters are B&W CFA Oil Ignitors normally burning No. 2 diesel oil. The CFA lighters will continue to be used with the new burners and scanning system. The burners, scanners, lighters and fuel specification sheets and outline drawings are included in Attachment 1, Scanner, Lighter and Fuel Specifications, and Outline Drawings.

Existing combustion zone stoichiometry is approximately 1.15. Nominal windbox pressures run in the range of 1.0 to 1.5 in. w.g. Burner windboxes are compartmentalized and fed by one (1) damper at each end of the compartment, operating in parallel. The width of the boiler (i.e. length of a compartment) is approximately 80 feet.

Note: See attached layouts of the existing windbox and burners. Pulverized coal is provided by one (1) of eight (8) MPS - 89G mills at a design rate of up to 68 tph at a fineness of 70 percent through 200 mesh.

3. **Burner Scope:** Contractor shall provide forty-eight (48) Low NOx Burners incorporating latest technology combustion design, including all associated hardware for installation, special tools, and technical direction during installation and startup. The burners shall operate compatibly and effectively with a newly installed overfire air system, which is to be capable of utilizing up to 20 percent of the total design combustion air flow.
4. **Flame Detection System Scope:** The bidder shall provide a complete offering for replacement of the existing Bailey Controls Flamon® Scanning System. Bids for both single and dual probe systems will be accepted and evaluated. Award will be based heavily upon evaluation of the experience list provided with each bid. Bidders may offer alternate bids for all flame scanning systems with which they have had experience.

Flame scanner systems shall include all hardware required for complete installation of the system, including wiring, conduit, and associated hardware for cable routing. Wiring schematics, wiring and installation specifications, and junction boxes with pre-installed, termination hardware shall be supplied by Contractor.

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

5. Burner Design: Burners provided for use at IGS shall adhere to the following provisions:
- a. Within the design phase of the Work, Contractor shall review all operational impacts on associated equipment and systems such as fans, pulverizers, dampers, etc. Any concerns regarding operating limitations or increase power demands noted within the modeling/design phase shall immediately be brought to the attention of the IPSC Contract Administrator.
 - b. Burner design and fabrication methodologies shall emphasize speed and ease of installation. The burner nozzles shall interface directly with the existing burner line flanges.
 - c. Burners shall be provided with combustion air flow sensors providing individual burner air flow indication in each annulus on each burner. Pre-wired panels, signal transducers, and displays shall be provided for displaying flow for each burner locally. Terminals shall be designed and provided within each panel for routing signals remotely. IPSC will have the responsibility to route the flow signals from the local panels to the control room if desired.
 - d. Burners shall provide for local manual air balance control, both between registers within each burner and between burners within a row. The registers shall remain operable under all operating conditions for at least the durations noted in Division C2, Burner and Scanner Performance Guarantees.
 - e. Temperature sensors installed at two (2) locations on each burner shall be provided and routed to a local cold-junction box at each burner level. The sensors shall be located in accordance with the direction of Contractor to identify and track the hottest temperatures occurring at the burner in both the in-service and out-of-service condition. Individual burner temperatures shall be provided at the local cold-junction boxes. Termination space shall be provided within the local cold-junction boxes for continuation of the circuits remotely for indication, monitoring, and alarm within the plant data acquisition system by IPSC as desired.
 - f. The burner assemblies shall be fabricated of quality material sufficient to withstand the significant thermal stresses occurring within the windbox as a result of both radiant and convective heating. Any deformation causing malfunction of register assemblies or misdirection of flow through the burner within the period of guaranteed operability shall be repaired at the earliest possible opportunity and charged to Contractor.

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

- g. Experience-based and verified wear-life shall be quoted within the bid for all burner components. No component shall last less than four (4) years before requiring rebuild, restoration, or replacement.
 - h. Burners shall be designed to operate continuously by IPSC without detrimental effects on boiler performance and steam side flexibility, within the ranges of carbon monoxide, unburned carbon, nitrogen oxides, and excess air specified in Division C2, Burner and Scanner Performance Guarantees.
 - i. Burners shall be designed for installation within the existing burner openings without pressure part modifications, unless clearly noted otherwise within the Proposal.
 - j. Burners shall be designed such that stable flame ignition occurs at the nozzle discharge.
 - k. Burners shall be designed for continuous operation with preheated air at an air heater outlet temperature of 750°F. This does not account for radiant and other heating sources.
 - l. Burners shall be equipped with an aspirated observation/viewing port to permit inspection of the flame. If necessary for flame diagnostics and adjustment, multiple observation doors shall be furnished. Doors shall be designed to permit observation during any load condition. Contractor (ABT) shall include one (1) port per burner assembly with observation glass to view flame. Each port will be equipped with purge air connection and ball valve should the need arise to purge the view pipe.
 - m. Burners shall include, and shall be provided with, new seal/cooling air piping and fittings, including a ball valve, from the burner connection to the header piping.
 - n. Air register operating mechanisms, joints, seals, slides, and linkages shall not be subject to binding from poor design, differential expansion, or from the accumulation of fly ash and shall remain operational without internal lubrication.
 - o. Air flow volume adjustment within each zone of the burner shall not be controlled with the same device controlling air swirl or spin within any air zone.
 - p. Burners shall be capable of stable operation continuously from 45 percent to 115 percent of rated BTU output of the burner without supplemental fuels.
6. Flame Detection System Design: The flame scanning system shall, as a minimum, include the following provisions:

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

- a. Flame scanner ports shall be sighted so flame scanner can readily and effectively discriminate between adjacent or opposing burners and its own burner flame in all operating modes and at all loads.
 - b. Flame detection system shall be provided with protective devices permitting the removal of the system from service with the boiler in operation.
 - c. Flame scanner ports shall include scanner cooling air and seal air provisions, where required. If not provided, or if shown to be adequate in operation, Contractor shall provide and install such hardware as required to address both heating and reliability issues.
 - d. Flame detection system shall be designed with IGS existing support systems in mind. Requirements for reliable operation of the scanning system (cooling air, power, etc.), shall be clearly identified within the bidding documents.
 - e. Flame detection system electronics shall be designed for operation in severe industrial environments. Contamination from dust, flyash, and ambient temperatures in excess of 120°F occur on a regular basis throughout the boiler structure.
 - f. Flame detection system and controllers shall be capable of communication in all versions of Modbus RTU communications protocol.
 - g. Flame detection system shall provide local indication of flame detected at each burner level. Control outputs to the burner management system shall be dry contacts.
7. Technical Support: Contractor shall consult with IPSC throughout the design development process, allowing IPSC to participate in the selection process of preferential items or common industrial equipment required within the design. Bidders shall include the names and direct dial telephone numbers of the lead project design engineers in each area of expertise in the bidding documents. Where possible and applicable, the name and telephone number of the assigned site construction coordinator shall also be provided. All technical advisory personnel assigned to support IPSC with this Project shall have a minimum of ten (10) years experience in the issues to be addressed.

During construction and startup, Contractor shall provide full-service technical support throughout the outage in all areas of expertise required for successful installation, startup, and tuning of the boiler. This shall occur regardless of whether Contractor is also selected to install the burner and flame detection systems. This shall include technical support in proper positioning, tuning, operation, and control of the burner registers, flame detection system, and affected boiler equipment.

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

Bidders shall include a minimum of two (2) weeks of support following startup to ensure stable operation of both the burner and flame detection systems. In addition, bidders shall include at least one (1) additional week (including travel, room, and boarding expenses) at IPP job site for two (2) people to witness and participate in the full-load operational testing. Should extended problems arise as a direct result of the Contract modifications, Contractor shall provide whatever level of support is required to address the problems, in a timely manner.

8. Installation: A primary focus of the Contract shall be the optimization of the Work to occur during unit off-line hours. Detailed planning of the Scope of Work for the Contract shall include a level of redundancy in equipment and manpower to ensure that guaranteed schedules are met.
- a. Bidders may submit proposals for installation of the burners and scanner systems as capabilities dictate. Where bidder elects to provide an installation bid, all equipment and materials of installation shall be provided by bidder. Where bidder elects not to bid the installation of these systems all equipment and materials of installation shall be provided by Contractor with the exception of wiring, conduit, and associated hardware for cable routing. Wiring schematics, wiring and installation specifications, burner flow instrumentation, local display/junction boxes, burner temperature display, and cold-junction boxes shall be supplied by Contractor with pre-installed termination hardware as defined in Division F2, Article 5, Burner Design.
 - b. Contractor shall be responsible for any modifications and/or damage to or around the burner openings or windbox associated with the Work. This includes, but is not limited to, refractory, seal plates, and waterwall tubing.
 - c. Contractor shall be responsible for design and installation of any modifications required for interface with the existing coal pipes. This includes modifications to routing, size, and connection to the new burners.
 - d. Contractor shall be responsible for design and installation of any additions or modifications to windboxes, windbox supports, burner supports, waterwall tubing, buckstay system, etc., or any other existing system or piece of equipment required for proper and successful operation of the new burners and/or flame detection systems.
 - e. Contractor shall be responsible for connecting new equipment to IPSC existing facilities, to include furnishing and installing connections to plant seal air or plant instrument air (including instrument shutoff valves for each device) where required.

DIVISION F2

DETAILED SPECIFICATIONS - DETAILED REQUIREMENTS

- f. Contractor shall be responsible to maintain Work areas in an organized and safe manner throughout the execution of the installation plan. IPSC shall retain the right to assess and require correction of any areas or situations it deems as impacting ongoing operations and maintenance. Waste material produced during a shift shall be disposed of by the end of the following shift.

At the conclusion of each outage, Contractor shall ensure that all Work areas associated with the Contract are restored, replaced, and/or cleaned in a manner similar in appearance to that found prior to the outage.

- g. Contractor shall provide and install replacement insulation anchors, insulation, lagging, and all other materials required for complete restoration of any and all boiler external surface removed or disturbed during or resulting from Contract Work. Contractor shall replace or install insulating materials of a quality meeting or exceeding the insulation system currently in use on the respective boiler and system components.


Spec. 45606

ATTACHMENT 1

SCANNER, LIGHTER AND FUEL SPECIFICATIONS, AND OUTLINE DRAWINGS

IP7_031445

Operating Instructions for **CFA OIL LIGHTER**



Babcock & Wilcox

IP7_031446

TABLE OF CONTENTS

SCOPE	3
DESCRIPTION AND PURPOSE.....	3
FUEL OIL.....	4
LIGHTER CAPACITY	4
ATOMIZING REQUIREMENTS.....	4
HIGH ENERGY IGNITOR.....	4
AIR CYLINDER DRIVES	4
SEAL AIR.....	5
PURGE AIR.....	5
ADJUSTMENTS.....	5
OPERATION	6
MAINTENANCE.....	6

DR91-1V-7AS Sept 81

SCOPE

These instructions deal with the care and operation of the CFA Oil Lighter. Separate instructions cover the lighter control, main burner, and related equipment.

DESCRIPTION AND PURPOSE

The CFA Lighter is a complete shop assembly consisting of a mounting sleeve, oil atomizer, high energy spark ignitor (HEI), and air cylinder drives for inserting and retracting the lighter components.

To achieve optimal atomization of the fuel, the lighter employs a steam or air assisted oil atomizer. The ignition source for the lighter fuel is provided by a high energy spark ignitor. Separate air cylinder drives are provided for positioning the lighter and high energy ignitor probe. The atomizer is inserted for firing and retracted when the lighter is out of service. Similarly, the ignitor probe is inserted to ignite the lighter fuel and retracted at the completion of the trial for ignition period. The ignitor probe is also inserted and energized when the atomizer is purged following normal lighter shutdown. Lighter insertion is proven by three-way air valves on each lighter which are connected in series to the control. Drawings of the lighter assembly and oil atomizer are at the rear of this instruction.

The CFA Lighter is designed primarily for lighting the main burner and stabilizing ignition of the main burner. The high input capability and the independently retractable ignitor probe feature also make it possible to utilize the lighter for boiler warmup. However, combustion efficiency and stack emissions are closely dependent upon the secondary air temperature. Normally, a minimum secondary air temperature of 70°F is required to ensure lighter flame stability. If the lighters are to be operated for extended periods for boiler warmup, steam or water coil air heaters should be used to raise secondary air temperature to a minimum of 150°F. In addition, lighter input should be limited to a maximum of 15 MKB per hour. This will provide acceptable combustion efficiency and stack appearance during the warmup period. Operation at higher capacities may proceed at an air temperature of approximately 250°F.

Performance of the lighter is highly dependent upon proper operation of the oil atomizer. Pluggage of the atomizer sprayer plate will result in poor atomization and/or poor distribution of the oil spray. Incomplete combustion and a distinct possibility of raw oil carry-over can result from operation under these conditions. Sprayer plate pluggage can be particularly troublesome during initial operation when mill scale and other foreign material left in the oil and atomizing medium piping can collect and plug the sprayer plate ports. Since lighters are often operated for extended periods during initial start-up while boiling-out and blowing steam lines, frequent inspection and cleaning of the atomizers is especially important during this period. However, routine inspection and cleaning should continue during subsequent operation.

Caution - If the sprayer plate should become plugged during operation, oil and atomizing medium under pressure may be trapped in the atomizer. When this condition exists, uncoupling of the atomizer will result in oil and atomizing medium spray from the atomizer body. Extreme care should be taken to avoid personal injury whenever the atomizer is uncoupled.

The B&W Type LC Lighter Control System is normally provided with the CFA Lighter. The control package performs all lighter functions: including lighter and high energy ignitor insertion and retraction, fuel, atomizing medium, and purging control automatically and in the proper sequence. Separate instructions are provided for the operation and maintenance of the Lighter Control System.

FUEL OIL

The CFA Lighter can be fired using No. 2 or No. 6 fuel oil as specified in ASTM D-396-73. Maximum allowable oil viscosity at the lighter atomizer is 135 ssu. No. 6 fuel oil will, therefore, require preheating. The oil temperature required at the lighter depends on the temperature - viscosity characteristics of the particular oil being fired. Normally, oil temperature in the range of 180° - 225° is required to maintain No. 6 oil at the above viscosity.

To help prevent sprayer plate oil port pluggage, B&W supplied lighter control packages designed for No. 2 oil service are equipped with 100 mesh oil filters. These filters serve a dual purpose of protecting the valves contained in the control package while also eliminating foreign material which could result in sprayer plate pluggage. Piping systems designed for service with No. 6 oil where individual shut-off valves are supplied for each lighter, should include a 32 mesh filter in the oil supply line upstream of the oil shut-off valves.

To prevent rapid pluggage of these filters and to protect upstream equipment, duplex strainers should be installed in the fuel oil pump suction and discharge piping. It is generally recommended that strainers in the suction line have a mesh no coarser than 1/16" and those on pump discharge be no coarser than 1/32".

LIGHTER CAPACITY

The lighter capacity can be varied within limits by adjusting the fuel oil pressure at the lighter. Capacity curves for the sprayer plate are located in the Performance Section.

ATOMIZING REQUIREMENTS

Air or dry steam (400 ° F maximum temperature) is required for atomization. Pressure and flow requirements can be found on the sprayer plate performance curve. It is recommended that lighters firing heavy fuel oil utilize steam for atomization. It is essential that atomizing media piping also be adequately filtered to reduce the potential for sprayer plate pluggage problems. B&W supplied lighter controls incorporate 100 mesh filters for this purpose.

HIGH ENERGY IGNITOR

Separate operating and maintenance instructions for the High Energy Ignitor (HEI) System are attached.

The HEI Power Supply may be mounted to any convenient structural steel. Due to ambient temperature limitations, mounting on the burner windbox is not permissible.

The ignitor is energized during the lighter ignition and post purge periods only and should be retracted at all other times. Ignitor operating time must be limited to the duty cycle specified by the manufacturer. Premature failure of power supply components will result from operation in excess of these limits.

AIR CYLINDER DRIVES

The air cylinder drives for the atomizer and High Energy Ignitor Probe require clean, dry compressed air at 100 to 125 psi. Flow control valves are provided on the cylinder air connections to control the speed of stroke.

SEAL AIR

Seal air is not required on balanced draft units. On pressure fired units, however, seal air should be supplied at the connection provided in the lighter mounting sleeve. Approximate requirements are 6 SCFM at 2" H₂O above windbox pressure. Aspirating air at 50-90 psi should also be available at this connection on pressure fired units for use during atomizer or HEI probe removal.


PURGE AIR

Air or dry steam at 90-150 psi is required to purge oil from the atomizer when the lighter is taken out of service.

ADJUSTMENTS

Before attempting to operate the lighter, the following checks and adjustments must be made to the lighter, its control and piping:

1. The atomizer and its sprayer plate should be cleaned and checked for correct assembly. Refer to the attached atomizer assembly drawing.
2. Adjustment is provided for positioning the ignitor probe with respect to the lighter shield and atomizer tip. This setting is made by use of the adjustable probe clamp attached to the ignitor drive cylinder rod.
3. The High Energy Ignitor Power Supply must be connected to the HEI probe with the conduit connector provided. Ignitor conduit is supplied in standard 15 ft. length and should not be adjusted in the field. Extra conduit length should be coiled and stored in a location where it will not interfere with other lighter components or burner front equipment.
4. The flow control valves on the air cylinder drives should be set to provide a smooth stroke and to prevent slamming the lighter components in either the inserted or retracted positions.
5. The actuator for the air interlock valve should be set to provide 3/16" maximum travel on the valve plunger.
6. The oil, atomizing and purge air lines should be steam cleaned to remove all debris and scale likely to clog the atomizer sprayer plate.
7. All piping connections should be leak tested and the piping should be checked for interferences with the lighter or ignitor stroke. All flexible hoses should be adjusted to hang in a vertical loop to permit lighter and ignitor movement without straining the hoses.



8. Strainers in the oil and atomizing media piping should be checked prior to start-up and cleaned as required. Condition of the strainers should be closely monitored, especially during initial operation.

OPERATION

Prior to operating the lighter, the operator should be thoroughly familiar with the lighter control, interlocks, main burners, and related equipment. Operation of the lighter in relation to furnace purging, air flow, and main fuel flow is described in the burner operating instructions. Normally, the four (4) operating conditions described below exist for the lighter.

1. **Retracted** - When the lighter is not in use, it should be retracted from its firing position to prevent furnace radiation from over-heating the atomizer sprayer plate and end cap. Lighter fuel oil, atomizing medium, and purge air are turned off and the ignitor is de-energized. Air pressure is normally maintained on the drive cylinders to keep the lighter atomizer and ignitor probe retracted.
2. **Light-Off** - The atomizer is moved to the firing position by reversing the air pressure to the air cylinder drive. When the lighter is in the firing position, the atomizing medium valve is opened to purge condensate from the piping. At the completion of the pre-purge period, the high energy ignitor probe is inserted and energized and the oil shut-off valve is opened. The ignitor probe is energized for the "Trial For Ignition" Period and then retracted by the ignitor drive cylinder independent of the atomizer. If successful lighter ignition is not established during this period, a normal shutdown should be initiated.
3. **Normal Shutdown** - During a normal shutdown of the lighter, all fuel oil is purged from the atomizer to prevent oil from dripping into the burner or windbox and to prevent atomizer coking. Purge media at a minimum of 90 psi is admitted to the atomizer after the fuel oil valve is closed with the High Energy Ignitor inserted and energized. Purging should continue for a minimum of two minutes. When the purge is complete, the ignitor is de-energized and the lighter and ignitor probe are retracted. The atomizing air or steam is left on during the purge period to prevent oil from backing up into the atomizer.
4. **Emergency Shutdown** - The emergency stop sequence requires that the oil and atomizing media valves be closed immediately and the lighter retracted without purging. Stopping in this mode will leave the lighter atomizer full of oil and subject to coking and dripping oil on burner parts, so the lighter should be sequenced through a normal shut-down as soon as conditions permit. The lighter Emergency Stop is required only when purging the atomizer will result in hazardous conditions.

MAINTENANCE

Since each installation operates under different conditions, a maintenance schedule must be established for each installation. The following maintenance schedule is recommended until operating experience indicates otherwise.

Weekly - Remove and clean the atomizer cap and sprayer plate, to prevent the cap and/or sprayer plate from seizing, a high temperature anti-seize compound should be used on the threads. (See Caution on Page 3).

Sprayer plates orifices are subject to wear so frequent inspection should be made to check for oversized or elongated holes. Orifice sizes can be readily checked by passing a twist drill of the specified size through each of the oil, atomizing medium and exit ports. In general, sprayer plates should be replaced when the orifice drill size exceeds the specified diameter by two drill sizes. Plates showing irregular orifice wear should be replaced immediately due to the potential for problems with maldistribution of the oil spray.


Rapid sprayer plate wear is usually caused by abrasive foreign matter in the oil or moisture in the atomizing medium.

Monthly or as required. - The lighter should be sequenced through a normal start and shutdown sequence to allow inspection for leaks in all fuel oil, atomizing media and control air connections. Proper mechanical operation of all moving parts and operation of the High Energy Ignition System should also be verified.





Yearly - All air cylinders should be flushed and lubricated. Condition of packing seals for the atomizer and High Energy Probe should be checked and replaced if necessary.

IP7_031453

REFERENCE LIST			REFERENCE LIST		
SYMBOL	DESCRIPTION	DWG. MK.	SYMBOL	DESCRIPTION	DWG. MK.
A	ATOMIZER ASSY	269375 E MK-1 LH	AN	ANALOG SIGNAL CABLE	269375 E MK-2 RH
B	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
C	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
D	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
E	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
F	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
G	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
H	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
I	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
J	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
K	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
L	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
M	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
N	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
O	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
P	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
Q	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
R	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
S	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
T	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
U	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
V	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
W	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
X	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
Y	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH
Z	ATOMIZER BODY	269375 E MK-1 LH	AP	ANALOG SIGNAL CABLE	269375 E MK-2 RH



- NOTES:**
- 1-LIGHTER MUST BE PACKED TO PROTECT FROM WATER & MOISTURE DURING SHIPMENT.
 - 2-PLUG ALL PORTS FOR SHIPMENT.
 - 3-VLV. FLOW CONTROL ASSY (AH & AG & AM) TO BE INSTALLED ON AIR CYLINDER 'U' BEFORE AIR CYLINDERS ARE BOLTED TO PLATE 'F'.
 - 4-SUPPORT AND SEAL ASSY SYM 'AK' TO BE ASSEMBLED TO LIGHTER BEFORE LIGHTER SHIELD SYM 'AJ' IS WELDED IN PLACE. (SEE VIEW BB)
 - 5-FIVE LARKS IN PROBE PIPE WITH PROBE TIP EXTENDING 1 IN. BEYOND SHIELD WITH 4-1/4 IN. INCREMENTS FIRST MARK FLUSH WITH PROBE CLAMP SYM 'L'.
 - 6-ALON SYM AS BEFORE WELDING TO INSURE ATOMIZER BODY IS HORIZONTAL TO ALLOW HOSES TO BE INSTALLED IN A VERTICAL POSITION AND PARALLEL TO EACH OTHER TO PREVENT TWISTING.
- FOR TO GRIND SYM AS TO INSURE CLEARANCE



SYMBOL	DESCRIPTION	DWG. MK.
1	ATOMIZER ASSY	269375 E MK-1 LH
2	ATOMIZER BODY	269375 E MK-1 LH
3	ATOMIZER BODY	269375 E MK-1 LH
4	ATOMIZER BODY	269375 E MK-1 LH
5	ATOMIZER BODY	269375 E MK-1 LH
6	ATOMIZER BODY	269375 E MK-1 LH
7	ATOMIZER BODY	269375 E MK-1 LH
8	ATOMIZER BODY	269375 E MK-1 LH
9	ATOMIZER BODY	269375 E MK-1 LH
10	ATOMIZER BODY	269375 E MK-1 LH

ASSEMBLY OIL LIGHTER TYPE	69375 E 10
---------------------------------	------------

Spec. 45606

ATTACHMENT 2

FUEL OIL ANALYSIS REPORT

IP7_031456

Intermountain Power Service Corporation
Fuels Laboratory
Fuel Oil Analysis Report

Date Analyzed:	7-2-03
Type of Fuel:	FUEL OIL
Supplier:	
Date Sampled:	6-29-03 17:30
Sampling Point:	TRUCK COMPOSITE
Sampled By:	RLH/JB
Sample Number:	8597

Comments: _____

ANALYTICAL RESULTS

Analysis	Method	Results
BTU/lb	ASTM D2382-88	19386
Sulfur %	ASTM D1552-90	0.3%
Cloud Point	ASTM D2500-91	12°F
Pour Point	ASTM D97-87	5°F
Water %	ASTM D1744-83	47.14g/0.00471%
Specific Gravity	ASTM D1298-85	57
API	ASTM D1298-85	33.2 / 32.2
Temperature		75°F

Comments: Wt. - 0.4881 W - 5.8 A - 9.1

Analyzed By: JB.

IP7_031457

Intermountain Power Service Corporation
Fuels Laboratory
Fuel Oil Analysis Report

Date Analyzed:	7-2-03
Type of Fuel:	FUEL OIL
Supplier:	
Date Sampled:	7-2-03
Sampling Point:	BV-59
Sampled By:	J/B
Sample Number:	8598

Comments: _____

ANALYTICAL RESULTS

Analysis	Method	Results
BTU/lb	ASTM D2382-88	19149
Sulfur %	ASTM D1552-90	0.3%
Cloud Point	ASTM D2500-91	-3 °F
Pour Point	ASTM D97-87	-11 °F
Water %	ASTM D1744-83	49.8µg 0.00498%
Specific Gravity	ASTM D1298-85	.55
API	ASTM D1298-85	33.8/32.5 °C API
Temperature		79 °F

Comments: WT. = 0.3285 W-7.2 6.7

Analyzed By: J.B.

IP7_031458

Spec. 45606

ATTACHMENT 3

GENERAL COAL PROPERTIES

IP7_031459

Jul-03

coal sampled May 2003

Weighted Totals

<u>Mine</u>	sampled	% of Total	% Na2O	HGI	Softening	HHVC Btu/lb	% H2O	% Ash	% Volatile	% Fixed Carbon	% Sulfur
	Total Tonnage				Temp						
Genwall Resources	27,501.08	5.81	2.04	45.5	2,148	12,426	6.95	8.51	39.04	45.50	0.67
Skyline (Product B) trucks	0.00	0.00	0.97	43.7	2,137	12,562	5.51	6.51	43.20	44.78	0.40
SUFCO (Product A)	195,613.19	41.35	2.96	42.4	2,122	11,292	8.37	11.06	37.57	43.00	0.39
Andalex	64,932.12	13.73	1.12	42.1	2,237	12,084	5.65	10.07	37.27	47.01	0.60
Andalex AMQ	0.00	0.00	0.84	39.1	2,277	11,981	6.64	9.44	34.78	49.14	0.56
West Ridge Resources	47,378.20	10.01	1.16	46.4	2,200	12,848	5.75	7.46	37.06	49.73	1.13
West Ridge Resources spc	27,929.48	5.90	0.94	45.9	2,234	13,069	5.22	7.07	37.53	50.18	1.18
Coastal-Dugout	26,777.20	5.66	0.48	40.4	2,357	11,977	5.80	11.45	35.72	47.03	0.68
Arch-Dugout (product B)	82,943.41	17.53	1.37	41.7	2,217	11,826	6.49	10.82	36.38	46.31	0.56
Arch (spot)	0.00	0.00	0.49	39.3	2,299	11,959	6.22	10.96	33.66	49.16	0.71
Totals	473,074.68	100.00	1.94	42.91	2,184	11,860	6.99	10.16	37.25	45.60	0.60

Ref Executive Summary
of ABE
Geopros

IP7_031460

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 11, 2003

MONTH OF: May, 2003

MINE: Andalex Resources

CONTRACT NUMBER: 00146

SHIPMENT NUMBERS: 03-178, 196, 206, 211, 216, 222 and 224.

TOTAL TONNAGE: 64932.12

TOTAL SHIPMENTS: 7

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32614			LAB NO. 32563	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	5.65	xxxx	7.16	xxxx
%ASH	10.07	10.67	10.10	10.88
%VOLATILE	37.27	39.50	37.18	40.05
%FIXED CARBON (by diff.)	47.01	49.83	45.56	49.07
%SULFUR	0.60	0.64	0.61	0.66
BTU/LB	12084	12808	11833	12746
%FLUORINE	0.0073	0.0077	0.0082	0.0088
HGI =		42.1	HGI =	n/a
ASH ANALYSIS				
	IPSC LAB		MINE SPLIT	
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	1.12		1.20	
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2192		xxxx	
ST=	2237		xxxx	
HT=	2413		xxxx	
FT=	2518		xxxx	

IP7_031461

INTERMOUNTAIN POWER SERVICE CORPORATION**CALCULATED COMPARISONS
COAL DELIVERIES**

MONTH: May, 2003
MINE: Andalex Resources
TRAINS: 03-178, 196, 206, 211, 216, 222 and 224.
TONNAGE: 64932.12

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.41	5.65
%DRY ASH:	10.72	10.67
%DRY SULFUR:	0.65	0.64
DRY BTU / LB:	12772	12808
AS RECEIVED BTU / LB:	11953	12084
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.12	
%DRY ASH:	11.04	
%DRY SULFUR:	0.67	
DRY BTU / LB:	12740	
AS RECEIVED BTU / LB:	11833	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.20	7.16
%DRY ASH:	10.92	10.88
%DRY SULFUR:	0.66	0.66
DRY BTU / LB:	12756	12746
AS RECEIVED BTU / LB:	11838	11833

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 11, 2003

MONTH OF: May, 2003

MINE: Arch-Dugout

CONTRACT NUMBER: 00472

SHIPMENT NUMBERS: 03-184, 188, 192, 199, 203, 213, 215, 221 and 226.

TOTAL TONNAGE: 82943.41

TOTAL SHIPMENTS: 9

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32613			LAB NO. xxxx	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	6.49	xxxx	xxxx	xxxx
%ASH	10.82	11.57	xxxx	xxxx
%VOLATILE	36.38	38.91	xxxx	xxxx
%FIXED CARBON (by diff.)	46.31	49.52	xxxx	xxxx
%SULFUR	0.56	0.60	xxxx	xxxx
BTU/LB	11826	12646	xxxx	xxxx
%FLUORINE	0.0074	0.0079	xxxx	xxxx
	HGI =	41.7	HGI =	xxxx
ASH ANALYSIS				
	IPSC LAB	MINE SPLIT		
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	1.37	xxxx		
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2180	xxxx		
ST=	2217	xxxx		
HT=	2254	xxxx		
FT=	2434	xxxx		

IP7_031463

INTERMOUNTAIN POWER SERVICE CORPORATION

CALCULATED COMPARISONS
COAL DELIVERIES

MONTH: May, 2003
MINE: Arch-Dugout 00472
TRAINS: 03-184, 188, 192, 199, 203, 213, 215, 221 and 226.
TONNAGE: 82943.41

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.22	6.49
% DRY ASH:	11.47	11.57
% DRY SULFUR:	0.60	0.60
DRY BTU / LB:	12610	12646
AS RECEIVED BTU / LB:	11699	11826
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.47	
% DRY ASH:	12.22	
% DRY SULFUR:	0.59	
DRY BTU / LB:	12515	
AS RECEIVED BTU / LB:	11580	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.51	
% DRY ASH:	12.10	
% DRY SULFUR:	0.59	
DRY BTU / LB:	12506	
AS RECEIVED BTU / LB:	11567	

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 11, 2003

MONTH OF: May, 2003

MINE: Coastal-Dugout

CONTRACT NUMBER: 70150

SHIPMENT NUMBERS: 03-182, 189 and 195.

TOTAL TONNAGE: 26777.20

TOTAL SHIPMENTS: 3

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32616			LAB NO. xxxx	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	5.80	xxxx	xxxx	xxxx
%ASH	11.45	12.15	xxxx	xxxx
%VOLATILE	35.72	37.92	xxxx	xxxx
%FIXED CARBON (by diff.)	47.03	49.93	xxxx	xxxx
%SULFUR	0.68	0.72	xxxx	xxxx
BTU/LB	11977	12715	xxxx	xxxx
%FLUORINE	0.0086	0.0091	xxxx	xxxx
HGI =		40.4	HGI =	xxxx
ASH ANALYSIS				
	IPSC LAB	MINE SPLIT		
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	0.48	xxxx		
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2312	xxxx		
ST=	2357	xxxx		
HT=	2407	xxxx		
FT=	2676	xxxx		

IP7_031465

INTERMOUNTAIN POWER SERVICE CORPORATION**CALCULATED COMPARISONS
COAL DELIVERIES**

MONTH: May, 2003
MINE: Coastal-Dugout 70150
TRAINS: 03-182, 189 and 195.
TONNAGE: 26777.20

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.57	5.80
% DRY ASH:	12.19	12.15
% DRY SULFUR:	0.72	0.72
DRY BTU / LB:	12710	12715
AS RECEIVED BTU / LB:	11875	11977
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.47	
% DRY ASH:	13.20	
% DRY SULFUR:	0.75	
DRY BTU / LB:	12491	
AS RECEIVED BTU / LB:	11683	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.53	
% DRY ASH:	13.14	
% DRY SULFUR:	0.74	
DRY BTU / LB:	12562	
AS RECEIVED BTU / LB:	11742	

IP7_031466

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 11, 2003

MONTH OF: May, 2003

MINE: Genwal Resources

CONTRACT NUMBER: 99405

SHIPMENT NUMBERS: 03-197, 228 and 229.

TOTAL TONNAGE: 27501.08

TOTAL SHIPMENTS: 3

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32617			LAB NO. 32580	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	6.95	xxxx	7.62	xxxx
%ASH	8.51	9.14	8.40	9.09
%VOLATILE	39.04	41.96	38.64	41.83
%FIXED CARBON (by diff.)	45.50	48.90	45.34	49.08
%SULFUR	0.67	0.72	0.71	0.77
BTU/LB	12426	13355	12396	13419
%FLUORINE	0.0072	0.0077	0.0088	0.0095
	HGI =	45.5	HGI =	45.2
ASH ANALYSIS				
	IPSC LAB		MINE SPLIT	
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	2.04		1.91	
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2148		2179	
ST=	2233		2223	
HT=	2284		2266	
FT=	2371		2402	

IP7_031467

INTERMOUNTAIN POWER SERVICE CORPORATION

**CALCULATED COMPARISONS
COAL DELIVERIES**

MONTH: May, 2003
MINE: Genwal Resources
TRAINS: 03-197, 228 and 229.
TONNAGE: 27501.08

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.65	6.95
% DRY ASH:	9.02	9.14
% DRY SULFUR:	0.75	0.72
DRY BTU / LB:	13389	13355
AS RECEIVED BTU / LB:	12365	12426
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.89	
% DRY ASH:	9.29	
% DRY SULFUR:	0.83	
DRY BTU / LB:	13354	
AS RECEIVED BTU / LB:	12301	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	7.94	7.62
% DRY ASH:	9.06	9.09
% DRY SULFUR:	0.74	0.77
DRY BTU / LB:	13346	13419
AS RECEIVED BTU / LB:	12287	12396

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 15, 2003

MONTH OF: May, 2003

MINE: Southern Utah Fuel Co.

CONTRACT NUMBER: 99149

SHIPMENT NUMBERS: 03-179,181,183,185,187,191,193,194,198,200,202,204,205,
207,209,210,214,217,219,223 and 225.

TOTAL TONNAGE: 195613.19

TOTAL SHIPMENTS: 21

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32612			LAB NO. 32776	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	8.37	xxxx	9.05	xxxx
%ASH	11.06	12.07	11.26	12.38
%VOLATILE	37.57	41.00	37.54	41.28
%FIXED CARBON (by diff.)	43.00	46.93	42.15	46.34
%SULFUR	0.39	0.43	0.42	0.46
BTU/LB	11292	12324	11118	12224
%FLUORINE	0.0072	0.0079	xxxx	xxxx
HGI =		42.4	HGI =	xxxx
ASH ANALYSIS				
	IPSC LAB	MINE SPLIT		
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	2.96	xxxx		
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2122	xxxx		
ST=	2154	xxxx		
HT=	2183	xxxx		
FT=	2271	xxxx		

IP7_031469

INTERMOUNTAIN POWER SERVICE CORPORATION

CALCULATED COMPARISONS
COAL DELIVERIES

MONTH: May, 2003

MINE: Southern Utah Fuel Co.

TRAINS: 03-179,181,183,185,187,191,193,194,198,200,202,204,205,207,209,210,
214,217,219,223 and 225.

TONNAGE: 195,613.19

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	9.21	8.37
% DRY ASH:	12.19	12.07
% DRY SULFUR:	0.44	0.43
DRY BTU / LB:	12259	12324
AS RECEIVED BTU / LB:	11130	11292
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	10.02	
% DRY ASH:	12.35	
% DRY SULFUR:	0.43	
DRY BTU / LB:	12253	
AS RECEIVED BTU / LB:	11025	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	9.85	9.05
% DRY ASH:	12.28	12.38
% DRY SULFUR:	0.44	0.46
DRY BTU / LB:	12258	12224
AS RECEIVED BTU / LB:	11051	11118

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 11, 2003

MONTH OF: May, 2003

MINE: West Ridge

CONTRACT NUMBER: 00442

SHIPMENT NUMBERS: 03-180, 190, 201, 212 and 218.

TOTAL TONNAGE: 47378.20

TOTAL SHIPMENTS: 5

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32615			LAB NO. 32582	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	5.75	xxxx	6.33	xxxx
%ASH	7.46	7.92	7.39	7.89
%VOLATILE	37.06	39.32	36.88	39.37
%FIXED CARBON (by diff.)	49.73	52.76	49.40	52.74
%SULFUR	1.13	1.20	1.16	1.24
BTU/LB	12848	13632	12746	13607
%FLUORINE	0.0066	0.0070	0.0062	0.0066
	HGI =	46.4	HGI =	46.2
ASH ANALYSIS				
	IPSC LAB	MINE SPLIT		
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	1.16	1.03		
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2162	2208		
ST=	2200	2242		
HT=	2239	2373		
FT=	2478	2529		

IP7_031471

INTERMOUNTAIN POWER SERVICE CORPORATION

**CALCULATED COMPARISONS
COAL DELIVERIES**

MONTH: May, 2003
MINE: West Ridge 00442
TRAINS: 03-180, 190, 201, 212 and 218.
TONNAGE: 47378.20

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.59	5.75
% DRY ASH:	8.11	7.92
% DRY SULFUR:	1.22	1.20
DRY BTU / LB:	13610	13632
AS RECEIVED BTU / LB:	12713	12848
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.48	
% DRY ASH:	8.30	
% DRY SULFUR:	1.24	
DRY BTU / LB:	13658	
AS RECEIVED BTU / LB:	12773	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.55	6.33
% DRY ASH:	8.13	7.89
% DRY SULFUR:	1.23	1.24
DRY BTU / LB:	13629	13607
AS RECEIVED BTU / LB:	12736	12746

IP7_031472

**INTERMOUNTAIN POWER SERVICE CORPORATION
TRAIN SHIPMENTS, MONTHLY COMPOSITE**

DATE: July 11, 2003

MONTH OF: May, 2003

MINE: West Ridge 00479

CONTRACT NUMBER: 00479

SHIPMENT NUMBERS: 03-186, 208 and 227.

TOTAL TONNAGE: 27929.48

TOTAL SHIPMENTS: 3

COAL ANALYSIS				
IPSC LAB, AUTO SAMPLE COMPOSITE			MINE SPLIT	
LAB NO. 32618			LAB NO. 32581	
	AS RECEIVED	DRY BASIS	AS RECEIVED	DRY BASIS
%MOISTURE	5.22	xxxx	6.17	xxxx
%ASH	7.07	7.46	6.86	7.31
%VOLATILE	37.53	39.60	37.14	39.58
%FIXED CARBON (by diff.)	50.18	52.94	49.83	53.11
%SULFUR	1.18	1.24	1.16	1.24
BTU/LB	13069	13788	12941	13792
%FLUORINE	0.0055	0.0058	0.0058	0.0062
	HGI =	45.9	HGI =	47.4
ASH ANALYSIS				
	IPSC LAB	MINE SPLIT		
%SODIUM OXIDE, Na ₂ O, IGNITED BASIS =	0.94	0.91		
FUSION TEMP., REDUCING ATMOSPHERE; ID=	2185	2223		
ST=	2234	2290		
HT=	2367	2396		
FT=	2532	2501		

IP7_031473

INTERMOUNTAIN POWER SERVICE CORPORATION

**CALCULATED COMPARISONS
COAL DELIVERIES**

MONTH: May, 2003
MINE: West Ridge 00479
TRAINS: 03-186, 208 and 227.
TONNAGE: 27929.48

IPSC LAB, AUTO SAMPLER	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	5.84	5.22
% DRY ASH:	7.33	7.46
% DRY SULFUR:	1.23	1.24
DRY BTU / LB:	13721	13788
AS RECEIVED BTU / LB:	12920	13069
MINE LAB, FINAL	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.41	
% DRY ASH:	7.65	
% DRY SULFUR:	1.24	
DRY BTU / LB:	13752	
AS RECEIVED BTU / LB:	12870	
IPSC LAB, MINE SPLIT	CALCULATED	LAB VALUE
% TOTAL MOISTURE:	6.45	6.17
% DRY ASH:	7.49	7.31
% DRY SULFUR:	1.25	1.24
DRY BTU / LB:	13755	13792
AS RECEIVED BTU / LB:	12867	12941

IP7_031474

TLT-Babcock, INC.
CONTRACT INFORMATION SHEET

A.O.

1	PERFORMANCE DATA <input checked="" type="checkbox"/> F.D. FAN <input type="checkbox"/> I.D. FAN <input type="checkbox"/> P.A. FAN						
2	(ALL QUANTITIES ARE PER FAN) 25.20 IN. HG. 4676' elev. ASSUMED BAROMETRIC PRESSURE:						
3	Two fan operation						
4	OPERATING POINT	1	2	3	4	5	6
5	BOILER LOAD	TB	MCR	100	75	50	25
6	INLET FLOW, M LBS/HR	4018.3	3335.6	3135.8	2461.7	1712.2	904.1
7	INLET VOLUME, MCFM	1154.7	958.5	901.1	707.4	492.0	259.8
8	INLET TEMP., F.	110	110	110	110	110	110
9	INLET DENSITY, LBS/CU. FT.	.058	.058	.058	.058	.058	.058
10	INLET PRESSURE, IN. WG.	-1.5	-1.2	-1.1	-0.7	-0.4	-0.1
11	STATIC PRESS. INCR, IN. WG.	19.5	10.9	10.0	7.2	4.83	2.97
12	DYNAMIC PRESS. AT INLET, IN. WG.	0.98					
13	LOSS FOR TURNING BEND AND DAMPER, IN. WG.	0.30					
14	LOSS FOR SILENCER INLET/OUTLET, IN. WG.	0.50					
15	TOTAL PRESS. INCR, IN. WG.	21.28	12.12	11.08	7.87	5.15	3.06
16	TOTAL DELIVERY HEAD (ADIABATIC), FT. GAS	1867	1075	984	699	460	274
17	FAN EFFICIENCY	88.0	89.3	88.0	76.5	61.0	40.0
18	POWER REQUIRED AT FAN SHAFT, HP.	4305	2027	1770	1136	652	312
19	FAN SPEED: 880 RPM	Continued on C.I.S. 6B					
20	FAN TORQUE AT MAX. POINT: 25,693 FT. LBS.						
21	FAN WR ² : 30,840 LB-FT ²						
22							
23							
24							
25	DESIGN CONDITIONS BASED ON <input type="checkbox"/> TLT-B <input checked="" type="checkbox"/> PURCHASER SPECS FOR GUARANTEE PERFORMANCE SEE CIS-7						
26	FOR HEAD VS. VOLUME DIAGRAM SEE DWG: FOR SPEED-TORQUE CURVE SEE DWG:						
REL. NO. AND DATE 0-1/15/82							CONTRACT NO 548-0581

CIS-6 A

IP7_031475

TLT-Babcock, INC.
CONTRACT INFORMATION SHEET

A.O.

1	PERFORMANCE DATA <input checked="" type="checkbox"/> F.D. FAN <input type="checkbox"/> I.D. FAN <input type="checkbox"/> P.A. FAN						
2	(ALL QUANTITIES ARE PER FAN) ASSUMED BAROMETRIC PRESSURE: 25.20 IN. HG. 4676' elev.						
3	Single Fan Operation						
4	OPERATING POINT	7	8	9	10	11	
5	BOILER LOAD	MCR	100	75	50	25	
6	INLET FLOW, M LBS/HR	6671.2	6271.7	4923.5	3424.3	1808.2	
7	INLET VOLUME, MCFM	1917.0	1802.2	1414.8	984.0	519.6	
8	INLET TEMP., F.	110	110	110	110	110	
9	INLET DENSITY, LBS/CU. FT.	.058	.058	.058	.058	.058	
10	INLET PRESSURE, IN. WG.	-1.20	-1.10	-0.7	-0.4	-0.1	
11	STATIC PRESS. INCR, IN. WG.	10.9	10.0	7.2	4.83	2.97	
12	DYNAMIC PRESS. AT INLET, IN. WG.						
13	LOSS FOR TURNING BEND AND DAMPER, IN. WG.						
14	LOSS FOR SILENCER INLET/OUTLET, IN. WG.						
15	TOTAL PRESS. INCR, IN. WG.	15.81	14.34	9.87	6.12	3.33	
16	TOTAL DELIVERY HEAD (ADIABATIC), FT. GAS	1396	1266	876	549	298	
17	FAN EFFICIENCY	72.5	73.0	73.5	69.5	55.0	
18	POWER REQUIRED AT FAN SHAFT, HP.	6487	5493	2963	1366	495	
19	FAN SPEED: 880 RPM						
20	FAN TORQUE AT MAX. POINT: 38,715 FT. LBS.						
21	FAN WR ² : 30,840 LB-FT ²						
22							
23							
24							
DESIGN CONDITIONS BASED ON <input type="checkbox"/> TLT-B <input checked="" type="checkbox"/> PURCHASER SPECS FOR GUARANTEE PERFORMANCE SEE CIS-7							
FOR HEAD VS. VOLUME DIAGRAM SEE DWG: FOR SPEED-TORQUE CURVE SEE DWG:							
REL. NO. AND DATE 0-1/15/82						CONTRACT NO. 548-0581	

IP7_031476

STARTING TORQUE CURVE

PREDICTED PERFORMANCE

AXIAL FLOW FAN WITH BLADE ADJUSTMENT SIZE: FAF 37.5/18-1

FAN SPEED (N): 880/700 RPM

MOMENT OF INERTIA (WR^2): 30,840 LB X FT²


POWER REQ'D. @ MAX. POINT (N): 6487 BHP

FAN TORQUE @ MAX. POINT (M_D): 38,716 FT-LBS

MOTOR STUB RADIAL LOAD (P_R): 2400 LBS

MOTOR STUB AXIAL LOAD (P_A): 0 LBS

FAN PERFORMANCE CURVE:



CUSTOMER: Intermountain Power Project
Intermountain Generating Station Units 1, 2, 3 & 4
Project File 9255.62.3402
Forced Draft Fans

ENGR:

TLT-Babcock Contract No. 548-0581/0591/0601/0611

DRAWING NO. B-TLT 70014

Page no.

TLT - Babcock II

IP7_031477

PERFORMANCE TEST RESULTS

TYPE/# OF BLADES NA 12 OF 16

SPEED (RPM) 880

TOTAL PRESSURE INCREASE (IN. W.G.) @ .058 LB/FT

$\psi = 0.4$

$\psi = 0.3$

$\psi = 0.2$

$\psi = 0.1$

$\phi = 0.4$

$\phi = 0.3$

1000

$\alpha = 0.2$

500

1500

- ⊕ - GUARANTEE POINTS
- ▲ - TEST RUN POINTS
- ! - DENOTES STALL

18 POINT

MCR POINT

100% POINT

75% POINT

50% POINT

IP7_031478

PERFORMANCE TEST RESULTS

TYPE/# OF BLADES NA 16 OF 16

SPEED - (RPM) 880

24

22

20

18

16

14

12

10

8

6

4

2

$\psi = 0.4$

$\psi = 0.3$

$\psi = 0.2$

$\psi = 0.1$

TOTAL PRESSURE INCREASE (IN.W.G.) @ .058 LB/FT²

18 POINT

MCR POINT

100% POINT

75% POINT

50% POINT

⊕ - GUARANTEE POINTS

▲ - TEST RUN POINTS

! - DENOTES STALL

$\phi = 0.3$

1000

1500

500

1500

1500

1500

1500

1500

$\phi = 0.4$

IP7_031479

PERFORMANCE TEST RESULTS

TYPE/ # OF BLADES NA 14 OF 16

SPEED (RPM) 880

24
22
20
18
16
14
12
10
8
6
4
2

$\psi = 0.4$

$\psi = 0.3$

$\psi = 0.2$

$\psi = 0.1$

TOTAL PRESSURE INCREASE (IN. W.G.) @ 0.000 LB./FT.

TB POINT

MCR POINT

100% POINT

75% POINT

50% POINT

⊕ - GUARANTEE POINTS

▲ - TEST RUN POINTS

! - DENOTES STALL

$\phi = 0.4$

$\phi = 0.3$

1000


$\phi = 0.2$

500

ϕ

IP7_031480

PERFORMANCE TEST RESULTS



TLT-BABCOCK, INC.

VARIABLE PITCH AXIAL FAN

PREDICTED PERFORMANCE


TYPE FAF 37.5 / 18.0 - 1

SPEED (RPM) - 880

NO. STAGES - 1

BLADE TYPE - N.A.

NO. BLADES/STAGE - 16



----- AIR FLOW (ACFM x 10³)

1500

1000

500

2000

BA-560
NOVEMBER 24 1981

IP7_031482

TLT-BABCOCK, INC.

VARIABLE PITCH AXIAL FAN

PREDICTED PERFORMANCE


TYPE FAF 37.5/18.0-1

SPEED (RPM) - 880

BLADE TYPE - N.A.

NO. STAGES - 1

NO. BLADES/STAGE - 16



BA-560
NOVEMBER 24, 1981

IP7_031483

TLT-BABCOCK, INC.

VARIABLE PITCH AXIAL FAN

PREDICTED PERFORMANCE

TYP


FAF 37.5 / 18.0 - 1

SPEED (RPM) - 700

NO. STAGES - 1

BLADE TYPE - N.A.

NO. BLADES/STAGE - 16



IP7_031484

TLT-BABCOCK, INC.


VARIABLE PITCH AXIAL FAN

PREDICTED PERFORMANCE

T E FAF 37.5/18.0-1

SPEED (RPM) - 880/700 NO. STAGES -1

BLADE TYPE -N.A. NO. BLADES/STAGE-16



INTERMOUNTAIN POWER PROJECT

ED. FANS UNITS 1 THRU 4

PROJECT FILE 9255.62.340Z

TOTAL DELIVERY VOLUME (ACFM x 10³)

BA-560

NOVEMBER 24, 1981

TLT-BABCOCK, INC.

VARIABLE PITCH AXIAL FAN

PREDICTED PERFORMANCE


PE FAF 37.5 / 18.0 - 1

SPEED (RPM) - 880 / 700

NO. STAGES - 1

BLADE TYPE - N.A.

NO. BLADES/STAGE - 16



INTERMOUNTAIN POWER PROJECT
 F.D. FANS UNITS 1 THRU 4
 PROJECT FILE 9255.62.3402

BA-560
 NOVEMBER 24, 1981

IP7_031486

TLT-BABCOCK, INC.

VARIABLE PITCH AXIAL FAN

PREDICTED PERFORMANCE

TYF-


FAF 37.5 / 18.0 - 1

SPEED (RPM) -

NO. STAGES - 1

BLADE TYPE - N.A.

NO. BLADES/STAGE - 16



INTERMOUNTAIN POWER PROJECT
F.D. FANS UNITS 1 THRU 4
PROJECT FILE 9255.62.3402

TOTAL DELIVERY VOLUME (ACFM x 10³)

BA-0560
Sept 16, 1982

IP7_031487

Spec. 45606

ATTACHMENT 4

FD FAN PERFORMANCE

IP7_031488

ATTACHMENT 5

PA FAN PERFORMANCE

XEROX Telecopier 7017; 8- 5-92 ; 15:57 ;

6173610493-

180186449707#

O DEN SIROCCO

nden Sirocco Inc.

Westinghouse Plaza, Suite 300
e Park, MA 02136
ophone (617) 361-3700
(617) 361-0483

lowden Group Company

August 5, 1992

To: Intermountain Power Service Corp.
Attention: Mr. Jon Christensen
From: Mr. Cecil Ireland

F A X M E S S A G E

Subject: I.P.P. - PA Fan Performance

Please find herewith revised curves for the PA fans at Intermountain Power, Delta, Utah. We apologize for our poor response in getting these curves out to you.

We have redrawn the curves, making separate ones for high and low speed.

The output of the top (90°) curve has been reduced slightly in line with other test data. The vane closure curves have been 'bunched' towards the tr curve and this makes the angles at the test points agree closely with what recorded during the tests. The power curves have been reconstructed to gi efficiencies observed on other tests and also to give the as - tested efficiencies at Intermountain. Finally, we have labelled the curves in degrees from closed, which is in line with your nomenclature. These now in effect, customized curves for the Intermountain project.

Turning now to Westinghouse report WMC-EEB-92-002, this redefines allc motor powers as 5000 HP at 1194 RPM and 3200 HP at 897 RPM and it is understanding that a 1.15 service factor on top of these values can ' accommodated.

IP7_031490

Mr. Jon Christensen

- 2 -

August 5, 1992

Two-Fan Low Speed Operation

We have indicated the nominal limit of 3,200 HP on the graph and it may be seen that any point on the curve is well within this power, without having to use any of the service factor.

One-Fan High Speed Operation

The tests showed the operating system to be to the right of the original specified system and we have shown this operating system as a dotted line. It is assumed, for purposes of discussion here, that higher fan loadings would lie on this line. Again we have shown lines for the power limitations. It may be seen that a duty of 375,000 CFM at 56.5 ins. SP can be reached at 5,000 BHP and a duty of 413,000 CFM at 69 ins. SP can be reached at 5,750 BHP.

We also include, for reference, the test results summary sheet originally faxed to you 12/10/91.

We hope the foregoing will allow you to proceed with your evaluation. If you have further questions regarding specific duties or conditions, or relative efficiencies, please let us know.

Regards,

Cecil Ireland

Cecil Ireland

CI/arm-1368E

cc: J. McLaughlin - Aurora, CO
L. Krieger - Aurora, CO
J. Srivastava - Hyde Park, MA
J. Sharer - Hyde Park, MA

Enclosures:

(Total pages faxed: 5)


IP7_031491

INTERMOUNTAIN POWER
2312D D-X-7.1V PA FAN
897 RPM - 0.0586 DENSITY
JULY 92 REVISED CURVE

2- FAN OPERATION
ORIGINAL SPECIFIED SYSTEM

JUNE 91 TESTS

MOTOR LIMIT 100 SE



INTERMOUNTAIN POWER

25V20 DEX 7W PA FAN

1194 RPM 0.534 DENSITY

JULY '92 REVISED CURVE

1- FAN OPERATION

ORIGINAL SPECIFIED SYSTEM

CLOSED

JUNE 91 TESTS


IP7_031493

HOWDEN SIROCCO

Howden Sirocco Inc.

One Westinghouse Plaza, Suite 300
Hyde Park, MA 02136
Telephone (617) 361-3700
Fax (617) 361-0493

A Howden Group Company



July 24, 1991

Intermountain Power Service Corporation
Route 1 Box 864
Delta, Utah 84624

Attention: Mr. Jon Christensen

Subject: I.P.P. - P.A. Fan Performance

Dear Jon:

Further to our update of June 28, 1991, we give below the findings from our analysis of the problems associated with one - fan operation at the Intermountain plant and we discuss the options available to overcome these problems.

There are three main factors causing the problem.

Firstly, as already stated, the tests have shown the fan efficiency to be lower than expected, especially at the high speed operating point. We now know that this has happened because some of the lower load regions of the basic selection data were incorrect.

Secondly, there is no margin on motor power. The quoted test block BHP at 897 RPM is 2217 while the motor is rated at 2000 HP and the 5% service factor raises this to only 2100 HP. At the high speed duty the quoted BHP is 3989 with a motor rating of 4000.

The combination of lower efficiency and motor power limitation creates a 'Catch 22' situation. The vane setting has to be reduced to keep the amps down and this reduces fan efficiency still further. The present fans are capable of developing much more output at both speeds and of doing it more efficiently, if only the vanes could be opened further.

Another factor which is adding to the problem is that the actual operating systems for one and two - fan operation are to the right hand side of the original specified systems. Depending on the actual volume-pressure required, this can add from zero to 4% to power at low speed and zero to about 6% at high speed. It seems that the possibility of a variance in operating system, particularly under one - fan operation, was not taken into account when sizing the motors.

Mr. John Christensen

Page Two

July 24, 1991

There appears to be only two options available to overcome the problem.

1. Replacing the present wheels and inlets.

We have tried a considerable number of wheel selections and find that none of these will develop the original MCR duty of 252000 CFM at 47 ins WG and do it within the present motor limit of 2100 BHP.

This prompted us to look at other possibilities. Our first idea was that, in the light of operating experience, the opportunity should be taken to re-specify the load points. We have, therefore, chosen revised load points as follows. These points take into account the fact that the systems are further to the right and also we have reduced the pressures to keep within motor powers. Your earlier tests indicate that 100% MCR operation required about 37 ins. WG (at graph conditions). We have marked these new points on the test results graph for comparison.

MCR: 275,000 CFM @41 Ins. SP.

High Speed: 350,000 CFM @56 Ins. SP.


However, even this course has problems. We can certainly select 2 or 3 different wheels which will achieve these duties within the present motor power. Unfortunately, for the wheel sizes required, the present housing is not sufficiently close to what it should be, which creates doubt as to whether this arrangement would perform satisfactorily.

This leaves us with one other suggestion, which is to select the fans for the high speed duty and to run at high speed for both modes. This means we could cope with a high speed duty of 350000 CFM at 57 to 58 ins. WG and stay well within the 4000 power limit. The MCR operation would be achieved by closing the vanes. There would no longer be a power or output limitation at MCR and our selections show that the efficiency at this vane setting would be about the same as is presently achieved at this load. The wheel diameter would be much the same as at present and thus the housing will be close to what is required.

2) Replace the motors.

The other option for solving the problem is obviously to modify or replace the motors. This option would be more expensive and a longer lead time would be associated with it.

IP7_031495



Mr. Jon Christensen
Page Three
July 24, 1991

We hope the foregoing will be helpful in deciding the most viable course of action and we await your comments with regard to the new duty points. If the high speed option as discussed above is acceptable, we would be able to fine tune the selection and work up budget prices and delivery information within 5 or 6 days.

Sincerely,

Wm. C. Ireland.

W. C. Ireland
Senior Development Engineer

WCI/srm-0840E

cc: Mr. L. W. Krieger - Aurora, CO
Mr. R. E. Mahoney
Mr. J. P. Srivastava
Mr. R. G. Eddy

IP7_031497

ATTACHMENT 6

EXISTING BURNER GENERAL LAYOUT


Spec. 45606


ATTACHMENT 7

SECONDARY AIR DUCT AND WINDBOX DRAWINGS


IP7_031500


U.8551








IP7_031503




















INTERMOUNTAIN POWER SERVICE CORPORATION

ADDENDUM

TO

SPECIFICATIONS 45606 - NOx BURNERS

The following nine (9) pages should be considered additional information and incorporated as Attachment No. 8 to Bidding Documents and Specifications 45606:

As Fired Coal Sample Analyses - IPSC Fuels Lab

ATTACHMENT 8

AS FIRED COAL SAMPLE ANALYSES - IPSC FUELS LAB

AS FIRED COAL SAMPLE ANALYSES - IPSC FUELS LAB

<u>Lab #</u>	<u>Date</u>	Dry <u>Ash%</u>	Dry <u>S%</u>	Dry <u>C%</u>	Dry <u>H%</u>	Dry <u>N%</u>	Dry <u>O%</u>	Dry <u>Btu/lb</u>	<u>MAF BTU</u>
31303	10/1/2002	12.78	0.75	70.21	4.89	1.54	9.83	12544	14383
31307	10/2/2002	10.46	0.66	71.53	4.91	1.55	10.89	12784	14278
31317	10/3/2002	11.49	0.67	70.91	4.78	1.52	10.62	12659	14303
31325	10/4/2002	10.13	0.69	72.00	4.87	1.57	10.74	12897	14350
31326	10/5/2002	9.99	0.70	72.05	4.91	1.60	10.74	12945	14382
31329	10/6/2002	10.11	0.65	71.72	4.83	1.59	11.09	12798	14238
31335	10/7/2002	9.41	0.74	72.49	4.93	1.57	10.85	13000	14351
31339	10/8/2002	8.36	0.86	73.76	5.00	1.61	10.42	13289	14502
31345	10/9/2002	9.11	0.86	73.18	5.00	1.63	10.22	13187	14508
31353	10/10/2002	9.72	0.77	72.72	4.93	1.65	10.20	13127	14540
31358	10/11/2002	10.72	0.66	71.96	4.71	1.59	10.37	12809	14347
31361	10/12/2002	10.17	0.80	72.15	4.78	1.63	10.47	12915	14377
31364	10/13/2002	10.08	0.72	72.08	4.73	1.55	10.84	12912	14360
31372	10/14/2002	9.85	0.77	72.27	4.84	1.58	10.69	12961	14377
31375	10/15/2002	10.21	0.76	72.21	4.99	1.60	10.22	12895	14361
31377	10/16/2002	10.58	0.76	71.87	4.90	1.61	10.27	12900	14426
31382	10/17/2002	9.76	0.70	72.51	4.93	1.64	10.46	13021	14429
31389	10/18/2002	9.28	0.72	73.69	5.18	1.61	9.52	13156	14502
31392	10/19/2002	9.43	0.70	72.75	5.05	1.58	10.49	13088	14451
31395	10/20/2002	9.19	0.67	73.05	5.12	1.58	10.38	13042	14362
31398	10/21/2002	10.06	0.67	72.17	4.98	1.56	10.57	12937	14385
31408	10/22/2002	10.27	0.61	71.62	4.72	1.51	11.27	12797	14262
31412	10/23/2002	11.65	0.61	70.35	4.76	1.50	11.13	12597	14258
31417	10/24/2002	9.96	0.61	71.89	4.73	1.36	11.45	12859	14282
31422	10/25/2002	10.29	0.69	72.04	4.74	1.57	10.67	12701	14158
31426	10/26/2002	9.52	0.80	73.02	4.83	1.62	10.21	13109	14488
31429	10/27/2002	9.42	0.78	72.60	5.11	1.54	10.56	13061	14419
31435	10/28/2002	10.30	0.70	71.80	5.01	1.47	10.71	12899	14379
31437	10/29/2002	9.66	0.75	72.46	4.78	1.51	10.85	12781	14147

AS FIRED COAL SAMPLE ANALYSES - IPSC FUELS LAB

<u>Lab #</u>	<u>Date</u>	<u>Time</u>	<u>Moist%</u>	<u>Ash%</u>	<u>S%</u>	<u>Btu/lb</u>	<u>Res Mois%</u>	<u>C%</u>	<u>H%</u>	<u>N%</u>	<u>O%</u>
31303	10/1/2002	17:00	7.39	11.84	0.69	11617	2.08	65.02	4.53	1.43	9.10
31307	10/2/2002	17:00	9.28	9.49	0.60	11598	2.17	64.89	4.45	1.41	9.88
31317	10/3/2002	17:00	9.07	10.45	0.61	11511	1.94	64.48	4.35	1.38	9.66
31325	10/4/2002	17:00	9.15	9.20	0.63	11717	2.19	65.41	4.42	1.43	9.76
31326	10/5/2002	17:00	9.00	9.09	0.64	11780	1.73	65.57	4.47	1.46	9.77
31329	10/6/2002	17:00	7.70	9.33	0.60	11813	1.97	66.20	4.46	1.47	10.24
31335	10/7/2002	17:25	7.69	8.69	0.68	12000	1.93	66.92	4.55	1.45	10.02
31339	10/8/2002	17:25	6.72	7.80	0.80	12396	1.68	68.80	4.66	1.50	9.72
31345	10/9/2002	17:00	6.77	8.49	0.80	12294	1.66	68.23	4.66	1.52	9.53
31353	10/10/2002	17:00	6.90	9.05	0.72	12221	1.43	67.70	4.59	1.54	9.50
31358	10/11/2002	17:00	7.35	9.93	0.61	11868	1.35	66.67	4.36	1.47	9.61
31361	10/12/2002	17:00	6.96	9.46	0.74	12016	1.25	67.13	4.45	1.52	9.74
31364	10/13/2002	17:00	7.86	9.29	0.66	11897	1.55	66.41	4.36	1.43	9.99
31372	10/14/2002	17:00	7.60	9.10	0.71	11976	1.59	66.78	4.47	1.46	9.88
31375	10/15/2002	17:00	7.04	9.49	0.71	11987	1.75	67.13	4.64	1.49	9.50
31377	10/16/2002	17:15	6.82	9.86	0.71	12020	1.33	66.97	4.57	1.50	9.57
31382	10/17/2002	17:00	7.15	9.06	0.65	12090	1.44	67.33	4.58	1.52	9.71
31389	10/18/2002	17:00	7.22	8.61	0.67	12206	1.30	68.37	4.81	1.49	8.83
31392	10/19/2002	17:00	6.80	8.79	0.65	12198	1.33	67.80	4.71	1.47	9.78
31395	10/20/2002	17:00	7.12	8.54	0.62	12113	1.55	67.85	4.76	1.47	9.64
31398	10/21/2002	17:00	6.78	9.38	0.62	12060	1.50	67.28	4.64	1.45	9.85
31408	10/22/2002	17:00	7.19	9.53	0.57	11877	2.04	66.47	4.38	1.40	10.46
31412	10/23/2002	17:00	7.54	10.77	0.56	11647	1.74	65.05	4.40	1.39	10.29
31417	10/24/2002	17:00	8.17	9.15	0.56	11808	2.37	66.02	4.34	1.25	10.51
31422	10/25/2002	17:00	7.19	9.55	0.64	11788	1.44	66.86	4.40	1.46	9.90
31426	10/26/2002	17:00	6.72	8.88	0.75	12228	1.57	68.11	4.51	1.51	9.52
31429	10/27/2002	17:00	7.64	8.70	0.72	12063	1.55	67.05	4.72	1.42	9.75
31435	10/28/2002	16:30	7.75	9.50	0.65	11899	1.73	66.24	4.62	1.36	9.88
31437	10/29/2002	17:00	7.72	8.91	0.69	11794	1.42	66.87	4.41	1.39	10.01

Test#							
Date Tested	7/7/2003	7/7/2003	7/9/2003	7/9/2003	7/2/2003	7/7/2003	7/8/2003
Unit	1	1	1	1	1	1	1
Mill	A	B	C	D	E	F	G
% Feeder Speed	80	80	80	80	80	80	80
Actual % Through 200 Mesh	73.90	68.20	70.60	68.80	75.40	74.00	65.40
Expected % Through 200 Mesh	62.26	64.41	68.22	67.12	62.74	62.67	66.26
HGI	44.0	45.7	48.1	47.4	44.8	44.0	46.5
Total Moisture	7.79	8.66	8.16	8.44	9.15	7.36	8.20
Air Dry Loss	6.46	7.30	6.89	7.07	7.59	5.92	6.44
As Received Btu	11,867	11,782	11,932	11,969	11,519	12,118	11,823

Test Period Average Data

Test							
Unit Pulv	1/A	1/B	1/C	1/D	1/E	1/F	1/G
% Feeder Speed	79.71	83.08	81.37	81.74	80.32	80.51	80.52
Actual Pulv Coal Flow (tph)	54.17	53.60	55.33	55.56	54.62	54.73	54.75
PA Damper Position (%)	75.51	82.06	98.98	77.43	87.74	75.59	74.52
PA Flow (%)	92.14	92.16	92.42	94.29	91.38	91.63	92.24
PA Inlet Damper Temp (DEGF)	300.77	322.53	325.48	310.52	316.49	322.19	325.57
PA D/P (INWC)	16.94	18.12	25.16	19.80	20.30	17.77	12.51
Disch Temp (DEGF)	150.00	151.07	150.92	150.03	150.94	151.02	150.95
Pulv Motor (amps)	68.48	58.57	67.91	61.27	79.34	64.04	51.72
PA Mass Flowrate (lb/mln)	3709	3639	3624	3663	3617	3596	3677
air to fuel ratio	2.02	1.93	1.98	2.01	1.98	1.99	2.00
Pulv hrs since 30K Overhaul	12395	15858	6315	2481	1884	13380	11708
Pulv H amp swing	9.24	6.16	7.96	6.78	10.63	8.71	5.62
PA Duct Pressure (INWC)	47.82	48.27	46.30	46.22	43.70	48.24	47.13
Hydraulic Skid Press FeedBack	2297	2219	392	2209	2159	2383	2046
Hydraulic Skid Press Set Pt	2388	2400	2399	2400	2388	2398	2397

Test

Mill	A	B	C	D	E	F	G
* Contract % Through 200 Mesh @ 95 % FDR SPEED	70	70	70	70	70	70	70
HGI Correction	0.880	0.914	0.962	0.948	0.896	0.880	0.930
Moisture Correction	0.975	0.967	0.971	0.969	0.964	0.981	0.976
Fineness Correction	1.118	1.086	1.028	1.045	1.111	1.112	1.058
Expected % Through 200 Mesh (Good @ 65 tph only)	62.26	64.41	68.22	67.12	62.74	62.67	66.26
Actual % Through 200 Mesh	73.90	68.20	70.60	68.80	75.40	74.00	65.40
Difference	11.64	3.79	2.38	1.68	12.66	11.33	-0.86
Ratio	118.69	105.88	103.49	102.50	120.18	118.07	98.71
% Retained on 30 & 50 Mesh	0.20	0.30	0.30	0.10	0.00	0.20	0.10
Actual % Through 50 Mesh	99.60	99.50	99.30	99.00	99.70	99.50	99.30
Actual % Through 100 Mesh	96.70	94.60	95.90	95.70	97.20	96.80	94.80

*Contract coal - HGI and air dry loss < 4%.

Expected is 100% fineness correction vs % through 200 mesh graph.

Expected

62.26

64.41

68.22

67.12

62.74


62.67

66.26

IP7_031517

CONTRACT INFORMATION SHEET

3



THESE CURVES ARE SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION.

DRAWN BY J. NEIDERT	DATE 2-1-82	APPROVED BY RND	DATE 2-5-82	A.O.
REL. NO. AND DATE 1 9-8-82		CONTRACT NO. 334-0614		FILE NO. RB-614

TITLE - D11 VERTICALLY-RISE COORDINATION CURVES - COAL (B)

CIS- 101.05

IP7_031518

[illegible]

SUBJECT Customer Information per Div. FI Article 7 DATE 12-8-81 PAGE 3 of 3

File
(10)
b

File
(11)

File
(12)
b

File
(13)

condary

r system

File
(14)

File
(15)

thru g

MCR 100% 75% 50% 25%						MCR 100% 75% 50% 25%					
MLB/HR Air: Tot. Air Ent. Pri. AH						Gas Velocity - fpm					
Tot. Air Ent. Sec. AH						Ent. Sec. SH S.I. = 24"					
Tot. Air Lvg. Pri. AH						Ent. Sec. SH S.I. = 12"					
Tot. Air Lvg. Sec. AH						Ent. Pendant RH					
Air Ent. Pri. AH @ 80° - CFM						Ent. Horiz. RH					
Total Air						Ent. Horiz. SH					
Air Ent. Sec. AH @ 80° - CFM						Coal Consumption					
						LB/HR					
Air Temp. Ent. Pri. AH											
" " Ent. Sec. AH											
Air Temp. Lvg. Pri. AH											
" " Lvg. Sec. AH											
Air Pressure - (inches H ₂ O)											
loss through air htr pri/sec											
loss through duct work											
required at bmr. windbox											
total required at AH inlet*											
Heat Absorbed by Boiler %											
Heat Loss % Due to:											
H ₂ O from combustion of hydrogen & moisture in fuel											
Theoretical dry gas											
Excess air & moisture @ air heater outlet (uncorrected)											
Moisture in theoretical air											
Radiation loss											
Unburned carbon											
Unacct. for & Manuf. margin											

RECEIVED FOR
DISTRIBUTION
SEP 7 1982
BLACK & VEATCH

THIS INFORMATION IS SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION.
DWG. JN-120881-3-0

6-10080

IP7_031520

SUBJECT Customer Information per Div. FI Article 7 DATE 12-8-81 PAGE 2 of 3

Article
7.1(c)(4)
(5)

ALL TEMPERATURES - HVT (°F)	MCR	100%	75%	50%	25%		MCR	100%	75%	50%	25%	
Gas Temp. Entering Flatens	2471	2440	2327	2080	1662	Flue Gas Temperature Lvg AH's (uncor/corr)						Article 7.1(c)
Gas Temp. Leaving Flatens	2108	2076	1963	1739	1375	Pri AH	313/279	312/280	316/281	323/280	335/280	
" " Ent. SSH S ₁ = 24"	2108	2076	1963	1739	1375	Sec AH	295/285	292/282	273/263	253/243	222/210	
" " Lvg. SSH S ₁ = 24"	1830	1804	1690	1500	1203	Gas CFM Lvg. AH's at T corrected						Article 7.1(c)
" " Ent. SSH S ₁ = 12"	1750	1776	1660	1475	1184	Total Air	414437	400069	355460	288912	213685	
" " Lvg. SSH S ₁ = 12"	1640	1615	1520	1351	1104	Sec AH	2566844	2433861	1900740	1344646	730180	
" " Ent. RH Outlet Bank	1615	1588	1488	1335	1085	Gas Flow Eng. AH's (MLB/HR) Pri AH	962.0	924.0	817.0	646.0	463.5	Article 7.1(c) a &
" " Lvg. RH Outlet Bank	1470	1449	1360	1231	996	" Sec AH	6588.2	6285.5	5054.9	3665.1	2024.8	
" " Ent. RH Intermedi. Pendant	1460	1435	1350	1220	988	Gas Flow Lvg. AH's (MLB/HR) Pri AH	1132.2	1093.0	971.0	793.0	601.5	
" " Lvg. RH Intermedi. Pend. Bank	1365	1340	1270	1147	926	Sec AH	6918.2	6600.5	5307.9	3881.1	2218.9	
" " Ent. Horiz. RH Bank (4)	1305	1285	1214	1093	886	Gas Distribution through horiz. convection pass (%) RH/FSH	41/59	44/56	60/40	75/25	30/62	Article 7.1(c)
" " Ent. Horiz. RH Bank (3)	1104	1094	1055	975	764	Excess Air - %						Article 7.1(c) a b c
" " Ent. Horiz. RH Bank (2)	988	962	958	899	701	leaving furnace	16	16	19.5	27	30	
" " Ent. Horiz. RH Bank (1)	862	860	844	802	635	leaving econ.	17	17	20.5	28	51	
" " Ent. Pri. SH Outlet Bank	1285	1269	1191	1062	877	*leaving airheaters	26	26	29.5	37	74	
" " Lvg. Pri. SH Outlet Bank	1230	1211	1119	978	845	*Primary & Secondary Airheaters Combined						
" " Ent. Horiz. Pri. SH Bank (3)	1190	1167	1063	910	815							
" " Ent. Horiz. Pri. SH Bank (2)	1055	1034	938	808	768							
" " Ent. Horiz. Pri. SH Bank (1)	920	903	826	736	724							
" " Ent. Econ. Bank (2)	842	827	764	694	693							
" " Ent. Econ. Bank (1)	765	751	686	603	598							
" " Ent. Airheaters	744	736	707	675	567							

RECEIVED FOR
DISTRIBUTION
SEP 1 1982
BLACK & VEATCH

THIS INFORMATION IS SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE
PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONTINUED
BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION.

DMG. JN-120881-2-0

6-10079

IP7_031521

SUBJECT: Customer Information per Div. FI Article 7

DATE 12-8-81 PAGE 1 OF 3

RECEIVED FOR
DISTRIBUTION

SEP 7 1962

STARK & VEATCH

Article
'1(c)(1)

	MCR		100%		75%		50%		25%						
	PRESS PSIG	TEMP °F	P PSIG	T °F	P PSIG	T °F	P PSIG	T °F	P PSIG	T °F					
Economizer Inlet Header	2880	554	2723	545	2600	512	2510	470	2458	405	Gas Pressure (in. H ₂ O)	MCR	100%	75%	25%
Economizer Intermediate Hdr.	2866	571	2711	561	2590	526	2501	481	2450	438	Leaving Furnace	-0.1	-0.1	-0.1	-0.1
Economizer Outlet Header	2841	574	2686	565	2567	529	2480	484	2430	443	Ent. Sec. SH S.A. = 24"	-0.1	-0.1	-0.1	-0.1
Steam Drum	2822	687	2670	679	2558	671	2475	667	2448	665	Ent. SSH Out. S.A. = 12"	-0.21	-0.20	-0.17	-0.14
Furnace Lower Wall Hdrs.	2879	667	2723	659	2608	656	2523	654	2472	651	Ent. NH Outlet Bank	-0.32	-0.30	-0.23	-0.17
Furnace Upper Wall Hdrs.	2827	687	2675	679	2562	671	2478	667	2430	665	Ent. NH Fend. Bank	-0.49	-0.47	-0.35	-0.23
Primary SH Inlet Headers	2791	695	2644	687	2544	683	2469	679	2426	674	Ent. Horiz. NH (4)	-0.72	-0.64	-0.46	-0.29
Primary SH Outlet Header	2773	720	2628	720	2536	709	2464	692	2425	692	Ent. Horiz. NH (3)	-1.10	-1.02	-0.93	-0.63
Furn. Platen SH Inlet Hdr.	2758	717	2615	706	2529	694	2461	692	2425	692	Ent. Horiz. NH (2)	-1.30	-1.23	-1.19	-0.85
Furn. Platen SH Outlet Hdr.	2732	784	2592	777	2516	777	2455	782	2423	781	Ent. Horiz. NH (1)	-1.58	-1.52	-1.56	-1.15
Secondary SH Inlet Hdrs.	2717	784	2579	777	2508	764	2452	775	2422	781	Ent. Pri. SSH Outlet Bank	-0.61	-0.55	-0.40	-0.23
Sec. SH Intermediate Manifolds	2699	914	2563	912	2500	908	2448	919	2421	892	Ent. Horiz. PSN (3)	-0.72	-0.64	-0.43	-0.24
Secondary SH Outlet Hdr.	2645	1005	2515	1005	2473	1005	2436	1005	2415	950	Ent. Horiz. PSN (2)	-0.88	-0.77	-0.47	-0.25
Reheat Inlet Header	575	625	546	623	420	583	287	553	141	530	Ent. Horiz. PSN (1)	-1.09	-0.93	-0.53	-0.26
Reheat Outlet Headers	551	1005	524	1005	402	1005	275	975	141	850	Ent. Econ. Bank (2)	-1.27	-1.07	-0.58	-0.27
	MCR		100%		75%		50%		25%		Ent. Econ. Bank (1)	-1.38	-1.16	-0.61	-0.28
First Stage Attenuator Data											Econ. Hopper Press.	-2.07	-2.01	-2.11	-1.62
(Lb/Hr) Total Expected Flow	43608		183359		161831		0.0		0.0						-0.56
" Design "	653453		616547		462909		222656		84201		Press. Ent. Pri. AH*	-4.20	-4.07	-3.86	-3.15
(psi) Expected Nozzle Δ P	1.0		11.1		8.2		0.0		0.0		Press. Ent. Sec. AH*	-3.71	-3.64	-3.32	-2.94
" Design "	77.7		66.6		38.6		8.7		1.2		Press. Lvg. Pri. AH	-6.05	-5.77	-5.26	-4.10
Second Stage Attenuator Data											Press. Lvg. Sec. AH	-7.61	-7.44	-6.12	-4.44
(Lb/Hr) Total Expected Flow	0.0		0.0		49581		18374		0.0		*Including stack effect				
" Design "	240392		384506		456107		230490		23201		THIS INFORMATION IS SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION (DWC. JN-120881-1-0)				
(psi) Expected Nozzle Δ P	0.0		0.0		1.2		1.0		0.0						
" Design "	24.4		57.7		81.4		20.0		1.0						
Reheat Attenuator Data															
(Lb/Hr) Total Design Flow	207480		197000		151600		103200		45480						
(psi) Design Nozzle Δ P	88.8		81.0		47.3		21.6		4.3						
(°F) Spray Water Temp.	343		342		325		302		265						

Article
7.1(c)
a, b
c

b1
b7C
b7D
title
1(c)(2)




THIS INFORMATION IS SUBMITTED FOR THE PURCHASER'S CONVENIENCE AND THE PERFORMANCE INDICATED THEREON SHALL NOT BE OFFERED BY THE COMPANY OR CONSTRUED BY THE PURCHASER AS A PROPOSAL OR CONTRACT OBLIGATION (DMC, JN-120681-1-0)

6-10078

IP7 031522

DISCLOSURE NOTICE:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
2. ADVANCED BURNER TECHNOLOGIES IS A REGISTERED SERVICE MARK OF ADVANCED BURNER TECHNOLOGIES. ALL OTHERS ARE SUBJECT TO ONE OR MORE U.S. PATENT APPLICATIONS.



ITEM NO.	QTY.	PART NUMBER	MATERIAL	DESCRIPTION
1	1	03008-100-A03-D0	SEE DRAWING	BURNER SHOP ASSEMBLY
2	15 LF	03008-100-A00-D01	—	BOLT HOLE GASKET TAPE 2" WIDE COMPRESS TO 1/8"
3	1	03008-500-A00-0	SEE DRAWING	VERTICAL FUEL DISTRIBUTION ASSEMBLY
4	1	03008-500-A02-D0	SEE DRAWING	HORIZONTAL FUEL DISTRIBUTOR
5	80	FW 1	STEEL	1" FLAT WASHER
6	40	HHBOLT 1.0000-8x3.5x1.75-C	STEEL	1"-8 UNC X 3 1/2" X 1 3/4" THREAD HEAVY HEX BOLT
7	40	HHNUT 1.0000-8-D-C	STEEL	1"-8 UNC HEAVY HEX NUT
8	1	D232666-105	SEE DRAWING	ABB FLAME SCANNER
9	1	03008-100-A03-D07	SEE DRAWING	CROSSOVER SUPPORT (SHIPPED WITH UNIT)
10	1	03008-100-A03-D02	ASTM A36 C.S.	78 1/4" ID X 2 3/4" X 1/4" THK BAR (SHIPPED WITH UNIT)
11	1	03008-100-A03-D09	ASTM A36 C.S.	L 3" X 3" X 5/16" THK ROLLED HW TO 57 1/4" ID (SHIPPED WITH UNIT)



- REMOVAL AND INSTALLATION NOTES:
1. REMOVE ELBOW
 2. INSTALL VFD ITEM 3 (VERTICAL FUEL DISTRIBUTOR) PER DRAWING 03008-500-A03-0 IN EXISTING ELBOW
 3. DISCONNECT SEAL AIR PIPING, OIL, STEAM LINES AND ALL ELECTRICAL LEADS
 4. REMOVE EXISTING SCANNERS, DISCARD.
 5. REMOVE EXISTING OIL IGNITER AND SET ASIDE FOR REUSE
 6. REMOVE INSULATION AND LAGGING AROUND EXISTING BURNER FRONT PLATE
 7. REMOVE EXISTING BURNER AND DISCARD
 8. BREAK TACK WELDS OF SUPPORT RING, ITEM 10
 9. INSTALL NEW BURNER. SEE DRAWING 03008-100-A01-FW AND 03008-100-A01-RW FOR BURNER LOCATION AND SPIN.
 10. CENTER BURNER IN FURNACE WALL OPENING AND LEVEL AND PLUMB BURNER. LOCATE TIP PER SIDE VIEW.
 11. INSTALL BURNER CROSSOVER SUPPORT ITEM 9 (03008-100-A03-D07). SHIM TO FIT TO EXISTING SUPPORT RAILS. COMPLETE WELDING PER SECTION D-D
 12. LOCATE SUPPORT RING, ITEM 10, AGAINST WINDBOX WALL. TACK WELD TO WINDBOX AND BURNER FRONT PLATE
 13. FINISH WELDING FRONT PLATE IN PLACE SEE DETAIL "C"
 14. INSTALL ITEM 4 HFD (HORIZONTAL FUEL DISTRIBUTOR) ON ELBOW WITH NEW GASKET, NUTS, BOLTS AND WASHERS.
 15. INSTALL COAL ELBOW & HORIZONTAL FUEL DISTRIBUTOR ASSEMBLY WITH NEW GASKETS, NUTS, BOLTS AND WASHERS.


16. IF NECESSARY, REPOSITION THE BURNER TO FIT UP WITH THE FUEL LINE.
17. FINISH WELDING BURNER FRONT AND SUPPORT RING.
18. INSTALL FLAME SCANNER PER ABB DRAWING: 902-2491-AA
STNRD-B232666-107
STNRD-D232665-025
STNRD-D232677-002
STNRD-00-D623232-000-001
29435E
19. INSTALL OIL IGNITER PER THIS DRAWING AND B&W DRAWING 29435E
20. INSTALL T/C LEADS PER MANUFACTURE INSTRUCTIONS.
21. MAKE ALL OIL AND STEAM CONNECTIONS.
22. MAKE ALL ELECTRICAL CONNECTIONS FOR THERMOCOUPLES, AND MAIN FLAME SCANNER.
23. REINSULATE AND LAG BURNER FRONT
24. AFTER DRAFT FANS HAVE BEEN STARTED CAREFULLY TIGHTEN ALL PACKING GLANDS TO STOP ANY LEAKS AROUND SHAFTS (DO NOT OVER TIGHTEN). RECHECK ALL OPERATORS FOR MOVEMENT.

GENERAL NOTES:
1. QUANTITY SHOWN IN BOM ARE FOR ONE UNIT
2. OVERLAP ENDS 2".
PURCHASE FROM:
HUNTER SALES CORP
3338 INDUSTRIAL BLVD.
BETHEL PARK, PA
412-833-4333
3. REFERENCE DRAWINGS
000-100-HANDLING



TOLERANCES UNLESS SPECIFIED		CUSTOMER DRAWING		ADVANCED BURNER TECHNOLOGIES	
UP TO 8" INCL	±0.016"	MACHINE WELD PARTS	NAME	DATE	
OVER 8" TO 12" INCL	±0.03"	DO NOT MANUALLY UPDATE	RJ	1/15/2004	
OVER 12" TO 24" INCL	±0.06"				
OVER 24" INCL	±0.125"				
SURFACE ROUGHNESS: 125		CHECKED		OPTI-FLOW BURNER	
BREAK SHARP CORNERS		BEG. APPR.		IGS UNIT 3	
DO NOT SCALE PRINT		MFG APPR.		FIELD ASSEMBLY	
CUSTOMER NAME		PLANT NAME		REV	
I.P.S.C.		IGS		C 03008-100-A02-D0	
PART NO.		QTY		SCALE 1:24	
A03008		24		SHEET 1 OF 1	
A03008		24			
CONTRACT NO.		PART NO.			

DISCLOSURE NOTICES:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
2. THE STRUCTURE AND OPERATION OF OPTI-FLOW FUEL DISTRIBUTION SYSTEM AND DUAL REGISTERS ARE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.



A	SPIN VANE DRIVE	IN TO OPEN	5 3/4"
B	EXISTING OIL IGNITOR		
C	ABB FIBER OPTIC FLAME SCANNER		
D	DAMPER DRIVE	IN TO OPEN	16"
E	SIGHT TUBE & PURGE VALVE	1/2" FNP	
F	INNER AIR ZONE DAMPER	PUSH TO OPEN	6"
G1	TIP THERMOCOUPLE JUNCTION BOX		
G2	BODY THERMOCOUPLE JUNCTION BOX		
H1	AIR FLOW MONITORING CONNECTIONS	TOTAL PRESSURE	
H2	AIR FLOW MONITORING CONNECTIONS	STATIC PRESSURE	

A03008	03008-100-A00-D0 CW	24
A03008	03008-100-A00-D0 CCW	24
CONTRACT NO.	PART NO.	QTY.

EST. WEIGHT: 8829.63 lb.
MATERIAL:
SIZE:
TYPE:
ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
CUSTOMER NAME
I.P.S.C.


TOLERANCES UNLESS SPECIFIED		
	MACHINE WELD FABRICATED PARTS	
UP TO 6" INCL	±0.016"	±0.03"
OVER 6" TO 12" INCL	±0.03"	±0.06"
OVER 12" TO 24" INCL	±0.05"	±0.09"
OVER 24"	±0.06"	±0.125"
ANGLES TO 30° SURFACE ROUGHNESS NOT EXCEED 125 BREAK SHARP CORNERS DO NOT SCALE PRINT		
PLANT NAME	UNIT	
IGS	2	

CAD GENERATED DRAWING DO NOT MANUALLY UPDATE	NAME	DATE
	RJ	10/27/2003
CHECKED		
ENG APPR.		
MFG APPR.		
G.A.		

REVISION			
3	1/17/2004	ADDED PURGE VALVE	RJ
2	12/10/2003	MOVED SCANNER TO OPPOSITE SIDE	RJ
1	11/20/2003	ADDED AIR FLOW MONITORING CONNECTIONS	RJ
REV	DATE	DESCRIPTION	BY
ADVANCED BURNER TECHNOLOGIES			
OPTI-FLOW BURNER IGS UNIT 3 GENERAL ARRANGEMENT			
SCALE	1:24	SHEET	1 OF 1

IP7_031524


DISCLOSURE NOTICE:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCE BURNER TECHNOLOGIES CORP. NO PART OF THIS DRAWING MAY BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, WITHOUT THE WRITTEN PERMISSION OF ADVANCE BURNER TECHNOLOGIES CORP.
2. THE STRUCTURE AND OPERATION OF THIS FUEL DISTRIBUTION SYSTEM AND DUAL REGISTER ARE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.



- NOTES:
- 1. CUSTOMER TO SUPPLY BURNER NUMBERS.
 - 2. CUSTOMER TO SUPPLY DRAWING TO SHOW ELBOW ORIENTATIONS.
 - 3. CUSTOMER TO SUPPLY PLATFORM ELEVATIONS.

1		1/7/2004		ADDED CUSTOMER COMMENTS		RJ	
REV.		DATE		REVISION		BY	
REVISIONS							
1		1/7/2004		ADVANCED BURNER TECHNOLOGIES CORP.			
2		1/7/2004		OPTI FLOW BURNER			
3		1/7/2004		ICS UNIT 2			
4		1/7/2004		GENERAL ARRANGEMENTS RW			
5		1/7/2004		GENERAL ARRANGEMENTS RW			
6		1/7/2004		GENERAL ARRANGEMENTS RW			
7		1/7/2004		GENERAL ARRANGEMENTS RW			
8		1/7/2004		GENERAL ARRANGEMENTS RW			
9		1/7/2004		GENERAL ARRANGEMENTS RW			
10		1/7/2004		GENERAL ARRANGEMENTS RW			
11		1/7/2004		GENERAL ARRANGEMENTS RW			
12		1/7/2004		GENERAL ARRANGEMENTS RW			
13		1/7/2004		GENERAL ARRANGEMENTS RW			
14		1/7/2004		GENERAL ARRANGEMENTS RW			
15		1/7/2004		GENERAL ARRANGEMENTS RW			
16		1/7/2004		GENERAL ARRANGEMENTS RW			
17		1/7/2004		GENERAL ARRANGEMENTS RW			
18		1/7/2004		GENERAL ARRANGEMENTS RW			
19		1/7/2004		GENERAL ARRANGEMENTS RW			
20		1/7/2004		GENERAL ARRANGEMENTS RW			
21		1/7/2004		GENERAL ARRANGEMENTS RW			
22		1/7/2004		GENERAL ARRANGEMENTS RW			
23		1/7/2004		GENERAL ARRANGEMENTS RW			
24		1/7/2004		GENERAL ARRANGEMENTS RW			
25		1/7/2004		GENERAL ARRANGEMENTS RW			
26		1/7/2004		GENERAL ARRANGEMENTS RW			
27		1/7/2004		GENERAL ARRANGEMENTS RW			
28		1/7/2004		GENERAL ARRANGEMENTS RW			
29		1/7/2004		GENERAL ARRANGEMENTS RW			
30		1/7/2004		GENERAL ARRANGEMENTS RW			
31		1/7/2004		GENERAL ARRANGEMENTS RW			
32		1/7/2004		GENERAL ARRANGEMENTS RW			
33		1/7/2004		GENERAL ARRANGEMENTS RW			
34		1/7/2004		GENERAL ARRANGEMENTS RW			
35		1/7/2004		GENERAL ARRANGEMENTS RW			
36		1/7/2004		GENERAL ARRANGEMENTS RW			
37		1/7/2004		GENERAL ARRANGEMENTS RW			
38		1/7/2004		GENERAL ARRANGEMENTS RW			
39		1/7/2004		GENERAL ARRANGEMENTS RW			
40		1/7/2004		GENERAL ARRANGEMENTS RW			
41		1/7/2004		GENERAL ARRANGEMENTS RW			
42		1/7/2004		GENERAL ARRANGEMENTS RW			
43		1/7/2004		GENERAL ARRANGEMENTS RW			
44		1/7/2004		GENERAL ARRANGEMENTS RW			
45		1/7/2004		GENERAL ARRANGEMENTS RW			
46		1/7/2004		GENERAL ARRANGEMENTS RW			
47		1/7/2004		GENERAL ARRANGEMENTS RW			
48		1/7/2004		GENERAL ARRANGEMENTS RW			
49		1/7/2004		GENERAL ARRANGEMENTS RW			
50		1/7/2004		GENERAL ARRANGEMENTS RW			
51		1/7/2004		GENERAL ARRANGEMENTS RW			
52		1/7/2004		GENERAL ARRANGEMENTS RW			
53		1/7/2004		GENERAL ARRANGEMENTS RW			
54		1/7/2004		GENERAL ARRANGEMENTS RW			
55		1/7/2004		GENERAL ARRANGEMENTS RW			
56		1/7/2004		GENERAL ARRANGEMENTS RW			
57		1/7/2004		GENERAL ARRANGEMENTS RW			
58		1/7/2004		GENERAL ARRANGEMENTS RW			
59		1/7/2004		GENERAL ARRANGEMENTS RW			
60		1/7/2004		GENERAL ARRANGEMENTS RW			
61		1/7/2004		GENERAL ARRANGEMENTS RW			
62		1/7/2004		GENERAL ARRANGEMENTS RW			
63		1/7/2004		GENERAL ARRANGEMENTS RW			
64		1/7/2004		GENERAL ARRANGEMENTS RW			
65		1/7/2004		GENERAL ARRANGEMENTS RW			
66		1/7/2004		GENERAL ARRANGEMENTS RW			
67		1/7/2004		GENERAL ARRANGEMENTS RW			
68		1/7/2004		GENERAL ARRANGEMENTS RW			
69		1/7/2004		GENERAL ARRANGEMENTS RW			
70		1/7/2004		GENERAL ARRANGEMENTS RW			
71		1/7/2004		GENERAL ARRANGEMENTS RW			
72		1/7/2004		GENERAL ARRANGEMENTS RW			
73		1/7/2004		GENERAL ARRANGEMENTS RW			
74		1/7/2004		GENERAL ARRANGEMENTS RW			
75		1/7/2004		GENERAL ARRANGEMENTS RW			
76		1/7/2004		GENERAL ARRANGEMENTS RW			
77		1/7/2004		GENERAL ARRANGEMENTS RW			
78		1/7/2004		GENERAL ARRANGEMENTS RW			
79		1/7/2004		GENERAL ARRANGEMENTS RW			
80		1/7/2004		GENERAL ARRANGEMENTS RW			
81		1/7/2004		GENERAL ARRANGEMENTS RW			
82		1/7/2004		GENERAL ARRANGEMENTS RW			
83		1/7/2004		GENERAL ARRANGEMENTS RW			
84		1/7/2004		GENERAL ARRANGEMENTS RW			
85		1/7/2004		GENERAL ARRANGEMENTS RW			
86		1/7/2004		GENERAL ARRANGEMENTS RW			
87		1/7/2004		GENERAL ARRANGEMENTS RW			
88		1/7/2004		GENERAL ARRANGEMENTS RW			
89		1/7/2004		GENERAL ARRANGEMENTS RW			
90		1/7/2004		GENERAL ARRANGEMENTS RW			
91		1/7/2004		GENERAL ARRANGEMENTS RW			
92		1/7/2004		GENERAL ARRANGEMENTS RW			
93		1/7/2004		GENERAL ARRANGEMENTS RW			
94		1/7/2004		GENERAL ARRANGEMENTS RW			
95		1/7/2004		GENERAL ARRANGEMENTS RW			
96		1/7/2004		GENERAL ARRANGEMENTS RW			
97		1/7/2004		GENERAL ARRANGEMENTS RW			
98		1/7/2004		GENERAL ARRANGEMENTS RW			
99		1/7/2004		GENERAL ARRANGEMENTS RW			
100		1/7/2004		GENERAL ARRANGEMENTS RW			

DISCLOSURE NOTICE:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCE BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCE BURNER TECHNOLOGIES IS PROHIBITED.
2. THE STRUCTURE AND OPERATION OPTI-FLOW® FUEL DISTRIBUTION SYSTEM AND DUAL REGISTER ARE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.




FRONT WALL BURNER ARRANGMENT
(STANDING OUTSIDE THE BOILER LOOKING NORTH OR INTO THE BOILER) ⚠

- NOTES:
⚠ 1. CUSTOMER TO SUPPLY BURNER NUMBERS.
2. CUSTOMER TO SUPPLY DRAWING TO SHOW ELBOW ORIENTATIONS.
3. CUSTOMER TO SUPPLY PLATFORM ELEVATIONS.


1 1/7/2004		ADDED CUSTOMER COMMENTS AND BURNER NUMBERS		RJ
NO.	DATE	REVISIONS	BY	
REVISIONS				
ADVANCED BURNER TECHNOLOGIES CORP.				
OPTI FLOW BURNER				
IGS UNIT 2				
GENERAL ARRANGEMENTS FW				
E1 03008-100-A01-FW				
1				

MATERIAL:	EST. WEIGHT:
SIZE:	ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
TYPE:	BRIDGE BURNER ORIENTED TO NOT SCALE BURNER
CUSTOMER NAME:	PLAY NAME
I.P.S.C.	IGS
	2

IP7_031527



DISCLOSURE NOTICES:
1. THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF ADVANCED BURNER TECHNOLOGIES. ANY REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF ADVANCED BURNER TECHNOLOGIES IS PROHIBITED.
2. THE STRUCTURE AND OPERATION OF OPTI-FLOW FUEL DISTRIBUTION SYSTEM AND DUAL REGISTERS ARE SUBJECT OF ONE OR MORE U.S. PATENT APPLICATIONS.



INLET OF ELBOW

CONTRACT NO.	PART NO.	QTY.

EST. WEIGHT: lb.
MATERIAL:
SIZE:
TYPE:
ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
CUSTOMER NAME

TOLERANCES UNLESS SPECIFIED		
	MACHINE WELD FABRICATED PARTS	
UP TO 6" INCL.	±0.015"	±0.03"
OVER 6" TO 12" INCL.	±0.03"	±0.05"
OVER 12" TO 24" INCL.	±0.05"	±0.09"
OVER 24"	±0.06"	±0.125"
ANGLES ±0° 30'		
SURFACE ROUGHNESS NOT EXCEED 125		
BREAK SHARP CORNERS		
DO NOT SCALE PRINT		
PLANT NAME	UNIT	

CAD GENERATED DRAWING DO NOT MANUALLY UPDATE	
NAME	DATE
DRAWN RJ	12/18/2003
CHECKED	
ENG APPR.	
MFG APPR.	
Q.A.	



OPTI-FLOW BURNER
EXISTING ELL MOD'S
INSTALLATION OF VFD

SHEET	03008-500-A03-D0	REV
SCALE	1:6	SHEET 1 OF 1

IP7_031528